

Master Capital Plan Our Community, Our Facilities



A Message from the Long Range Planning Committee (LRPC)

The DCSD Long Range Planning Committee (LRPC) is pleased to present the 2021-2022 Master Capital Plan (MCP). Due to the challenges associated with the COVID pandemic, the LRPC was not able to publish a MCP for the 2020-2021 school year.

Celebrations

Funds from the 2018 bond have allowed DCSD to address security upgrades at all neighborhood and charter schools, the most urgent capital improvement projects, and needed purchases for Information and Technology, and buses. In addition, the Castle View High School expansion has been completed, and other major building projects are on the immediate horizon including a new alternative education school.

Challenges

Like school districts across the country, DCSD faced more challenges than usual during 2020, with COVID changing the ability to use school buildings and buses at full capacity as social distancing was required. Overall public school enrollment decreased across the state, including in DCSD where we saw an enrollment decline as families made adjustments due to COVID. In addition, in DCSD, approximately 3,150 students enrolled in the eLearning option to learn 100% remotely from home.

A high demand for homes has propelled new housing growth across Douglas County and in 2020 3,656 residential building permits were issued by the county. These challenges have made projecting student enrollment in the future more challenging than ever.

School Capacity and Boundary Analysis

A significant portion of the LRPC's work this year was focused on the School Capacity Boundary Analysis, the likes of which had not been done in many years. For several years, the LRPC has been monitoring discrepancies in enrollment projections across DCSD. While some areas of DCSD show growth of student populations, other areas show a leveling off of student numbers and even a decline in certain schools.

The School Capacity and Boundary Analysis began in 2019 with the hiring of Western Demographics to study student populations across DCSD to better understand enrollment projections, potential impacts, and to make recommendations about potential solutions. What is clear is that there are multiple issues if a school is either over-enrolled or substantially under-enrolled. For instance, an over-enrolled school can have difficulties presenting adequate instructional space which puts pressure on the school environment while schools with under-enrollment often face challenges in maintaining teachers and staff and presenting a full range of educational programming due to insufficient funds.

The LRPC, in collaboration with DCSD staff and Western Demographics, has proposed boundary changes that may alleviate some school over-enrollment challenges. A critical part of the process has been outreach to the community, principals, and staff in the affected areas, by intently listening and carefully considering concerns and suggestions provided by all stakeholders (households with and without children, businesses, elected officials, etc.), as to the impact of changes. In May of 2020, the DCSD proceeded to begin implementation of our recommendations as well as moving some sixth-grade classes from overcrowded elementary schools to middle schools with excess capacity. Several boundary changes were made to unbuilt housing developments to better utilize available capacity in nearby schools as well as changes implemented in April of 2021 to relieve crowding in areas of completed housing developments.

To best utilize DCSD's school facilities, more recommendations will be forthcoming from the LRPC as the future holds significant changes in our county's population. Simultaneous student growth in some areas of the county and student decline in other areas requires ongoing, continuous analysis. With or without funding to build new schools, it will be necessary to routinely reevaluate boundaries while at the same time assessing the possibility of increased bus transportation. When multiple elementary schools located in close proximity have low enrollment projections then programs and policies must be researched. Similarly, low enrollment projections in several middle schools require careful analysis in order to propose possible solutions.


The LRPC's work was complicated by unforeseen events over the last many months due to COVID. The effect of the pandemic on DCSD enrollment will need to be considered going forward. The recent boundary and grade configuration changes are intended to address only the most urgent needs of the school district. The LRPC will continue to research these issues and recommend more boundary or grade configuration changes to address other neighborhood schools which have current or projected issues with under- or over-enrollment. Any potential recommendations to the Board of Education will continue to be in coordination with DCSD staff, outside consultants as necessary, and, of course, members of the public. This research is part of the ongoing mission of the LRPC and is expected to continue for the foreseeable future.

Conclusion

The LRPC succeeds because of the amazing collaboration amongst community volunteers serving on the committee, staff, expert consultants and incredible community participation during our virtual outreach (related to boundary changes). The amazing volunteers of the LRPC dedicate countless hours to thoughtfully review, refine and improve the planning for the future of DCSD. Together, all the stakeholders will continue to adapt and overcome the obstacles that we encounter to ensure students thrive.

Table of Contents

Celebrating the Bond	1
Master Capital Plan Leaders and Partners	4
Executive Summary	6
Existing Condition	10
Methodology	18
New Construction	22
School Capacity	30
Neighborhood, Magnet and Alternative School Facility Needs	34
District-wide Needs	220
Charter School Needs	231
Summary	270
Appendix 1-History of Capital Improvements	274
Appendix 2-Development Summary	285
Appendix 3-Capital Needs by Year	292
Appendix 4-Capital Needs Deltas	298
Appendix 5-Capital Needs by Tier	299
Appendix 6-2018 Bond Construction Table	300




2018 Bond Construction Testimonials

Castle View High School

The passage of the 2018 5B Bond was monumental for the Castle View High School community as it enabled the launch of the much-needed, and longawaited F-Pod expansion. The Castle View F-Pod will consist of 28,000 square feet of state-of-the-art teaching and learning spaces designed to address our two primary goals: programming and capacity. A Design Advisory Group comprised of students, parents, teachers, and building leaders was utilized to carefully prioritize and address our school needs with the design. The expansion will provide optimal environments for three growing Career and Technical Education programs that have previously been constrained by space: Engineering, Broadcast/Journalism, and Biotechnology. It will also provide the general classroom capacity to eliminate the need for some of the mobile buildings on our campus, benefitting both security and logistics. The groundbreaking for the expansion took place in May of 2020 and it is on track for completion for the start of the 2021-2022 school year. On behalf of the students, staff, and parents of Castle View High School - truly, all of Sabercat Nation - I want to express my overwhelming gratitude to the voters of Douglas County for their support. – Dr. Rex Corr, Principal



Words cannot express how thankful we are for the 2018 bond work done at Eldorado. Our school had so much work done. We had a new roof, new



South Ridge Elementary School

South Ridge had a lot of work done over the summer of 2020 from the Bond that Douglas County Voters passed in November 2018. Our



ELDOR


school looks and feels amazing with all of the updates. The renovations and updates have created a safer and better functioning school. Students and staff can now focus on their academic and social-emotional learning rather than being distracted by the previous deficits in their learning environment. South Ridge is one of the older buildings and a staple in the Castle Rock community. Being able to preserve not only the traditions and memories that have been part of South Ridge for nearly 50 years, but now the renovations will help to keep amazing things happening at South Ridge for years to come! - Erin McDonald, Former South Ridge Elementary Principal, Current Executive Director of Schools



2018 Bond New Construction

Castle View High School F-Pod

The \$14.5 million project is underway to bring a long awaited 28,000-square-foot expansion to the campus dubbed the "F-Pod." Inside the F-Pod, students will find three new science rooms, one with a biotechnology laboratory. There will be a two-classroom engineering suite with shop space and a journalism suite with broadcast studio space. Several standard classrooms will finish out the wing. In addition to proper space for the school's enrollment levels, the new wing will allow Castle View to customize classrooms for programs that are currently housed into rooms not designed to support them.



Career Technical Education (CTE) Construction in Ten (10) High Schools

The \$15M of bond funding has been allocated to 10 high schools, including 1 non-traditional high school, to increase the offerings of Career & Technical Education (CTE) programming in a systemic regional approach. These funds have provided new CTE programs, scaled up existing successful CTE programs to ensure compliance with industry standards, and enhanced student engagement in programming through the introduction of AR/VR technology. By providing these CTE opportunities, DCSD students combine learning with real-world experiences, and develop crucial academic, technical, and employability skills. Students have the opportunity to earn industry certifications that will prepare them for employment within specific industries. The funding provided by our stakeholders is being used efficiently and effectively to prepare our students for future education and workforce opportunities.

This page left intentionally blank

Master Capital Plan Overview

The Douglas County School District Master Capital Plan encompasses a five-year period (2021-2026) and represents an important tool in the district's planning decisions. It is used to identify and prioritize school sites for future schools in order to satisfy student enrollment needs. It is also used to prioritize funding for capital reinvestment and new construction. Recognizing that school facilities must adapt to fluid educational requirements and the district exists in a dynamic community, it is imperative that planning for future educational and facility needs of the district is ongoing. This document is updated on an annual basis in coordination with the Long Range Planning Committee.

DCSD Leadership and Partners

Administration

Corey Wise, Superintendent of Schools Richard D. Cosgrove, P.E., Chief Operations Officer Sid Rundle, Student Support Services Officer Mary Kay Klimesh, General Counsel Andrew Abner, Deputy Superintendent Danelle Haitt, Deputy Superintendent Stacey Rader, Communications Officer Matt Reynolds, Chief Assessment and Data Officer Mark Blair, Chief Technology Officer Kate Kotaska, Chief Financial Officer

Board of Education

Christina Ciancio-Schor, Director District D Anthony Graziano, Director District B Elizabeth Hanson, Director District C Krista Holtzmann, Director District G Kevin Leung, Director District E Susan Meek, Director District A David Ray, Director District F

Long RangePlanning Committee

East Planning Area

Patti Anderson, Ponderosa High School Katie Wyatt, Ponderosa High School Lee-Anne Strickoff, Chaparral High School Jamie Wolf, Chaparral High School Stephanie Van Zante, Legend High School

West Planning Area

Bob Binder, Castle View High School Steven Franger, Douglas County High School Michael Formento, Douglas County High School

North Planning Area

John Freeman, Highlands Ranch High School Brad Geiger, Highlands Ranch High School Michelle Major, ThunderRidge High School Cathy Lees, ThunderRidge High School Valerie Richmond, Mountain Vista High School Jennifer Huettl, Mountain Vista High School Meghan McDonald, Rock Canyon High School

Charters

Rudy Lukez, Charter Schools Jason Page, Charter Schools

Larry Mugler, At Large Kirk Harris, At Large

Non-Voting Members and Board Liaisons

Aubrie Duncan, Elementary School Representative Emma Peters, DCSD Student Body Member Krista Holtzmann, Board Director LRPC Liason Susan Meek, Board Director LRPC Liaison Leela Rajasekar, DCSD Director of Construction Richard Cosgrove, Chief Operations Officer Derek Stertz, Planning Manager

Long Range Planning Committee

The Long Range Planning Committee was created in 1983 to work with Douglas County School District. The committee is comprised of two representatives from each high school feeder area, two at-large members, two charter school representatives, and a representative of the development and home building community. The Long Range Planning Committee is one of five committees of the Board of Education. The charge of the Long Range Planning Committee is to continually analyze community population data, evaluate population impacts on district education and support facilities, and collect community feedback. The committee also recommends appropriate actions to the Board of Education regarding school attendance boundaries, facility usage (including facility construction, renovation, or closure) and anticipated capital outlay requirements. Every year the committee presents the updated Master Capital Plan to the Board of Education with recommendations for specific projects that may be needed in the next five years. In 2020 the Board of Education adopted the following priorities for the Long Range Planning Committee.


- 1. Capacity/Boundaries Consultation. The LRPC will continue to assist as necessary to give input and recommend appropriate actions to the Board of Education regarding school attendance boundaries, facility usage, mobile classrooms and other capacity and boundary related suggestions. Assistance will include, but not necessarily be limited to, the following:
 - a. The LRPC will collaborate with DCSD staff as current enrollment numbers and future projections are validated. Community population change and trend data will be reviewed.
 - b. The LRPC will collaborate with DCSD staff as urgent and timely scenarios are assessed, and provide recommendations to the Board of Education.
 - c. The LRPC will provide support facilitating Capacity/Boundary Community meetings.
 - d. The LRPC will review the final findings of DCSD staff, and present LRPC feedback to the Board of Education.
- 2. Master Capital Plan. The LRPC will review, make recommendations and present to the Board of Education the Master Capital Plan (MCP), which will include, but not be limited to, making recommendations for capital maintenance, safety enhancements (at a general level of detail) and construction that may be needed in the next six years. The LRPC will also continue to assist as necessary with the further integration and inclusion of charter school needs within the MCP.
- 3. Property, Facility and Land Inventory. Upon request from the Board of Education, the LRPC will assess site feasibility for specific proposed uses by evaluating DCSD staff recommendations, assessing community impacts, collecting community feedback and making appropriate recommendations regarding how a site will be used. The LRPC will collaborate with DCSD staff to maintain a comprehensive list of the properties and facilities in which DCSD has an ownership interest. This list will include designation of the most appropriate uses for each.
- 4. CART. The LRPC will continue to provide LRPC representation on CART, which results in CART recommendations to the Board.

Early in 2019, Douglas County School District sold \$250 million in general obligation bonds as approved by voters in the November 2018 election. The proceeds from the bonds provide funds for capital needs such as security upgrades, facility repairs, classroom furnishings, buses, and technology. DCSD continues to use bond proceeds to fund Tier 1 and select Tier 2 needs at schools constructed before 2007. In addition, proceeds are enhancing safety and security systems and address urgent capital repairs at DCSD Charter Schools. Bond funds have made the long-awaited F-pod addition to Castle View High School a reality, which adds approximately 400 new seats. These funds are also being put to work with the construction of an Alternative Education school on the Pine Drive site just North of Parker Town Hall.

Over the next 5 years, it is estimated that the total cost of Douglas County School District's capital needs will be \$765-847 million dollars. Of that total, approximately \$423 million is for new construction, \$138-198 million is for reinvestment in the district's school and support facilities, \$50 million is needed for safety & security needs, \$39 million is needed for transportation needs (includes costs for buses and support fleet), \$32 million is needed for information technology needs, \$8-11 million is needed for furniture, fixtures and equipment upgrades and \$6.6 million is needed to replace some of the district's aging mobiles. Approximately \$200K is needed for playground equipment and \$1 million is needed as a contingency. Needs totaled by type can be seen in the figure on the next page. Please note that the costs shown in the figure reflect base construction cost only. Additional costs related to project management and inflation are anticipated and reflected as a range throughout the rest of this document.

Identified capital needs have been classified into a four-tier system with a Tier 1 classification representing the most critical items and a Tier 4 classification representing the least. Douglas County School District's most important reinvestment items (those needs with a Tier 1 classification) are estimated to cost approximately \$109 million over the next five years. In addition to new Tier 1 needs, \$3.5 million is funded by the 2018 Bond and is scheduled for completion. \$94 million is anticipated for Tier 2 needs. Tier 3 needs are estimated to cost approximately \$48 million, and Tier 4 needs are estimated to cost approximately \$11.6 million.

Costs associated with contingency and needed playground equipment have not been tiered and prioritized. Some capital needs submitted by charter schools have not been placed into the tier classification system. New construction needs are also not tiered. These items have been summed separately, outside the tier and priority classification. In total, these untiered needs total approximately \$469 million over the next five years. Needs totaled by Tier can be seen in the figure on the following page.



Estimated Cost (in 2021 Dollars): \$735,474,698 Estimated Project Management Costs Range: \$19,736,734 - \$70,372,234

Estimated Inflation Range: \$9,573,892 - \$41,167,923

Estimated Total Cost: \$764,785,324 - \$847,014,666


The Bond Planning Process and the Role of the Master Capital Plan

The number of funded capital projects has increased exponentially because of the 2018 Bond. This necessitates ensuring the capital planning and funding process is transparent and well understood with respect to Bond planning and the role of the Master Capital Plan (MCP). The MCP is a 5-year plan. The Bond Plan can vary in years based on the amount of money allocated. In the 2018 Bond, four years of Tier 1 and half of Tier 2 projects were identified. The Bond funding did not cover the full amount of 5 years of projects.

The Capital Improvement Plan (CIP) is the source data of the capital improvement needs. The Planning Department's Facilities Planner maintains the CIP. The CIP is used to track projects and components at all the district facilities, including the life cycle of materials and equipment. It is updated with the most current information and is a living document, thus constantly changing.


The Process for Creating the Master Capital Plan

In January of every year an extract of the CIP data is conducted that identifies capital needs for the next 5 years. For example, the 2017 extracted CIP data contained needs from 2018 through 2022 (5 Years). The extract of data contains projects, estimated costs, urgency, tiers and other details about each item. The Planning Department begins to format the data into spreadsheets and publishes the format for the MCP. The CIP data extract is the primary source for the MCP; however, it is not the only data points. District Staff and the MCP Subcommittee (a group of Long-Range Planning Committee) bring questions, answers and other items for consideration to the LRPC. Once the MCP gets to a certain level of completion, it is provided to the LRPC for Review. The LRPC approves the MCP and presents it to the Board of Education for adoption and publication.




The 2018 Bond Plan Process

The bond plan is separate from the MCP and the CIP. The CIP is a source of information that is used to develop the Bond plan. The Bond plan was developed from the 2018 CIP, extracted in August of 2018. The extraction of the data demonstrated needed projects was presented to the Board of Education (BoE). Based on this presentation, the 2018 Bond plan was developed and promoted for an election. Once passed, the plan was delivered to the District's outside vendor (NV5). Implementation of the Bond plan began and is continually reported on.



How does the CIP, MCP and the Bond Plan Data Relate?


The LRPC and the MCP detail the 5 year needs for the school district's facilities. It is focused on future needs. The CIP is the source of this information and has a longer time horizon that can push out to 25 years because of the life cycle of a component or system. The Bond is derived from the CIP; however, it can be limited in its anticipated years based on the amount of funding that is available.



Existing Conditions

Douglas County School District is Colorado's third largest school district, serving approximately 64,000 students in preschool through twelfth grade. The district encompasses 48 elementary schools, 9 middle schools, 9 high schools, 5 alternative schools, 19 charter schools, and includes 42 preschool locations and employs approximately 8,600 employees.

Douglas County School District teachers and staff are leaders of public education in Colorado, with many innovative educational approaches tailored to our students. Support and coordination can be found at the District level, but each school has the flexibility to build its own instructional programs. Parents can find many different choices through the District such as open enrollment, charter schools, instruction for gifted and talented students, magnet schools, an International Baccalaureate program, Advanced Placement courses and other special programs. Our vision is to "create responsible citizens who contribute to society." We strive to maintain a well-researched, integrated and standards-based curriculum, a rich array of extracurricular offerings and strong community involvement.



Population

The Douglas County population estimate for January 1, 2021 is 379,000 persons, a 2.4% increase from the previous year's estimate of 370,000. The Census Bureau and the State of Colorado also produce population estimates using different methodologies. The most current estimate available from the Census Bureau, for July 1, 2019, is 351,154 for Douglas County. The upcoming 2020 Census will be a complete count of the U.S. population. The results will be the most accurate population count available and will be used to inform current and future County population estimates.

Permit Trends

Permits issued for new housing in Douglas County increased 7.4% compared to 2019, with 3,656 housing units permitted in 2020. This change is due primarily to increases in permit issuance for single family and town home housing units, particularly in Castle Rock, Castle Pines, Parker, the Pinery Separated Urban Area, and the Chatfield Urban Area. Permits for multi-family and condominium housing units decreased from 2020. Over 1,000,000 square feet of commercial space was completed in 2020, which includes over 460,000 square feet of commercial and retail space and 364,000 square feet of warehouse and industrial space.

Residential Development

In 2020, 3,731 new housing units were completed in Douglas County, which was a 2.8% increase in the total housing stock. The County's total housing stock as of January 1, 2021, is 136,815 units. Single family detached houses account for 72% of that total. The incorporated cities and towns in Douglas County contain 44% of the total housing stock. Ninety-two percent of all housing units are located in the urbandesignated areas of the County, which is 18% of the total land area of the County.

Residential Sales

The median price of all homes sold in Douglas County in the 4th Quarter of 2020 was \$542,000, which is an 11.75% increase compared to the same quarter last year. The number of sales of newly built and existing single-family houses, townhouses, and condominiums in 2020 increased 13% compared to 2019.

Annual Income

The 2018 average annual wage for jobs located in Douglas County was \$69,726, which was an 8.4% increase from the previous year. According to the 2019 American Community Survey, the median household income in Douglas County was \$119,730, which ranks 9th in the nation for highest median household income among counties. The 2019 American Community Survey also shows that 2.5% of the population had incomes below the poverty level.


Annual Employment

The number of jobs located in Douglas County increased 4.1% from 2018 to 2019, bringing the average annual total to 130,787 jobs. The largest super sectors in the County in 2019 were professional and business services with 18.3% of jobs, followed by retail trade (14.8%), and leisure and hospitality (13.5%). The three super sectors with the largest numerical increases in jobs were financial activities which gained 3,132 jobs, professional and business services which gained 819 jobs, and education and health services which gained 730 jobs.

Source: Douglas County Department of Community Development, 2020 Demographic Summary

Enrollment Trends and Changes in 2020-21

Based on the Colorado Department of Education's official 2020 October count the Douglas County School District saw a decrease of 4,326 students from the 2019-20 school year to the 2020-21 school year. The total enrollment declined from 67,305 to 62,979. This represents a 6.43% decrease in enrollment over the past year.



Year	Total Enrollment	Absolute Change	Growth Rate
2003	42,009		
2004	44,762	2,753	6.55%
2005	48,043	3,281	7.33%
2006	50,370	2,327	4.84%
2007	52,983	2,613	5.19%
2008	58,723	5,740	10.83%
2009	59,932	1,209	2.06%
2010	61,465	1,533	2.56%
2011	63,114	1,649	2.68%
2012	64,657	1,543	2.44%
2013	66,230	1,573	2.43%
2014	66,702	472	0.71%
2015	66,896	194	0.29%
2016	67,470	574	0.86%
2017	67,597	127	0.19%
2018	67,591	-6	-0.01%
2019	67,305	-286	-0.42%
2020	62,979	-4,326	-6.43%

Neighborhood schools saw a decrease of 2,855 students while Charter schools saw a decrease of 1,369 students over the last school year. The decrease in neighborhood school enrollment occurred largely in the elementary grade levels and was most significant within the North Planning Area, which includes the Highlands Ranch, Mountain Vista, Rock Canyon, and ThunderRidge feeders and attendance areas. Enrollment at neighborhood elementary schools decreased by 2,411 students overall and by 1,618 students within the North Planning Area. The decrease in enrollment is partially due to the departure of Ascent Classical Academy and Hope Online Learning Academy Elementary Schools from the district. This enrollment loss accounts for approximately half of the ~6% decline and the Covid-19 pandemic accounts for the remaining ~3% decline. Excluding the two referenced programs, Charter school enrollment remained stable from the 2019-20 school year to the 2020-21 school year with a total increase of 21 students. Alternative education, home education, magnet school, PK, and online enrollment all remained relatively stable from 2019-20 to the current school year and can be viewed in the below tables.

Planning Area/Grade Level	2019 Enrollment	2020 Enrollment	Absolute Change	Growth Rate
East	15,646	14,950	-696	-4.45%
Elementary School	6,746	6,230	-516	-7.65%
High School	5,848	5,883	35	0.60%
Middle School	3,052	2,837	-215	-7.04%
North	23,560	21,942	-1,618	-6.87%
Elementary School	11,142	9,913	-1,229	-11.03%
High School	8,413	8,268	-145	-1.72%
Middle School	4,005	3,761	-244	-6.09%
West	10,075	9,534	-541	-5.37%
Elementary School	4,377	3,711	-666	-15.22%
High School	3,991	4,020	29	0.73%
Middle School	1,707	1,803	96	5.62%
Grand Total	49,281	46,426	-2,855	-5.79%

2019-20 to 2020-21 Neighborhood School Enrollment Growth by Planning Area and Grade Level. The above table summarizes totals and enrollment change for DCSD neighborhood schools only.

Grades Served	2019 Enrollment	2020 Enrollment	Absolute Change	Growth Rate
Elementary School	23,081	20,597	-2,484	-10.76%
High School	18,546	18,435	-111	-0.60%
Middle School	8,764	8,401	-363	-4.14%
Pre-K	118	82	-36	-30.51%

2019-20 to 2020-21 by Grade Level. Neighborhood school, alternative education, magnet school, and PK enrollment are included in the above figures. Charter school, online, and home school enrollment are not included in the above figures.

School Type	2019 Enrollment	2020 Enrollment	Absolute Change	Growth Rate
Alternative	294	264	-30	-10.20%
Charter	16,454	15,085	-1,369	-8.32%
Home Education	307	334	27	8.79%
Magnet	816	743	-73	-8.95%
Neighborhood	49,281	46,426	-2,855	-5.79%
Online	35	45	10	28.57%
Pre-K	118	82	-36	-30.51%
Grand Total	67,305	62,979	-4,326	-6.43%

2019-20 to 2020-21 by School Type. The above table includes all DCSD enrollment.

2020-21 Enrollment Projections Summary

The Planning and Construction Department projects K-12 using the cohort method, and then adjusts the projections based upon birth rate, historic kindergarten enrollment, open enrollment, and residential development. For capacity planning purposes, pre-school enrollment is added to the enrollment projections at those schools with existing pre-school programs. Not including pre-school, enrollment is projected to increase by 801 students for neighborhood schools and by 360 student for charter schools. The majority of neighborhood school enrollment growth is anticipated to occur in the elementary schools with a growth of 692 elementary students projected for the 2021-22 school year. Neighborhood schools in the West Planning Area are projected to increase more than other areas of the district with an anticipated increase of 370 students.

Planning Area/Grade Level	2020-21 to 2021-22 Projected Growth
East	241
Elementary School	201
High School	-49
Middle School	89
North	200
Elementary School	285
High School	22
Middle School	-107
West	370
Elementary School	206
High School	123
Middle School	41
Grand Total	801

2021-22 Projected Enrollment Growth. Eagle Academy is projected to decrease by 10 students and brings the total, district-wide projected increase for neighborhood schools to 801.

Following the 2021-22 school year, enrollment is projected to steadily decrease each year of the five year outlook.

Year	District Managed Enrollment	Charter Enrollment	Alternative Education Enrollment	Grand Total	Absolute Change
2021	47,461	15,361	970	63,793	801
2022	46,274	15,692	961	62,927	-866
2023	45,533	15,618	958	62,109	-818
2024	44,946	15,648	952	61,546	-563
2025	44,409	15,729	941	61,079	-467
2026	43,879	15,771	941	60,591	-488

2021-22 through 2026-27 Projected Enrollment Growth.

This page left intentionally blank



Identifying and Prioritizing Facility and Site Needs

Douglas County School District staff updates the Master Capital Plan on an annual basis. The process for identifying and prioritizing Douglas County School District's capital needs includes two distinct steps: facility assessments and prioritizing needs based on the site component tier and priority matrix score. Below is an explanation of how these steps are performed.

Facility Assessments

Facility capital needs in the Master Capital Plan (MCP) come from a Capital Improvement Plan (CIP) list, a database for the assessment of assets for district facilities. The majority of the list includes the building/site systems and components in need of repair, replacement or upgrade. The CIP is a 5-year projection tool to help maintain our campuses so they function as intended or better.

A facility assessment (or inventory) is a comprehensive review of a facility's assets. Facility assessments are a standard method for establishing baseline information about the systems and components in a new or existing facility. An assessment is a way of determining the "status" of the facility at a given time - that is, it provides a snapshot of how the various systems and components are operating. A primary objective of a facility assessment is to measure the value of an aging asset relative to the cost of replacing that asset. Thus, facilities assessments are a tool for projecting future capital maintenance costs.

Assessment asset needs can consist of the following:

- •Deferred maintenance Systems and components that are past their end of life and create higher maintenance and future replacement costs
- •Life Cycle Projection Systems and components that are projected to fail within a specific time period based on industry standards
- •Damage/Wear Systems and components that have not met life cycle but have been physically damaged by some means or excessive use causing non-optimal performance
- •Compliance Systems and components that are in need of replacement, upgrades, or were added to meet federal and local codes or requirements. These are usually ADA requirements and building code changes
- •System Improvements Projects that may improve systems to perform more efficiently and save future capital resources.
- •Growth Space and areas that are needed due to increases in student population and additional support staff
- •Functionality Systems that are deemed necessary due to policies concerning security enhancements and IT infrastructure

Assessments on newer facilities take place at about the 10-year mark of opening looking forward to a 15-year projected life. Starting in 2015-16, all facilities are being assessed every 5 years. Some assets of a facility may be placed in the CIP based on known life cycle. The majority of systems and components fall within a life cycle range of 15-40 years.

On-site facility assessments are currently performed by the Facility Capital Planner. The Facility Capital Planner collaborates with Principals, Building Engineers, Maintenance Managers and staff in helping supply information to be placed in the CIP. Information may come from the maintenance work order system if the capital cost cannot be justified by the yearly maintenance budget. Architects, Engineers, and Consultants may also be used to determine major deficiencies when warranted.

The yearly maintenance repair budget is separate from the CIP although sometimes items may be performed in conjunction with each other. Typically, capital repair/replacement costs over \$5,000 are listed in the CIP, although the yearly maintenance budget may be used for repair/replacement costs up to around \$30,000. Costs under \$5,000 in the CIP are usually deficiency items that would be combined with others in the same type of project for cost savings.

Currently, the items in the CIP are for capital renewal only. Other major "wants" not for growth or equability of other facilities are placed outside the CIP but continue to be tracked to be considered at a future date if deemed appropriate. Many energy conservation projects for energy and water savings have been taken out of the CIP but are still tracked and may be done if the return on investment (ROI) is warranted in the future.

Prioritizing Needs

Tier Classification

The Planning & Construction team, with input from Security, Transportation, and IT staff, is responsible for classifying needs based on a four tier structure. These tiers are used to rank the significance of the replacement or upgrade of facility assets, systems, components, and services as they affect the occupancy of a facility or level of service requirements. The tiers used to classify the above are as follows:

Tier	Description
Tier 1	Assets, systems and components that are necessary to occupy a facility and/or may cause large financial costs if a breakdown occurs, along with Federal, State, and Local mandated statutes and code compliance issues. Typical assets in this tier include (but are not limited to) roofing, plumbing infrastructure, HVAC, electrical systems, fire sprinkler repair/replacement, fire alarm, irrigation systems and controllers, major structural movement, site utilities, SPED buses; and state statutes for door hardware fire and security compliance.
Tier 2	Assets, systems and components for suitable occupancy of a facility including security systems and components; and priority bus and support vehicle replacement. Typical assets in this tier include (but are not limited to) building exterior envelope and finishes, interior finishes, flooring, plumbing fixtures, minor mechanical, paving, surfacing, high school athletic fields, cameras, card readers, replacement buses, and snowplow trucks.
Tier 3	Assets, systems and components that are part of a facility infrastructure but do not directly affect the occupancy of the facility including security upgrades and additions; and transportation buses and support vehicles for growth. Typical assets in this tier include (but are not limited to) interior wall structure and finishes, interior doors, ceiling finishes, casework, FF&E (furniture, features, and equipment), cosmetic building structure, multi-purpose fields at elementary and middle schools, additional software programs to enhance security; and additional buses and support vehicles.
Tier 4	Assets, systems and components that are more aesthetic in nature, do not affect building occupancy, and deemed the least important upgrades. Typical assets in this tier include (but are not limited to) landscaping, exterior structures, a variety of site work, and additional security doors.

The Safety and Security Department identifies and prioritizes its capital needs based on a variety of criteria. These criteria range from risk to safety, necessity in order to comply with Federal, State, or Local mandates, frequency of system failure, potential impact to current level of service, life expectancy, the potential to enhance systems, and process improvement strategies.

The Transportation Department identifies and prioritizes fleet related capital needs in two ways. First, assets that present a significant safety concern are identified. This means that the continued operation of the asset places personnel safety, or the safety of others, in jeopardy. Assets identified in this operating condition may have

Methodology cont.

components or entire structures that will not pass safety inspections. These would be assets that need to be replaced within one year. Second, assets in a mechanical condition requiring ongoing repairs that exceed current value are identified. If these vehicles can no longer be repaired, upgraded, or maintained, they are listed as needing replacement over the next five years.

The IT Department identifies and prioritizes solutions and projects based on the effectiveness and impact to student education delivery. District technology initiatives are proposed by the IT Department based on continual review of school staff and student educational requirements, administrative leadership, and reference to industry best practice solutions. A business case is developed to define scope, deliverables, resources, and cost estimates which are then prioritized by IT leadership. A portfolio review is conducted to ensure new initiatives are unified solutions across the district and maximize delivery of student education in alignment with our strategic goals. With a wealth of technology solutions and opportunities, the IT Department focuses priority on providing the district students, staff, and administration with the most value to provide the greatest education for the students.

Priority Classification

Every project/need that has been listed in the CIP is ranked based on five different 'levels' of criteria. The criteria 'levels' used to score projects include the following:

Priority Criteria	Definition
Cause	This criteria level is used to evaluate and score projects based on why they are needed. For example, a project could be needed to respond to or prevent a known life safety and health risk, to be code compliant, or because the system or component has failed. It could also be needed to increase functionality and efficiency or to align with district strategic priorities. A project that is required to prevent or respond to a known life safety and health risk would rank higher than a project that is desired or preferred by facility users. Similarly, a project required for code, regulatory or contract compliance would rank higher than a project that would enable the advancement of district-wide goals and strategies
I .	Potential to interrupt educational programming. Using this criteria level, a failing system or building component that has the potential to result in a full or partial school closure would score higher than a failing system or component that does not directly disrupt classroom instruction.
Risk	Level of risk a system or component failure poses to staff, students, and the district as a whole. Types or risks considered vary widely and include everything from safety and health risk to financial and legal risks. Using this criteria level, a failing system or component that has the potential to compromise student and staff health and safety or close a facility would rank higher than one where the only potential risk is an opportunity loss for improvement.
	When item it is expected to fail based on life cycle expectancy. A building component that is past its expected life cycle would score higher than a component that has not reached the end of its expected life.
Extent of Impact	The extent to which a potential failure could impact the district. For example, a potential failure that could impact the entire district would score higher than a potential failure that would only impact one classroom.


Final rank scores for each criteria level are multiplied to calculate an overall priority score. Scores range from 1-8000 with a score of 1 being a project of the highest priority and a project with a score of 8000 being of the lowest priority. For simplicity, needs have been classified as high, medium, or low priority using the classification method shown below.

High Priority: 1-200 Priority Score

Medium Priority: 201-1,000 Priority Score Low Priority: 1,001-8,000 Priority Score

How to Assess Capital Priorities

Every opportunity for capital reinvestment has been classified based on its priority score and its tier. These two classifications have been combined to create the twelve different classes shown in the illustration below. Those opportunities and projects classified as Tier 1-High can be considered the most urgent and those classified as Tier 4-Low can be considered the least urgent. Estimated construction costs have been summarized for each of the classes and are shown on each facility profile page.



Estimating Costs for Facility and Site Needs

Along with identifying and prioritizing facility needs, the Planning & Construction team works to provide accurate cost estimates for these needs. These cost estimates are derived by calculating estimates for:

- 1) Component and/or system reinvestment (materials and labor only)
- 2) Potential project management costs and
- 3) Additional costs due to inflation

The method used for calculating these three separate costs is discussed below. Reinvestment costs which are displayed in the 'Estimated Construction Cost-2021' field are contract materials and labor costs only. In general, capital reinvestment work will always require some level of regulatory, professional services, and contracting costs.

Calculating Estimated Construction Costs

Estimated costs in the Capital Improvement Plan are developed in a multitude of ways:

- •RS Means Estimating Software RS Means is the industry standard for estimating construction, remodeling, and repair. Costs from RS Means are contractor costs only
- •Similar types or projects Estimates are based on similar projects the district has completed in the past (marked up according to an inflation factor as necessary)
- •Outside resources Architects, Engineers, and Consultants may be used to help derive cost estimates. Estimates vary over time due to many factors. This can include:
 - •Prices for commodities and material can vary within a few months
 - •Labor shortages drive contractor costs higher (Colorado is currently experiencing a labor shortage)
 - •The time of year when the project is bid and project constructed (schools typically have a majority of work done over the summer break)

Calculating Estimated Project Management Costs

Along with materials and labor costs, the estimated total project cost also includes costs for design, construction, and professional services. Typically these types of costs that need to be accounted for can include fees associated with one or a combination of any of the following:

- Architectural and design fees
- Trade professional fees
- •Inspections, permitting and or code compliance fees
- Contingency (costs due to unforeseen circumstances)
- Contractor overhead and profit

These fees can vary depending on regulatory requirements, the size, and the complexity of a project. Dependent on these factors, these costs can range from an additional 10-43% of the estimated construction cost. For example, these additional costs would be around 10% of construction costs if DCSD were to resurface a tennis court. In this instance a consultant would help to determine the product to use, create specifications for the work to be done, and help in bidding and project oversight. To replace a tennis court with post-tension concrete, additional costs would be on the higher end. The district would need to contract with a soils testing agency, a structural engineer, and an observation and testing agency to assure product installation compliance. Contractor fees would be higher due to the specialized nature of the work.

Calculating Estimated Inflation Costs


Inflation for construction materials and labor is also included in Master Capital Plan cost estimates. An assumed 5% annual increase is used to determine a range of potential additional inflation costs for each project.


How to Assess Project Cost

Every need has an estimated construction cost, an estimated range for potential project management costs, and an estimated range for inflation. Cost estimates on the low end of the range assume a 10% mark-up for potential regulatory, professional services, and contracting costs. Cost estimates on the high end of the range assume a 43% mark-up. Inflation cost estimates on the low end of the range assume work will occur in year two of the five year outlook. Inflation estimates on the high end of the range assume work will not occur until year five.

Materials and labor

10%-43% Mark-up







Inflation

2018 Bond Funded Items

In late January 2019, DCSD sold approximately \$250 million in general obligation bonds as approved by voters in the November 2018 election. The proceeds from the bonds provide one-time funds for capital needs such as security upgrades, facility repairs, classroom furnishings, buses and technology. Projects that are to be funded by the 2018 Bond are called out on individual school pages. These projects are part of the 2022 Bond package and are anticipated to begin work in 2022.



2018 Bond funded projects that have been completed or are contracted to be completed in 2021 are also called out on individual school pages. The total amount spent on projects and/or the total amount contracted for projects is provided for each facility.





New Construction Needs

1-5 Year Needs

Based on existing school capacities, five-year enrollment projections for the district, and new residential development, the Planning & Construction Department has identified a need for the below listed new construction over the next five years. These priorities may change as findings from boundary and capacity analyses become available.

- New elementary school in The Canyons development (Castle Pines)
- New elementary school in Northeast Castle Rock (Castle Rock)
- New elementary school in the Cobblestone Ranch development (Castle Rock)
- New elementary school in the Crystal Valley development (Castle Rock)
- New elementary school in the Solstice development (Northwest Douglas County))
- New elementary school in the Sierra Ridge development (East Lone Tree/West Parker)
- New school in the Sterling Ranch development (Northwest Douglas County)
- An addition to Sierra Middle School (Parker)
- An addition to the early childhood center in the West Planning Area (Castle Rock)
- New Special Education school (location to be determined)
- An expansion to the Nutrition Services Warehouse (Castle Rock)
- New terminal and land for bus and support vehicle fleet maintenance and operations (Parker)
- New terminal satellite facility and land for bus and support vehicle fleet maintenance and operations (Castle Rock)

6-10 Year Needs

The Planning & Construction Department also monitors capital needs beyond the five-year Master Capital Plan. In the next six to ten years, the following new construction needs are projected in order to accommodate future capacity and operational support needs:

- New elementary school in The Meadows development (Castle Rock)
- New elementary school in the Anthology Hess development (Parker)
- New high school in the Ridgegate development (Lone Tree/West Parker)
- New joint middle school-high school in the Sterling Ranch development (Northwest Douglas County)
- Additional space and facilities for DC Student Support Center, eDCSD programming, and Bridge programming (locations to be determined)
- New terminal and land for bus and support vehicle maintenance and operations (Northwest Douglas County)

Land Needs

The Planning & Construction Department works with local municipalities and land developers to ensure suitable sites are dedicated to the school district for projected new construction needs. Based on best practices and past facility prototypes, the following acreages have been identified as suitable for the construction of new schools:

- Elementary Schools: 12 acres
- PK-8 Schools: 15-17 acres

Middle Schools: 30 acres

High Schools: 60 acres

*For more information on dedicated school sites see our

land inventory maps in Appendix 4



New Construction Costs

The Planning & Construction Department has calculated construction costs using three different scenarios. Cost estimates have been calculated using 1) Current Douglas County School District Standards, 2) Value Engineered Standards, and 3) Residential/Commercial Standards. Cost estimates for new construction are estimated using data from recent bids for public schools in Colorado with similar facility standards. The Planning & Construction Department compared recent contractor bids and projected budgets with public school districts in the Denver area for new high, middle, PK-8 and elementary schools. The cost per square foot of these actual bids and detailed cost estimates from pre-qualified architects and engineers for Transportation and Nutrition Services support facilities are the basis for the new construction cost estimates. The school districts used to benchmark costs have similar facility standards. The cost estimates reflect inflation based on Producer Price Index (PPI) data.

Scenario 1: Current DCSD Standards

Douglas County School District currently builds to the highest standards possible. These standards are meant to ensure durable, high quality facilities that will last for the next 50-75 years. The District focuses on providing building components which are long lasting, require minimal maintenance, provide energy efficiency savings, and increase student and staff comfort. DCSD's current standards are meant to increase the quality and life of the building while reducing maintenance and utility costs. Adhering to these standards requires investing larger amounts up front but provide intermittent cost savings in reduced maintenance over time.

Scenario 2: Value Engineered Standards

To derive cost estimates for new construction under this scenario the Planning & Construction team researched industry approaches to reducing costs while still maintaining the functionality of facilities for their intended use. This scenario focuses on reducing DCSD's upfront purchase costs while still providing the value needed by our end users. Some examples of the types of reductions that would be made under this scenario are summarized in the following table.

DCSD Standards Component	Value Engineered Component	Loss
Automated/calibrated lighting and mechanical controls	Manual lighting and mechanical controls	Energy efficiency
Carpeting	Hard surface flooring	Noise control/comfort
Brick/Block Walls	IWAAA sidina	Noise control/ease, cost and frequency of maintenance/shortened useful life
Fully adhered, un-ballasted roof (sealed, non-permeable membrane)	Ballasted roof	Ease, cost, and frequency of maintenance/shortened useful life
Drop ceilings	Open ceilings	Noise control/aesthetics
Daylighting (translucent panels, skylights, etc.)	No daylighting	Energy efficiency/comfort
Painted walls	Vinyl wall coverings	Ease, cost, and frequency of maintenance/shortened useful life

By pursuing a Value Engineered scenario, DCSD would see initial savings due to decreased purchase costs of building components. However, these reductions ultimately result in increased maintenance costs, increased utility usage costs, and costs associated with more frequent replacement of building components that are beyond their useful life. It should also be pointed out that the initial purchase cost savings seen in this scenario can often be at the expense of comfort and aesthetics.

Scenario 3: Least Expensive Facility Standard

This scenario would dramatically decrease the useful life of building components and would result in facilities meant to last approximately 25 years rather than the standard 50-75 years DCSD currently targets. In addition to the tradeoffs made in the Value Engineered scenario, DCSD could achieve significant upfront savings by constructing slab on grade rather than using a structural foundation, constructing wood frame facilities in lieu of metal framing and

masonry, eliminating carpet and drop ceilings, eliminating lighting, mechanical, and electrical controls, and reducing security systems and technology. In this scenario, DCSD would face much greater costs associated with continual maintenance and increased utility costs. In general, finishes are of a lower quality in this scenario. Cost estimates were not calculated for all listed new construction. This is due to the fact that portions of school facilities cannot be built using these standards. Special learning environments (labs, art rooms, etc.), athletic amenities, and special education spaces have specific facility requirements and needs that cannot be built to alternative standards. Rather, it is more accurate to say that for typical learning spaces only, an additional 60% in initial capital savings could be achieved with the use of these standards.

1-5 Year Needs

New Construction Need	DCSD Standards Cost	Value Engineered Standards Cost
Typical Enrollment/Neighborhood Schools		
Northeast Castle Rock Elementary School	\$42,288,281	\$35,945,039
Cobblestone Ranch Elementary School	\$42,288,281	\$35,945,039
Crystal Valley Elementary School	\$42,288,281	\$35,945,039
Solstice Elementary School	\$42,288,281	\$35,945,039
Sierra Ridge Elementary School	\$42,288,281	\$35,945,039
The Canyons in Castle Pines Elementary School	\$57,813,525	\$49,141,496
Sterling Ranch School	\$57,813,525	\$49,141,496
Sierra Middle School Expansion	\$16,761,905	\$14,247,619
Special Programming		
Castle Rock Early Childhood Center Addition	\$2,890,676	\$2,457,075
Special Education School	\$10,984,570	\$9,336,884
Support Facilities		
Castle Rock Satellite Bus Terminal Land Purchase	\$2,609,565	\$2,609,565
Castle Rock Satellite Bus Terminal	\$2,833,677	\$2,408,625
Castle Rock Nutrition Services Warehouse Expansion	\$4,452,921	\$3,784,983
Parker Bus Terminal Land Purchase	\$6,262,957	\$6,262,957
Parker Bus Terminal	\$49,224,722	\$41,841,013
Total (Includes Estimated Inflation)	\$423,089,448	\$360,956,908

^{*}Note* The construction of both the Sierra Ridge Elementary School and expansion of Sierra Middle School are not needed to address capacity needs in the Chaparral High School feeder. The construction of either a new elementary school or an expansion of Sierra Middle School would be considered to address current capacity needs.

6-10 Year Needs

New Construction Need	DCSD Standards Cost	Value Engineered Standards Cost	
Typical Enrollment/Neighborhood Schools			
Meadows Elementary School	\$53,872,886	\$45,791,953	
Anthology Hess Elementary School	\$53,872,886	\$45,791,953	
Ridgegate High School	\$146,265,327	\$124,325,528	
Sterling Ranch Joint Middle School-High School	\$186,333,786	\$158,383,718	
Special Programming			
eDCSD Facility	\$5,781,352	\$4,914,149	
DC Support Center	\$7,378,634	\$6,271,839	
Bridge Programming	\$10,406,434	\$8,845,469	
Support Facilities			
Northwest Bus Terminal Land Purchase	\$6,993,635	\$6,993,635	
Northwest Bus Terminal	\$70,131,085	\$59,611,422	
Total (Includes Estimated Inflation)	\$541,036,025	\$460,929,666	

Alternatives to New Construction

New construction is only one of the many options available for meeting the district's capacity needs. To address expected growth in the next five years as well as in the next ten years, opportunities for utilizing already existing capacity exist. However, along with these opportunities come risks. The following pages provide information on some of the most feasible opportunities (and the risks they present) for addressing some of the district's anticipated capacity needs.

Neighborhood Schools

The following table reviews alternatives to constructing new neighborhood schools. The need for new neighborhood schools is driven primarily by shifting demographics and development. This type of enrollment growth can be addressed by reconfiguring attendance boundaries, grades and calendars.

Alternative to New Construction	Alternative Risk	Timeframe Needed
The Canyons in Castle Pines Elementary S	School	
1) Reboundary elementary attendance areas in the Rock Canyon High School feeder to utilize existing capacity and balance enrollment. 2) Alter school calendars and class scheduling to reduce number of students simultaneously using elementary facilities in feeder	1) Increased commute time for North Castle Pines students (i.e., some of the current Timber Trail attendance area would be allocated to Wildcat or Redstone attendance area) and exacerbation of existing connectivity and congestion issues between NW Castle Pines and SE Highlands Ranch. Potential congestion, safety, and accessibility issues with K-6 students from The Canyons development crossing I-25 to attend neighborhood school. 2) Could interfere with parent schedules, and extracurricular and/or after school activities. Increased wear and tear on facility and makes routine maintenance and work on facility more difficult.	1-5 Years
Northeast Castle Rock Elementary School		
1) Reboundary Castle Rock region elementary attendance areas in Douglas County High School feeder to utilize existing capacity and balance enrollment. 2) Alter school calendar and class scheduling to reduce number of students simultaneously using facility 3) Perform grade reconfiguration and utilize existing capacity at Mesa Middle School	1) Not a long term solution; existing K-6 facilities and available mobile pads in this feeder cannot accommodate complete build out of Castle Oaks, Castleview Estates, and Crystal Valley Ranch. May go against community desires and preference for current neighborhood school. 2) Could interfere with parent schedules, and extracurricular and/or after school activities. Increased wear and tear on facility and makes routine maintenance and work on facility more difficult. 3) Impact on school staff and program. May go against community desires and preference for current grade configuration. Only beneficial if reconfiguration does not under or over enroll nearby schools and/or interrupt feeder pattern. Existing facility may not have the amenities and features needed for 6th grade programming. More expensive than reboundary option.	1-5 Years
Cobblestone Ranch Elementary School		
1) Reboundary Cobblestone Ranch development into the Mountain View-Northeast Elementary attendance area. 2) Alter school calendars and class scheduling to reduce number of students simultaneously using elementary facilities in feeder	1) Two different neighborhood schools for one development. Could under-enroll Franktown or over-enroll Mountain View-Northeast Elementary schools. May go against community desires and preference for current neighborhood school 2) Could interfere with parent schedules, and extracurricular and/or after school activities. Increased wear and tear on facility and makes routine maintenance and work on facility more difficult.	1-5 Years

		Timeframe
Alternative to New Construction	Alternative Risk	Needed
Crystal Valley Elementary School		
1) Reboundary elementary attendance areas in the Douglas County High School feeder to utilize existing capacity and balance enrollment 2) Alter school calendars and class scheduling to reduce number of students simultaneously using elementary facilities in feeder 3) Perform grade reconfiguration and utilize existing capacity at Mesa Middle School	 Potential increased commute time for students and parents. Potential congestion, safety, and accessibility issues as updated attendance area boundaries may need to cross major roads and intersections in order to balance enrollment. May go against community desires and preference for current neighborhood school. Could interfere with parent schedules, and extracurricular and/or after school activities. Increased wear and tear on facility and makes routine maintenance and work on facility more difficult. Impact on school staff and program. May go against community desires and preference for current grade configuration. Only beneficial if reconfiguration does not under or over enroll nearby schools and/or interrupt feeder pattern. Existing facility may not have the amenities and features needed for 6th grade programming. More expensive than reboundary option. 	1-5 Years
Solstice Elementary School		
1) Reboundary elementary school attendance areas in the ThunderRidge High School feeder to utilize existing capacity and balance enrollment. 2) Alter school calendars and class scheduling to reduce number of students simultaneously using elementary facilities in feeder 3) Perform grade reconfiguration and utilize existing capacity at Ranch View Middle School	1) Potential increased commute time for students and parents. Potential congestion, safety, and accessibility issues as updated attendance area boundaries will need to cross major roads and intersections in order to balance enrollment. Potential congestion, safety, and accessibility issues. May go against community desires and preference for current neighborhood school. 2) Could interfere with parent schedules, and extracurricular and/or after school activities. Increased wear and tear on facility and makes routine maintenance and work on facility more difficult. 3) Impact on school staff and program. May go against community desires and preference for current grade configuration. Only beneficial if reconfiguration does not under or over enroll nearby schools and/or interrupt feeder pattern. Existing facility may not have the amenities and features needed for 6th grade programming. More expensive than reboundary option.	1-5 Years
Sierra Ridge Elementary School		
1) Reboundary elementary attendance areas in the Chaparral feeder to utilize existing capacity and balance enrollment 2) Alter school calendars and class scheduling to reduce number of students simultaneously using elementary facilities in feeder 3) Expand facility and reconfigure grades at Sierra Middle School	1) Potential increased commute time for students and parents. Potential congestion, safety, and accessibility issues as updated attendance area boundaries may need to cross major roads and intersections in order to balance enrollment. May go against community desires and preference for current neighborhood school. 2) Could interfere with parent schedules, and extracurricular and/or after school activities. Increased wear and tear on facility and makes routine maintenance and work on facility more difficult. 3) Impact on school staff and program. May go against community desires and preference for current grade configuration. Only beneficial if reconfiguration does not under or over enroll nearby schools and/or interrupt feeder pattern. Only achievable if site constraints are minimal or nonexistent. Core areas of facility may still be strained and overcrowded. More expensive than reboundary option.	1-5 Years

Neighborhood Schools cont.

Alternative to New Construction	Alternative Risk	Timeframe Needed
Sierra Middle School Expansion		
1) Reboundary elementary attendance areas in the Chaparral feeder to utilize existing capacity and balance enrollment	See alternative risks for Sierra Ridge Elementary School	1-5 Years
Sterling Ranch School		
1) Reboundary elementary school attendance areas in the ThunderRidge High School feeder to utilize existing capacity and balance enrollment. 2) Alter school calendars and class scheduling to reduce number of students simultaneously using elementary facilities in feeder 3) Perform grade reconfiguration and utilize existing capacity at Ranch View Middle School	1) Potential increased commute time for students and parents. Potential congestion, safety, and accessibility issues as updated attendance area boundaries will need to cross major roads and intersections in order to balance enrollment. Potential congestion, safety, and accessibility issues. May go against community desires and preference for current neighborhood school. 2) Could interfere with parent schedules, and extracurricular and/or after school activities. Increased wear and tear on facility and makes routine maintenance and work on facility more difficult. 3) Impact on school staff and program. May go against community desires and preference for current grade configuration. Only beneficial if reconfiguration does not under or over enroll nearby schools and/or interrupt feeder pattern. Existing facility may not have the amenities and features needed for 6th grade programming. More expensive than reboundary option.	1-5 Years
The Meadows Elementary School		
1)Partner with nearby charter schools to weight lottery for students residing in The Meadows development (Castle Rock). 2) Reboundary elementary attendance areas in the Meadows to utilize existing capacity and balance enrollment 3) Alter school calendars and class scheduling to reduce number of students simultaneously using elementary facilities in feeder 4) Expand facility and reconfigure grades at Castle Rock Middle School	1)Students/parents residing in The Meadows do not prefer nearby charter schools and do not enroll. Nearby charter schools reach ideal program capacity with outside enrollment (students residing outside the Castle View feeder) before The Meadows is built out. 2) Potential increased commute time for students and parents. Potential congestion, safety, and accessibility issues as updated attendance area boundaries may need to cross major roads and intersections in order to balance enrollment. May go against community desires and preference for current neighborhood school.	6-10 Years
Anthology Hess Elementary School		
1) Reboundary elementary attendance areas in South Parker to utilize existing capacity and balance enrollment 2) Alter school calendars and class scheduling to reduce number of students simultaneously using elementary facilities in feeder 3) Perform grade reconfiguration and utilize existing capacity at Sagewood Middle School	1) Potential increased commute time for students and parents. Potential congestion, safety, and accessibility issues as updated attendance area boundaries will need to cross major roads and intersections in order to balance enrollment. Potential congestion, safety, and accessibility issues. May go against community desires and preference for current neighborhood school. 2) Could interfere with parent schedules, and extracurricular and/or after school activities. Increased wear and tear on facility and makes routine maintenance and work on facility more difficult. 3) Impact on school staff and program. May go against community desires and preference for current grade configuration. Only beneficial if reconfiguration does not under or over enroll nearby schools and/or interrupt feeder pattern. Existing facility may not have the amenities and features needed for 6th grade programming. More expensive than reboundary option.	6-10 Years

Neighborhood Schools cont.

Alternative to New Construction	Alternative Risk	Timeframe Needed
Ridgegate High School		
1) Reboundary high school feeders in the East Planning Area to balance enrollment and utilize existing capacity at Ponderosa High School. 2) Fully utilize existing capacity at Ponderosa High School and Douglas County High School through addition and/or relocation of community desired programming.	1) Reboundary of high school feeders would affect all schools and levels in the East Planning area. Elementary and middle school population would be impacted along with high school population. It also may not be logistically possible to balance enrollment while maintaining existing programming and transportation connectivity. 2) Potential of increased commute times for students and/or no access to busing services (without a boundary change). If not monitored closely, could over-enroll Ponderosa and Douglas County High Schools or under-enroll Chaparral and Legend High Schools.	6-10 Years
Sterling Ranch High School		
Reboundary middle and high school feeders in the North Planning Area to balance enrollment and utilize existing and anticipated capacity at Ranch View and Cresthill Middle Schools and ThunderRidge and Highlands Ranch High Schools.	Reboundary of middle school and high school feeders would affect all schools and levels in the North Planning area. It may not be logistically possible to balance enrollment while maintaining existing programming and transportation connectivity. If not monitored closely, could under-enroll or over-enroll North Planning Area middle and high schools.	6-10 Years

Special Programming and Support Facilities

The following table reviews alternatives to constructing new facilities for special programming and support facilities. The need for these facilities is driven by shifting demographics, development, and programming needs. However, unlike neighborhood schools, the need for this space cannot be fully ameliorated by reconfiguring attendance boundaries, grades, or calendars.

Alternative to New Construction	Alternative Risk	Timeframe Needed
Early Childhood Centers (Castle Rock)		
Place PK students in under-utilized elementary school facilities.	Elementary facilities may not be able to accommodate PK students as K-6 student growth occurs within that attendance area. Elementary school facilities may not currently have the special features and amenities needed for early childhood education.	1-5 Years
DC Support Center		
Fully utilize existing capacity at other schools.	Potential of increased commute times for students and parents and increased transportation cost for the District. Current neighborhood school facilities may not currently have the special features and amenities needed for DC Support Center programming.	1-5 Years
Special Education School		
Fully utilize existing capacity at other schools.	Potential of increased commute times for students and parents and increased transportation cost for the District. Current high school facilities may not currently have the special features and amenities needed for special needs programming.	1-5 Years
Nutrition Service Warehouse Expansion		
Lease a warehouse and freezer space at an off site location	The cost of leasing is very expensive and leased space does not provide joint warehouse and freezer space as needed by Nutrition Services. Off site warehouse and freezer inventory would increase storage costs and decrease management efficiency.	1-5 Years

Special Programming and Support Facilities cont.

Alternative to New Construction	Alternative Risk	Timeframe Needed		
eDCSD Facility	eDCSD Facility			
Fully utilize existing capacity at other schools.	Potential of increased commute times for students and parents and increased transportation cost for the District. Current neighborhood school facilities may not currently have the special features and amenities needed for eDCSD programming.	6-10 Years		
Bridge Programming				
Fully utilize existing capacity at other schools.	Potential of increased commute times for students and parents and increased transportation cost for the District. Current neighborhood school facilities may not currently have the special features and amenities needed for Bridge programming.	6-10 Years		
Parker, Castle Rock, and Northwest Doug	Parker, Castle Rock, and Northwest Douglas County Bus Terminals and Land Purchase			
1) Utilize available parking at existing schools 2) Plan for satellite transportation parking on dedicated school sites (DCSD owned sites with no schools)	Increased operational costs to shuttle drivers to and from buses. Increased operational costs to shuttle buses to central terminals for cleaning and maintenance. Potential security concerns and vandalism to vehicles if not fenced and lit. Dedicated school sites may need rezoning.	1-5 Years for Parker and Castle Rock Terminals 6-10 Years for Northwest Douglas County Terminal		

Master Planned Approach for Facilities Supporting District-Wide Needs

DCSD has made a significant investment in the development of postsecondary pathways where students are able to earn industry credentials, guaranteed transferable college credit and work-based learning opportunities. Over the past year and as part of the 2018 Bond, DCSD was able to invest \$15 million in Career and Technical Education (CTE) pathways in all neighborhood high schools. Students are now able to equitably access programming pathways in cosmetology, industrial arts and design, film and media, culinary arts, biotechnology, forensic science. This commitment will provide our DCSD students a significant competitive advantage in preparing them to be postsecondary and workforce ready. The need to continue this investment is dire in order to continue to increase the District's persistence and matriculation data where students are more prepared to navigate the postsecondary world.

In addition to the efforts to include CTE in each of the District's high schools, the District also needs to include district-wide Career and Technical Education and Alternative Education. While the 2018 Bond included funds for this programming, the need for these learning opportunities continues to grow at a fast pace. Ensuring students are prepared and have the in-demand skills to enter the workforce is an essential strategy to meeting economic and business needs in Colorado. At the secondary level, the goal is for all students to understand and articulate their individual skill set, how they relate to potential careers and jobs, and graduate with these in-demand skills from high school. Colorado industry representatives are clear that students who graduate from high school and seek to work in Colorado need in-demand skills that meet business, industry and higher education standards.

Douglas County School District is committed to providing our students with authentic, project-based learning, allowing them to explore industries, and gain the real-world knowledge and skills they will need to be successful. State approved CTE programs are taught by Douglas County School District teachers who have received State CTE credentialing in their respective discipline and program. In Douglas County School District, Work-Based Learning (WBL) is one way education and industry partnerships are partnering to ensure that students have the skills and career exposure needed to build pathways to meaningful careers. Work-Based Learning is a program designed to connect students with career pathways of interest by partnering with businesses in the community. Through experiences including career readiness training, clinical experiences, credit-for-work experiences, industry-sponsored projects, internships and pre-apprenticeships, high school students have the opportunity to explore career pathways

Master Planned Approach for Facilities Supporting District-Wide Needs cont.

and develop career readiness skills.

In order to improve this programming and support for students, an initiative has been identified to enhance the facility planning process in a consolidated, long-range approach for programs and departments which support the entire district with educational programming and operations. To date, facilities for programs and support functions have been used based on the availability of property for purchase or lease, and general location. While some functions need to be dispersed geographically, this approach has caused some inefficiencies in the lack of consolidated functions when desired, travel between facilities with a loss of productive time and mileage reimbursement, and increased maintenance, custodial and utility costs. One-time revenue and annual savings could also be realized depending on the relocation and consolidation of certain functions and disposition of property.

Functions which are important for students and staff district-wide are located at the following locations:


- -Opportunity School (Teddy Lane), Lone Tree Bridge Lone Tree, Early Childhood Education, Child Find, Eagle Academy
- -D.C. Oakes, Castle Rock Alternative Education High School
- -Early Childhood Center, Castle Rock Child Find, Preschool
- -Cantril, Castle Rock Staff Development, Curriculum, Instruction & Assessment, Cloverleaf School, Administration, Preschool
- -West Support Center, Castle Rock Budget, Accounting, Finance, Accounts Payable, Payroll, Facility Rental, Strategic Sourcing, Information Technology, Student Data, Student Support, Warehouse
- -Wilcox, Castle Rock Superintendent, Deputy Superintendents, Communications, Choice Programming, Learning Services, Legal, Human Resources, Athletics & Activities, Student Support, Risk Management, Board of Education
- -West Service Center, Castle Rock Transportation, Operations & Maintenance, Security, Nutrition Services, Chief Operations Officer, Planning, Construction
- -District Media Center, Castle Rock
- -Joint Service Center, Parker Transportation
- -Franktown Support Facility, Parker Grounds, Operations & Maintenance
- -North Support Facility, Douglas County Transportation, Operations & Maintenance
- -Bridge, Parker
- -Bridge, Highlands Ranch
- -Bridge, Castle Rock (located in Douglas County High School)
- -Inverness, Douglas County eDCSD, Student Assistance, School Leadership
- -Stone Canyon Outdoor Edventures, Douglas County

This page left intentionally blank



Monitoring and Estimating Capacity Needs

The Planning Department tracks the facility and mobile capacity available at each neighborhood school in comparison to current and projected enrollment. The chart below is used by staff to evaluate which facilities are being over or under utilized and also which schools may require an additional mobile or some other capacity relief method in future years.



Staff also tracks the total number of seats available at each school including seats provided by mobiles currently on-site.

A chart showing facility and mobile capacity available at each neighborhood school in comparison to current and projected enrollment is on each individual school page in this document. Below is a description of each capacity total shown in the chart and a brief explanation of how each figure is derived.

The total reflects the capacity available at a school during the 20210-21 school This total demonstrates the capacity that would be available at a school year and includes the capacity provided by mobiles currently on site. site if all mobile pads were occupied and being used for enrollment. This capacity figure assumes that a traditional, single track calendar is being Since all DCSD schools currently use a single track calendar this is the sum of the utilized. "capacity on traditional calendar" figure plus any additional capacity provided by mobiles currently on-site. A typical mobile provides 56 extra seats. The If the phrase "Also current capacity at..." is also listed here, this indicates example used below shows capacity options at Copper Mesa Elementary. At this school there are 3 mobile pads on-site but only 1 is currently occupied with that a school currently has all of its mobile pads occupied. a mobile being used for enrollment. The current capacity available at Buffalo Ridge Elementary = 506+56. The capacity available at Buffalo Ridge Elementary if all mobile pads were occupied would = 506+(56*3). Student Enrollment - Historic & Projected Capacity with all mobile pads occupied = 707 This total reflects the school facility's ideal program capacity Capacity currently available on-site = 651 using a traditional calendar. In reference to school capacity, a traditional calendar is defined as any calendar that is not year round. These calendars are also referred to as single track calendars because all the students and staff are in school or on vacation at the same time. Currently all DCSD schools utilize a traditional calendar. 531 If the phrase "Also current capacity at..." is listed here, this indicates that a school currently has no mobiles on-site. 2016-17 2019-20 2024-25 2025-26 2017-18 2018-19 2021-22

Overutilized and Underutilized Neighborhood Schools

The Planning Department classifies overutilized schools in need of a capacity solution as any school with a 95% or higher utilization rate. These identified schools are broken into two categories; those schools projected to be overutilized by the 2021-22 school year and those projected to be overutilized by year five of the five-year outlook. The Planning Department classifies underutilized schools in need of a capacity solution as any school with a 65% or lower utilization rate. These identified schools are broken into two categories; those schools projected to be underutilized in the 2021-22 school year and those projected to be underutilized by year five of the five-year outlook

	North Planning Area				
Feeder	Feeder 2021 Over Utilized 2021 Under Utilized Schools Schools		2025 Over Utilized Schools	2025 Under Utilized School	
	Acres Green Elementary	Cresthill Middle School	Acres Green Elementary	Cresthill Middle School	
Highlands Ranch	Eagle Ridge Elementary		Eagle Ridge Elementary	Highlands Ranch High School	
	Fox Creek Elementary				
	Northridge Elementary		Mountain Vista High School	Bear Canyon Elementary	
Manustain Vieta	Mountain Vista High School			Copper Mesa Elementary	
Mountain Vista				Heritage Elementary	
				Mountain Ridge Middle School	
	Buffalo Ridge Elementary		Buffalo Ridge Elementary		
Rock Canyon	Wildcat Mountain Elementary		Timber Trail Elementary		
ROCK Carryon	Rocky Heights Middle School				
	Rock Canyon High School				
ThunderRidge		Saddle Ranch Elementary	Coyote Creek Elementary	Saddle Ranch Elementary	
ThunderRidge			Roxborough Intermediate		

	East Planning Area				
Feeder	2021 Over Utilized Schools	2021 Under Utilized Schools	2025 Over Utilized Schools	2025 Under Utilized School	
	Cherokee Trail Elementary		Cherokee Trail Elementary		
Chaparral	Pine Grove Elementary		Pine Grove Elementary		
Chaparrai	Prairie Crossing Elementary		Prairie Crossing Elementary		
	Chaparral High School		Chaparral High School		
	Franktown Elementary	Sagewood Middle School	Franktown Elementary	Sagewood Middle School	
Ponderosa			Northeast Elementary	Ponderosa High School	
ronderosa					
	Frontier Valley Elementary		Frontier Valley Elementary		
	Gold Rush Elementary		Gold Rush Elementary		
Legend	Iron Horse Elementary		Legend High School		
	Pioneer Elementary				
	Legend High School				

Overutilized and Underutilized Neighborhood Schools cont.

		West Planning A	rea	
Feeder	2021 Over Utilized Schools	2021 Under Utilized Schools	2025 Over Utilized Schools	2025 Under Utilized School
	Meadow View Elementary		Clear Sky Elementary	Sedalia Elementary
Castle View	Soaring Hawk Elementary		Meadow View Elementary	Castle Rock Middle School
Castle view	Castle View High School			
	Castle Rock Elementary	Cherry Valley Elementary	Castle Rock Elementary	Cherry Valley Elementary
Douglas County	South Ridge Elementary		Sage Canyon Elementary	
			South Ridge Elementary	

Capacity Relief Alternatives and Implementation

New construction and the other opportunities (and associated risks) discussed in this document are only some of the options available to the district to address over-utilized facilities. A variety of alternative methods exist and are carefully reviewed and considered by staff and the LRPC as enrollment growth occurs. Each alternative exhibits benefits as well as shortcomings. Below is a list of the additional capacity relief measures that could be considered along with their benefits and shortcomings.

Alternatives Using Existing Capacity



Boundary Change: Shifting attendance boundary lines to increase or decrease the number of neighborhood students in that specific attendance area. This approach doesn't destablize special programs, in most situations will only apply to new students and provides the DCSD community with a predictable and constant set of criteria for decisions. However this approach can take years to fully implement, can be less effective in a choice district and can be disruptive to families and students. In addition, actual impact can vary from the projected impact with this approach and staff must be careful to not over or under enroll nearby schools.



Calendar Change: Altering school calendar and class scheduling to reduce the number of students simultaneously utilizing school facilities. This approach makes greater use of existing facilities, keeps current attendance areas and neighborhoods intact, keeps current programming intact, and is relatively quick to implement. However, this approach makes regular facility maintenance and repair more difficult, could be challenging to parent's schedules, could interfere with extracurricular and after school activities, and results in additional wear and tear on the facility.



Grade Reconfiguration: Changing grade structure of a school in order to increase or decrease the overall enrollment. Like a calendar change, this approach makes use of existing facilities, keeps existing attendance areas and programming intact, and is relatively quick to implement. However, this approach may go against parent preference for current grade configuration, could impact school staff and programming, and could cause a transportation burden for families and staff.



Overflow Busing: Busing students to nearby schools with capacity. This approach makes greater use of existing facilities and is relatively quick to implement. However, this approach may be inconvenient for staff, parents, and students, would likely result in increased transportation costs and runs counter to the concept of a neighborhood school and promoting walkable, safe routes to neighborhood schools. In addition, this approach is only preferable when capacity is available at a facilities in relatively close proximity to overutilized facilities.



Program Change: Moving or replicating stand-alone programs to underutilized space. In addition to making use of existing facilities, keeping current attendance areas intact, and being relatively quick to implement, this approach can also benefit students living in other attendance areas. However, this approach could destabilize the overall effectiveness of the program and facilities may not be equipped with the special features and amenities needed for that program. In addition, this approach may cause a transportation burden and has the potential to impact school staff.

Alternatives Which Provide Additional Capacity



Building Addition: Addition or expansion of current building footprint in order to add more classroom space. This approach keeps current attendance areas and programming intact but is more expensive than program and/or calendar changes, does not reduce overutilization of the core facility spaces, and must take into account site constraints.



Mobiles: Installing additional modular units. This approach offers ultimate flexibility in responding to changes in enrollment, offers efficient short term relief, and is less costly than permanent buildings and additions. However, modular units typically lack the architectural quality, special features, and amenities that permanent classrooms have and should not be considered a long term solution. In addition, this approach must also take site constraints into consideration and does not reduce overutilization of the core facility spaces.



Purchase and Tenant Finish: Purchasing already existing space and tenant finish to meet DCSD program needs. This approach could be cost effective in comparison to new construction and is typically quicker to implement than new construction. However, this alternative is subject to market availability and costs and it may be difficult to find properties that fully meet DCSD criteria and needs.

2020-21 School Capacity and Boundary Analysis

For several years the Long Range Planning Committee (LRPC) has been monitoring the variances in enrollment projections across the Douglas County Schools District. While some areas of the district show current and projected growth of student populations, other areas show a leveling off of student numbers and even a decline in projected student numbers in certain schools.

As a result, the LRPC, in coordination with staff, recommended that the Board of Education allocate funds to study the student populations across the District and make recommendations about potential solutions. The LRPC has worked with Western Demographics and District staff to better understand the enrollment projections and the potential impacts. This was of course complicated by unforeseen events over the last year and the potential impact of the pandemic on district enrollment will need to be considered going forward.

What is clear is that there are a number of potential problems if a school is either over-enrolled or substantially underenrolled. An over-enrolled school can have difficulties presenting adequate instructional space and put pressure on the school environment. There are also educational complications in an over enrolled school. Schools with under-enrollment often face challenges in maintaining teachers and staff and can be challenged to offer full educational programming due to a decrease in funding.

There are a number of potential methods to address enrollment concerns. The LRPC in association with staff has procured a consultant that specializes in analysis of attendance areas and has proposed a series of boundary changes that may alleviate some school crowding. In addition in some areas the District has moved sixth grade classes from overcrowded elementary schools to middle schools with more capacity.

A key part of the process has been and will remain outreach to the public in the affected areas, taking into account concerns and suggestions provided by the public, including parents, as to the impact of changes. The overall mission of any change in attendance areas is to actively balance enrollment through attendance areas while minimizing the impact to students and families. This is coupled with the need to provide an educational environment that meets a high level of service and is what is best for kids.


The recent boundary and grade configuration changes are intended to address the most urgent needs of the District and its families. The LRPC and staff plan to continue to research these issues and potentially recommend more boundary or grade configuration changes to address both under enrollment and overcrowding issues in neighborhood schools. Any potential changes will continue to be in coordination with district educators and leaders. This research is part of the ongoing mission of the LRPC and is expected to continue over the next few years.




13524 Acres Green Drive Littleton, CO 80124 Highlands Ranch High School Feeder Area, K-6 Funded by 1974 Bond Opened in 1975

Site Acreage:12 Facility Square Feet: 50,480 Mobiles on-site: 3

Acres Green Elementary-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$2,468,400 Estimated Total Project Costs: \$2,838,420 - \$4,060,506



Following is the list of currently unfunded facility projects at Acres Green Elementary

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
Tier 1	Install seperate irrigation meter. Add booster pump	\$10,400	\$1,000-\$4,400	\$520-\$2,236
Funded by the 2018 Bond	Replace generator and associated equipment	\$75,000	\$7,500-\$32,300	\$3,750-\$16,125
1-High	Replace roof top units ²	\$1,000,000	\$100,000-\$430,000	\$50,000-\$215,000
1-Medium	Replace boiler(s) ²	\$250,000	\$25,000-\$107,500	\$12,500-\$53,750
	Exterior wall, recaulk control joints	\$4,700	\$400-\$2,000	\$235-\$1,011
	Recaulk exterior windows	\$16,400	\$1,700-\$7,100	\$820-\$3,526
	Refurbish/replace retractable partitions	\$44,000	\$4,400-\$19,000	\$2,200-\$9,460
	Replace fabricated toilet partition(s)	\$9,900	\$1,000-\$4,300	\$495-\$2,129
	Replace restroom flooring	\$71,500	\$7,200-\$30,800	\$3,575-\$15,373
2-High	Replace trough washing stations with sinks	\$17,600	\$1,800-\$7,600	\$880-\$3,784
2-High	Replace fixed casework	\$60,000	\$6,000-\$25,800	\$3,000-\$12,900
	Mill and overlay bus loop	\$50,000	\$5,000-\$21,500	\$2,500-\$10,750
	Resurface parking lot	\$100,000	\$10,000-\$43,000	\$5,000-\$21,500
	Repair/replace sidewalk(s)	\$20,000	\$2,000-\$8,600	\$1,000-\$4,300
	Repair/replace asphalt walkways	\$50,000	\$5,000-\$21,500	\$2,500-\$10,750
	Replace asphalt playground	\$100,000	\$10,000-\$43,000	\$5,000-\$21,500
2-Medium	Repair/replace areas of curb as needed	\$10,000	\$1,000-\$4,300	\$500-\$2,150
	Recaulk wall foundation	\$7,900	\$700-\$3,300	\$395-\$1,699
3-High	Replace/repair suspended ceiling	\$83,800	\$8,300-\$36,000	\$4,190-\$18,017
5-riigii	Renovate multi-use field	\$50,000	\$5,000-\$21,500	\$2,500-\$10,750
	Renovate upper baseball fields	\$15,600	\$1,500-\$6,600	\$780-\$3,354
3-Medium	Fire sprinkle building	\$408,500	\$40,800-\$175,600	\$20,425-\$87,828
4-High	Renovate/repair areas of grass around school	\$2,100	\$200-\$900	\$105-\$452
4-Medium	Add landscaping at NW corner of school site	\$11,000	\$1,100-\$4,800	\$550-\$2,365

Estimated Total Construction Costs (in 2021 Dollars): \$2,468,400 Estimated Project Management Costs Range: \$246,600 - \$1,061,400 Estimated Inflation Range: \$123,420 - \$530,706

Estimated Total Project Costs: \$2,838,420 - \$4,060,506

Tier 1 Projects Not Using 2018 Bond Funding

Project Symbol	Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
5	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.


Summary of Projects	Total Cost	
2019-2020 Completed Projects		
Upgrade control system Refinish, sand, and paint interior doors Replace interior door hinges Furniture	\$353,618	
2021 Contracted Projects		
Upgrade fire alarm system	\$162,110	




10345 Arrowwood Drive Highlands Ranch, CO 80130 Highlands Ranch High School Feeder Area, K-6 Funded by 1997 Bond Opened in 2000

Site Acreage:10 Facility Square Feet: 51,668 Mobiles on-site: 1

Arrowwood Elementary-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$847,100 Estimated Total Project Costs: \$974,655 - \$1,393,827



Following is the list of currently unfunded facility projects at Arrowwood Elementary

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
1-High	Install water sensing level switches in basement ²	\$25,000	\$2,500-\$10,800	\$1,250-\$5,375
1-Medium	Replace boiler(s) ²	\$250,000	\$25,000-\$107,500	\$12,500-\$53,750
1-Medium	Chilled Water Systems. Replace chiller ²	\$300,000	\$30,000-\$129,000	\$15,000-\$64,500
	Repair footings at playground entrance	\$21,600	\$2,200-\$9,300	\$1,080-\$4,644
	Exterior wall,repair CMU at cooling tower	\$2,200	\$300-\$1,000	\$110-\$473
2-High	Repair fixed wall(s)	\$2,200	\$300-\$1,000	\$110-\$473
2-nigii	Repair operable partition(s)	\$12,100	\$1,300-\$5,300	\$605-\$2,602
	Replace restroom flooring	\$40,000	\$4,000-\$17,200	\$2,000-\$8,600
	Repair/replace sidewalk(s)	\$81,900	\$8,200-\$35,200	\$4,095-\$17,609
3-High	Repair cafeteria floor, movement issues	\$19,500	\$2,000-\$8,400	\$975-\$4,193
3-High	Renovate multi-use field	\$80,000	\$8,000-\$34,400	\$4,000-\$17,200
2 Madium	Vinyl coverings repair/replacement	\$2,800	\$300-\$1,200	\$140-\$602
3-Medium	Replace dumpster enclosure	\$3,300	\$400-\$1,500	\$165-\$710
4-High	Renovate/replace areas of landscaping around site	\$6,500	\$700-\$2,800	\$325-\$1,398

Estimated Total Construction Costs (in 2021 Dollars): \$847,100 Estimated Project Management Costs Range: \$85,200 - \$364,600 Estimated Inflation Range: \$42,355 - \$182,127

Estimated Total Project Costs: \$974,655 - \$1,393,827

Tier 1 Projects Not Using 2018 Bond Funding

		5
Project Symbol	Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
5	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.

Summary of Projects	Total Cost	
2019-2020 Completed Projects		
Replacement of fire alarm system Replacement of cooling towers Reseal and recaulk exterior wall joints and windows Repair and replacement of kitchen flooring Replacement of door hardware with restricted key system Upgrade irrigation system Replacement of generator Replace and paint roof Replacement of sink countertops	\$1,806,491	
2021 Contracted Projects		
No projects contracted for 2021	N/A	



9660 Salford Lane Highlands Ranch, CO 80126 Mountain Vista High School Feeder Area, K-6


Funded by 1989 Bond Opened in 1990

Site Acreage:12 Facility Square Feet: 53,237 Mobiles on-site: 3

Bear Canyon Elementary-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$1,525,400 Estimated Total Project Costs: \$1,754,270 - \$2,509,061



Following is the list of currently unfunded facility projects at Bear Canyon Elementary

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Upgrade control system ²	\$300,000	\$30,000-\$129,000	\$15,000-\$64,500
1-High	Replace main switchgear ¹	\$100,000	\$10,000-\$43,000	\$5,000-\$21,500
1-High	Replace original panels and transformers ¹	\$110,000	\$11,000-\$47,300	\$5,500-\$23,650
	Upgrade fire alarm system ¹	\$160,000	\$16,000-\$68,800	\$8,000-\$34,400
	Replace exterior windows	\$73,100	\$7,300-\$31,400	\$3,655-\$15,717
	Refurbish/replace retractable partitions	\$17,900	\$1,800-\$7,600	\$895-\$3,849
	Replace restroom flooring	\$4,000	\$400-\$1,800	\$200-\$860
2-High	Replace fixtures in staff restrooms	\$2,800	\$300-\$1,200	\$140-\$602
	Replace sink fixtures in staff restrooms	\$1,900	\$200-\$800	\$95-\$409
	Replace fixed casework	\$60,000	\$6,000-\$25,800	\$3,000-\$12,900
	Repair/replace sidewalk(s)	\$51,000	\$5,100-\$21,900	\$2,550-\$10,965
	Replace carpet	\$350,000	\$35,000-\$150,500	\$17,500-\$75,250
2-Medium	Replace/repair suspended ceiling	\$143,000	\$14,300-\$61,500	\$7,150-\$30,745
	Resurface parking lot	\$59,600	\$5,900-\$25,500	\$2,980-\$12,814
3-High	Renovate multi-use field	\$2,800	\$300-\$1,200	\$140-\$602
4-High	Recaulk wall foundation	\$7,400	\$800-\$3,200	\$370-\$1,591
4-riigii	Renovate/repair areas of grass around school	\$81,900	\$8,200-\$35,200	\$4,095-\$17,609

Estimated Total Construction Costs (in 2021 Dollars): \$1,525,400 Estimated Project Management Costs Range: \$152,600 - \$655,700 Estimated Inflation Range: \$76,270 - \$327,961

Estimated Total Project Costs: \$1,754,270 - \$2,509,061

Tier 1 Projects Not Using 2018 Bond Funding

Project Symbol	Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
5	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.


Summary of Projects	Total Cost	
2019-2020 Completed Projects		
No projects completed in 2019-20	N/A	
2021 Contracted Projects		
Replace roof top units Replace toilet partitions Replace cafeteria and kitchen flooring	\$1,583,346	



7075 N. Shoreham Drive Castle Pines, CO 80108 Rock Canyon High School Feeder Area, K-5 Funded by 1993 Bond Opened in 1997


Site Acreage:10 Facility Square Feet: 51,020 Mobiles on-site: 1

Buffalo Ridge Elementary-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



\$500,000 \$1,000,000

Estimated Total Construction Costs (in 2021 Dollars): \$917,800 Estimated Total Project Costs: \$1,055,590 - \$1,509,927



Following is the list of currently unfunded facility projects at Buffalo Ridge Elementary

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
1-High	Replace boiler(s) ²	\$250,000	\$25,000-\$107,500	\$12,500-\$53,750
	Exterior paint	\$8,500	\$900-\$3,700	\$425-\$1,828
	Recaulk exterior windows	\$13,800	\$1,400-\$5,900	\$690-\$2,967
	Repair/replace storefront windows	\$31,900	\$3,200-\$13,800	\$1,595-\$6,859
2-High	Replace retractable partition(s)	\$17,000	\$1,700-\$7,300	\$850-\$3,655
2-nign	Replace fabricated toilet partition(s)	\$35,000	\$3,500-\$15,100	\$1,750-\$7,525
	Resurface parking lot	\$80,000	\$8,000-\$34,400	\$4,000-\$17,200
	Repair/replace sections of sidewalk as necessary	\$5,300	\$600-\$2,300	\$265-\$1,140
	Resurface playpad	\$33,700	\$3,400-\$14,500	\$1,685-\$7,246
	Bypass grease interceptor	\$8,500	\$900-\$3,700	\$425-\$1,828
3-Medium	Fire sprinkle building	\$428,500	\$42,800-\$184,200	\$21,425-\$92,128
	Repair retaining wall(s)	\$2,000	\$200-\$900	\$100-\$430
4-High	Recaulk wall foundation	\$3,600	\$300-\$1,500	\$180-\$774

Estimated Total Construction Costs (in 2021 Dollars): \$917,800 Estimated Project Management Costs Range: \$91,900 - \$394,800 Estimated Inflation Range: \$45,890 - \$197,327

Estimated Total Project Costs: \$1,055,590 - \$1,509,927

Tier 1 Projects Not Using 2018 Bond Funding

Project Symbol	Category Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
5	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.


Summary of Projects	Total Cost		
2019-2020 Completed Projects			
No projects completed in 2019-20	N/A		
2021 Contracted Projects			
Upgrade control system Replace swamp cooling units with mechanical cooling Replace roof top units Replace kitchen and cafeteria flooring	\$2,566,302		



1103 Canyon Drive Castle Rock, CO 80104 Douglas County High School Feeder Area, K-6 Funded by 1984 Bond Opened in 1984


Site Acreage:15.4 Facility Square Feet: 52,907 Mobiles on-site: 1

Castle Rock Elementary-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



\$500,000 Estimated Total Construction Costs (in 2021 Dollars): \$762,500 Estimated Total Project Costs: \$877,025 - \$1,254,338

\$1,000,000 \$1,500,000



Following is the list of currently unfunded facility projects at Castle Rock Elementary

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
1-High	Evaluate and replace branch wiring as needed ²	\$100,000	\$10,000-\$43,000	\$5,000-\$21,500
1-High	Replace generator and associated equipment ²	\$75,000	\$7,500-\$32,300	\$3,750-\$16,125
	Paint exterior trim, windows, and doors	\$9,400	\$900-\$4,000	\$470-\$2,021
	Recaulk exterior windows	\$4,900	\$500-\$2,100	\$245-\$1,054
	Refurbish/replace retractable partitions	\$18,700	\$1,900-\$8,100	\$935-\$4,021
	Replace stair tread	\$4,600	\$400-\$1,900	\$230-\$989
2-High	Replace cafeteria VCT	\$20,000	\$2,000-\$8,600	\$1,000-\$4,300
2-nign	Replace kitchen flooring	\$75,000	\$7,500-\$32,300	\$3,750-\$16,125
	Replace restroom flooring	\$40,000	\$4,000-\$17,200	\$2,000-\$8,600
	Replace water cooler(s), drinking fountain(s)	\$4,300	\$500-\$1,900	\$215-\$925
	Fill parking lot cracks	\$2,900	\$300-\$1,200	\$145-\$624
	Repair/replace sidewalk(s)	\$5,300	\$600-\$2,300	\$265-\$1,140
2-Medium	Replace gym carpet	\$40,000	\$4,000-\$17,200	\$2,000-\$8,600
2-Medium	Boiler room piping, add VFDs to motors/pumps	\$53,200	\$5,300-\$22,800	\$2,660-\$11,438
	Recaulk wall foundation	\$7,400	\$800-\$3,200	\$370-\$1,591
3-High	Replace/repair suspended ceiling	\$143,000	\$14,300-\$61,500	\$7,150-\$30,745
3-nigii	Replace wooden basketball backboards in gym	\$153,300	\$15,300-\$65,900	\$7,665-\$32,960
	Renovate multi-use field	\$5,500	\$600-\$2,400	\$275-\$1,183

Estimated Total Construction Costs (in 2021 Dollars): \$762,500 Estimated Project Management Costs Range: \$76,400 - \$327,900 Estimated Inflation Range: \$38,125 - \$163,938

Estimated Total Project Costs: \$877,025 - \$1,254,338

Tier 1 Projects Not Using 2018 Bond Funding

Project Symbol	Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.


Summary of Projects	Total Cost
2019-2020 Completed Projects	
No projects completed in 2019-20	N/A
2021 Contracted Projects	
Upgrade control system Replace roof Replace rooft Replace rooftop units Upgrade fire alarm system HVAC, replace MAUs and exhaust fans Replace cabinet heaters Replace main switchgear and associated electrical distribution Recaulk exterior wall control joints Replace sink countertops Replace carpet Furniture	\$3,498,635




2575 Meadows Boulevard Castle Rock, CO 80126 Castle View High School Feeder Area, 7-8 Funded by 1993 Bond Opened in 1996

Site Acreage:22 Facility Square Feet: 128,680 Mobiles on-site: 0

Castle Rock Middle School-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$1,354,800 Estimated Total Project Costs: \$1,558,140 - \$2,228,682



\$1,000,000

Following is the list of currently unfunded facility projects at Castle Rock Middle School

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Install water sensing level switches in basement ²	\$25,000	\$2,500-\$10,800	\$1,250-\$5,375
1-High	Replace boiler(s) ²	\$250,000	\$25,000-\$107,500	\$12,500-\$53,750
	Upgrade Water Treatment Systems ¹	\$17,000	\$1,700-\$7,300	\$850-\$3,655
1-Medium	Replace main switchgear ²	\$100,000	\$10,000-\$43,000	\$5,000-\$21,500
1-Medium	Replace original panels and transformers ²	\$100,000	\$10,000-\$43,000	\$5,000-\$21,500
	Exterior wall, recaulk control joints	\$4,900	\$500-\$2,100	\$245-\$1,054
	Recaulk exterior windows	\$24,500	\$2,400-\$10,500	\$1,225-\$5,268
	Refurbish/replace retractable partitions	\$12,800	\$1,300-\$5,500	\$640-\$2,752
2-High	Replace fabricated toilet partition(s)	\$45,000	\$4,500-\$19,400	\$2,250-\$9,675
2-nigii	Replace kitchen flooring	\$75,000	\$7,500-\$32,300	\$3,750-\$16,125
	Theatre & stage equipment, upgrade stand controller	\$4,900	\$500-\$2,100	\$245-\$1,054
	Raise library computer counter tops	\$15,000	\$1,500-\$6,500	\$750-\$3,225
	Repair/replace sidewalk(s)	\$5,300	\$600-\$2,300	\$265-\$1,140
2-Medium	Replace/refinish fixed casework as necessary	\$150,000	\$15,000-\$64,500	\$7,500-\$32,250
3-High	Recaulk wall foundation	\$9,800	\$1,000-\$4,200	\$490-\$2,107
5-nigii	Regular Stairs. Reseal concrete stairs	\$6,100	\$600-\$2,600	\$305-\$1,312
	Replace/repair suspended ceiling	\$3,700	\$300-\$1,500	\$185-\$796
	Replace chalk boards with white boards	\$76,700	\$7,700-\$33,000	\$3,835-\$16,491
3-Medium	Upgrade sink, exhaust system, storage in Tech area	\$185,400	\$18,500-\$79,700	\$9,270-\$39,861
	Repair retaining wall(s)	\$5,300	\$600-\$2,300	\$265-\$1,140
	Replace goal posts on athletic field	\$197,200	\$19,700-\$84,700	\$9,860-\$42,398
	Fix drainage problem on east side of school	\$20,600	\$2,100-\$8,900	\$1,030-\$4,429
4-Medium	Replace some trees	\$20,600	\$2,100-\$8,900	\$1,030-\$4,429

Estimated Total Construction Costs (in 2021 Dollars): \$1,354,800 Estimated Project Management Costs Range: \$135,600 - \$582,600 Estimated Inflation Range: \$67,740 - \$291,282

Estimated Total Project Costs: \$1,558,140 - \$2,228,682

Tier 1 Projects Not Using 2018 Bond Funding

Project Symbol	Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
5	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.

Summary of Projects	Total Cost	
2019-2020 Completed Projects		
Upgrade HVAC system Commission system Replace generator and associated equipment Replace carpet and VCT flooring in classroom Replace non-restricted key system with restricted system Replace sink countertops with single surface	\$1,009,076	
2021 Contracted Projects		
Renovate elevator	\$99,323	




5254 North Meadows Drive Castle Rock, CO 80109 Castle View High School Feeder Area, 9-12


Funded by 2003 Bond Opened in 2006

Site Acreage: 35.4 Facility Square Feet: 218,106 Mobiles on-site: 8

Castle View High School-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$3,668,900 Estimated Total Project Costs: \$4,219,345 - \$6,035,414



Following is the list of currently unfunded facility projects at Castle View High School

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
1-High	Replace generator and associated equipment ²	\$75,000	\$7,500-\$32,300	\$3,750-\$16,125
1-Medium	Replace roof top units ²	\$2,500,000	\$250,000-\$1,075,000	\$125,000-\$537,500
	Exterior wall, re-seal CMU, recaulk control joints	\$63,000	\$6,300-\$27,000	\$3,150-\$13,545
	Recaulk exterior windows	\$76,700	\$7,700-\$33,000	\$3,835-\$16,491
2-High	Theater and Stage Equipment, Upgrade lighting and sound sy	\$100,000	\$10,000-\$43,000	\$5,000-\$21,500
	Resurface parking lot	\$23,900	\$2,400-\$10,300	\$1,195-\$5,139
	Repair/replace sidewalk(s)	\$5,300	\$600-\$2,300	\$265-\$1,140
2-Medium	Replace restroom flooring	\$75,000	\$7,500-\$32,300	\$3,750-\$16,125
2-wealum	Replace carpet	\$750,000	\$75,000-\$322,500	\$37,500-\$161,250

Estimated Total Construction Costs (in 2021 Dollars): \$3,668,900 Estimated Project Management Costs Range: \$367,000 - \$1,577,700 Estimated Inflation Range: \$183,445 - \$788,814

Estimated Total Project Costs: \$4,219,345 - \$6,035,414

Tier 1 Projects Not Using 2018 Bond Funding

Project Symbol	Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.


Summary of Projects	Total Cost		
2019-2020 Completed Projects			
Upgrade fire alarm system Upgrade control system Replace roof Elevator Door and door hardware Fire alarm HVAC	\$3,169,138		
2021 Contracted Projects			
No projects contracted for 2021	N/A		




15665 Brookstone Drive Parker, CO 80134 Chaparral High School Feeder Area, 9-12 Funded by 1993 Bond Opened in 1997

Site Acreage: 50 Facility Square Feet: 240,367 Mobiles on-site: 4

Chaparral High School-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$1,774,800 Estimated Total Project Costs: \$2,041,140 - \$2,919,582



Following is the list of currently unfunded facility projects at Chaparral High School

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
1-High	Replace boiler(s) ²	\$400,000	\$40,000-\$172,000	\$20,000-\$86,000
1-Medium	Overhaul elevator #2 ²	\$250,000	\$25,000-\$107,500	\$12,500-\$53,750
	Exterior wall, re-seal CMU, recaulk control joints	\$58,500	\$5,800-\$25,100	\$2,925-\$12,578
	Recaulk exterior windows	\$73,100	\$7,300-\$31,400	\$3,655-\$15,717
	Fix exterior window(s) leakage	\$153,300	\$15,300-\$65,900	\$7,665-\$32,960
	Replace (4) four rollup doors at kitchen	\$15,400	\$1,600-\$6,700	\$770-\$3,311
	Continuous hinges on storefront doors need replaced	\$9,700	\$1,000-\$4,200	\$485-\$2,086
	Replace interior door(s)	\$5,300	\$600-\$2,300	\$265-\$1,140
2-High	Replace fabricated toilet partition(s)	\$66,000	\$6,600-\$28,400	\$3,300-\$14,190
2 mgn	Replace sink countertop(s)	\$42,200	\$4,200-\$18,100	\$2,110-\$9,073
	Replace kitchen flooring	\$77,000	\$7,700-\$33,200	\$3,850-\$16,555
	Upgrade/replace showers	\$18,000	\$1,800-\$7,700	\$900-\$3,870
	Replace approximately 100 seats in auditorium	\$3,100	\$300-\$1,400	\$155-\$667
	Resurface parking lot	\$12,800	\$1,300-\$5,500	\$640-\$2,752
	Repair/replace sidewalk(s)	\$9,800	\$1,000-\$4,200	\$490-\$2,107
	Upgrade theatre and stage lighting and sound systems	\$100,000	\$10,000-\$43,000	\$5,000-\$21,500
3-High	Recaulk wall foundation	\$34,100	\$3,500-\$14,700	\$1,705-\$7,332
3-riigii	Repair floor in closet between rooms 322 and 207	\$3,700	\$300-\$1,500	\$185-\$796
	Vinyl coverings repair/replacement	\$106,300	\$10,600-\$45,700	\$5,315-\$22,855
3-Medium	Replace/repair suspended ceiling	\$6,400	\$700-\$2,800	\$320-\$1,376
3-Medium	Fire sprinkle building	\$321,800	\$32,200-\$138,400	\$16,090-\$69,187
	Replace softball field fence	\$8,300	\$800-\$3,500	\$415-\$1,785

Estimated Total Construction Costs (in 2021 Dollars): \$1,774,800 Estimated Project Management Costs Range: \$177,600 - \$763,200 Estimated Inflation Range: \$88,740- \$381,582

Estimated Total Project Costs: \$2,041,140 - \$2,919,582

Tier 1 Projects Not Using 2018 Bond Funding

Project Symbol	Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
5	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.


Summary of Projects	Total Cost	
2019-2020 Completed Projects		
Replace generator and associated equipment Replace gym bleachers Replace flooring in cafeteria, commons, and hallways	\$1,344,456	
2021 Contracted Projects		
Update air distribution system Replace rooftop units Replace main gas line at meter Upgrade and add HW loop to water treatment and glycol distribution system Replace irrigation controllers Renovate elevator #1 Install new roof on F-pod	\$7,799,850	



17302 Clarke Farms Dr. Parker, CO 80134 Chaparral High School Feeder Area, K-6 Funded by 1984 Bond Opened in 1989


Site Acreage: 10 Facility Square Feet: 53,237 Mobiles on-site: 3

Cherokee Trail Elementary-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



\$500,000 \$1,000,000

Estimated Total Construction Costs (in 2021 Dollars): \$895,400 Estimated Total Project Costs: \$1,029,870 - \$1,473,211



Following is the list of currently unfunded facility projects at Cherokee Trail Elementary

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
1-High	Upgrade control system ²	\$300,000	\$30,000-\$129,000	\$15,000-\$64,500
	Refurbish/replace retractable partitions	\$12,800	\$1,300-\$5,500	\$640-\$2,752
2-High	Replace kitchen flooring	\$75,000	\$7,500-\$32,300	\$3,750-\$16,125
2-nigii	Replace gas piping on roof	\$2,000	\$200-\$900	\$100-\$430
	Replace fixed casework	\$77,000	\$7,700-\$33,200	\$3,850-\$16,555
2-Medium	Replace restroom flooring	\$15,000	\$1,500-\$6,500	\$750-\$3,225
2-Medium	Replace carpet	\$330,000	\$33,000-\$141,900	\$16,500-\$70,950
3-High	Recaulk wall foundation	\$7,400	\$800-\$3,200	\$370-\$1,591
3-riigii	Renovate multi-use field	\$38,500	\$3,900-\$16,600	\$1,925-\$8,278
4-High	Renovate/repair areas of grass around school	\$30,700	\$3,100-\$13,200	\$1,535-\$6,601
4-riigii	Replace metal edging with concrete mow strip	\$7,000	\$700-\$3,000	\$350-\$1,505

Estimated Total Construction Costs (in 2021 Dollars): \$895,400 Estimated Project Management Costs Range: \$89,700 - \$385,300 Estimated Inflation Range: \$44,770 - \$192,511

Estimated Total Project Costs: \$1,029,870 - \$1,473,211

Tier 1 Projects Not Using 2018 Bond Funding

Project Symbol	Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
5	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.


Summary of Projects	Total Cost
2019-2020 Completed Projects	
No projects completed in 2019-20	N/A
2021 Contracted Projects	
Replace sealtite and wiring to roof equipment Replace rooftop units Replace exterior windows Upgrade fire alarm system Repair/replace main skylight Replace lavatories, toilets and urinals Replace old exit signs Upgrade VAV boxes Replace original panels and transformers Repair/replace areas of cracked sidewalk Replace main switchgear Furniture	\$1,846,858



9244 South State Highway 83 Franktown, CO 80116 Douglas County High School Feeder Area, K-6 Funded prior to 1952 Opened in 1952


Site Acreage: 4 Facility Square Feet: 4,657 Mobiles on-site: 1

Cherry Valley Elementary-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



\$500,000 Estimated Total Construction Costs (in 2021 Dollars): \$247,500

Estimated Total Project Costs: \$284,675 - \$407,113



\$1,000,000

Following is the list of currently unfunded facility projects at Cherry Valley Elementary

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
1-High	Replace piping at propane tanks ⁴	\$21,700	\$2,200-\$9,300	\$1,085-\$4,666
1-Medium	Upgrade control system ²	\$25,000	\$2,500-\$10,800	\$1,250-\$5,375
	Replace kitchen flooring	\$20,000	\$2,000-\$8,600	\$1,000-\$4,300
2-High	Replace carpet in modulars	\$91,600	\$9,100-\$39,300	\$4,580-\$19,694
	Resurface parking lot	\$2,000	\$200-\$900	\$100-\$430
2-Medium	Replace floor urinals with wall mount	\$27,500	\$2,800-\$11,900	\$1,375-\$5,913
Z-Wedium	Replace sink(s)	\$3,900	\$400-\$1,700	\$195-\$839
	Replace/repair suspended ceiling	\$2,100	\$200-\$900	\$105-\$452
3-High	Replace/repair suspended ceiling	\$10,400	\$1,000-\$4,400	\$520-\$2,236
	Replace all fencing at around school perimeter	\$4,800	\$500-\$2,000	\$240-\$1,032
	Install new synthetic turf for multi-use field	\$38,500	\$3,900-\$16,600	\$1,925-\$8,278

Estimated Total Construction Costs (in 2021 Dollars): \$247,500 Estimated Project Management Costs Range: \$24,800 - \$106,400 Estimated Inflation Range: \$12,375 - \$53,213

Estimated Total Project Costs: \$284,675 - \$407,113

Tier 1 Projects Not Using 2018 Bond Funding

Project Symbol	Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
5	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.

Summary of Projects	Total Cost		
2019-2020 Completed Projects			
Reseal, recaulk, and repair cracks in exterior wall CMU and joints Replace single pane windows Replace gym and restroom flooring Replace non-restricted key system with restricted system Repair soffit on original building Replace two exterior doors Furniture Sidewalks	\$338,317		
2021 Contracted Projects			
No projects contracted for 2021	N/A		




12130 Canterberry Parkway Parker, CO 80134 Legend High School Feeder Area, 6-8

Funded by 2006 Bond Opened in 2010


Site Acreage: 22 Facility Square Feet: 132,414 Mobiles on-site: 4

Cimarron Middle School-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



\$1,000,000

Estimated Total Construction Costs (in 2021 Dollars): \$725,000 Estimated Total Project Costs: \$833,750 - \$1,192,675



Following is the list of currently unfunded facility projects at Cimarron Middle School

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
1-High	Upgrade fire alarm system ²	\$375,000	\$37,500-\$161,300	\$18,750-\$80,625
1-Medium	Upgrade control system ²	\$350,000	\$35,000-\$150,500	\$17,500-\$75,250

Estimated Total Construction Costs (in 2021 Dollars): \$725,000 Estimated Project Management Costs Range: \$72,500 - \$311,800 Estimated Inflation Range: \$36,250 - \$155,875

Estimated Total Project Costs: \$833,750 - \$1,192,675

Tier 1 Projects Not Using 2018 Bond Funding


	ne. Trojects that asmig 20 to bottom and and				
Project Symbol	Category	Category Definition			
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.			
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.			
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.			
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.			
5	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.			




1470 Clear Sky Way Castle Rock, CO 80109 Castle View High School Feeder Area, K-6 Funded by 2006 Bond Opened in 2008

Site Acreage:10 Facility Square Feet: 73,146 Mobiles on-site: 2

Clear Sky Elementary-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$941,100 Estimated Total Project Costs: \$1,082,355 - \$1,548,237



Following is the list of currently unfunded facility projects at Clear Sky Elementary

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Install water sensing level switches in basement ²	\$25,000	\$2,500-\$10,800	\$1,250-\$5,375
1-High	Upgrade control system ¹	\$385,000	\$38,500-\$165,600	\$19,250-\$82,775
	Upgrade fire alarm system ¹	\$210,000	\$21,000-\$90,300	\$10,500-\$45,150
2-High	Exterior wall, re-seal CMU, recaulk control joints	\$16,500	\$1,700-\$7,100	\$825-\$3,548
	Paint metal at window shades, metal stantions	\$5,500	\$600-\$2,400	\$275-\$1,183
	Recaulk exterior windows	\$16,500	\$1,700-\$7,100	\$825-\$3,548
2-Medium	Resurface parking lot	\$2,000	\$200-\$900	\$100-\$430
	Repair/resurface playground as necessary	\$5,800	\$500-\$2,400	\$290-\$1,247
	Replace artficial turf	\$3,900	\$400-\$1,700	\$195-\$839
3-Medium	Vinyl coverings repair/replacement	\$2,800	\$300-\$1,200	\$140-\$602
	Renovate/repair areas of grass around school	\$268,100	\$26,800-\$115,300	\$13,405-\$57,642

Estimated Total Construction Costs (in 2021 Dollars): \$941,100 Estimated Project Management Costs Range: \$94,200 - \$404,800 Estimated Inflation Range: \$47,055 - \$202,337

Estimated Total Project Costs: \$1,082,355 - \$1,548,237

Tier 1 Projects Not Using 2018 Bond Funding

	,	
Project Symbol	Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
5	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.


Summary of Projects	Total Cost	
2019-2020 Completed Projects		
Elevator modernizations	\$3,244	
2021 Contracted Projects		
Sidewalks	\$140,000	



3501 Poston Parkway Highlands Ranch, CO 80126 Mountain Vista High School Feeder Area, K-6 Funded by 2000 Bond Opened in 2006


Site Acreage: 10 Facility Square Feet: 56,868 Mobiles on-site: 2

Copper Mesa Elementary-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



\$500,000 \$1,000,000

Estimated Total Construction Costs (in 2021 Dollars): \$836,600 Estimated Total Project Costs: \$962,330 - \$1,376,469



Following is the list of currently unfunded facility projects at Copper Mesa Elementary

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
1-High	Install water sensing level switches in basement ²	\$25,000	\$2,500-\$10,800	\$1,250-\$5,375
1-High	Replace generator and associated equipment ²	\$75,000	\$7,500-\$32,300	\$3,750-\$16,125
	Recaulk exterior windows	\$15,300	\$1,600-\$6,600	\$765-\$3,290
	Refurbish/replace retractable partitions	\$12,800	\$1,300-\$5,500	\$640-\$2,752
2-High	Repair cracking in bus loop	\$50,000	\$5,000-\$21,500	\$2,500-\$10,750
2-nigii	Repair parking lot cracks	\$20,600	\$2,100-\$8,900	\$1,030-\$4,429
	Repair/replace areas of curb as needed	\$111,300	\$11,100-\$47,800	\$5,565-\$23,930
	Repair/replace sidewalk(s)	\$5,500	\$600-\$2,400	\$275-\$1,183
	Replace fabricated toilet partitions	\$35,000	\$3,500-\$15,100	\$1,750-\$7,525
	Replace gym carpet	\$40,000	\$4,000-\$17,200	\$2,000-\$8,600
2-Medium	Replace restroom flooring	\$40,000	\$4,000-\$17,200	\$2,000-\$8,600
2-Medium	Replace cafeteria VCT	\$20,000	\$2,000-\$8,600	\$1,000-\$4,300
	Replace carpet	\$350,000	\$35,000-\$150,500	\$17,500-\$75,250
	Repair/resurface playground as necessary	\$11,800	\$1,200-\$5,100	\$590-\$2,537
	Vinyl coverings repair/replacement	\$6,200	\$600-\$2,700	\$310-\$1,333
3-Medium	Repair insulation at water heater	\$12,800	\$1,300-\$5,500	\$640-\$2,752
	Replace plants in N playground area	\$5,300	\$600-\$2,300	\$265-\$1,140

Estimated Total Construction Costs (in 2021 Dollars): \$836,600 Estimated Project Management Costs Range: \$83,900 - \$360,000 Estimated Inflation Range: \$41,830 - \$179,869

Estimated Total Project Costs: \$962,330 - \$1,376,469

Tier 1 Projects Not Using 2018 Bond Funding

	,	3
Project Symbol	Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
5	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.


Summary of Projects	Total Cost		
2019-2020 Completed Projects			
No projects completed in 2019-20	N/A		
2021 Contracted Projects			
Upgrade control system Recaulk exterior wall control joints, reseal CMU Upgrade fire alarm system Replace ballasted with fully adhered roof Replace sink countertops	\$1,302,096		



8780 Venneford Ranch Road Highlands Ranch, CO 80126 Highlands Ranch High School Feeder Area, K-6 Funded by 1993 Bond Opened in 1995


Site Acreage: 8 Facility Square Feet: 51,020 Mobiles on-site: 2

Cougar Run Elementary-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



\$500,000 \$1,000,000

Estimated Total Construction Costs (in 2021 Dollars): \$1,311,000 Estimated Total Project Costs: \$1,507,750 - \$2,156,765



Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
Tier 1 Funded by the 2018 Bond	Upgrade irrigation system	\$12,800	\$1,300-\$5,500	\$640-\$2,752
1-High	Replace boiler(s) ²	\$250,000	\$25,000-\$107,500	\$12,500-\$53,750
1-Medium	Replace main switchgear ¹	\$100,000	\$10,000-\$43,000	\$5,000-\$21,500
1-Medium	Replace original panels and transformers ²	\$100,000	\$10,000-\$43,000	\$5,000-\$21,500
	Paint exterior window, doors & frames	\$4,100	\$400-\$1,800	\$205-\$882
	Repair/replace storefront windows	\$32,500	\$3,200-\$14,000	\$1,625-\$6,988
	Refurbish/replace retractable partitions	\$12,800	\$1,300-\$5,500	\$640-\$2,752
	Replace fabricated toilet partition(s)	\$35,000	\$3,500-\$15,100	\$1,750-\$7,525
	Replace sink countertop(s)	\$30,000	\$3,000-\$12,900	\$1,500-\$6,450
2-High	Replace cafeteria VCT	\$20,000	\$2,000-\$8,600	\$1,000-\$4,300
2-nigii	Repair cafeteria flooring	\$1,000	\$100-\$500	\$50-\$215
	Replace hallway/classroom flooring	\$12,800	\$1,300-\$5,500	\$640-\$2,752
	Replace hallway/classroom flooring	\$10,900	\$1,100-\$4,700	\$545-\$2,344
	Replace kitchen flooring	\$75,000	\$7,500-\$32,300	\$3,750-\$16,125
	Replace floor drain in kitchen	\$1,000	\$100-\$500	\$50-\$215
	Upgrade gym sound system	\$88,000	\$8,800-\$37,900	\$4,400-\$18,920
2-Medium	Replace/refinish fixed casework as necessary	\$60,000	\$6,000-\$25,800	\$3,000-\$12,900
3-High	Recaulk wall foundation	\$3,600	\$300-\$1,500	\$180-\$774
3-nigii	Repair structural damage from movement issues	\$14,200	\$1,500-\$6,100	\$710-\$3,053
	Vinyl coverings repair/replacement	\$4,400	\$500-\$1,900	\$220-\$946
3-Medium	Bypass grease interceptor	\$9,000	\$900-\$3,800	\$450-\$1,935
	Fire sprinkle building	\$433,900	\$43,400-\$186,500	\$21,695-\$93,289

Estimated Total Construction Costs (in 2021 Dollars): \$1,311,000 Estimated Project Management Costs Range: \$131,200 - \$563,900

Estimated Inflation Range: \$65,550 - \$281,865 Estimated Total Project Costs: \$1,507,750 - \$2,156,765

Tier 1 Projects Not Using 2018 Bond Funding

The Tribjects Not osing 2010 bollar allaling			
Project Symbol	Category	Category Definition	
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.	
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.	
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.	
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.	
	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.	

Completed and Contracted Projects Using 2016 Bond Funding		
Summary of Projects	Total Cost	
2019-2020 Completed Projects		
Replace VAV boxes (air distribution system) Upgrade control system Replace roof top units Replace generator and associated equipment Recoat exterior wall CMU weather proofing, recaulk control joints Replace exterior windows Replace gym carpet Move hot water heater, install on demand pumps Replace interior door hardware	\$2,406,905	
2021 Contracted Projects		
No projects contracted for 2021	N/A	




2861 Baneberry Court Highlands Ranch, CO 80129 ThunderRidge High School Feeder Area, K-6


Funded by 1993 Bond Opened in 1995

Site Acreage: 10 Facility Square Feet: 54,220 Mobiles on-site: 1

Coyote Creek Elementary-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$1,769,600 Estimated Total Project Costs: \$2,035,080 - \$2,910,664



Following is the list of currently unfunded and to be funded with the 2018 Bond facility projects at Coyote Creek Elementary

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
Tier 1 Funded by the	Replace exhaust fans	\$107,000	\$10,700-\$45,900	\$5,350-\$23,005
2018 Bond	Replace generator and associated equipment	\$75,000	\$7,500-\$32,300	\$3,750-\$16,125
1-High	Upgrade fire alarm system ²	\$160,000	\$16,000-\$68,800	\$8,000-\$34,400
	Upgrade control system ²	\$300,000	\$30,000-\$129,000	\$15,000-\$64,500
1-Medium	Replace main switchgear ²	\$100,000	\$10,000-\$43,000	\$5,000-\$21,500
	Replace original panels and transformers ²	\$100,000	\$10,000-\$43,000	\$5,000-\$21,500
	Repair crack at cafeteria slab, see flooring	\$5,800	\$500-\$2,400	\$290-\$1,247
	Exterior wall, re-seal CMU, recaulk control joints	\$19,500	\$2,000-\$8,400	\$975-\$4,193
	Recaulk exterior windows	\$13,800	\$1,400-\$5,900	\$690-\$2,967
	Repair NE entry leaking at floor	\$11,500	\$1,100-\$4,900	\$575-\$2,473
2-High	Repair operable partition(s)	\$12,100	\$1,300-\$5,300	\$605-\$2,602
Z-High	Replace kitchen flooring	\$75,000	\$7,500-\$32,300	\$3,750-\$16,125
	Replace carpet	\$1,800	\$200-\$800	\$90-\$387
	Replace lavatory faucets	\$18,000	\$1,800-\$7,700	\$900-\$3,870
	Replace art room counter tops	\$10,000	\$1,000-\$4,300	\$500-\$2,150
	Repair parking lot cracks	\$25,300	\$2,600-\$10,900	\$1,265-\$5,440
	Replace restroom flooring	\$40,000	\$4,000-\$17,200	\$2,000-\$8,600
2-Medium	Replace cafeteria VCT	\$20,000	\$2,000-\$8,600	\$1,000-\$4,300
Z-Wedium	Replace carpet	\$350,000	\$35,000-\$150,500	\$17,500-\$75,250
	Replace/refinish fixed casework as necessary	\$60,000	\$6,000-\$25,800	\$3,000-\$12,900
	Recaulk wall foundation	\$3,600	\$300-\$1,500	\$180-\$774
3-High	Vinyl coverings repair/replacement \$5,800	\$500-\$2,400	\$290-\$1,247	
3-riigii	Replace insulation throughout building (valve leaks)	\$21,500	\$2,100-\$9,200	\$1,075-\$4,623
	Resod/renovate soccer and softball field	\$50,900	\$5,100-\$21,800	\$2,545-\$10,944
3-Medium	Vinyl coverings repair/replacement	\$4,900	\$500-\$2,100	\$245-\$1,054
3-Mediuili	Replace/repair suspended ceiling	\$171,600	\$17,200-\$73,800	\$8,580-\$36,894
4-High	Replace metal edger with concrete mow band	\$6,500	\$700-\$2,800	\$325-\$1,398

Estimated Total Construction Costs (in 2021 Dollars): \$1,769,600 Estimated Project Management Costs Range: \$177,000 - \$760,600 Estimated Inflation Range: \$88,480 - \$380,464

Estimated Total Project Costs: \$2,035,080 - \$2,910,664

Tier 1 Projects Not Using 2018 Bond Funding


	,	3
Project Symbol	Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
5	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.




9195 Cresthill Lane Highlands Ranch, CO 80130 Highlands Ranch High School Feeder Area, 7-8 Funded by 1989 Bond Opened in 1990

Site Acreage:12 Facility Square Feet: 134,400 Mobiles on-site: 0

Cresthill Middle School-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$2,357,100 Estimated Total Project Costs: \$2,710,655 - \$3,877,477



Following is the list of currently unfunded and to be funded with the 2018 Bond facility projects at Cresthill Middle

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
Tier 1 Funded by the 2018 Bond	Replace main switchgear	\$44,000	\$4,400-\$19,000	\$2,200-\$9,460
1-High	Upgrade fire alarm system ²	\$350,000	\$35,000-\$150,500	\$17,500-\$75,250
1-Medium	Upgrade control system ²	\$600,000	\$60,000-\$258,000	\$30,000-\$129,000
	Exterior wall, recaulk control joints	\$4,900	\$500-\$2,100	\$245-\$1,054
	Replace exterior windows	\$97,500	\$9,800-\$41,900	\$4,875-\$20,963
2-High	Recaulk exterior windows	\$39,000	\$3,900-\$16,700	\$1,950-\$8,385
Z-High	Replace hallway/classroom flooring	\$185,400	\$18,500-\$79,700	\$9,270-\$39,861
	Replace kitchen flooring	\$75,000	\$7,500-\$32,300	\$3,750-\$16,125
	Replace/refinish fixed casework as necessary	\$200,000	\$20,000-\$86,000	\$10,000-\$43,000
2-Medium	Replace carpet	\$750,000	\$75,000-\$322,500	\$37,500-\$161,250
3-High	Recaulk wall foundation	\$3,600	\$300-\$1,500	\$180-\$774
3-Medium	Vinyl coverings repair/replacement	\$7,700	\$800-\$3,400	\$385-\$1,656

Estimated Total Construction Costs (in 2021 Dollars): \$2,357,100 Estimated Project Management Costs Range: \$235,700 - \$1,013,600

Estimated Inflation Range: \$117,855 - \$506,777 Estimated Total Project Costs: \$2,710,655 - \$3,877,477

Tier 1 Projects Not Using 2018 Bond Funding

Project Symbol	Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
5	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.



9350 Teddy Lane Highlands Ranch, CO 80130


Funded by General Fund Opened in 2017

Site Acreage:1.7 Facility Square Feet: 26,121

Highlands Ranch High School Feeder Area, Alternative Education

DCSD Opportunity Center-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority






Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs		
		ojects identified at this time. All security and technology related————————————————————————————————————				


961 South Plum Creek Boulevard Castle Rock, CO 80104 Douglas County High School Feeder Area, 9-12 Funded by Certificate of Participation **Building Purchased: 2002**

Site Acreage: 3.3 Facility Square Feet: 21,725 Mobiles on-site: 0

DC Oakes High School-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$815,000 Estimated Total Project Costs: \$937,250 - \$1,340,925



Following is the list of currently unfunded and to be funded with the 2018 Bond facility projects at DC Oakes

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Replace roof on DMO	\$75,000	\$7,500-\$32,300	\$3,750-\$16,125
Tier 1	Replace roof top units	\$150,000	\$15,000-\$64,500	\$7,500-\$32,250
Funded by the	Upgrade control system	\$55,000	\$5,500-\$23,700	\$2,750-\$11,825
2018 Bond	Replace main switchgear	\$55,000	\$5,500-\$23,700	\$2,750-\$11,825
	Upgrade fire alarm system	\$80,000	\$8,000-\$34,400	\$4,000-\$17,200
	Replace condensing units ²	\$75,000	\$7,500-\$32,300	\$3,750-\$16,125
1-High	Evaluate and replace branch wiring as needed ²	\$100,000	\$10,000-\$43,000	\$5,000-\$21,500
	Replace generator and associated equipment ²	\$75,000	\$7,500-\$32,300	\$3,750-\$16,125
2-Medium	Replace carpet	\$150,000	\$15,000-\$64,500	\$7,500-\$32,250

Estimated Total Construction Costs (in 2021 Dollars): \$815,000 Estimated Project Management Costs Range: \$81,500 - \$350,700 Estimated Inflation Range: \$40,750 - \$175,225

Estimated Total Project Costs: \$937,250 - \$1,340,925

Tier 1 Projects Not Using 2018 Bond Funding

Project Symbol	Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.

Summary of Projects	Total Cost		
2019-2020 Completed Projects			
Doors and door hardware	\$1,128		
2021 Contracted Projects			
No projects contracted for 2021	N/A		




Castle Rock, CO 80104 Douglas County High School Feeder Area, 9-12


Funded by 1960 Bond Opened in 1961

Site Acreage: 50 Facility Square Feet: 268,232 (North), 106,616 (South) Mobiles on-site: 1

Douglas County High School-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$8,747,100 Estimated Total Project Costs: \$10,059,455 - \$14,387,027



Following is the list of currently unfunded and to be funded with the 2018 Bond facility projects at Douglas County High

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
Tier 1 Funded by the	Upgrade irrigation system-piping within pump building, increase diameter	\$11,000	\$1,100-\$4,800	\$550-\$2,365
2018 Bond	Upgrade irrigation system-replace mainlines	\$5,800	\$500-\$2,400	\$290-\$1,247
	Replace South building elevator ⁴	\$171,600	\$17,200-\$73,800	\$8,580-\$36,894
	Revise art room ventilation systems ⁴	\$31,000	\$3,100-\$13,300	\$1,550-\$6,665
1-High	Upgrade fire alarm system ²	\$350,000	\$35,000-\$150,500	\$17,500-\$75,250
1-nigii	Replace generator and associated equipment ¹	\$75,000	\$7,500-\$32,300	\$3,750-\$16,125
	South Building: Revise art room ventilation systems ⁴	\$20,700	\$2,100-\$8,900	\$1,035-\$4,451
	Upgrade fire alarm system ²	\$600,000	\$60,000-\$258,000	\$30,000-\$129,000
1-Medium	Replace storm inlets and reconnect to storm drain south side of S bldg ⁴	\$180,800	\$18,100-\$77,700	\$9,040-\$38,872

Estimated Total Construction Costs (in 2021 Dollars): \$8,747,100 Estimated Project Management Costs Range: \$875,000 - \$3,759,300 Estimated Inflation Range: \$437,355 - \$1,880,627

Estimated Total Project Costs: \$10,059,455 - \$14,387,027

Tier 1 Projects Not Using 2018 Bond Funding

Project Symbol	Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
5	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.

Summary of Projects	Total Cost
2019-2020 Completed Projects	
Replace/repair doors and door hardware Replace exterior doors, frames, and hardware Furniture	\$530,529
2021 Contracted Projects	
Replace/repair air distribution systems Replace/repair hot water distribution system and hot water service Renovate elevator Replace natural gas service Replace gutters and downspouts Replace/repair skylights Refinish soffits Recaulk control joints, repair masonry exterior walls Seal window frames and repair sills Fire seal fixed walls Replace unit heaters Replace water meter Provide south lot lighting	\$12,425,537

Douglas County High cont.

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Repair foundation on bleacher walls	\$46,400	\$4,600-\$19,900	\$2,320-\$9,976
	Provide lift or ramp to auditorium main stage	\$47,300	\$4,800-\$20,400	\$2,365-\$10,170
	ADA conforming auto shop ramp	\$5,300	\$600-\$2,300	\$265-\$1,140
	Repair loose brick mortar on south exterior parapet wall	\$6,400	\$700-\$2,800	\$320-\$1,376
	Repair 2 holes in exterior masonry at north wall of library	\$1,100	\$200-\$500	\$55-\$237
	Repoint joints at Life Mgmt Wing and west face Auditorium	\$6,600	\$700-\$2,900	\$330-\$1,419
	Repaint CMU exterior walls at Industrial Arts, downspouts, and E HallKalwall monitor	\$10,400	\$1,000-\$4,400	\$520-\$2,236
	Repaint steel beams / columns at Life Mgmt Wing, wood transoms above Metal Shop door and at Boiler Room and wood soffit at door F.	\$15,600	\$1,500-\$6,600	\$780-\$3,354
	Caulk perimeters at windows	\$2,700	\$300-\$1,100	\$135-\$581
	Reglaze windows in 66 & 67, rusting frames	\$500	\$-\$200	\$25-\$108
	Refinish exterior Y,I North doors and frames	\$2,700	\$300-\$1,100	\$135-\$581
	Make rolling doors at student store and attendance office ADA compliant	\$9,900	\$1,000-\$4,300	\$495-\$2,129
	Upgrade auditorium with wheel chair spaces for ADA	\$800	\$100-\$400	\$40-\$172
	Reconstruct auditorium control room	\$16,500	\$1,700-\$7,100	\$825-\$3,548
	Upgrade restrooms in two story addition, restroom in north hall, and old locker rooms	\$46,500	\$4,600-\$19,900	\$2,325-\$9,998
	Fire seal area separation wall penetrations	\$11,500	\$1,100-\$4,900	\$575-\$2,473
	Replace fabricated toilet partition(s)	\$8,800	\$900-\$3,800	\$440-\$1,892
	Replace handrails on stairs in E-Wing	\$13,800	\$1,400-\$5,900	\$690-\$2,967
	Replace restroom flooring	\$20,000	\$2,000-\$8,600	\$1,000-\$4,300
	North- E Wing entries do not have recessed mats	\$1,500	\$100-\$600	\$75-\$323
	Replace science CR 62 floor tile	\$7,600	\$800-\$3,300	\$380-\$1,634
	Replace carpetingge	\$92,800	\$9,300-\$39,900	\$4,640-\$19,952
	Replace/repair suspended ceiling	\$21,300	\$2,100-\$9,100	\$1,065-\$4,580
2-High	Replace lavatories and sinks	\$24,500	\$2,400-\$10,500	\$1,225-\$5,268
g	Replace sink(s)	\$2,700	\$300-\$1,100	\$135-\$581
	Replace sink(s)	\$38,700	\$3,800-\$16,600	\$1,935-\$8,321
	Revise piping at sinks in classroom 53	\$5,300	\$600-\$2,300	\$265-\$1,140
	Replace leaking fixtures north building teacher's lounge	\$2,700	\$300-\$1,100	\$135-\$581
	Replace faucets at art sinks Provide plaster sink with large capacity plaster trap (N Art	\$2,700 \$10,600	\$300-\$1,100 \$1,100-\$4,600	\$135-\$581 \$530-\$2,279
	room)	,	¢1,000,¢4,300	·
	Replace the wash fountain & DF	\$10,200	\$1,000-\$4,300	\$510-\$2,193
	Replace water cooler(s), drinking fountain(s) Revise drainage piping in auto shop-code compliance	\$53,900 \$9,400	\$5,400-\$23,200 \$900-\$4,000	\$2,695-\$11,589 \$470-\$2,021
	Replace floor sinks and drains and all connected waste piping below the floor within the kitchen of the north building	\$175,900	\$17,600-\$75,700	\$8,795-\$37,819
	Replace floor drains and revise drainage connections within kitchen at south building	\$13,500	\$1,300-\$5,700	\$675-\$2,903
	Upgrade grease interceptor	\$41,400	\$4,100-\$17,800	\$2,070-\$8,901
	Replace grease interceptor	\$32,800	\$3,300-\$14,100	\$1,640-\$7,052
	Replace deck mounted gas turrets at north building	\$17,600	\$1,800-\$7,600	\$880-\$3,784
	Replace curtain and track system.	\$18,600	\$1,900-\$8,000	\$930-\$3,999
	Replace auditorium theatrical equipment	\$88,000	\$8,800-\$37,900	\$4,400-\$18,920
	Upgrade lighting and sound systems	\$100,000	\$10,000-\$43,000	\$5,000-\$21,500
	Replace fixed casework-North bldg., science room, no ADA accessible sinks	\$750,000	\$75,000-\$322,500	\$37,500-\$161,250
	Replace fixed casework-North bldg, Sci 36,37,60,61, replace center top edge peel & wood veneer peel	\$30,000	\$3,000-\$12,900	\$1,500-\$6,450
	Replace fixed casework -North bdg, replace doors and sliding hardware in display cases	\$30,000	\$3,000-\$12,900	\$1,500-\$6,450

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Replace fixed casework-North bldg teachers lounge, no ADA accessible sinks	\$66,000	\$6,600-\$28,400	\$3,300-\$14,190
	Replace fixed casework-North bldg, photography cr's, not ADA accessible, no ADA sinks	\$30,000	\$3,000-\$12,900	\$1,500-\$6,450
	Replace fixed casework-North bldg, main entry concession, transaction counter too high, not ADA accessible	\$8,000	\$800-\$3,400	\$400-\$1,720
	Replace fixed casework-North bldg, career center, transaction counter too high, not ADA accessible	\$11,000	\$1,100-\$4,800	\$550-\$2,365
	Replace fixed casework-North bldg, Art 42, countertops too high, not ADA accessible, no ADA accessible sinks	\$38,400	\$3,900-\$16,500	\$1,920-\$8,256
	Replace fixed casework-North bldg, science cr's, countertops too high, no ADA sinks	\$6,100	\$600-\$2,600	\$305-\$1,312
	Replace fixed casework-North bldg, at admin, countertops too high and sink not ADA accessible	\$16,500	\$1,700-\$7,100	\$825-\$3,548
	Add more casework in SPED Kitchen	\$15,000	\$1,500-\$6,500	\$750-\$3,225
	Resurface parking lot	\$11,000	\$1,100-\$4,800	\$550-\$2,365
	Remove/replace broken concrete curbing	\$81,900	\$8,200-\$35,200	\$4,095-\$17,609
	Repair/replace sidewalk(s)	\$51,200	\$5,100-\$22,000	\$2,560-\$11,008
	Repair/replace sidewalk(s)	\$9,800	\$1,000-\$4,200	\$490-\$2,107
	Repair/replace sidewalk(s)	\$5,300	\$600-\$2,300	\$265-\$1,140
				· ·
	Rework pedestrian route through parking lot	\$28,200	\$2,800-\$12,100	\$1,410-\$6,063
	Provide accessible, to grade route(Commons 100 and Gym 103)	\$112,800	\$11,300-\$48,500	\$5,640-\$24,252
	Repair/replace sidewalk(s)	\$22,600	\$2,300-\$9,700	\$1,130-\$4,859
	Repair/replace sidewalk(s)	\$48,700	\$4,800-\$20,900	\$2,435-\$10,471
	Storage 102B, infill south wall masonry openings	\$2,700	\$300-\$1,100	\$135-\$581
	Provide ej cover at exterior brick wall west of main north entry where previous addition meets existing building	\$2,800	\$300-\$1,200	\$140-\$602
2-High	Compression seal at ext wall located east of main north entry missing above 4' and loose below 4' - replace with ej cover	\$2,800	\$300-\$1,200	\$140-\$602
	Southeast entrance exterior wall projecting rowlock brick trim courses have been broken off. Remove and replace all broken rowlock trim and replace with new flush rowlock brick	\$30,400	\$3,000-\$13,100	\$1,520-\$6,536
	Repair cracks in Stucco fascia east & south elevations South Bldg. Caulk and repaint	\$9,000	\$900-\$3,800	\$450-\$1,935
	Repair cracks in exterior stone façade at 7+ locations (South Bldg)	\$14,600	\$1,400-\$6,200	\$730-\$3,139
	Exterior wall, repair CMU	\$1,500	\$100-\$600	\$75-\$323
	Caulk perimeters at windows	\$25,700	\$2,500-\$11,000	\$1,285-\$5,526
	South Commons & Lobby exterior single glazed HM window frames. Provide new aluminum storefront framing with insulated glass	\$171,500	\$17,200-\$73,800	\$8,575-\$36,873
	DOORS SOUTH / Exterior HM windows, doors/frames rusting; refinish all locations	\$7,900	\$700-\$3,300	\$395-\$1,699
	Upgrade stage, stage office, dressing rooms and costume storage room for ADA	\$24,700	\$2,500-\$10,600	\$1,235-\$5,311
	Upgrade restrooms throughout building as needed	\$48,700	\$4,800-\$20,900	\$2,435-\$10,471
	Upgrade single staff toilet rooms	\$131,500	\$13,100-\$56,500	\$6,575-\$28,273
	Install complying HC stall, accessories or grab bars in restrooms 100N, 100O, 103E, 103I, 43D, 43F	\$27,300	\$2,800-\$11,800	\$1,365-\$5,870
	Repair fixed wall(s)	\$2,200	\$300-\$1,000	\$110-\$473
	Replace toilet partitions	\$2,800	\$300-\$1,200	\$140-\$602
	Replace toilet partitions	\$52,700	\$5,300-\$22,700	\$2,635-\$11,331
	Replace corridor stair handrails	\$15,100	\$1,500-\$6,500	\$755-\$3,247
	·		î	
	Re-configure, add handrails, rebuild stairs at stage 100	\$25,700	\$2,500-\$11,000	\$1,285-\$5,526
	Replace stair tread	\$8,500	\$900-\$3,700	\$425-\$1,828
	Repair hallway/classroom flooring	\$5,500	\$600-\$2,400	\$275-\$1,183
	Replace hallway/classroom flooring	\$3,800	\$400-\$1,600	\$190-\$817
	Replace hallway/classroom flooring	\$11,800	\$1,200-\$5,100	\$590-\$2,537



Douglas County High cont.

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Replace hallway/classroom flooring	\$60,400	\$6,100-\$26,000	\$3,020-\$12,986
	South 101 Dance, ramp wood flooring boards cupped. Replace and threshold	\$2,700	\$300-\$1,100	\$135-\$581
	South 104B Office, 50, 50B, 53B, 66A remove and replace VCT beyond life	\$8,300	\$800-\$3,500	\$415-\$1,785
	South 50A, 50C Office, remove VCT beyond life; provide carpet	\$2,900	\$300-\$1,200	\$145-\$624
	South 102A Office, remove exist'g carpet Provide new carpet and rubber base.	\$1,500	\$100-\$600	\$75-\$323
	Replace carpet	\$142,500	\$14,200-\$61,300	\$7,125-\$30,638
2-High	Replace sink faucet at math office in south building	\$1,500	\$100-\$600	\$75-\$323
	Replace fixed casework-South bldg, new doors and latches, repair damage in Art area, countertops peeling.	\$408,500	\$40,800-\$175,600	\$20,425-\$87,828
	Replace fixed casework-South bldg.	\$200,000	\$20,000-\$86,000	\$10,000-\$43,000
	Replace fixed casework-South bldg, main office transaction desk split, loose and peeling edges and surface.	\$4,800	\$500-\$2,000	\$240-\$1,032
	Replace fixed casework-South bldg, at admin, reception countertop not ADA accessible	\$204,300	\$20,400-\$87,900	\$10,215-\$43,925
	Resurface parking lot	\$20,600	\$2,100-\$8,900	\$1,030-\$4,429
	Repair/replace sidewalk(s)	\$9,800	\$1,000-\$4,200	\$490-\$2,107
	Edge of wood Stage floor broken, tacky.	\$3,200	\$400-\$1,400	\$160-\$688
	Remove abandoned water and waste piping	\$2,700	\$300-\$1,100	\$135-\$581
	Special HVAC Systems and Equipment. Needs-Provide key switch and push button style to meet code for gas control stations at all science classrooms	\$51,400	\$5,200-\$22,100	\$2,570-\$11,051
2-Medium	Special HVAC Systems and Equipment. Needs-Revise natural gas piping feeding to the north classroom wing to be overhead	\$22,000	\$2,200-\$9,500	\$1,100-\$4,730
	Reposition dumpster area for direct trash truck access.	\$11,000	\$1,100-\$4,800	\$550-\$2,365
	Regrade and repave parking	\$3,100	\$300-\$1,400	\$155-\$667
	Regrade and repave parking	\$53,800	\$5,400-\$23,200	\$2,690-\$11,567
	Replace restroom flooring	\$50,000	\$5,000-\$21,500	\$2,500-\$10,750
	Eliminate neutralization as neededs insouth building	\$5,300	\$600-\$2,300	\$265-\$1,140
	Auto Shop sectional doors operational, need minor repairs to replace seals and missing rollers.	\$900	\$100-\$400	\$45-\$194
	Repair masonry mortar at drinking fountains southwest corner of gym	\$2,700	\$300-\$1,100	\$135-\$581
	Repair cracked masonry over window at interior corridor.(NW corner of courtyard)	\$4,100	\$400-\$1,800	\$205-\$882
	Repair cracked masonry at SW interior corner of Commons	\$12,900	\$1,300-\$5,600	\$645-\$2,774
	Repair fixed wall(s)	\$900	\$100-\$400	\$45-\$194
	North Bldg groundface CMU stained, grimy. Paint w/ oilbased enamel	\$20,700	\$2,100-\$8,900	\$1,035-\$4,451
	Replace/repair suspended ceiling	\$40,300	\$4,000-\$17,300	\$2,015-\$8,665
	Replace pipe insulation on all domestic hot water system	\$122,000	\$12,200-\$52,500	\$6,100-\$26,230
3-High	Temp CR area at South Bldg bare from foot traffic. Dress up grade and reseed	\$306,500	\$30,700-\$131,800	\$15,325-\$65,898
Jingii	Repair corner court yard inner wall	\$35,900	\$3,600-\$15,400	\$1,795-\$7,719
	Repair floor slab cracks or joints approx. 7 locations	\$15,600	\$1,500-\$6,600	\$780-\$3,354
	(damaged flooring) Classroom #54 concrete slab is raised 1"-2" for entire center portion of room. +/- 4' wide apron slopes down at entire	\$25,700	\$2,500-\$11,000	\$1,285-\$5,526
	room perimeter.	¢10.700	#1.000 #0.100	#03F #4 033
	Repair cracks in concrete columns	\$18,700	\$1,900-\$8,100	\$935-\$4,021
	South Restroom 7P, install new floor expansion joint cover along east wall	\$2,000	\$200-\$900	\$100-\$430
	Gym 103 gyp board at east wall above lockers is damaged by balls- replace with more durable material	\$6,500	\$700-\$2,800	\$325-\$1,398
	Corridor 100G, replace broken face shell and infill gap around north wall fire alarm horn.	\$1,500	\$100-\$600	\$75-\$323

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Communication Room 60G, replace missing east wall above ceiling CMU face shell	\$1,500	\$100-\$600	\$75-\$323
	Replace loose brick cap south wall Science #11	\$1.500	\$100-\$600	\$75-\$323
	Repair masonry near base of drain alcove at Wood Shop	\$2,700	\$300-\$1,100	\$135-\$581
	Repair cracked masonry north stair corridor	\$5,300	\$600-\$2,300	\$265-\$1,140
	Repair cracked masonry at north wall of Dance Studio	\$5,300	\$600-\$2,300	\$265-\$1,140
3-High	Repair cracked masonry, add control joints (south wall)	\$15,600	\$1,500-\$6,600	\$780-\$3,354
3 mg	Patch cracks in GB bulkheads at north wall of entry Lobby	\$7,900	\$700-\$3,300	\$395-\$1,699
	Replace/repair suspended ceiling	\$25,200	\$2,600-\$10,900	\$1,260-\$5,418
	Replace/repair suspended ceiling	\$900	\$100-\$400	\$45-\$194
	Replace/repair suspended ceiling	\$400	\$-\$100	\$20-\$86
	Replace/repair suspended ceiling	\$2,000	\$200-\$900	\$100-\$430
	Add window coverings at faculty lounge	\$23,300	\$2,300-\$9,900	\$1,165-\$5,010
	Install acoustical wall panels in Vocal Room	\$38,700	\$3,800-\$16,600	\$1,935-\$8,321
	Paint interior	\$51,400	\$5,200-\$22,100	\$2,570-\$11,051
	Vinyl coverings repair/replacement	\$4,800	\$500-\$2,000	\$240-\$1,032
	Fences Add estate fence with mesh along south side	\$7,600	\$800-\$3,300	\$380-\$1,634
	Replace sections of chain link fence	\$33,900	\$3,400-\$14,600	\$1,695-\$7,289
	Repair/replace fence at parking lot west of North bldg.	\$6,100	\$600-\$2,600	\$305-\$1,312
	Add site fencing to limit cut through by students	\$33,900	\$3,400-\$14,600	\$1,695-\$7,289
	Replace chain Link fence at Metal Shop	\$10,400	\$1,000-\$4,400	\$520-\$2,236
			. , ,	
	Backfill needed, sidewalks & curb	\$56,400	\$5,600-\$24,200	\$2,820-\$12,126
	Backfill needed, sidewalks & curb	\$9,800	\$1,000-\$4,200	\$490-\$2,107
	Replace steel edger NW South bldg w/ bend-a-board.	\$65,500	\$6,500-\$28,100	\$3,275-\$14,083
	Rework grading, flatwork, storm system in courtyard	\$102,300	\$10,300-\$44,000	\$5,115-\$21,995
3-Medium	Pipe downspouts to storm system E side North building	\$20,600	\$2,100-\$8,900	\$1,030-\$4,429
	Regrade, modify storm pipes, downspouts at greenhouse	\$127,800	\$12,700-\$54,900	\$6,390-\$27,477
	Regrade and clean out riprap inlet S of stadium	\$6,100	\$600-\$2,600	\$305-\$1,312
	Landscape pedestrian path from S lot to N entry of S bldg.	\$169,100	\$16,900-\$72,700	\$8,455-\$36,357
	Replace wooden site furnishings w/ non-wooden	\$65,500	\$6,500-\$28,100	\$3,275-\$14,083
	Landscape and irrigate NE side of N bldg.	\$28,200	\$2,800-\$12,100	\$1,410-\$6,063
	Install headwalls NW corner South Bldg.	\$48,700	\$4,800-\$20,900	\$2,435-\$10,471
	Regrade, add fence, seed and irrigation E of South bldg.	\$12,000	\$1,200-\$5,200	\$600-\$2,580
	Repair asphalt, curb & gutter, inlet S parking lot	\$14,300	\$1,500-\$6,200	\$715-\$3,075
	Sod, irrigate and add fence along path to E parking lot	\$563,100	\$56,300-\$242,200	\$28,155-\$121,067
	Install underground storm drain S side of SW playfield	\$2,700	\$300-\$1,100	\$135-\$581
	Repair walls & door frames, repaint South in lower level, faculty lounge, special ed, admin, support spaces	\$108,000	\$10,800-\$46,400	\$5,400-\$23,220
	Paint interior	\$49,000	\$4,900-\$21,000	\$2,450-\$10,535
	Provide dishwasher at teacher's lounge in south building	\$2,700	\$300-\$1,100	\$135-\$581
	Shot Put Area; upgrade to DCSD standard	\$7,000	\$700-\$3,000	\$350-\$1,505
	Playing Fields, upgrade to DSCD standard	\$141,000	\$14,100-\$60,600	\$7,050-\$30,315
	Add shade trees west of South Bldg and in NW parking lot	\$76,700	\$7,700-\$33,000	\$3,835-\$16,491
	Replace mulch around perimeter of North Bldg.	\$20,800	\$2,100-\$9,000	\$1,040-\$4,472
4-Medium	Repair & replace North building lot landscape and mulch	\$15,600	\$1,500-\$6,600	\$780-\$3,354
	Remove existing dirt road to Central Playfield	\$90,500	\$9,000-\$38,900	\$4,525-\$19,458
	Repair erosion at east stadium entrance, landscaping	\$255,500	\$25,500-\$109,800	\$12,775-\$54,933
	Improve native growth on south side of building	\$17,000	\$1,700-\$7,300	\$850-\$3,655
	Irrigated landscaping along Front Street frontage	\$12,000	\$1,200-\$5,200	\$600-\$2,580
	Provide disposer at teacher's lounge sink	\$1,500	\$100-\$600	\$75-\$323



7716 Timberline Road Lone Tree, CO 80124 Highlands Ranch High School Feeder Area, K-6

Funded by 1984 Bond Opened in 1989


Site Acreage: 8 Facility Square Feet: 53,237 Mobiles on-site: 3

Eagle Ridge Elementary-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



\$1,000,000 \$500,000

> Estimated Total Construction Costs (in 2021 Dollars): \$523,700 Estimated Total Project Costs: \$602,185 - \$861,496



Following is the list of currently unfunded facility projects at Eagle Ridge Elementary

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Refurbish/replace retractable partitions	\$12,800	\$1,300-\$5,500	\$640-\$2,752
2-High	Replace kitchen flooring	\$75,000	\$7,500-\$32,300	\$3,750-\$16,125
	Replace fixed casework	\$185,400	\$18,500-\$79,700	\$9,270-\$39,861
2-Medium	Repair cracking concrete, service drive	\$10,400	\$1,000-\$4,400	\$520-\$2,236
3-High	Recaulk wall foundation	\$3,600	\$300-\$1,500	\$180-\$774
5-nigii	Renovate multi-use field	\$39,600	\$4,000-\$17,100	\$1,980-\$8,514
3-Medium	Vinyl coverings repair/replacement	\$6,200	\$600-\$2,700	\$310-\$1,333
4-High	Renovate/repair areas of grass around school	\$185,400	\$18,500-\$79,700	\$9,270-\$39,861
4-riigii	Replace metal edging with concrete mow strip	\$5,300	\$600-\$2,300	\$265-\$1,140

Estimated Total Construction Costs (in 2021 Dollars): \$523,700 Estimated Project Management Costs Range: \$52,300 - \$225,200 Estimated Inflation Range: \$26,185 - \$112,596

Estimated Total Project Costs: \$602,185 - \$861,496

Summary of Projects	Total Cost		
2019-2020 Completed Projects			
Replace cafeteria VCT flooring Replace carpet	\$252,542		
2021 Contracted Projects			
Upgrade VAVs (air distribution system) Update control system Replace rooftop units Replace exterior windows Upgrade fire alarm system Replace lavatories, toilets, urinals Replace panels and transformers Replace main switchgear	\$2,790,167		




1305 Timbervale Trail Highlands Ranch, CO 80126 ThunderRidge High School Feeder Area, K-6


Funded by 2000 Bond Opened in 2001

Site Acreage: 10 Original square feet: 51,688 Mobiles on-site: 2

Eldorado Elementary-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$1,167,200 Estimated Total Project Costs: \$1,342,560- \$1,920,048



Following is the list of currently unfunded facility projects at Eldorado Elementary

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Install water sensing level switches in basement ²	\$25,000	\$2,500-\$10,800	\$1,250-\$5,375
1-High	Re-glaze skylights ¹	\$30,700	\$3,100-\$13,200	\$1,535-\$6,601
	Chilled Water Systems. Replace cooling tower ¹	\$100,000	\$10,000-\$43,000	\$5,000-\$21,500
	Replace boiler(s) ²	\$250,000	\$25,000-\$107,500	\$12,500-\$53,750
1-Medium	Replace/repair boiler room piping as necessary ¹	\$27,500	\$2,800-\$11,900	\$1,375-\$5,913
	Chilled Water Systems. Replace chiller ²	\$300,000	\$30,000-\$129,000	\$15,000-\$64,500
	Recaulk exterior windows	\$14,300	\$1,500-\$6,200	\$715-\$3,075
	Paint exterior doors	\$600	\$100-\$200	\$30-\$129
	Replace sink countertop(s)	\$30,000	\$3,000-\$12,900	\$1,500-\$6,450
	Replace restroom flooring	\$40,000	\$4,000-\$17,200	\$2,000-\$8,600
2-High	Resurface asphalt bus loop	\$50,000	\$5,000-\$21,500	\$2,500-\$10,750
	Resurface parking lot	\$62,500	\$6,300-\$26,900	\$3,125-\$13,438
	Repair/replace areas of curb as needed	\$141,000	\$14,100-\$60,600	\$7,050-\$30,315
	Repair/replace sidewalk(s)	\$9,400	\$900-\$4,000	\$470-\$2,021
	Replace asphalt playground	\$5,300	\$600-\$2,300	\$265-\$1,140
	Re-glaze all storefronts as necessary	\$8,300	\$800-\$3,500	\$415-\$1,785
2-Medium	Replace fabricated toilet partition(s)	\$35,000	\$3,500-\$15,100	\$1,750-\$7,525
2-Medium	Replace hallway/classroom flooring	\$8,300	\$800-\$3,500	\$415-\$1,785
	Replace kitchen flooring	\$16,500	\$1,700-\$7,100	\$825-\$3,548
3-High	Recaulk wall foundation	\$3,800	\$400-\$1,600	\$190-\$817
2 Modium	Repair operable partition(s)	\$2,800	\$300-\$1,200	\$140-\$602
3-Medium	Vinyl coverings repair/replacement	\$6,200	\$600-\$2,700	\$310-\$1,333

Estimated Total Construction Costs (in 2021 Dollars): \$1,167,200 Estimated Project Management Costs Range: \$117,000 - \$501,900 Estimated Inflation Range: \$58,360 - \$250,948

Estimated Total Project Costs: \$1,342,560 - \$1,920,048

Tier 1 Projects Not Using 2018 Bond Funding

Project Symbol	Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
5	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.


Summary of Projects	Total Cost		
2019-2020 Completed Projects			
Upgrade control system Replace generator and associated equipment Recaulk exterior wall control joings, re-seal CMU masonry Upgrade fire alarm system Replace cafeteria, and gym flooring Replace non-restricted key system with restricted Replace roof (ballasted with fully adhered) Paint metal roof	\$1,930,765		
2021 Contracted Projects			
No project contracted for 2021	N/A		



104 Lovington Street Castle Rock, CO 80104 Douglas County High School Feeder Area, K-6 Funded by 2000 Bond Opened in 2003


Site Acreage: 10 Facility Square Feet: 56,566 Mobiles on-site: 1

Flagstone Elementary-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



\$500,000 \$1,000,000

Estimated Total Construction Costs (in 2021 Dollars): \$1,067,500 Estimated Total Project Costs: \$1,227,573 - \$1,755,913



Following is the list of currently unfunded facility projects at Flagstone Elementary

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Install water sensing level switches in basement ²	\$25,000	\$2,500-\$10,800	\$1,250-\$5,375
1-High	Chilled Water Systems. Replace cooling tower ¹	\$100,000	\$10,000-\$43,000	\$5,000-\$21,500
	Replace generator and associated equipment 1	\$75,000	\$7,500-\$32,300	\$3,750-\$16,125
1-Medium	Chilled Water Systems. Replace chiller ⁴	\$300,000	\$30,000-\$129,000	\$15,000-\$64,500
	Exterior wall, re-seal CMU, recaulk control joints	\$27,900	\$2,800-\$11,900	\$1,395-\$5,999
	Paint exterior trim, windows and doors	\$9,400	\$900-\$4,000	\$470-\$2,021
2-High	Recaulk exterior windows	\$15,400	\$1,600-\$6,700	\$770-\$3,311
2-nign	Recaulk exterior door frames	\$1,100	\$200-\$500	\$55-\$237
	Resurface asphalt bus loop	\$50,000	\$5,000-\$21,500	\$2,500-\$10,750
	Resurface parking lot	\$26,700	\$2,600-\$11,400	\$1,335-\$5,741
	Replace fabricated toilet partitions	\$35,000	\$3,500-\$15,100	\$1,750-\$7,525
2-Medium	Replace cafeteria VCT	\$20,000	\$2,000-\$8,600	\$1,000-\$4,300
2-Medium	Replace gym carpet	\$40,000	\$4,000-\$17,200	\$2,000-\$8,600
	Replace carpet	\$330,000	\$33,000-\$141,900	\$16,500-\$70,950
3-High	Recaulk wall foundation	\$3,600	\$300-\$1,500	\$180-\$774
	Renovate multi-use field	\$4,900	\$500-\$2,100	\$245-\$1,054
3-Medium	Vinyl coverings repair/replacement	\$3,500	\$300-\$1,400	\$175-\$753


Estimated Total Construction Costs (in 2021 Dollars): \$1,067,500 Estimated Project Management Costs Range: \$106,700 - \$458,900 Estimated Inflation Range: \$53,375 - \$229,513

Estimated Total Project Costs: \$1,227,575 - \$1,755,913

Tier 1 Projects Not Using 2018 Bond Funding

Project Symbol	Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	4 Replacement Determined As Not Needed Upon Inspection, the component was in good working order a not to need replacement at this time.	
	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.

Summary of Projects	Total Cost
2019-2020 Completed Projects	
Replace Trane controls with Delta Furniture	\$424,255
2021 Contracted Projects	
Upgrade fire alarm system Replace ballasted with fully adhered roof Replace domestic water heater and piping Upgrade clock system Replace sink countertops Replace restroom floor	\$1,904,766




6585 Collegiate Drive Highlands Ranch, CO 801306 Highlands Ranch High School Feeder Area, K-6


Funded by 1993 Bond Opened in 1995

Site Acreage: 12 Facility Square Feet: 54,226 Mobiles on-site: 2

Fox Creek Elementary-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$1,596,200 Estimated Total Project Costs: \$1,835,510 - \$2,625,583



Following is the list of currently unfunded and to be funded with the 2018 Bond facility projects at Fox Creek Elementary

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
Tier 1 Funded by the	Replace seals at main corridor skylights	\$10,000	\$1,000-\$4,300	\$500-\$2,150
2018 Bond	Replace generator and associated equipment	\$75,000	\$7,500-\$32,300	\$3,750-\$16,125
1-High	Upgrade fire alarm system ²	\$160,000	\$16,000-\$68,800	\$8,000-\$34,400
	Upgrade control system ²	\$300,000	\$30,000-\$129,000	\$15,000-\$64,500
1-Medium	Replace main switchgear ²	\$100,000	\$10,000-\$43,000	\$5,000-\$21,500
	Replace original panels and transformers ²	\$100,000	\$10,000-\$43,000	\$5,000-\$21,500
	Special Foundations. Needs-Pre-school slab sinking, repair	\$2,900	\$300-\$1,200	\$145-\$624
	Exterior wall, re-seal CMU, recaulk control joints	\$19,500	\$2,000-\$8,400	\$975-\$4,193
	Recaulk exterior windows	\$13,800	\$1,400-\$5,900	\$690-\$2,967
2-High	Replace sink countertop(s)	\$30,000	\$3,000-\$12,900	\$1,500-\$6,450
2-filgii	Replace gym carpet	\$40,000	\$4,000-\$17,200	\$2,000-\$8,600
	Replace hallway/classroom flooring	\$29,900	\$2,900-\$12,800	\$1,495-\$6,429
	Replace kitchen flooring	\$70,000	\$7,000-\$30,100	\$3,500-\$15,050
	Replace carpet	\$5,800	\$500-\$2,400	\$290-\$1,247
	Replace gym carpet	\$15,600	\$1,600-\$6,800	\$780-\$3,354
2-Medium	Replace cafeteria VCT	\$20,000	\$2,000-\$8,600	\$1,000-\$4,300
2-Medium	Replace carpet	\$350,000	\$35,000-\$150,500	\$17,500-\$75,250
	Replace/refinish fixed casework as necessary	\$60,000	\$6,000-\$25,800	\$3,000-\$12,900
3-High	Recaulk wall foundation	\$3,600	\$300-\$1,500	\$180-\$774
3-nigii	Renovate multi-use field	\$30,700	\$3,100-\$13,200	\$1,535-\$6,601
	Vinyl coverings repair/replacement	\$6,100	\$600-\$2,600	\$305-\$1,312
3-Medium	Replace pads at backstops in gym. Replace chalkboards with white boards	\$153,300	\$15,300-\$65,900	\$7,665-\$32,960

Estimated Total Construction Costs (in 2021 Dollars): \$1,596,200 Estimated Project Management Costs Range: \$159,500 - \$686,200 Estimated Inflation Range: \$79,810 - \$343,183

Estimated Total Project Costs: \$1,835,510 - \$2,625,583

Tier 1 Projects Not Using 2018 Bond Funding


Duningt		
Project Symbol	Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
5	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.




1384 North State Highway 83 Franktown, CO 80116 Ponderosa High School Feeder Area, K-5 Funded by 1978 Bond Opened in 1980

Site Acreage: 23 Facility Square Feet: 36,147 Mobiles on-site: 3

Franktown Elementary-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$940,700 Estimated Total Project Costs: \$1,081,735 - \$1,547,451



Following is the list of currently unfunded facility projects at Franktown Elementary

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
1-High	Evaluate and replace branch wiring as needed ²	\$100,000	\$10,000-\$43,000	\$5,000-\$21,500
	Refurbish/replace retractable partitions	\$51,200	\$5,100-\$22,000	\$2,560-\$11,008
2-High	Replace trough washing stations with sinks	\$17,600	\$1,800-\$7,600	\$880-\$3,784
Z-Iligii	Replace fixed casework	\$60,000	\$6,000-\$25,800	\$3,000-\$12,900
	Repair/replace sidewalk(s)	\$51,200	\$5,100-\$22,000	\$2,560-\$11,008
	Recaulk wall foundation	\$8,400	\$800-\$3,600	\$420-\$1,806
3-High	Renovate play field and other site improvements	\$81,900	\$8,200-\$35,200	\$4,095-\$17,609
	Install new synthetic turf for multi-use field	\$41,100	\$4,100-\$17,600	\$2,055-\$8,837
	Vinyl coverings repair/replacement	\$6,200	\$600-\$2,700	\$310-\$1,333
	Vinyl coverings repair/replacement	\$5,500	\$600-\$2,400	\$275-\$1,183
3-Medium	Fire sprinkle building	\$408,500	\$40,800-\$175,600	\$20,425-\$87,828
	Renovate/repair areas of grass around school	\$74,200	\$7,400-\$31,900	\$3,710-\$15,953
	Remove/replace plants	\$11,000	\$1,100-\$4,800	\$550-\$2,365
4-High	Renovate/repair areas of grass around school	\$23,900	\$2,400-\$10,300	\$1,195-\$5,139

Estimated Total Construction Costs (in 2021 Dollars): \$940,700 Estimated Project Management Costs Range: \$94,000 - \$404,500 Estimated Inflation Range: \$47,035 - \$202,251

Estimated Total Project Costs: \$1,081,735 - \$1,547,451

Tier 1 Projects Not Using 2018 Bond Funding

Project Symbol	Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
5	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.

Summary of Projects	Total Cost	
2019-2020 Completed Projects		
Upgrade clock system Upgrade control system Replace roof top units Install new generator and associated emergency systems Recault exterior wall control joints, repair masonry Recaulk windows Replace toilet partitions Upgrade fire alarm system Replace kitchen and restroom flooring Replace interior door hardware Repair entry soffit Silver coat parapet walls Replace/repair entry classroom storefronts Sand and paint exterior doors	\$2,102,742	
2021 Contracted Projects		
No project contracted for 2021	N/A	



23919 East Canterberry Trail Parker, CO 80138 Legend High School Feeder Area, K-5


\$155,700

High


Funded by 2000 Bond Opened in 2003

Site Acreage:10 Facility Square Feet: 55,868 Mobiles on-site: 2

Frontier Valley Elementary-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$794,500 Estimated Total Project Costs: \$914,025 - \$1,307,018



Following is the list of currently unfunded facility projects at Frontier Valley Elementary

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Install water sensing level switches in basement ²	\$25,000	\$2,500-\$10,800	\$1,250-\$5,375
1-High	Re-glaze skylights ¹	\$30,700	\$3,100-\$13,200	\$1,535-\$6,601
	Chilled Water Systems. Replace cooling tower ¹	\$100,000	\$10,000-\$43,000	\$5,000-\$21,500
1-Medium	Repair insulation in boiler room ¹	\$1,100	\$200-\$500	\$55-\$237
	Recaulk exterior windows	\$14,300	\$1,500-\$6,200	\$715-\$3,075
	Recaulk windows. Clean framing. Repair frames	\$5,300	\$600-\$2,300	\$265-\$1,140
	Paint exterior doors	\$600	\$100-\$200	\$30-\$129
	Replace fabricated toilet partitions	\$35,000	\$3,500-\$15,100	\$1,750-\$7,525
	Replace sink countertop(s)	\$30,000	\$3,000-\$12,900	\$1,500-\$6,450
2-High	Replace restroom flooring	\$40,000	\$4,000-\$17,200	\$2,000-\$8,600
	Resurface asphalt bus loop	\$50,000	\$5,000-\$21,500	\$2,500-\$10,750
	Resurface parking lot	\$102,300	\$10,300-\$44,000	\$5,115-\$21,995
	Repair/replace areas of curb as needed	\$83,500	\$8,400-\$35,900	\$4,175-\$17,953
	Repair/replace sidewalk(s)	\$76,700	\$7,700-\$33,000	\$3,835-\$16,491
	Replace asphalt playground	\$84,600	\$8,500-\$36,400	\$4,230-\$18,189
	Recaulk wall foundation	\$3,700	\$300-\$1,500	\$185-\$796
3-High	Upper Floor cracks, cafeteria floor moving	\$10,400	\$1,000-\$4,400	\$520-\$2,236
	Renovate multi-use field	\$95,100	\$9,500-\$40,900	\$4,755-\$20,447
3-Medium	Vinyl coverings repair/replacement	\$6,200	\$600-\$2,700	\$310-\$1,333

Estimated Total Construction Costs (in 2021 Dollars): \$794,500 Estimated Project Management Costs Range: \$79,800 - \$341,700 Estimated Inflation Range: \$39,725 - \$170,818

Estimated Total Project Costs: \$914,025 - \$1,307,018

Tier 1 Projects Not Using 2018 Bond Funding

Project Symbol	Category Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.

Summary of Projects	Total Cost	
2019-2020 Completed Projects		
Upgrade control system Replace generator and associated equipment Recaulk exterior wall control joints and seal masonry CMU Upgrade fire alarm system Replace carpet Replace roof	\$1,106,946	
2021 Contracted Projects		
No projects contracted for 2021	N/A	




12021 South Swift Fox Way Parker, CO 80134 Legend High School Feeder Area, K-5 Funded by 2006 Bond Opened in 2008

Site Acreage:10 Facility Square Feet: 73,146 Mobiles on-site: 0

Gold Rush Elementary-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$1,468,100 Estimated Total Project Costs: \$1,688,705 - \$2,415,142



Following is the list of currently unfunded facility projects at Gold Rush Elementary

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Install water sensing level switches in basement ²	\$25,000	\$2,500-\$10,800	\$1,250-\$5,375
1-High	Upgrade control system ³	\$385,000	\$38,500-\$165,600	\$19,250-\$82,775
	Upgrade fire alarm system ³	\$210,000	\$21,000-\$90,300	\$10,500-\$45,150
2-High	Exterior wall, repair flashing on east side front entry	\$1,700	\$200-\$700	\$85-\$366
2-nign	Exterior wall, recaulk expansion joints, reseal CMU	\$16,500	\$1,700-\$7,100	\$825-\$3,548
	Paint exterior metal, poles, railings, and sunshades	\$5,500	\$600-\$2,400	\$275-\$1,183
	Recaulk exterior windows	\$16,500	\$1,700-\$7,100	\$825-\$3,548
2-Medium	Resurface parking lot	\$671,600	\$67,200-\$288,800	\$33,580-\$144,394
2-Medium	Repair/replace sidewalk(s)	\$11,300	\$1,100-\$4,800	\$565-\$2,430
	Repair retaining wall(s)	\$18,500	\$1,900-\$8,000	\$925-\$3,978
	Repair/resurface playground as necessary	\$42,500	\$4,300-\$18,300	\$2,125-\$9,138
	Recaulk wall foundation	\$3,300	\$400-\$1,500	\$165-\$710
3-Medium	Vinyl coverings repair/replacement	\$1,100	\$200-\$500	\$55-\$237
	Renovate/repair areas of grass around school	\$59,600	\$5,900-\$25,500	\$2,980-\$12,814

Estimated Total Construction Costs (in 2021 Dollars): \$1,468,100 Estimated Project Management Costs Range: \$147,200 - \$631,400 Estimated Inflation Range: \$73,405 - \$315,642

Estimated Total Project Costs: \$1,688,705 - \$2,415,142

Tier 1 Projects Not Using 2018 Bond Funding

Project Symbol	Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
5	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.


Summary of Projects	Total Cost		
2019-2020 Completed Projects			
Elevator modernization	\$3,169		
2021 Contracted Projects			
No projects contracted for 2021	N/A		




3350 Summit View Parkway Highlands Ranch, CO 80126 Mountain Vista High School Feeder Area, K-6 Funded by 1997 Bond Opened in 2001

Site Acreage:10 Facility Square Feet: 51,668 Mobiles on-site: 3

Heritage Elementary-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$1,091,300 Estimated Total Project Costs: \$1,254,965 - \$1,795,030



Following is the list of currently unfunded facility projects at Heritage Elementary

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
1-High	Install water sensing level switches in basement ²	\$25,000	\$2,500-\$10,800	\$1,250-\$5,375
1-Medium	Replace boiler(s) ²	\$250,000	\$25,000-\$107,500	\$12,500-\$53,750
1-Medium	Chilled Water Systems. Replace chiller and cooling tower ¹	\$400,000	\$40,000-\$172,000	\$20,000-\$86,000
	Paint exterior doors	\$600	\$100-\$200	\$30-\$129
	Replace fabricated toilet partitions	\$35,000	\$3,500-\$15,100	\$1,750-\$7,525
	Resurface asphalt bus loop	\$50,000	\$5,000-\$21,500	\$2,500-\$10,750
2-High	Resurface parking lot	\$81,900	\$8,200-\$35,200	\$4,095-\$17,609
	Repair/replace areas of curb as needed	\$71,200	\$7,100-\$30,600	\$3,560-\$15,308
	Repair/replace sidewalk(s)	\$25,600	\$2,500-\$10,900	\$1,280-\$5,504
	Replace asphalt playground	\$81,900	\$8,200-\$35,200	\$4,095-\$17,609
2-Medium	Paint exterior metal	\$5,500	\$600-\$2,400	\$275-\$1,183
3-High	Recaulk wall foundation	\$3,700	\$300-\$1,500	\$185-\$796
3-nigii	Renovate multi-use field	\$9,400	\$900-\$4,000	\$470-\$2,021
	Repair operable partition(s)	\$2,800	\$300-\$1,200	\$140-\$602
3-Medium	Vinyl coverings repair/replacement	\$6,200	\$600-\$2,700	\$310-\$1,333
	Renovate/repair areas of grass around school	\$42,500	\$4,300-\$18,300	\$2,125-\$9,138

Estimated Total Construction Costs (in 2021 Dollars): \$1,091,300 Estimated Project Management Costs Range: \$109,100 - \$469,100 Estimated Inflation Range: \$54,565 - \$234,630

Estimated Total Project Costs: \$1,254,965 - \$1,795,030

Tier 1 Projects Not Using 2018 Bond Funding

Project Symbol	Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
5	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.


Summary of Projects	Total Cost		
2019-2020 Completed Projects			
Replace generator and associated equipment Recaulk exterior wall control joints. Seal masonry CMU Recaulk windows Upgrade fire alarm system Replace restroom flooring Replace non-restricted key system with restricted Reglaze skylights Replace ballasted roof with fully adhered Paint metal roof	\$1,392,689		
2021 Contracted Projects			
No projects contracted for 2021	N/A		




9375 Cresthill Lane Highlands Ranch, CO 80130 Highlands Ranch High School Feeder Area, 9-12 Funded by 1984 Bond Opened in 1985

Site Acreage: 70.82 Facility Square Feet: 243,408 Mobiles on-site: 0

Highlands Ranch High School-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$2,499,000 Estimated Total Project Costs: \$2,874,150 - \$4,111,085



Following is the list of currently unfunded facility projects at Highlands Ranch High

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
1-High	Evaluate and replace branch wiring as needed ²	\$100,000	\$10,000-\$43,000	\$5,000-\$21,500
	Recaulk exterior windows	\$60,400	\$6,100-\$26,000	\$3,020-\$12,986
	Reglaze storefront windows and recaulk windows at auditorium entry	\$30,700	\$3,100-\$13,200	\$1,535-\$6,601
	Paint exterior doors	\$5,300	\$600-\$2,300	\$265-\$1,140
	Replace hallway/classroom flooring	\$1,188,000	\$118,800-\$510,900	\$59,400-\$255,420
2 High	Replace kitchen flooring	\$71,500	\$7,200-\$30,800	\$3,575-\$15,373
2-High	Replace restroom flooring	\$40,000	\$4,000-\$17,200	\$2,000-\$8,600
	Replace auditorium seating	\$66,000	\$6,600-\$28,400	\$3,300-\$14,190
	Theater and Stage Equipment, upgrade lighting and sound systems	\$100,000	\$10,000-\$43,000	\$5,000-\$21,500
	Replace fixed casework	\$200,000	\$20,000-\$86,000	\$10,000-\$43,000
	Repair/replace sidewalk(s)	\$9,800	\$1,000-\$4,200	\$490-\$2,107
2-Medium	Replace carpet	\$247,500	\$24,800-\$106,500	\$12,375-\$53,213
	Recaulk wall foundation	\$9,500	\$1,000-\$4,100	\$475-\$2,043
3-High	Replace all fencing around school perimeter	\$20,600	\$2,100-\$8,900	\$1,030-\$4,429
3-High	Renovate multi-use field	\$35,900	\$3,600-\$15,400	\$1,795-\$7,719
	Replace site lighting poles and fixtures	\$31,700	\$3,200-\$13,700	\$1,585-\$6,816
3-Medium	Vinyl coverings repair/replacement	\$15,600	\$1,500-\$6,600	\$780-\$3,354
4-High	Renovate/repair areas of grass around school	\$255,500	\$25,500-\$109,800	\$12,775-\$54,933
4-Medium	Add/replace trees, bushes, other landscape plantings	\$11,000	\$1,100-\$4,800	\$550-\$2,365

Estimated Total Construction Costs (in 2021 Dollars): \$2,499,000 Estimated Project Management Costs Range: \$250,200 - \$1,074,800 Estimated Inflation Range: \$124,950-\$537,285

Estimated Total Project Costs: \$2,874,150 - \$4,111,085

Tier 1 Projects Not Using 2018 Bond Funding

Project Symbol	Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
5	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.

Summary of Projects	Total Cost
2019-2020 Completed Projects	
Replace main gym bleachers Replace door hardware (2018 installation of restricted key system) Furniture	\$1,129,745
2021 Contracted Projects	
Replace boilers Upgrade clock system Replace rooftop units Recaulk exterior wall control joints Replace windows Replace toilet partitions Replace gym floor Replace irrigation system Replace panels and transformers Replace ballasted with fully adhered roof	\$9,341,065




20151 Tallman Drive Parker, CO 80138 Legend High School Feeder Area, K-5 Funded by 1997 Bond Opened in 1998

Site Acreage:10 Facility Square Feet: 51,676 Mobiles on-site: 1

Iron Horse Elementary-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$1,558,500 Estimated Total Project Costs: \$1,792,325 - \$2,563,778



Following is the list of currently unfunded facility projects at Iron Horse Elementary

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Install water sensing level switches in basement ²	\$25,000	\$2,500-\$10,800	\$1,250-\$5,375
1-High	Replace boiler(s) ²	\$250,000	\$25,000-\$107,500	\$12,500-\$53,750
1-High	Replace insulation in places ¹	\$8,500	\$900-\$3,700	\$425-\$1,828
	Replace DHW heater ¹	\$18,900	\$1,800-\$8,000	\$945-\$4,064
	Paint metal roof	\$8,500	\$900-\$3,700	\$425-\$1,828
	Recaulk exterior windows	\$13,800	\$1,400-\$5,900	\$690-\$2,967
	Repair/replace storefront windows	\$2,200	\$300-\$1,000	\$110-\$473
	Repair or replace exterior doors	\$2,400	\$200-\$1,000	\$120-\$516
	Repair fixed wall(s)	\$5,800	\$500-\$2,400	\$290-\$1,247
2-High	Refurbish/replace retractable partitions	\$17,000	\$1,700-\$7,300	\$850-\$3,655
	Replace sink countertop(s)	\$30,000	\$3,000-\$12,900	\$1,500-\$6,450
	Replace main hallway restrooms with poured acrylic	\$8,800	\$900-\$3,800	\$440-\$1,892
	Replace exhaust fans	\$22,900	\$2,300-\$9,900	\$1,145-\$4,924
	Repair/replace sections of sidewalk as necessary	\$3,100	\$300-\$1,400	\$155-\$667
	Paint fuel distribution gas pipe to prevent corrosion	\$12,000	\$1,200-\$5,200	\$600-\$2,580
3-High	Recaulk wall foundation	\$3,600	\$300-\$1,500	\$180-\$774
3-riigii	Recaulk wall foundation	\$1,800	\$200-\$800	\$90-\$387
	Vinyl coverings repair/replacement	\$9,200	\$900-\$3,900	\$460-\$1,978
3-Medium	Replace/repair suspended ceiling	\$6,500	\$700-\$2,800	\$325-\$1,398
	Bypass grease interceptor	\$8,500	\$900-\$3,700	\$425-\$1,828
4-High	Renovate/repair areas of grass around school	\$1,100,000	\$110,000-\$473,000	\$55,000-\$236,500

Estimated Total Construction Costs (in 2021 Dollars): \$1,558,500 Estimated Project Management Costs Range: \$155,900 - \$670,200 Estimated Inflation Range: \$77,925 - \$335,078

Estimated Total Project Costs: \$1,792,325 - \$2,563,778

Tier 1 Projects Not Using 2018 Bond Funding

	, , , , , , , , , , , , , , , , , , ,			
Project Symbol	Category	Category Definition		
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.		
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.		
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.		
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.		
5	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.		


Summary of Projects	Total Cost		
2019-2020 Completed Projects			
Replace chiller and cooling tower Replace and move bell schedule Replace generator Recaulk exterior wall control joints and seal and repair CMU Replace roof flashing and trim Replace cafeteria and kitchen flooring Replace unrestricted with restricted key system Upgrade irrigation system controller Expand MDF closet Replace ballasted roof with fully adhered	\$1,311,364		
2021 Contracted Projects			
No projects contracted for 2021	N/A		




1103 West Perry Park Avenue Larkspur, CO 80118 Castle View High School Feeder Area, K-6 Funded by 1970 Bond Opened in 1972

Site Acreage: 10 Facility Square Feet: 30,675 Mobiles on-site: 0

Larkspur Elementary-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$1,946,800 Estimated Total Project Costs: \$2,238,540 - \$3,201,962



Following is the list of currently unfunded and to be funded with the 2018 Bond facility projects at Larkspur Elementary

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Replace area E roof	\$28,700	\$2,900-\$12,400	\$1,435-\$6,171
Tier 1	Replace section C roof	\$30,000	\$3,000-\$12,900	\$1,500-\$6,450
	Upgrade fire alarm system	\$140,000	\$14,000-\$60,200	\$7,000-\$30,100
2018 Bond	Install new generator and associated systems	\$75,000	\$7,500-\$32,300	\$3,750-\$16,125
	Upgrade irrigation system	\$33,900	\$3,400-\$14,600	\$1,695-\$7,289
	Replace boiler(s) ²	\$150,000	\$15,000-\$64,500	\$7,500-\$32,250
1-Medium	Replace main switchgear ²	\$100,000	\$10,000-\$43,000	\$5,000-\$21,500
	Replace original panels and transformers ²	\$100,000	\$10,000-\$43,000	\$5,000-\$21,500
	Recaulk exterior windows	\$7,900	\$700-\$3,300	\$395-\$1,699
	Repair or refinish exterior doors	\$5,300	\$600-\$2,300	\$265-\$1,140
	Replace fabricated toilet partition(s)	\$20,000	\$2,000-\$8,600	\$1,000-\$4,300
2-High	Replace restroom flooring	\$40,000	\$4,000-\$17,200	\$2,000-\$8,600
2-nigii	Replace sink(s)	\$1,700	\$200-\$700	\$85-\$366
	Replace trough washing stations with sinks	\$6,000	\$600-\$2,500	\$300-\$1,290
	Replace fixed casework	\$60,000	\$6,000-\$25,800	\$3,000-\$12,900
	Repair/replace sidewalk(s)	\$19,100	\$1,900-\$8,200	\$955-\$4,107
	Exterior wall, repair areas of metal siding	\$10,400	\$1,000-\$4,400	\$520-\$2,236
	Paint exterior	\$8,300	\$800-\$3,500	\$415-\$1,785
2-Medium	Repair areas of parking lot (asphalt)	\$69,700	\$6,900-\$29,900	\$3,485-\$14,986
	Repair/replace areas of curb as needed	\$81,900	\$8,200-\$35,200	\$4,095-\$17,609
	Crack fill asphalt playground as necessary	\$306,500	\$30,700-\$131,800	\$15,325-\$65,898
	Recaulk wall foundation	\$5,800	\$500-\$2,400	\$290-\$1,247
	Repair rusting columns at gym west side	\$7,900	\$700-\$3,300	\$395-\$1,699
	Improve drainage of lot, mobile site, and bus loop	\$42,900	\$4,300-\$18,500	\$2,145-\$9,224
3-High	Refinish all fixed walls	\$20,600	\$2,100-\$8,900	\$1,030-\$4,429
	Replace/repair suspended ceiling	\$85,800	\$8,600-\$36,900	\$4,290-\$18,447
	Repair/replace fencing where needed, wood and metal	\$8,300	\$800-\$3,500	\$415-\$1,785
	Renovate multi-use field	\$95,100	\$9,500-\$40,900	\$4,755-\$20,447
3-Medium	Vinyl coverings repair/replacement	\$6,200	\$600-\$2,700	\$310-\$1,333
5-Wediuili	Fire sprinkle building	\$379,800	\$37,900-\$163,200	\$18,990-\$81,657

Estimated Total Construction Costs (in 2021 Dollars): \$1,946,800 Estimated Project Management Costs Range: \$194,400 - \$836,600 Estimated Inflation Range: \$97,340 - \$418,562

Estimated Total Project Costs: \$2,238,540 - \$3,201,962

Tier 1 Projects Not Using 2018 Bond Funding

Project Symbol	Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
5	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.


Summary of Projects	Total Cost	
2019-2020 Completed Projects		
Replace interior doors, sand and paint door frames, replace door hardware Roofing	\$231,136	
2021 Contracted Projects		
No projects contracted for 2021	N/A	




12736 South Red Rosa Circle Parker, CO 80134 Ponderosa High School Feeder Area, K-5 Funded by 2000 Bond Opened in 2003

Site Acreage:10 Facility Square Feet: 56,868 Mobiles on-site: 0

Legacy Point Elementary-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$1,248,000 Estimated Total Project Costs: \$1,435,100 - \$2,052,820



Following is the list of currently unfunded facility projects at Legacy Point Elementary

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Install water sensing level switches in basement ²	\$25,000	\$2,500-\$10,800	\$1,250-\$5,375
1-High	Chilled Water Systems. Replace cooling tower ¹	\$100,000	\$10,000-\$43,000	\$5,000-\$21,500
	Replace generator and associated equipment ¹	\$75,000	\$7,500-\$32,300	\$3,750-\$16,125
	Paint exterior trim, windows and doors	\$9,400	\$900-\$4,000	\$470-\$2,021
	Fix exterior window(s) leakage	\$10,400	\$1,000-\$4,400	\$520-\$2,236
	Recaulk exterior windows	\$15,400	\$1,600-\$6,700	\$770-\$3,311
2-High	Recaulk exterior door frames	\$1,100	\$200-\$500	\$55-\$237
2-riigii	Replace stair tread	\$4,800	\$500-\$2,000	\$240-\$1,032
	Resurface asphalt bus loop	\$50,000	\$5,000-\$21,500	\$2,500-\$10,750
	Resurface parking lot	\$57,200	\$5,800-\$24,600	\$2,860-\$12,298
	Repair/replace sidewalk(s)	\$5,800	\$500-\$2,400	\$290-\$1,247
	Replace fabricated toilet partitions	\$35,000	\$3,500-\$15,100	\$1,750-\$7,525
	Replace cafeteria VCT	\$20,000	\$2,000-\$8,600	\$1,000-\$4,300
2-Medium	Replace carpet	\$350,000	\$35,000-\$150,500	\$17,500-\$75,250
2-Medium	Replace gym carpet	\$40,000	\$4,000-\$17,200	\$2,000-\$8,600
	Replace gym carpet	\$16,000	\$1,600-\$6,900	\$800-\$3,440
	Replace carpet	\$350,000	\$35,000-\$150,500	\$17,500-\$75,250
	Recaulk wall foundation	\$3,600	\$300-\$1,500	\$180-\$774
3-High	Replace blinds as necessary	\$12,900	\$1,300-\$5,600	\$645-\$2,774
	Renovate multi-use field	\$33,000	\$3,300-\$14,200	\$1,650-\$7,095
3-Medium	Vinyl coverings repair/replacement	\$3,500	\$300-\$1,400	\$175-\$753
4-Medium	Place bollards in front of conference room	\$29,900	\$2,900-\$12,800	\$1,495-\$6,429

Estimated Total Construction Costs (in 2021 Dollars): \$1,248,000 Estimated Project Management Costs Range: \$124,700 - \$536,500 Estimated Inflation Range: \$62,400 - \$268,320

Estimated Total Project Costs: \$1,435,100 - \$2,052,820

Tier 1 Projects Not Using 2018 Bond Funding

Project Symbol	Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
5	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.


Summary of Projects	Total Cost	
2019-2020 Completed Projects		
Replace Trane controls with Delta Recaulk exterior wall control joints, patch cracks and water seal CMU Upgrade fire system Replace restroom flooring Repair elevator Replace ballasted with fully adhered roof Replace sink countertops with single surface	\$746,332	
2021 Contracted Projects		
No projects contracted for 2021	N/A	




22219 Hilltop Road Parker, CO 80134 Legend High School Feeder Area, 9-12 Funded by 2003 Bond Opened in 2008

Site Acreage: 45 Facility Square Feet: 256,865 Mobiles on-site: 5

Legend High School-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$2,604,600 Estimated Total Project Costs: \$2,995,630 - \$4,284,889



Following is the list of currently unfunded facility projects at Legend High

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
1-High	Upgrade control system ³	\$1,045,000	\$104,500-\$449,400	\$52,250-\$224,675
1-High	Upgrade fire alarm system ³	\$350,000	\$35,000-\$150,500	\$17,500-\$75,250
2-High	Upgrade theater lighting and sound systems	\$100,000	\$10,000-\$43,000	\$5,000-\$21,500
	Exterior wall, repair moisture penetration	\$5,500	\$600-\$2,400	\$275-\$1,183
	Paint metal railings	\$1,700	\$200-\$700	\$85-\$366
	Recaulk exterior windows	\$71,500	\$7,200-\$30,800	\$3,575-\$15,373
2-Medium	Replace carpet	\$5,500	\$600-\$2,400	\$275-\$1,183
2-Medium	Resurface parking lot	\$756,800	\$75,700-\$325,500	\$37,840-\$162,712
	Repair/replace sidewalk(s)	\$6,100	\$600-\$2,600	\$305-\$1,312
	Resurface track	\$220,000	\$22,000-\$94,600	\$11,000-\$47,300
	Replace artificial turf	\$12,800	\$1,300-\$5,500	\$640-\$2,752
	Mitigate wall foundation movement at F pod (E wing)	\$22,000	\$2,200-\$9,500	\$1,100-\$4,730
3-Medium	Vinyl coverings repair/replacement	\$2,200	\$300-\$1,000	\$110-\$473
	Renovate/repair areas of grass around school	\$5,500	\$600-\$2,400	\$275-\$1,183

Estimated Total Construction Costs (in 2021 Dollars): \$2,604,600 Estimated Project Management Costs Range: \$260,800 - \$1,120,300 Estimated Inflation Range: \$130,230 - \$559,989

Estimated Total Project Costs: \$2,995,630 - \$4,284,889

Tier 1 Projects Not Using 2018 Bond Funding

	,	3
Project Symbol	Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.


Summary of Projects	Total Cost		
2019-2020 Completed Projects			
Furniture	\$57,805		
2021 Contracted Projects			
No projects contracted for 2021	N/A		




9375 Heritage Hills Circle Lone Tree, CO 80124 Highlands Ranch High School Feeder Area, K-6 Funded by Certificate of Participation Opened in 2007

Site Acreage: 9.7 Facility Square Feet: 57,509 Mobiles on-site: 0

Lone Tree Elementary-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars):\$1,303,000 Estimated Total Project Costs: \$1,498,950 - \$2,143,745



Following is the list of currently unfunded facility projects at Lone Tree Elementary

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Install water sensing level switches in basement ²	\$25,000	\$2,500-\$10,800	\$1,250-\$5,375
1-High	Replace ballasted roof with fully adhered ³	\$650,000	\$65,000-\$279,500	\$32,500-\$139,750
1-High	Upgrade control system ³	\$330,000	\$33,000-\$141,900	\$16,500-\$70,950
	Upgrade fire alarm system ³	\$140,000	\$14,000-\$60,200	\$7,000-\$30,100
2-High	Exterior wall, recaulk control joints, seal masonry CMU	\$16,500	\$1,700-\$7,100	\$825-\$3,548
2-nigii	Recaulk windows and clean framing	\$13,200	\$1,400-\$5,700	\$660-\$2,838
	Recaulk exterior windows	\$13,200	\$1,400-\$5,700	\$660-\$2,838
	Replace sink countertop(s)	\$30,000	\$3,000-\$12,900	\$1,500-\$6,450
2-Medium	Replace cafeteria VCT	\$2,200	\$300-\$1,000	\$110-\$473
	Resurface/repair parking lot	\$51,200	\$5,100-\$22,000	\$2,560-\$11,008
	Repair/replace sidewalk(s)	\$20,600	\$2,100-\$8,900	\$1,030-\$4,429
	Recaulk wall foundation	\$3,300	\$400-\$1,500	\$165-\$710
3-Medium	Repair operable partition(s)	\$2,800	\$300-\$1,200	\$140-\$602
5-wealum	Vinyl coverings repair/replacement	\$2,200	\$300-\$1,000	\$110-\$473
	Renovate/repair areas of grass around school	\$2,800	\$300-\$1,200	\$140-\$602

Estimated Total Construction Costs (in 2021 Dollars): \$1,303,000 Estimated Project Management Costs Range: \$130,800 - \$560,600 Estimated Inflation Range: \$65,150 - \$280,145

Estimated Total Project Costs: \$1,498,950 - \$2,143,745

Tier 1 Projects Not Using 2018 Bond Funding

	,	3
Project Symbol	Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
5	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.




9500 Stonegate Parkway Parker, CO 80134 Chaparral High School Feeder Area, K-6 Funded by 2006 Bond Opened in 2007

Site Acreage:10 Facility Square Feet: 73,146 Mobiles on-site: 1

Mammoth Heights Elementary-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$1,011,900 Estimated Total Project Costs: \$1,164,095 - \$1,664,859



Following is the list of currently unfunded facility projects at Mammoth Heights Elementary

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Install water sensing level switches in basement ²	\$25,000	\$2,500-\$10,800	\$1,250-\$5,375
1-High	Upgrade control system ³	\$385,000	\$38,500-\$165,600	\$19,250-\$82,775
	Upgrade fire alarm system ³	\$210,000	\$21,000-\$90,300	\$10,500-\$45,150
2-High	Exterior wall, recaulk expansion joints, reseal CMU	\$16,500	\$1,700-\$7,100	\$825-\$3,548
	Paint metal of sun shades	\$5,500	\$600-\$2,400	\$275-\$1,183
	Recaulk exterior windows	\$16,500	\$1,700-\$7,100	\$825-\$3,548
	Repair fixed wall(s)	\$600	\$100-\$200	\$30-\$129
2-Medium	Resurface parking lot	\$88,000	\$8,800-\$37,900	\$4,400-\$18,920
2-Medium	Repair/replace sidewalk(s)	\$112,800	\$11,300-\$48,500	\$5,640-\$24,252
	Repair retaining wall(s)	\$31,900	\$3,200-\$13,800	\$1,595-\$6,859
	Repair retaining wall(s)	\$10,400	\$1,000-\$4,400	\$520-\$2,236
	Repair/resurface playground as necessary	\$95,100	\$9,500-\$40,900	\$4,755-\$20,447
	Recaulk wall foundation	\$3,300	\$400-\$1,500	\$165-\$710
3-Medium	Vinyl coverings repair/replacement	\$2,200	\$300-\$1,000	\$110-\$473
3-Medium	Replace/repair boiler room piping as necessary	\$1,100	\$200-\$500	\$55-\$237
	Renovate/repair areas of grass around school	\$8,000	\$800-\$3,400	\$400-\$1,720

Estimated Total Construction Costs (in 2021 Dollars): \$1,011,900 Estimated Project Management Costs Range: \$101,600 - \$435,400 Estimated Inflation Range: \$50,595 - \$217,559

Estimated Total Project Costs: \$1,164,095 - \$1,664,859

Tier 1 Projects Not Using 2018 Bond Funding

Project Symbol	Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
5	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.


Summary of Projects	Total Cost
2019-2020 Completed Projects	
Elevator modernization	\$3,169
2021 Contracted Projects	
No projects contracted for 2021	N/A




3700 Butterfield Crossing Castle Rock, CO 80109 Castle View High School Feeder Area, K-6 Funded by 1997 Bond Opened in 2000

Site Acreage: 15 Facility Square Feet: 51,668 Mobiles on-site: 1

Meadow View Elementary-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$423,700 Estimated Total Project Costs: \$487,285 - \$697,096



Following is the list of currently unfunded facility projects at Meadow View Elementary

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
1-High	Chilled Water Systems. Replace cooling tower ¹	\$100,000	\$10,000-\$43,000	\$5,000-\$21,500
	Replace retractable partition(s)	\$17,000	\$1,700-\$7,300	\$850-\$3,655
	Replace fabricated toilet partition(s)	\$35,000	\$3,500-\$15,100	\$1,750-\$7,525
	Resurface asphalt bus loop	\$50,000	\$5,000-\$21,500	\$2,500-\$10,750
2-High	Resurface parking lot	\$50,500	\$5,100-\$21,800	\$2,525-\$10,858
	Repair/replace areas of curb as needed	\$88,000	\$8,800-\$37,900	\$4,400-\$18,920
	Repair/replace sections of sidewalk as necessary	\$12,600	\$1,200-\$5,400	\$630-\$2,709
	Replace playground asphalt playpad	\$37,900	\$3,800-\$16,300	\$1,895-\$8,149
3-High	Vinyl coverings repair/replacement	\$5,800	\$500-\$2,400	\$290-\$1,247
3-nigii	Renovate multi-use field	\$4,900	\$500-\$2,100	\$245-\$1,054
3-Medium	Replace dumpster enclosure with new enclosure	\$5,500	\$600-\$2,400	\$275-\$1,183
5-Medium	Repair retaining wall(s)	\$16,500	\$1,700-\$7,100	\$825-\$3,548

Estimated Total Construction Costs (in 2021 Dollars): \$423,700 Estimated Project Management Costs Range: \$42,400 - \$182,300 Estimated Inflation Range: \$21,185 - \$91,096

Estimated Total Project Costs: \$487,285 - \$697,096

Tier 1 Projects Not Using 2018 Bond Funding

Project Symbol	Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
5	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.

Summary of Projects	Total Cost
2019-2020 Completed Projects	
Upgrade control system Replace non-restricted key system with restricted Replace generator Recaulk exterior wall control joints, repair stress cracks, reseal CMU Recaulk windows Upgrade fire alarm system Replace kitchen and restroom flooring Upgrade irrigation controller Replace ballasted with fully adhered roof Replace sink countertops with single surface Repair water infiltraiton at storefront entrances Install water sensing level switches in basement Replace boiler(s)	\$1,570,248
2021 Contracted Projects	
No projects contracted for 2021	N/A



365 Mitchell Street Castle Rock, CO 80104 Douglas County High School Feeder Area, 6-8


Funded by 2003 Bond Opened in 2008

Site Acreage: 22 Facility Square Feet: 132,414 Mobiles on-site: 0

Mesa Middle School-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$1,282,800 Estimated Total Project Costs: \$1,475,540 - \$2,110,302



Following is the list of currently unfunded facility projects at Mesa Middle

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Install water sensing level switches in basement ²	\$25,000	\$2,500-\$10,800	\$1,250-\$5,375
1.115	Upgrade control system ²	\$650,000	\$65,000-\$279,500	\$32,500-\$139,750
1-High	Upgrade fire alarm system ³	\$340,000	\$34,000-\$146,200	\$17,000-\$73,100
	Replace generator and associated equipment ³	\$75,000	\$7,500-\$32,300	\$3,750-\$16,125
2-High	Exterior wall, recaulk expansion joints, reseal CMU	\$27,500	\$2,800-\$11,900	\$1,375-\$5,913
	Recaulk exterior windows	\$25,300	\$2,600-\$10,900	\$1,265-\$5,440
	Replace sink countertop(s)	\$42,200	\$4,200-\$18,100	\$2,110-\$9,073
2-Medium	Replace carpet	\$5,500	\$600-\$2,400	\$275-\$1,183
2-Medium	Check water supply, hot water mixes with cold water	\$600	\$100-\$200	\$30-\$129
	Resurface parking lot	\$57,200	\$5,800-\$24,600	\$2,860-\$12,298
	Repair/replace sidewalk(s)	\$16,500	\$1,700-\$7,100	\$825-\$3,548
3-Medium	Repair CMU at planter boxes	\$18,000	\$1,800-\$7,700	\$900-\$3,870

Estimated Total Construction Costs (in 2021 Dollars): \$1,282,800 Estimated Project Management Costs Range: \$128,600 - \$551,700 Estimated Inflation Range: \$64,140 - \$275,802

Estimated Total Project Costs: \$1,475,540 - \$2,110,302

Tier 1 Projects Not Using 2018 Bond Funding


Project Symbol	Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
5	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.




10590 Mountain Vista Ridge Highlands Ranch, CO 80126 Mountain Vista High School Feeder Area, 7-8 Funded by 2000 Bond Opened in 2003

Site Acreage: 31.7 Facility Square Feet: 136,760 Mobiles on-site: 2

Mountain Ridge Middle School-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$2,581,200 Estimated Total Project Costs: \$2,968,460 - \$4,245,958



Following is the list of currently unfunded facility projects at Mountain Ridge Middle

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Install water sensing level switches in basement ²	\$25,000	\$2,500-\$10,800	\$1,250-\$5,375
1-High	Replace ballasted roof with fully adhered ¹	\$1,000,000	\$100,000-\$430,000	\$50,000-\$215,000
	Replace generator and associated equipment 1	\$75,000	\$7,500-\$32,300	\$3,750-\$16,125
	Paint exterior trim and doors	\$9,400	\$900-\$4,000	\$470-\$2,021
	Recaulk exterior windows	\$26,200	\$2,600-\$11,300	\$1,310-\$5,633
2. High	Recaulk exterior door frames	\$1,100	\$200-\$500	\$55-\$237
2-High	Refurbish/replace retractable partitions	\$23,300	\$2,300-\$9,900	\$1,165-\$5,010
	Resurface parking lot	\$550,000	\$55,000-\$236,500	\$27,500-\$118,250
	Repair/replace sections of sidewalk as necessary	\$12,000	\$1,200-\$5,200	\$600-\$2,580
	Replace fabricated toilet partitions	\$50,000	\$5,000-\$21,500	\$2,500-\$10,750
2-Medium	Replace cafeteria vinyl flooring	\$50,000	\$5,000-\$21,500	\$2,500-\$10,750
	Replace carpet	\$715,000	\$71,500-\$307,500	\$35,750-\$153,725
	Recaulk wall foundation	\$5,300	\$600-\$2,300	\$265-\$1,140
	Repair prestress concrete tees at cafeteria/commons	\$15,600	\$1,500-\$6,600	\$780-\$3,354
3-High	Repair floor movement occurring south of commons expansion joint	\$9,400	\$900-\$4,000	\$470-\$2,021
	Renovate multi-use field	\$6,400	\$700-\$2,800	\$320-\$1,376
3-Medium	Vinyl coverings repair/replacement	\$4,800	\$500-\$2,000	\$240-\$1,032
4-High	Renovate areas of landscaping around school	\$2,700	\$300-\$1,100	\$135-\$581

Estimated Total Construction Costs (in 2021 Dollars): \$2,581,200 Estimated Project Management Costs Range: \$258,200 - \$1,109,800 Estimated Inflation Range: \$129,060 - \$554,958

Estimated Total Project Costs: \$2,968,460 - \$4,245,958

Tier 1 Projects Not Using 2018 Bond Funding

Project Symbol	Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.


Summary of Projects	Total Cost
2019-2020 Completed Projects	
No projects completed in 2019-20	N/A
2021 Contracted Projects	
Replace cooling tower Replace control system Recaulk exterior wall control joints, repair crack in gym wall Replace toilet partitions Upgrade fire alarm system Repair gym bleachers Replace cafeteria flooring Replace sink countertops with single surface	\$1,777,566



8502 East Pinery Parkway Parker, CO 80134 Ponderosa High School Feeder Area, K-2 Funded by 1978 Bond Opened in 1980


Site Acreage: 10 Facility Square Feet: 48,638 Mobiles on-site: 0

Mountain View Primary School-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



\$500,000 \$1,000,000

Estimated Total Construction Costs (in 2021 Dollars): \$917,700 Estimated Total Project Costs: \$1,055,385 - \$1,509,506



Following is the list of currently unfunded facility projects at Mountain View Elementary

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
1-High	Evaluate and replace branch wiring as needed ²	\$100,000	\$10,000-\$43,000	\$5,000-\$21,500
	Refurbish/replace retractable partitions	\$51,200	\$5,100-\$22,000	\$2,560-\$11,008
	Refinish stage floor	\$5,300	\$600-\$2,300	\$265-\$1,140
	Replace trough washing stations with sinks	\$17,600	\$1,800-\$7,600	\$880-\$3,784
2-High	Replace fixed casework	\$60,000	\$6,000-\$25,800	\$3,000-\$12,900
	Repair/replace areas of curb as needed	\$102,300	\$10,300-\$44,000	\$5,115-\$21,995
	Repair/replace sidewalk(s)	\$23,900	\$2,400-\$10,300	\$1,195-\$5,139
	Repair/resurface playground as necessary	\$95,100	\$9,500-\$40,900	\$4,755-\$20,447
2-Medium	Re-caulk control joints	\$2,800	\$300-\$1,200	\$140-\$602
3-High	Caulk wall foundation	\$8,300	\$800-\$3,500	\$415-\$1,785
5-nigii	Install new synthetic turf for multi-use field	\$30,700	\$3,100-\$13,200	\$1,535-\$6,601
3-Medium	Vinyl coverings repair/replacement	\$6,200	\$600-\$2,700	\$310-\$1,333
	Fire sprinkle building	\$408,500	\$40,800-\$175,600	\$20,425-\$87,828
4-High	Renovate/repair areas of grass around school	\$5,800	\$500-\$2,400	\$290-\$1,247

Estimated Total Construction Costs (in 2021 Dollars): \$917,700 Estimated Project Management Costs Range: \$91,800 - \$394,500 Estimated Inflation Range: \$45,885 - \$197,306

Estimated Total Project Costs: \$1,055,385 - \$1,509,506

Tier 1 Projects Not Using 2018 Bond Funding

Project Symbol	Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
5	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.


Summary of Projects	Total Cost	
2019-2020 Completed Projects		
Upgrade control system Replace rooftop units Recaulk windows, repair rusted windows Replace restroom partitions and flooring Upgrade fire alarm system Upgrade irrigation system Resurface bus loop and parking lot Silver coat parapet walls Repair and refinish exterior doors Repair and replace classroom storefronts	\$2,138,041	
2021 Contracted Projects		
No projects contracted for 2021	N/A	




10585 Mountain Vista Ridge Highlands Ranch, CO 80126 Mountain Vista High School Feeder Area, 9-12 Funded by 1997 Bond Opened in 2001

Site Acreage: 93.2 Facility Square Feet: 241,604 Mobiles on-site: 4

Mountain Vista High School-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$2,836,700 Estimated Total Project Costs: \$3,262,135 - \$4,666,391



Following is the list of currently unfunded facility projects at Mountain Vista High

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
1-High	Paint metal roof ¹	\$9,000	\$900-\$3,900	\$450-\$1,935
Tiligii	Replace roof top units ¹	\$1,040,000	\$104,000-\$447,200	\$52,000-\$223,600
	Overhaul elevator(s) ²	\$125,000	\$12,500-\$53,800	\$6,250-\$26,875
1-Medium	Replace boiler(s) ²	\$400,000	\$40,000-\$172,000	\$20,000-\$86,000
	Chilled Water Systems. Replace chiller and cooling tower ²	\$400,000	\$40,000-\$172,000	\$20,000-\$86,000
	Recaulk exterior windows	\$77,800	\$7,800-\$33,500	\$3,890-\$16,727
	Recaulk/reglaze curtain wall windows	\$41,100	\$4,100-\$17,600	\$2,055-\$8,837
	Paint exterior doors	\$900	\$100-\$400	\$45-\$194
2-High	Replace cafeteria VCT	\$75,000	\$7,500-\$32,300	\$3,750-\$16,125
Z-riigii	Replace restroom flooring	\$75,000	\$7,500-\$32,300	\$3,750-\$16,125
	Upgrade theater lighting and sound systems	\$100,000	\$10,000-\$43,000	\$5,000-\$21,500
	Resurface parking lot	\$2,100	\$200-\$900	\$105-\$452
	Repair/replace sections of sidewalk as necessary	\$25,000	\$2,500-\$10,800	\$1,250-\$5,375
	Replace hallway/classroom flooring	\$82,500	\$8,300-\$35,500	\$4,125-\$17,738
2-Medium	Replace carpet	\$200,000	\$20,000-\$86,000	\$10,000-\$43,000
2-Medium	Add additional parking and new roadways for traffic flow	\$29,300	\$2,900-\$12,600	\$1,465-\$6,300
	Repair retaining wall(s)	\$2,700	\$300-\$1,100	\$135-\$581
3-High	Recaulk wall foundation	\$36,700	\$3,600-\$15,700	\$1,835-\$7,891
	Renovate multi-use field	\$74,200	\$7,400-\$31,900	\$3,710-\$15,953
	Repair crack in slab where it meets upper floor	\$11,000	\$1,100-\$4,800	\$550-\$2,365
3-Medium	Repair operable partition(s)	\$8,300	\$800-\$3,500	\$415-\$1,785
3-Mediuili	Refinish interior doors	\$5,500	\$600-\$2,400	\$275-\$1,183
	Vinyl coverings repair/replacement	\$15,600	\$1,500-\$6,600	\$780-\$3,354

Estimated Total Construction Costs (in 2021 Dollars): \$2,836,700 Estimated Project Management Costs Range: \$283,600 - \$1,219,800 Estimated Inflation Range: \$141,835 - \$609,891

Estimated Total Project Costs: \$3,262,135 - \$4,666,391

Tier 1 Projects Not Using 2018 Bond Funding

	,	3
Project Symbol	Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
5	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.


Summary of Projects	Total Cost
2019-2020 Completed Projects	
Replace carpet in hallways and office Replace non-restricted with restricted key system	\$890,690
2021 Contracted Projects	
Upgrade control system Replace generator and associated equipment Recaulk exterior wall control joints, seal masonry CMU, repair cracks Repair toilet partitions Replace kitchen flooring Repair upper level crack in floor Paint roof equipment Replace ballasted with fully adhered roof	\$4,707,040




6598 North State Highway 83 Parker, CO 80134 Ponderosa High School Feeder Area, 3-5 Funded by 1960 Bond Opened in 1966

Site Acreage:15 Facility Square Feet: 47,660 Mobiles on-site: 0

Northeast Intermediate School-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$1,976,700 Estimated Total Project Costs: \$2,273,335 - \$3,251,791



Following is the list of currently unfunded and to be funded with the 2018 Bond facility projects at Northeast Elementary

Tier & Priority Class	ity Project Description		Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
Tier 1 Funded by the 2018 Bond Upgrade irrigation system		\$18,700	\$1,900-\$8,100	\$935-\$4,021
	Paint CMU chiller enclosure	\$1,100	\$200-\$500	\$55-\$237
	Recaulk exterior windows	\$14,600	\$1,400-\$6,200	\$730-\$3,139
	Repair/replace, sand/paint entry/classroom storefronts	\$20,600	\$2,100-\$8,900	\$1,030-\$4,429
	Replace fabricated toilet partition(s)	\$35,000	\$3,500-\$15,100	\$1,750-\$7,525
2-High	Replace kitchen flooring	\$75,000	\$7,500-\$32,300	\$3,750-\$16,125
	Resurface asphalt bus loop	\$100,000	\$10,000-\$43,000	\$5,000-\$21,500
	Resurface parking lot	\$165,700	\$16,600-\$71,200	\$8,285-\$35,626
	Repair/replace sidewalk(s)	\$521,400	\$52,200-\$224,300	\$26,070-\$112,101
	Repair/resurface playground as necessary	\$95,100	\$9,500-\$40,900	\$4,755-\$20,447
2-Medium	Repair laminated roof support beams	\$16,500	\$1,700-\$7,100	\$825-\$3,548
2-Medium	Fix site drainage issues around building	\$4,900	\$500-\$2,100	\$245-\$1,054
3-High	Repair foundation wall on south side	\$20,600	\$2,100-\$8,900	\$1,030-\$4,429
	Recaulk wall foundation	\$8,000	\$800-\$3,400	\$400-\$1,720
	Vinyl coverings repair/replacement	\$6,200	\$600-\$2,700	\$310-\$1,333
3-Medium	Fire sprinkle building	\$408,500	\$40,800-\$175,600	\$20,425-\$87,828
	Replace picnic tables front side of building	\$126,800	\$12,600-\$54,500	\$6,340-\$27,262
4-High	Renovate/repair areas of grass around school	\$338,000	\$33,800-\$145,300	\$16,900-\$72,670

Estimated Total Construction Costs (in 2021 Dollars): \$1,976,700 Estimated Project Management Costs Range: \$197,800 - \$850,100 Estimated Inflation Range: \$98,835 - \$424,991

Estimated Total Project Costs: \$2,273,335 - \$3,251,791

Summary of Projects	Total Cost	
2019-2020 Completed Projects		
Intall new generator and associated emergency systems Recaulk exterior wall control joints, repair grout, fix crack on West side Replace all old casework Replace cafeteria, gym, and restroom flooring Replace carpet Fix gutter and downspout drainage Replace non-restricted with restricted key system Replace original panel and transformers Replace roof and roof finishes Sand and paint exterior doors	\$1,447,449	
2021 Contracted Projects		
No projects contracted for 2021	N/A	




6555 Southpark Road Highlands Ranch, CO 80126 Mountain Vista High School Feeder Area, K-6


Funded by Capital Reserve Opened in 1982

Site Acreage:10 Facility Square Feet: 48,055 Mobiles on-site: 4

Northridge Elementary-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$2,135,000 Estimated Total Project Costs: \$2,455,250 - \$3,511,925



Following is the list of currently unfunded and to be funded with the 2018 Bond facility projects at Northridge Elementary

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Replace original panels and transformers	\$100,000	\$10,000-\$43,000	\$5,000-\$25,000
Tier 1	Replace domestic water heater and associated piping	\$92,800	\$9,300-\$39,900	\$4,640-\$19,952
Funded by the	Paint roof AHUs	\$2,000	\$200-\$900	\$100-\$430
2018 Bond	Replace make-up air unit in kitchen	\$59,600	\$5,900-\$25,500	\$2,980-\$12,814
	Replace generator and associated equipment	\$75,000	\$7,500-\$32,300	\$3,750-\$16,125
1 Himb	Evaluate and replace branch wiring as needed ²	\$100,000	\$10,000-\$43,000	\$5,000-\$21,500
1-High	Upgrade fire alarm system ²	\$175,000	\$17,500-\$75,300	\$8,750-\$37,625
	Exterior trim and doors need painted	\$8,400	\$800-\$3,600	\$420-\$1,806
	Replace exterior windows	\$73,100	\$7,300-\$31,400	\$3,655-\$15,717
	Recaulk exterior windows	\$13,800	\$1,400-\$5,900	\$690-\$2,967
	Refurbish/replace retractable partitions	\$27,900	\$2,800-\$11,900	\$1,395-\$5,999
	Replace fabricated toilet partition(s)	\$35,000	\$3,500-\$15,100	\$1,750-\$7,525
	Repair hallway/classroom flooring	\$4,800	\$500-\$2,000	\$240-\$1,032
	Replace kitchen flooring	\$75,000	\$7,500-\$32,300	\$3,750-\$16,125
2-High	Replace restroom flooring	\$40,000	\$4,000-\$17,200	\$2,000-\$8,600
2-nigii	Replace carpet	\$330,000	\$33,000-\$141,900	\$16,500-\$70,950
	Replace sink(s)	\$18,700	\$1,900-\$8,100	\$935-\$4,021
	Replace water cooler(s), drinking fountain(s)	\$2,900	\$300-\$1,200	\$145-\$624
	Replace fixed casework	\$60,000	\$6,000-\$25,800	\$3,000-\$12,900
	Resurface asphalt bus loop	\$37,300	\$3,800-\$16,100	\$1,865-\$8,020
	Resurface parking lot	\$34,000	\$3,400-\$14,700	\$1,700-\$7,310
	Repair/replace sections of sidewalk as necessary	\$10,400	\$1,000-\$4,400	\$520-\$2,236
	Replace playground play pads	\$268,100	\$26,800-\$115,300	\$13,405-\$57,642
2-Medium	Exterior wall, repair CMU and brick at corners	\$9,400	\$900-\$4,000	\$470-\$2,021
	Recaulk wall foundation	\$3,600	\$300-\$1,500	\$180-\$774
3-High	Replace/repair suspended ceiling	\$143,000	\$14,300-\$61,500	\$7,150-\$30,745
3 mgn	Replace blinds as necessary	\$16,500	\$1,700-\$7,100	\$825-\$3,548
	Renovate multi-use field	\$306,500	\$30,700-\$131,800	\$15,325-\$65,898
3-Medium	Repair drainage issues at front of site	\$9,400	\$900-\$4,000	\$470-\$2,021
4-High	Renovate/repair areas of grass around school	\$2,800	\$300-\$1,200	\$140-\$602

Estimated Iotal Construction Costs (in 2021 Dollars): \$2,135,000 Estimated Project Management Costs Range: \$213,500 - \$917,900

Estimated Inflation Range: \$106,750 - \$459,025 Estimated Total Project Costs: \$2,455,250 - \$3,511,925

Tier 1 Projects Not Using 2018 Bond Funding

Project Symbol	Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
5	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.


Summary of Projects	Total Cost	
2019-2020 Completed Projects		
Flooring Toilet partitions	\$394,327	
2021 Contracted Projects		
No projects contracted for 2021	N/A	



10450 Stonegate Parkway Parker, CO 80134 Chaparral High School Feeder Area, K-6 Funded by 1993 Bond Opened in 1995


Site Acreage:10 Facility Square Feet: 55,016 Mobiles on-site: 4

Pine Grove Elementary-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



\$1,000,00

Estimated Total Construction Costs (in 2021 Dollars): \$1,406,000 Estimated Total Project Costs: \$1,616,800 - \$2,312,590



Following is the list of currently unfunded facility projects at Pine Grove Elementary

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
1-High	Upgrade fire alarm system ²	\$175,000	\$17,500-\$75,300	\$8,750-\$37,625
	Upgrade control system ²	\$300,000	\$30,000-\$129,000	\$15,000-\$64,500
1-Medium	Replace main switchgear ²	\$100,000	\$10,000-\$43,000	\$5,000-\$21,500
	Replace original panels and transformers ²	\$100,000	\$10,000-\$43,000	\$5,000-\$21,500
	Paint all exterior doors, door and window frames	\$8,400	\$800-\$3,600	\$420-\$1,806
	Recaulk exterior windows	\$13,800	\$1,400-\$5,900	\$690-\$2,967
	Refurbish/replace retractable partitions	\$12,800	\$1,300-\$5,500	\$640-\$2,752
2-High	Refinish interior doors	\$8,600	\$900-\$3,700	\$430-\$1,849
	Replace sink countertop(s)	\$30,000	\$3,000-\$12,900	\$1,500-\$6,450
	Resurface parking lot	\$6,100	\$600-\$2,600	\$305-\$1,312
	Repair/replace sidewalk(s)	\$10,400	\$1,000-\$4,400	\$520-\$2,236
	Replace cafeteria VCT	\$20,000	\$2,000-\$8,600	\$1,000-\$4,300
	Replace restroom flooring	\$40,000	\$4,000-\$17,200	\$2,000-\$8,600
2-Medium	Replace gym carpet	\$40,000	\$4,000-\$17,200	\$2,000-\$8,600
	Replace carpet	\$350,000	\$35,000-\$150,500	\$17,500-\$75,250
	Replace/refinish fixed casework as necessary	\$60,000	\$6,000-\$25,800	\$3,000-\$12,900
	Recaulk wall foundation	\$3,600	\$300-\$1,500	\$180-\$774
3-High	Repair/replace insulation in several areas	\$47,600	\$4,700-\$20,400	\$2,380-\$10,234
	Renovate sod at multi-use field	\$30,700	\$3,100-\$13,200	\$1,535-\$6,601
3-Medium	Vinyl coverings repair/replacement	\$18,000	\$1,800-\$7,700	\$900-\$3,870
4-High	Replace metal edger at shrub beds with concrete mow band. Regrade hillside between play area and ball field	\$31,000	\$3,100-\$13,300	\$1,550-\$6,665

Estimated Total Construction Costs (in 2021 Dollars): \$1,406,000 Estimated Project Management Costs Range: \$140,500 - \$604,300 Estimated Inflation Range: \$70,300 - \$302,290

Estimated Total Project Costs: \$1,616,800 - \$2,312,590

Tier 1 Projects Not Using 2018 Bond Funding

Project Symbol	Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
5	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.

Summary of Projects	Total Cost	
2019-2020 Completed Projects		
No projects completed in 2019-20	N/A	
2021 Contracted Projects		
Replace swamp cooling units with mechanical cooling Replace exhaust fans throughout building Recaulk exterior wall control joints, reseal CMU Replace toilet partitions Replace kitchen flooring	\$464,635	




6475 East Ponderosa Drive Parker, CO 80138 Chaparral High School Feeder Area, K-6


Funded by 1978 Bond Opened in 1980

Site Acreage: 30 (North & South) Facility Square Feet: 39,687 (North), 51,938 (South) Mobiles on-site: 3

Pine Lane Elementary-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$3,469,900 Estimated Total Project Costs: \$3,990,695 - \$5,708,329



Following is the list of currently unfunded and to be funded with the 2018 Bond facility projects at Pine Lane Elementary

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
Tier 1 Funded by the 2018 Bond	Upgrade irrigation system	\$10,400	\$1,000-\$4,400	\$520-\$2,236
1-High	Replace roof top units ²	\$1,000,000	\$100,000-\$430,000	\$50,000-\$215,000
1-High	Evaluate and replace branch wiring as needed ²	\$100,000	\$10,000-\$43,000	\$5,000-\$21,500
1-Medium	Paint metal roof ¹	\$10,000	\$1,000-\$4,300	\$500-\$2,150

Estimated Total Construction Costs (in 2021 Dollars): \$3,469,900 Estimated Project Management Costs Range: \$347,300 - \$1,492,400 Estimated Inflation Range: \$173,495 - \$746,029

Estimated Total Project Costs: \$3,990,695 - \$5,708,329

Tier 1 Projects Not Using 2018 Bond Funding

Project Symbol	Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.

2019-2020 Completed Projects	
Refinish interior doors and doorframes Replace non-restricted with restricted key system	\$522,776
2021 Contracted Projects	
Upgrade control system Replace rooftop units Install new generator and associated emergency systems Recaulk exterior wall control joints, repair grout Replace toilet partitions Upgrade fire alarm system Replace original casework Replace restroom flooring Upgrade irrigation system Repair/replace sections of sidewalk Replace playground Replace metal roof, silver coat parapet walls, seal brick Repair/replace classroom storefronts Replace porch/partition roof beams Install new roofing system Rework gutters and downspouts	\$8,833,503

Pine Lane Elementary cont.

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Recaulk exterior windows	\$7,900	\$700-\$3,300	\$395-\$1,699
	Repair/replace entry storefronts	\$30,700	\$3,100-\$13,200	\$1,535-\$6,601
	Replace retractable partition(s)	\$76,700	\$7,700-\$33,000	\$3,835-\$16,491
	Replace cafeteria VCT	\$33,000	\$3,300-\$14,200	\$1,650-\$7,095
	Replace kitchen flooring	\$92,100	\$9,200-\$39,600	\$4,605-\$19,802
	Resurface asphalt bus loop	\$75,000	\$7,500-\$32,300	\$3,750-\$16,125
	Resurface parking lot	\$88,000	\$8,800-\$37,900	\$4,400-\$18,920
2-High	Recaulk exterior windows	\$16,400	\$1,700-\$7,100	\$820-\$3,526
Z-High	Repair or refinish exterior doors	\$5,300	\$600-\$2,300	\$265-\$1,140
	Refurbish/replace retractable partitions	\$51,200	\$5,100-\$22,000	\$2,560-\$11,008
	Replace fabricated toilet partition(s)	\$35,000	\$3,500-\$15,100	\$1,750-\$7,525
	Replace kitchen flooring	\$75,000	\$7,500-\$32,300	\$3,750-\$16,125
	Replace trough washing stations with sinks	\$17,600	\$1,800-\$7,600	\$880-\$3,784
	Replace fixed casework	\$60,000	\$6,000-\$25,800	\$3,000-\$12,900
	Resurface asphalt bus loop	\$75,000	\$7,500-\$32,300	\$3,750-\$16,125
	Resurface parking lot	\$81,900	\$8,200-\$35,200	\$4,095-\$17,609
	Exterior wall, repair stucco	\$2,200	\$300-\$1,000	\$110-\$473
	Replace exterior doors	\$82,500	\$8,300-\$35,500	\$4,125-\$17,738
2-Medium	Exterior entrances need painted again	\$3,900	\$400-\$1,700	\$195-\$839
	Replace kitchen flooring	\$75,000	\$7,500-\$32,300	\$3,750-\$16,125
	Improve parking areas and access	\$9,400	\$900-\$4,000	\$470-\$2,021
	Recaulk wall foundation	\$5,800	\$500-\$2,400	\$290-\$1,247
	Replace/repair suspended ceiling	\$171,600	\$17,200-\$73,800	\$8,580-\$36,894
3-High	Renovate multi-use field	\$81,900	\$8,200-\$35,200	\$4,095-\$17,609
	Recaulk wall foundation	\$8,300	\$800-\$3,500	\$415-\$1,785
	Renovate multi-use field	\$55,000	\$5,500-\$23,700	\$2,750-\$11,825
	Repair steel beams and concrete foundation	\$5,500	\$600-\$2,400	\$275-\$1,183
	Vinyl coverings repair/replacement	\$6,200	\$600-\$2,700	\$310-\$1,333
3-Medium	Install sprinkler system	\$428,900	\$42,900-\$184,500	\$21,445-\$92,214
	Vinyl coverings repair/replacement	\$5,300	\$600-\$2,300	\$265-\$1,140
	Flooring Tile. Replace entry way tile	\$12,000	\$1,200-\$5,200	\$600-\$2,580
	Replace/repair suspended ceiling	\$137,500	\$13,800-\$59,200	\$6,875-\$29,563
	Fire sprinkle building	\$408,500	\$40,800-\$175,600	\$20,425-\$87,828
	Repair drainage issues at front of site	\$4,800	\$500-\$2,000	\$240-\$1,032
4-High	Renovate/repair areas of grass around school	\$19,500	\$2,000-\$8,400	\$975-\$4,193
	Renovate/repair areas of grass around school	\$4,900	\$500-\$2,100	\$245-\$1,054

This page left intentionally blank




10881 Riva Ridge Street Parker, CO 80134 Legend High School Feeder Area, K-5


Funded by 1993 Bond Opened in 1997

Site Acreage:10 Facility Square Feet: 51,020 Mobiles on-site: 3

Pioneer Elementary-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$988,100 Estimated Total Project Costs: \$1,136,605 - \$1,625,442



Following is the list of currently unfunded and to be funded with the 2018 Bond facility projects at Pioneer Elementary

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
Tier 1 Funded by the 2018 Bond	Upgrade irrigation system	\$11,000	\$1,100-\$4,800	\$550-\$2,365
1-High	Replace boiler(s) ²	\$250,000	\$25,000-\$107,500	\$12,500-\$53,750
	Paint exterior	\$8,500	\$900-\$3,700	\$425-\$1,828
	Recaulk exterior windows	\$13,800	\$1,400-\$5,900	\$690-\$2,967
	Refurbish/replace retractable partitions	\$17,000	\$1,700-\$7,300	\$850-\$3,655
2-High	Replace sink countertop(s)	\$30,000	\$3,000-\$12,900	\$1,500-\$6,450
2-nigii	Replace cafeteria VCT	\$20,000	\$2,000-\$8,600	\$1,000-\$4,300
	Replace cafeteria VCT	\$16,500	\$1,700-\$7,100	\$825-\$3,548
	Replace hallway/classroom flooring	\$8,300	\$800-\$3,500	\$415-\$1,785
	Replace playground play pads	\$30,700	\$3,100-\$13,200	\$1,535-\$6,601
3-High	Recaulk wall foundation	\$3,600	\$300-\$1,500	\$180-\$774
5-mign	Replace chalk boards with white boards	\$148,300	\$14,900-\$63,800	\$7,415-\$31,885
3-Medium	Vinyl coverings repair/replacement	\$4,400	\$500-\$1,900	\$220-\$946
	Replace/repair suspended ceiling	\$6,900	\$700-\$2,900	\$345-\$1,484
	Remove grease interceptor	\$8,500	\$900-\$3,700	\$425-\$1,828
	Fire sprinkle building	\$328,700	\$32,900-\$141,400	\$16,435-\$70,671
	Replacement at hill area	\$81,900	\$8,200-\$35,200	\$4,095-\$17,609

Estimated Total Construction Costs (in 2021 Dollars): \$988,100 Estimated Project Management Costs Range: \$99,100 - \$424,900 Estimated Inflation Range: \$49,405 - \$212,442

Estimated Total Project Costs: \$1,136,605 - \$1,625,442

Tier 1 Projects Not Using 2018 Bond Funding

Project Symbol	Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
5	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.


Summary of Projects	Total Cost	
2019-2020 Completed Projects		
Upgrade controls Replace swamp cooling units with mechanical cooling Replace roof top units Replace generator and associated equipment Upgrade and replace exhaust fans Recaulk and reseal exterior CMU wall Replace kitchen flooring Replace hot water storage tank Replace unrestricted with restricted key system Repair and replace areas of sidewalk Replace original carpeting in gym Furniture	\$2,563,092	
2021 Contracted Projects		
No projects contracted for 2021	N/A	




9340 Commerce Center St. Highlands Ranch, CO 80129 Funded by 2006 Bond Opened in 2009 Site Acreage: 1.86 Facility Square Feet: 18,765

ThunderRidge High School Feeder Area, Alternative Education

Plum Creek Academy-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$270,00 Estimated Total Project Costs: \$310,500 - \$444,150



Following is the list of currently unfunded facility projects at Plum Creek Academy

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
1-High	Upgrade fire alarm system ²	\$120,000	\$12,000-\$51,600	\$6,000-\$25,800
1-Medium	Upgrade control system ²	\$150,000	\$15,000-\$64,500	\$7,500-\$32,250

Estimated Total Construction Costs (in 2021 Dollars): \$270,000 Estimated Project Management Costs Range: \$27,000 - \$116,100 Estimated Inflation Range: \$13,500 - \$58,050

Estimated Total Project Costs: \$310,500 - \$444,150

Tier 1 Projects Not Using 2018 Bond Funding


Project Symbol	Category Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
5	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.




7007 East Bayou Gulch Road Parker, CO 80134 Ponderosa High School Feeder Area, 9-12 Funded by 1978 Bond Opened in 1982

Site Acreage: 65 Facility Square Feet: 248,300 Mobiles on-site: 0

Ponderosa High School-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$2,191,600 Estimated Total Project Costs: \$2,520,480 - \$3,604,894



Following is the list of currently unfunded facility projects at Ponderosa High

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Chilled Water Systems. Replace cooling tower ⁴	\$100,000	\$10,000-\$43,000	\$5,000-\$21,500
1-Hiah	Evaluate and replace branch wiring as needed ²	\$100,000	\$10,000-\$43,000	\$5,000-\$21,500
1-High	Replace generator and associated equipment ²	\$75,000	\$7,500-\$32,300	\$3,750-\$16,125
	Replace auxiliary bleachers in gym ⁴	\$229,900	\$23,000-\$98,900	\$11,495-\$49,429

Estimated Total Construction Costs (in 2021 Dollars): \$2,191,600 Estimated Project Management Costs Range: \$219,300 - \$942,100 Estimated Inflation Range: \$109,580 - \$471,194

Estimated Total Project Costs: \$2,520,480 - \$3,604,894

Tier 1 Projects Not Using 2018 Bond Funding

Project Symbol	Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.

Summary of Projects	Total Cost	
2019-2020 Completed Projects		
Evaluate and repair air distribution system Upgrade auxiliary equipment Upgrade boilers and associated controls and pump Upgrade change-over distribution system Retest and recommission air and water systems Upgrade controls Replace band area roof top unit Install new gas supply lines for kitchen Replace toilet partitions Upgrade fire alarm system Replace main gym bleachers Replace carpet, VCT, and tile flooring throughout building Upgrade glycol distribution systems Upgrade hot water distribution Replace insulation Replace irrigation controllers Upgrade lavatory to autosensor Evaluate and redesign package units Renovate elevators Replace ballasted with fully adhered roof Evaluate and redesign terminal self contained units	\$8,161,824	
2021 Contracted Projects		
No projects contracted for 2021	N/A	

Ponderosa High cont.

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Exterior wall, recaulk control joints	\$9,800	\$1,000-\$4,200	\$490-\$2,107
	Replace exterior windows	\$389,200	\$38,900-\$167,400	\$19,460-\$83,678
	Recaulk exterior windows	\$48,700	\$4,800-\$20,900	\$2,435-\$10,471
	Replace exterior doors	\$127,400	\$12,800-\$54,800	\$6,370-\$27,391
	Replace main roof hatch	\$2,700	\$300-\$1,100	\$135-\$581
	Upgrade water closets to autoflush valves	\$25,600	\$2,500-\$10,900	\$1,280-\$5,504
	Replace wash fountain	\$23,100	\$2,400-\$10,000	\$1,155-\$4,967
2-High	Upgrade/replace showers	\$25,600	\$2,500-\$10,900	\$1,280-\$5,504
	Upgrade acid waste system	\$17,000	\$1,700-\$7,300	\$850-\$3,655
	Upgrade air purifiers	\$42,500	\$4,300-\$18,300	\$2,125-\$9,138
	Upgrade paint spray booth ventilation	\$76,600	\$7,700-\$32,900	\$3,830-\$16,469
	Upgrade theater lighting and sound systems	\$100,000	\$10,000-\$43,000	\$5,000-\$21,500
	Remove chalkboards or repurpose	\$5,300	\$600-\$2,300	\$265-\$1,140
	Refurbish lockers.	\$9,400	\$900-\$4,000	\$470-\$2,021
	Resurface parking lot	\$83,500	\$8,400-\$35,900	\$4,175-\$17,953
	Replace restroom flooring	\$3,700	\$300-\$1,500	\$185-\$796
2-Medium	Remove/replace ceiling finishings (sound proofing)	\$63,300	\$6,300-\$27,200	\$3,165-\$13,610
	Replace grease interceptor	\$25,600	\$2,500-\$10,900	\$1,280-\$5,504
2 High	Recaulk wall foundation	\$9,800	\$1,000-\$4,200	\$490-\$2,107
3-High	Install new blinds with window replacement	\$3,200	\$400-\$1,400	\$160-\$688
	Install new sprinkler system, replace existing heads	\$466,800	\$46,700-\$200,700	\$23,340-\$100,362
3-Medium	Install asphalt parking lots	\$81,900	\$8,200-\$35,200	\$4,095-\$17,609
5-wealum	Repair/replace cable fence and split rail fence	\$12,000	\$1,200-\$5,200	\$600-\$2,580
	Improve drainage on east and west sides	\$34,000	\$3,400-\$14,700	\$1,700-\$7,310


This page left intentionally blank




11605 S. Bradbury Ranch Drive Parker, CO 80134 Chaparral High School Feeder Area, K-6 Funded by 1997 Bond Opened in 2001

Site Acreage: 8.6 Facility Square Feet: 51,668 Mobiles on-site: 5

Prairie Crossing Elementary-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$1,196,800 Estimated Total Project Costs: \$1,376,340 - \$1,968,712



Following is the list of currently unfunded facility projects at Prairie Crossing Elementary

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Install water sensing level switches in basement ²	\$25,000	\$2,500-\$10,800	\$1,250-\$5,375
1-High	Re-glaze skylights ⁴	\$30,700	\$3,100-\$13,200	\$1,535-\$6,601
	Chilled Water Systems. Replace cooling tower ¹	\$100,000	\$10,000-\$43,000	\$5,000-\$21,500
1-Medium	Replace boiler(s) ²	\$250,000	\$25,000-\$107,500	\$12,500-\$53,750
1-Medium	Chilled Water Systems. Replace chiller ¹	\$300,000	\$30,000-\$129,000	\$15,000-\$64,500
	Recaulk exterior windows	\$14,300	\$1,500-\$6,200	\$715-\$3,075
	Fix exterior window(s) leakage	\$51,200	\$5,100-\$22,000	\$2,560-\$11,008
	Paint exterior doors	\$600	\$100-\$200	\$30-\$129
	Replace fabricated toilet partitions	\$35,000	\$3,500-\$15,100	\$1,750-\$7,525
2-High	Replace restroom flooring	\$40,000	\$4,000-\$17,200	\$2,000-\$8,600
	Resurface asphalt bus loop	\$50,000	\$5,000-\$21,500	\$2,500-\$10,750
	Resurface parking lot	\$88,000	\$8,800-\$37,900	\$4,400-\$18,920
	Repair/replace areas of curb as needed	\$29,900	\$2,900-\$12,800	\$1,495-\$6,429
	Replace asphalt playground	\$81,900	\$8,200-\$35,200	\$4,095-\$17,609
3-High	Recaulk wall foundation	\$3,800	\$400-\$1,600	\$190-\$817
3-High	Renovate multi-use field	\$81,900	\$8,200-\$35,200	\$4,095-\$17,609
3-Medium	Repair operable partition(s)	\$8,300	\$800-\$3,500	\$415-\$1,785
3-Medium	Vinyl coverings repair/replacement	\$6,200	\$600-\$2,700	\$310-\$1,333

Estimated Total Construction Costs (in 2021 Dollars): \$1,196,800 Estimated Project Management Costs Range: \$119,700 - \$514,600 Estimated Inflation Range: \$59,840 - \$257,312

Estimated Total Project Cost: \$1,376,340 - \$1,968,712

Tier 1 Projects Not Using 2018 Bond Funding

Project Symbol	Category	Category Definition			
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.			
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.			
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.			
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.			
5	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.			

Summary of Projects	Total Cost	
2019-2020 Completed Projects		
Upgrade control system Replace generator and associated equipment Recaulk exterior wall control joints, seal masonry CMU Upgrade fire alarm system Replace kitchen flooring Replace unrestricted with restricted key system Paint metal roof Repair/replace sections of sidewalk Replace ballasted with fully adhered roof	\$1,064,667	
2021 Contracted Projects		
No projects contracted for 2021	N/A	




1731 Wildcat Reserve Parkway Highlands Ranch, CO 80129 ThunderRidge High School Feeder Area, 7-8 Funded by 1996 Bond Opened in 1997

Site Acreage: 20 Facility Square Feet: 127,951 Mobiles on-site: 0

Ranch View Middle School-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$2,032,400 Estimated Total Project Costs: \$2,336,920 - \$3,342,966



Following is the list of currently unfunded and to be funded with the 2018 Bond facility projects at Ranch View Middle

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
Tier 1 Funded by the 2018 Bond	Upgrade irrigation system	\$6,100	\$600-\$2,600	\$305-\$1,312
	Install water sensing level switches in basement ²	\$25,000	\$2,500-\$10,800	\$1,250-\$5,375
1-High	Replace domestic water heater system ¹	\$85,800	\$8,600-\$36,900	\$4,290-\$18,447
1-High	Chilled Water Systems. Replace chiller ²	\$300,000	\$30,000-\$129,000	\$15,000-\$64,500
	Replace generator and associated equipment 1	\$75,000	\$7,500-\$32,300	\$3,750-\$16,125
1-Medium	Overhaul elevator(s) ²	\$125,000	\$12,500-\$53,800	\$6,250-\$26,875
i-weatum	Replace boiler(s) ²	\$300,000	\$30,000-\$129,000	\$15,000-\$64,500

Estimated Total Construction Costs (in 2021 Dollars): \$2,032,400 Estimated Project Management Costs Range: \$202,900 - \$873,600 Estimated Inflation Range: \$101,620 - \$436,966

Estimated Total Project Costs: \$2,336,920 - \$3,342,966

Tier 1 Projects Not Using 2018 Bond Funding

Project Symbol	Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
5	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.

Summary of Projects	Total Cost			
2019-2020 Completed Projects				
Replace current Simplex clock system Upgrade control system Recaulk exterior wall control joints Replace restroom toilet partitions Repair/replace bleachers Replace kitchen and hallway flooring Replace unrestricted with restricted key system Replace ballasted with fully adhered roof Repair and paint exterior doors	\$2,390,938			
2021 Contracted Projects				
No projects contracted for 2021	N/A			

Ranch View Middle cont.

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Recaulk exterior windows	\$24,500	\$2,400-\$10,500	\$1,225-\$5,268
	Replace sink countertop(s)	\$42,200	\$4,200-\$18,100	\$2,110-\$9,073
	Refinish stairs at stage	\$2,400	\$200-\$1,000	\$120-\$516
	Replace cafeteria VCT	\$5,800	\$500-\$2,400	\$290-\$1,247
	Repair hallway/classroom flooring	\$1,300	\$100-\$500	\$65-\$280
	Replace restroom flooring	\$50,000	\$5,000-\$21,500	\$2,500-\$10,750
2-High	Paint gas piping to prevent corrosion	\$700	\$100-\$300	\$35-\$151
	Replace exhaust fans	\$63,000	\$6,300-\$27,000	\$3,150-\$13,545
	Resurface asphalt bus loop	\$100,000	\$10,000-\$43,000	\$5,000-\$21,500
	Resurface parking lot	\$81,900	\$8,200-\$35,200	\$4,095-\$17,609
	Repair/replace areas of curb as needed	\$550,000	\$55,000-\$236,500	\$27,500-\$118,250
	Repair/replace sidewalk(s)	\$10,400	\$1,000-\$4,400	\$520-\$2,236
	Repair/replace fencing at dumpster area	\$9,700	\$1,000-\$4,200	\$485-\$2,086
2-Medium	Repair concrete at basketball court	\$8,300	\$800-\$3,500	\$415-\$1,785
	Recaulk wall foundation	\$4,700	\$400-\$2,000	\$235-\$1,011
	Replace/repair suspended ceiling	\$15,200	\$1,500-\$6,600	\$760-\$3,268
2 High	Repair prestress flooring at commons	\$12,000	\$1,200-\$5,200	\$600-\$2,580
3-High	Vinyl coverings repair/replacement	\$5,800	\$500-\$2,400	\$290-\$1,247
	Reseed and top dress both fields	\$74,200	\$7,400-\$31,900	\$3,710-\$15,953
	Repair plant structure in front of school, metal rusting	\$22,600	\$2,300-\$9,700	\$1,130-\$4,859
3-Medium	Replace and add fencing at front entrance	\$10,800	\$1,100-\$4,700	\$540-\$2,322
	Repair retaining wall(s)	\$7,900	\$700-\$3,300	\$395-\$1,699
4-High	Renovate/repair areas of grass around school	\$1,100	\$200-\$500	\$55-\$237
4-Medium	Replace/add trees and bushes	\$11,000	\$1,100-\$4,800	\$550-\$2,365


This page left intentionally blank




9970 Glenstone Circle Highlands Ranch, CO 80130 Rock Canyon High School Feeder Area, K-5 Funded by 2000 Bond Opened in 2005

Site Acreage:11.8 Facility Square Feet: 56,868 Mobiles on-site: 2

Redstone Elementary-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$1,287,200 Estimated Total Project Costs: \$1,480,260 - \$2,117,448



Following is the list of currently unfunded facility projects at Redstone Elementary

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
1-High	Install water sensing level switches in basement ²	\$25,000	\$2,500-\$10,800	\$1,250-\$5,375
1-High	Replace generator and associated equipment ²	\$75,000	\$7,500-\$32,300	\$3,750-\$16,125
	Exterior wall, recaulk control joints	\$4,000	\$400-\$1,700	\$200-\$860
	Exterior wall, reseal CMU	\$15,300	\$1,600-\$6,600	\$765-\$3,290
	Recaulk exterior windows	\$15,300	\$1,600-\$6,600	\$765-\$3,290
2-High	Refurbish/replace retractable partitions	\$3,300	\$400-\$1,500	\$165-\$710
	Replace sink countertop(s)	\$22,300	\$2,200-\$9,500	\$1,115-\$4,795
	Resurface asphalt bus loop	\$50,000	\$5,000-\$21,500	\$2,500-\$10,750
	Repair parking lot cracks	\$48,700	\$4,800-\$20,900	\$2,435-\$10,471
	Replace fabricated toilet partitions	\$35,000	\$3,500-\$15,100	\$1,750-\$7,525
	Replace restroom flooring	\$40,000	\$4,000-\$17,200	\$2,000-\$8,600
2-Medium	Replace gym carpet	\$40,000	\$4,000-\$17,200	\$2,000-\$8,600
	Replace cafeteria VCT	\$20,000	\$2,000-\$8,600	\$1,000-\$4,300
	Replace carpet	\$350,000	\$35,000-\$150,500	\$17,500-\$75,250
	Structural Slab on Grade. Needs-Repair crack in floor at staff	\$2,000	\$200-\$900	\$100-\$430
3-High	Replace/repair suspended ceiling	\$3,300	\$400-\$1,500	\$165-\$710
	Repair/replace sidewalk(s)	\$10,400	\$1,000-\$4,400	\$520-\$2,236
	Paint interior	\$1,500	\$100-\$600	\$75-\$323
	Vinyl coverings repair/replacement	\$6,200	\$600-\$2,700	\$310-\$1,333
3-Medium	Repair retaining wall(s)	\$169,100	\$16,900-\$72,700	\$8,455-\$36,357
	Reonvate areas of worn grass	\$330,000	\$33,000-\$141,900	\$16,500-\$70,950
	Remove/replace plants	\$10,400	\$1,000-\$4,400	\$520-\$2,236
4-Medium	Renovate/repair areas of grass around school	\$10,400	\$1,000-\$4,400	\$520-\$2,236

Estimated Total Construction Costs (in 2021 Dollars): \$1,287,200 Estimated Project Management Costs Range: \$128,700 - \$553,500 Estimated Inflation Range: \$64,360 - \$276,748

Estimated Total Project Costs: \$1,480,260 - \$2,117,448

Tier 1 Projects Not Using 2018 Bond Funding


Project Symbol	Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
5	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.

Summary of Projects	Total Cost		
2019-2020 Completed Projects			
No projects completed in 2019-20	N/A		
2021 Contracted Projects			
Upgrade control system Upgrade fire system Replace ballasted with fully adhered roof	\$1,278,299		


3960 Trail Boss Lane Castle Rock, CO 80104 Douglas County High School Feeder Area, K-6 Funded by 2000 Bond Opened in 2006

Site Acreage: 16 Facility Square Feet: 35,863 Mobiles on-site: 2

Renaissance Expeditionary-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$1,441,100 Estimated Total Project Costs: \$1,657,155 - \$2,370,637



Following is the list of currently unfunded facility projects at Renaissance Elementary Magnet

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
1-High	Replace generator and associated equipment ²	\$75,000	\$7,500-\$32,300	\$3,750-\$16,125
1-Medium	Replace roof top units ²	\$1,000,000	\$100,000-\$430,000	\$50,000-\$215,000
	Exterior wall, repair cracks	\$2,900	\$300-\$1,200	\$145-\$624
	Paint exterior	\$8,600	\$900-\$3,700	\$430-\$1,849
	Paint exterior doors	\$2,400	\$200-\$1,000	\$120-\$516
2-High	Replace sink countertop(s)	\$7,200	\$700-\$3,100	\$360-\$1,548
	Replace hallway/classroom flooring	\$3,600	\$300-\$1,500	\$180-\$774
	Paint gas piping on roof to prevent corrosion	\$700	\$100-\$300	\$35-\$151
	Repair parking lot cracks	\$24,500	\$2,400-\$10,500	\$1,225-\$5,268
	Replace cafeteria VCT	\$20,000	\$2,000-\$8,600	\$1,000-\$4,300
	Replace restroom flooring	\$25,000	\$2,500-\$10,800	\$1,250-\$5,375
2-Medium	Replace gym carpet	\$40,000	\$4,000-\$17,200	\$2,000-\$8,600
	Replace carpet	\$200,000	\$20,000-\$86,000	\$10,000-\$43,000
	Replace fabricated toilet partitions	\$25,000	\$2,500-\$10,800	\$1,250-\$5,375
2.115mb	Recaulk wall foundation	\$3,600	\$300-\$1,500	\$180-\$774
3-High	Repair ponding at roof access section	\$2,600	\$300-\$1,200	\$130-\$559

Estimated Total Construction Costs (in 2021 Dollars): \$1,441,100 Estimated Project Management Costs Range: \$144,000 - \$619,700 Estimated Inflation Range: \$72,055 - \$309,837

Estimated Total Project Costs: \$1,657,155 - \$2,370,637

Tier 1 Projects Not Using 2018 Bond Funding

Project Symbol	Liatedory	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
5	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.


Summary of Projects	Total Cost	
2019-2020 Completed Projects		
No projects completed in 2019-20	N/A	
2021 Contracted Projects		
Fire alarms	\$124,391	




5810 McArthur Ranch Road Highlands Ranch, CO 80124 Rock Canyon High School Feeder Area, 9-12 Funded by 1997 Bond Opened in 2003

Site Acreage: 80 Facility Square Feet: 248,055 Mobiles on-site: 0

Rock Canyon High School-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$3,895,200 Estimated Total Project Costs: \$4,479,360 - \$6,407,668



Following is the list of currently unfunded facility projects at Rock Canyon High

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
1-High	Replace roof top units ²	\$2,500,000	\$250,000-\$1,075,000	\$125,000-\$537,500
1-High	Replace generator and associated equipment ²	\$75,000	\$7,500-\$32,300	\$3,750-\$16,125
	Exterior wall, reseal CMU	\$38,000	\$3,800-\$16,300	\$1,900-\$8,170
	Recaulk exterior windows	\$74,400	\$7,400-\$32,000	\$3,720-\$15,996
2-High	Replace cafeteria VCT	\$75,000	\$7,500-\$32,300	\$3,750-\$16,125
	Upgrade theater lighting and sound systems	\$100,000	\$10,000-\$43,000	\$5,000-\$21,500
	Repair parking lot cracks, potholes	\$55,000	\$5,500-\$23,700	\$2,750-\$11,825
	Replace sink countertop(s)	\$42,200	\$4,200-\$18,100	\$2,110-\$9,073
	Replace fabricated toilet partitions	\$35,000	\$3,500-\$15,100	\$1,750-\$7,525
2-Medium	Replace restroom flooring	\$75,000	\$7,500-\$32,300	\$3,750-\$16,125
2-Wedium	Replace carpet	\$750,000	\$75,000-\$322,500	\$37,500-\$161,250
	Add/expand roadways and exit for traffic flow	\$29,300	\$2,900-\$12,600	\$1,465-\$6,300
	Repair/replace sidewalk(s)	\$8,300	\$800-\$3,500	\$415-\$1,785
3-High	Recaulk wall foundation	\$38,000	\$3,800-\$16,300	\$1,900-\$8,170

Estimated Total Construction Costs (in 2021 Dollars): \$3,895,200 Estimated Project Management Costs Range: \$389,400 - \$1,675,000 Estimated Inflation Range: \$194,760 - \$837,468

Estimated Total Project Costs: \$4,479,360 - \$6,407,668

Tier 1 Projects Not Using 2018 Bond Funding

	,	
Project Symbol	Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.


Summary of Projects	Total Cost
2019-2020 Completed Projects	
Upgrade control system SPED calming rooms	\$685,308
2021 Contracted Projects	
Upgrade fire alarm system Exterior walls Flooring Roofing	\$3,012,566



400 North Heritage Road Castle Rock, CO 80104 Douglas County High School Feeder Area, K-6 Funded by 1984 Bond Opened in 1988


Site Acreage: 7.5 Facility Square Feet: 53,237 Mobiles on-site: 3

Rock Ridge Elementary-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



\$0 \$500,000 \$1,000,000

> Estimated Total Construction Costs (in 2021 Dollars): \$464,400 Estimated Total Project Costs: \$534,020 - \$763,946



Following is the list of currently unfunded facility projects at Rock Ridge Elementary

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
2-High	Replace kitchen flooring	\$75,000	\$7,500-\$32,300	\$3,750-\$16,125
	Replace gym carpet with sport flooring	\$40,000	\$4,000-\$17,200	\$2,000-\$8,600
2-Medium	Replace gym carpet	\$15,800	\$1,600-\$6,800	\$790-\$3,397
	Replace carpet	\$330,000	\$33,000-\$141,900	\$16,500-\$70,950
3-High	Vinyl coverings repair/replacement	\$3,600	\$300-\$1,500	\$180-\$774

Estimated Total Construction Costs (in 2021 Dollars): \$464,400 Estimated Project Management Costs Range: \$46,400 - \$199,700 Estimated Inflation Range: \$23,220 - \$99,846

Estimated Total Project Costs: \$534,020 - \$763,946


Summary of Projects	Total Cost
2019-2020 Completed Projects	
No projects completed in 2019-20	N/A
2021 Contracted Projects	
Upgrade control system Upgrade fire alarm system Replace roof Replace roof top units Replace main switchgear Upgrade clock system Replace generator and associated equipment Replace restroom sink countertops Replace cafeteria and restroom flooring Replace original fixed casework in classrooms and offices Exterior concrete ramps Furniture SPED calming rooms	\$3,485,118




11033 Monarch Boulevard Highlands Ranch, CO 80124 Rock Canyon High School Feeder Area, 6-8 Funded by 1997 Bond Opened in 2003

Site Acreage: 23.3 Facility Square Feet: 136,760 Mobiles on-site: 5

Rocky Heights Middle School-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$2,622,800 Estimated Total Project Costs: \$3,016,340 - \$4,314,402



Following is the list of currently unfunded facility projects at Rocky Heights Middle

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
1-High	Replace ballasted roof with fully adhered ¹	\$1,000,000	\$100,000-\$430,000	\$50,000-\$215,000
r-riigii	Replace generator and associated equipment ¹	\$75,000	\$7,500-\$32,300	\$3,750-\$16,125
	Re-caulk control joints	\$5,400	\$600-\$2,400	\$270-\$1,161
	Paint exterior trim and doors	\$9,400	\$900-\$4,000	\$470-\$2,021
	Recaulk exterior windows	\$26,200	\$2,600-\$11,300	\$1,310-\$5,633
	Recaulk exterior door frames	\$1,100	\$200-\$500	\$55-\$237
	Refurbish/replace retractable partitions	\$18,700	\$1,900-\$8,100	\$935-\$4,021
2-High	Replace fabricated toilet partition(s)	\$45,000	\$4,500-\$19,400	\$2,250-\$9,675
2 mgn	Replace sink countertop(s)	\$40,100	\$4,000-\$17,200	\$2,005-\$8,622
	Replace cafeteria VCT	\$50,000	\$5,000-\$21,500	\$2,500-\$10,750
	Replace restroom flooring	\$40,000	\$4,000-\$17,200	\$2,000-\$8,600
	Replace sink(s)	\$27,900	\$2,800-\$11,900	\$1,395-\$5,999
	Resurface parking lot	\$83,500	\$8,400-\$35,900	\$4,175-\$17,953
	Repair/replace sections of sidewalk as necessary	\$10,400	\$1,000-\$4,400	\$520-\$2,236
2-Medium	Replace carpet	\$715,000	\$71,500-\$307,500	\$35,750-\$153,725
	Recaulk wall foundation	\$5,300	\$600-\$2,300	\$265-\$1,140
3-High	Repair upper floor movement occurring south of commons	\$9,400	\$900-\$4,000	\$470-\$2,021
	Renovate multi-use field	\$440,000	\$44,000-\$189,200	\$22,000-\$94,600
3-Medium	Vinyl coverings repair/replacement	\$4,800	\$500-\$2,000	\$240-\$1,032
4-High	Renovate areas of landscaping around school	\$15,600	\$1,500-\$6,600	\$780-\$3,354

Estimated Total Construction Costs (in 2021 Dollars): \$2,622,800 Estimated Project Management Costs Range: \$262,400 - \$1,127,700

Estimated Inflation Range: \$131,140 - \$563,902 Estimated Total Project Costs: \$3,016,340 - \$4,314,402

Tier 1 Projects Not Using 2018 Bond Funding

Project Symbol	I (STERIOTY	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
5	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.

Summary of Projects	Total Cost
2019-2020 Completed Projects	
No projects completed in 2019-20	N/A
2021 Contracted Projects	
Replace control system Upgrade fire alarm system Replace cooling tower	\$1,995,163




7370 Village Circle East Littleton, CO 80125 ThunderRidge High School Feeder Area, 3-6 Funded by 2006 Bond Opened in 2008

Site Acreage:14 Facility Square Feet: 68,751 Mobiles on-site: 0

Roxborough Intermediate School-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$724,000 Estimated Total Project Costs: \$832,900 - \$1,191,260



\$1,000,000

Following is the list of currently unfunded facility projects at Roxborough Intermediate

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Install water sensing level switches in basement ²	\$25,000	\$2,500-\$10,800	\$1,250-\$5,375
1-High	Upgrade control system ³	\$385,000	\$38,500-\$165,600	\$19,250-\$82,775
	Upgrade fire alarm system ³	\$210,000	\$21,000-\$90,300	\$10,500-\$45,150
1-Medium	Replace/repair boiler room piping as necessary ³	\$1,100	\$200-\$500	\$55-\$237
2-High	Exterior wall, recaulk control joints, reseal CMU	\$16,500	\$1,700-\$7,100	\$825-\$3,548
2-Medium	Paint exterior metal, poles, railings, and sunshades	\$5,500	\$600-\$2,400	\$275-\$1,183
2-Medium	Recaulk exterior windows	\$16,500	\$1,700-\$7,100	\$825-\$3,548
3-High	Install synthetic turf field in lieu of grass field.	\$55,000	\$5,500-\$23,700	\$2,750-\$11,825
3-Medium	Recaulk wall foundation	\$3,300	\$400-\$1,500	\$165-\$710
3-Medium	Renovate/repair areas of grass around school	\$6,100	\$600-\$2,600	\$305-\$1,312

Estimated Total Construction Costs (in 2021 Dollars): \$724,000 Estimated Project Management Costs Range: \$72,700 - \$311,600 Estimated Inflation Range: \$36,200 - \$155,660

Estimated Total Project Costs: \$832,900 - \$1,191,260

Tier 1 Projects Not Using 2018 Bond Funding

Project Symbol	Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
5	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.


Summary of Projects	Total Cost		
2019-2020 Completed Projects			
Elevator modernizations	\$3,394		
2021 Contracted Projects			
Sidewalks	\$140,000		




8000 Village Circle West Littleton, CO 80125 ThunderRidge High School Feeder Area, K-2 Funded by 1989 Bond Opened in 1991

Site Acreage: 12.4 Facility Square Feet: 53,491 Mobiles on-site: 0

Roxborough Primary School-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$2,575,600 Estimated Total Project Costs: \$2,961,780 - \$4,236,854



Following is the list of currently unfunded and to be funded with the 2018 Bond facility projects at Roxborough Primary

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
Tier 1	Replace main switchgear	\$110,000	\$11,000-\$47,300	\$5,500-\$23,650
Funded by the 2018 Bond	Replace original panels and transformers	\$110,000	\$11,000-\$47,300	\$5,500-\$23,650
	Upgrade control system ²	\$300,000	\$30,000-\$129,000	\$15,000-\$64,500
1-High	Upgrade fire alarm system ²	\$160,000	\$16,000-\$68,800	\$8,000-\$34,400
	Replace generator and associated equipment ²	\$75,000	\$7,500-\$32,300	\$3,750-\$16,125
	Replace/refinish fixed casework as necessary	\$60,000	\$6,000-\$25,800	\$3,000-\$12,900
	Exterior wall, recaulk control joints	\$3,600	\$300-\$1,500	\$180-\$774
	Exterior wall, recoat CMU, repair cracks	\$18,300	\$1,800-\$7,900	\$915-\$3,935
	Replace exterior windows	\$95,100	\$9,500-\$40,900	\$4,755-\$20,447
	Replace exterior windows	\$73,100	\$7,300-\$31,400	\$3,655-\$15,717
	Recaulk exterior windows	\$19,500	\$2,000-\$8,400	\$975-\$4,193
	Replace hollow metal doors at entry	\$9,700	\$1,000-\$4,200	\$485-\$2,086
2-High	Replace gym flooring	\$40,000	\$4,000-\$17,200	\$2,000-\$8,600
Z-Higii	Replace kitchen flooring	\$75,000	\$7,500-\$32,300	\$3,750-\$16,125
	Replace restroom flooring	\$40,000	\$4,000-\$17,200	\$2,000-\$8,600
	Replace gym flooring	\$28,800	\$2,900-\$12,400	\$1,440-\$6,192
	Replace lavatory faucets	\$12,000	\$1,200-\$5,200	\$600-\$2,580
	Resurface asphalt bus loop	\$50,000	\$5,000-\$21,500	\$2,500-\$10,750
	Resurface parking lot	\$638,000	\$63,800-\$274,400	\$31,900-\$137,170
	Repair/replace sidewalk(s)	\$10,400	\$1,000-\$4,400	\$520-\$2,236
	Repair/resurface playground as necessary	\$101,500	\$10,100-\$43,600	\$5,075-\$21,823
2-Medium	Replace carpet	\$350,000	\$35,000-\$150,500	\$17,500-\$75,250
3-High	Recaulk wall foundation	\$3,600	\$300-\$1,500	\$180-\$774
	Refinish interior doors	\$19,100	\$1,900-\$8,200	\$955-\$4,107
3-Medium	Vinyl coverings repair/replacement	\$7,300	\$700-\$3,100	\$365-\$1,570
4-Medium	Repair drainage issues	\$165,600	\$16,600-\$71,200	\$8,280-\$35,604

Estimated Total Construction Costs (in 2021 Dollars): \$2,575,600 Estimated Project Management Costs Range: \$257,400 - \$1,107,500 Estimated Inflation Range: \$128,780 - \$553,754

Estimated Total Project Costs: \$2,961,780 - \$4,236,854

Tier 1 Projects Not Using 2018 Bond Funding

Project Symbol	Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.




805 West English Sparrow Trail Highlands Ranch, CO 80129 ThunderRidge High School Feeder Area, K-6


Funded by 1997 Bond Opened in 2001

Site Acreage:10 Facility Square Feet: 51,688 Mobiles on-site: 2

Saddle Ranch Elementary-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$444,100 Estimated Total Project Costs: \$510,705 - \$730,482



Following is the list of currently unfunded facility projects at Saddle Ranch Elementary

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
1-High	High Install water sensing level switches in basement ²		\$2,500-\$10,800	\$1,250-\$5,375
	Recaulk exterior windows	\$13,800	\$1,400-\$5,900	\$690-\$2,967
	Replace roof hatch	\$10,800	\$1,100-\$4,700	\$540-\$2,322
	Repair operable partition(s)	\$12,100	\$1,300-\$5,300	\$605-\$2,602
2-High	Replace fabricated toilet partition(s)	\$35,000	\$3,500-\$15,100	\$1,750-\$7,525
2-nigii	Replace sink countertops with single surface	\$30,000	\$3,000-\$12,900	\$1,500-\$6,450
	Replace kitchen flooring	\$75,000	\$7,500-\$32,300	\$3,750-\$16,125
	Replace gym sound system	\$10,800	\$1,100-\$4,700	\$540-\$2,322
	Repair/replace sections of sidewalk as necessary	\$25,600	\$2,500-\$10,900	\$1,280-\$5,504
	Recaulk wall foundation	\$3,600	\$300-\$1,500	\$180-\$774
3-High	Vinyl coverings repair/replacement	\$5,800	\$500-\$2,400	\$290-\$1,247
	Renovate multi-use field, resod	\$101,500	\$10,100-\$43,600	\$5,075-\$21,823
	Replace gates and dumpster enclosure	\$18,700	\$1,900-\$8,100	\$935-\$4,021
	Install new fence at playground next to basketball court	\$25,600	\$2,500-\$10,900	\$1,280-\$5,504
3-Medium	Install retaining wall(s)	\$18,000	\$1,800-\$7,700	\$900-\$3,870
	Replace top on shade structure	\$17,000	\$1,700-\$7,300	\$850-\$3,655
	Remove/replace plants	\$5,300	\$600-\$2,300	\$265-\$1,140
4-High	Renovate/repair areas of grass around school	\$6,100	\$600-\$2,600	\$305-\$1,312
4-Medium	Repair area between parking lot and main drive	\$4,400	\$500-\$1,900	\$220-\$946

Estimated Total Construction Costs (in 2021 Dollars): \$444,100 Estimated Project Management Costs Range: \$44,400 - \$190,900

Estimated Inflation Range: \$22,205 - \$95,482 Estimated Total Project Costs: \$510,705 - \$730,482

Tier 1 Projects Not Using 2018 Bond Funding

Project	Category	Category Definition
Symbol	3 ,	C 7
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.

Summary of Projects	Total Cost		
2019-2020 Completed Projects			
Replace chiller and cooling tower Replace generator and associated equipment Recaulk exterior wall control joints. Reseal CMU and repair stress cracks Fix storefront window and hallway skylight leaks Upgrade fire alarm system Resurface art room countertops and replace FRP behind sinks Replace irrigation controllers and sprinkler heads Replace ballasted with fully adhered roof Recplace door hardware, install restricted key system Furniture	\$2,197,857		
2021 Contracted Projects			
No projects contracted for 2021	N/A		




2420 Autumn Sage Street Castle Rock, CO 80104 Mountain Vista High School Feeder Area, K-6


Funded by 2006 Bond Opened in 2010

Site Acreage:10 Facility Square Feet: 73,146 Mobiles on-site: 2

Sage Canyon Elementary-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$585,000 Estimated Total Project Costs: \$672,750 - \$962,375



Following is the list of currently unfunded facility projects at Sage Canyon Elementary

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
1-High	Install water sensing level switches in basement crawl spaces ²	\$25,000	\$2,500-\$10,800	\$1,250-\$5,375
	Upgrade fire alarm system ²	\$210,000	\$21,000-\$90,300	\$10,500-\$45,150
1-Medium	Upgrade control system ²	\$350,000	\$35,000-\$150,500	\$17,500-\$75,250

Estimated Total Construction Costs (in 2021 Dollars): \$585,000 Estimated Project Management Costs Range: \$58,500 - \$251,600

Estimated Inflation Range: \$29,250 - \$125,775 Estimated Total Project Costs: \$672,750 - \$962,375

Tier 1 Projects Not Using 2018 Bond Funding

Project Symbol	Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
5	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.


Summary of Projects	Total Cost		
2019-2020 Completed Projects			
Elevator modernization	\$3,169		
2021 Contracted Projects			
No projects contracted for 2021	N/A		




4725 Fox Sparrow Drive Parker, CO 80134 Ponderosa High School Feeder Area, 6-8 Funded by 1995 Bond Opened in 1997

Site Acreage: 23.3 Facility Square Feet: 127,951 Mobiles on-site: 0

Sagewood Middle School-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$1,600,700 Estimated Total Project Costs: \$1,840,935 - \$2,633,451



Following is the list of currently unfunded facility projects at Sagewood Middle

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
1-High	Install water sensing level switches in basement ²	\$25,000	\$2,500-\$10,800	\$1,250-\$5,375
i-mign	Chilled Water Systems. Replace chiller ²	\$300,000	\$30,000-\$129,000	\$15,000-\$64,500
1-Medium	Overhaul elevator(s) ²	\$125,000	\$12,500-\$53,800	\$6,250-\$26,875
1-Medium	Replace boiler(s) ²	\$300,000	\$30,000-\$129,000	\$15,000-\$64,500
	Recaulk exterior windows	\$24,500	\$2,400-\$10,500	\$1,225-\$5,268
	Repair fixed wall(s)	\$1,300	\$100-\$500	\$65-\$280
	Replace fabricated toilet partition(s)	\$45,000	\$4,500-\$19,400	\$2,250-\$9,675
2-High	Replace sink countertops with single surface	\$30,000	\$3,000-\$12,900	\$1,500-\$6,450
2-nign	Resurface asphalt bus loop	\$75,000	\$7,500-\$32,300	\$3,750-\$16,125
	Resurface parking lot	\$88,000	\$8,800-\$37,900	\$4,400-\$18,920
	Repair/replace areas of curb as needed	\$83,500	\$8,400-\$35,900	\$4,175-\$17,953
	Repair/replace sidewalk(s)	\$9,800	\$1,000-\$4,200	\$490-\$2,107
3-High	Top dress and reseed multipurpose field	\$20,600	\$2,100-\$8,900	\$1,030-\$4,429
	Install and repair fencing	\$19,500	\$2,000-\$8,400	\$975-\$4,193
3-Medium	Repair retaining wall(s)	\$7,000	\$700-\$3,000	\$350-\$1,505
3-Medium	Renovate softball infield	\$74,200	\$7,400-\$31,900	\$3,710-\$15,953
	Replace football and soccer goal posts	\$306,500	\$30,700-\$131,800	\$15,325-\$65,898
4-High	Renovate/repair areas of grass around school	\$11,000	\$1,100-\$4,800	\$550-\$2,365
4 Madium	Plant trees around ballfields	\$18,700	\$1,900-\$8,100	\$935-\$4,021
4-Medium	Install landscaping around ballfields	\$36,100	\$3,600-\$15,500	\$1,805-\$7,762

Estimated Total Construction Costs (in 2021 Dollars): \$1,600,700 Estimated Project Management Costs Range: \$160,200 - \$688,600 Estimated Inflation Range: \$80,035 - \$344,151

Estimated Total Project Costs: \$1,840,935 - \$2,633,451

Tier 1 Projects Not Using 2018 Bond Funding

Project Symbol	Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.

Summary of Projects	Total Cost		
2019-2020 Completed Projects			
Repair/replace cooling tower Upgrade control system Replace generator and associated equipment Recaulk exterior wall joints and repair cracks Repair/replace gym bleachers Replace ballasted with fully adhered roof. Replace insulation and flashing Repair/replace flooring Replace skylights Replace unrestricted with restricted key system Upgrade irrigation system Furniture	\$2,268,223		
2021 Contracted Projects			
No projects contracted for 2021	N/A		




8898 South Maplewood Drive Highlands Ranch, CO 80126 Mountain Vista High School Feeder Area, K-6


Funded by 1984 Bond Opened in 1986

Site Acreage: 11.1 Facility Square Feet: 53,237 Mobiles on-site: 3

Sand Creek Elementary-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$1,667,600 Estimated Total Project Costs: \$1,917,680 - \$2,742,934



Following is the list of currently unfunded facility projects at Sand Creek Elementary

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Replace ballasted roof with fully adhered ¹	\$750,000	\$75,000-\$322,500	\$37,500-\$161,250
1-High	Replace domestic water heater and associated piping ¹	\$92,800	\$9,300-\$39,900	\$4,640-\$19,952
	Evaluate and replace branch wiring as needed ²	\$100,000	\$10,000-\$43,000	\$5,000-\$21,500
	Replace exterior windows	\$73,100	\$7,300-\$31,400	\$3,655-\$15,717
	Recaulk exterior windows	\$19,500	\$2,000-\$8,400	\$975-\$4,193
	Refurbish/replace retractable partitions	\$18,700	\$1,900-\$8,100	\$935-\$4,021
2 High	Replace hallway/classroom flooring	\$4,800	\$500-\$2,000	\$240-\$1,032
2-High	Replace carpet	\$330,000	\$33,000-\$141,900	\$16,500-\$70,950
	Replace fixed casework	\$60,000	\$6,000-\$25,800	\$3,000-\$12,900
	Resurface asphalt bus loop	\$50,000	\$5,000-\$21,500	\$2,500-\$10,750
	Resurface parking lot	\$88,000	\$8,800-\$37,900	\$4,400-\$18,920
	Recaulk wall foundation	\$3,600	\$300-\$1,500	\$180-\$774
	Refinish interior doors	\$46,500	\$4,600-\$19,900	\$2,325-\$9,998
3-High	Replace blinds as necessary	\$2,700	\$300-\$1,100	\$135-\$581
	Replace wooden basketball backboards in gym	\$10,400	\$1,000-\$4,400	\$520-\$2,236
	Replace health room beds	\$12,800	\$1,300-\$5,500	\$640-\$2,752
4-High	Renovate/repair areas of grass around school	\$4,700	\$400-\$2,000	\$235-\$1,011

Estimated Total Construction Costs (in 2021 Dollars): \$1,667,600 Estimated Project Management Costs Range: \$166,700 - \$716,800 Estimated Inflation Range: \$83,380 - \$358,534

Estimated Total Project Costs: \$1,917,680 - \$2,742,934

Tier 1 Projects Not Using 2018 Bond Funding

Project Symbol	L Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
5	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.

Summary of Projects	Total Cost
2019-2020 Completed Projects	
Replace rooftop units	\$282,802
2021 Contracted Projects	
Upgrade control system Replace generator and associated equipment Recaulk exterior wall control joints, repair cracking at front wall Replace toilet partitions Upgrade fire alarm system Replace kitchen flooring Replace original panels and transformers Replace sinks with single surface countertop Replace main switchgear	\$3,525,440




5449 North Huxtable Street Sedalia, CO 80135 Castle View High School Feeder Area, K-6


Funded prior to 1952 Opened in 1952

Site Acreage:5 Facility Square Feet: 35,177 Mobiles on-site: 0

Sedalia Elementary-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$2,624,200 Estimated Total Project Costs: \$3,017,410 - \$4,316,303



Following is the list of currently unfunded and to be funded with the 2018 Bond facility projects at Sedalia Elementary

Tier & Priority Class	Y I Project Description		Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Replace fully adhered roof sections F,G,H,J	\$150,000	\$15,000-\$64,500	\$7,500-\$32,250
	Replace existing built up roof, sections A,C,E	\$100,000	\$10,000-\$43,000	\$5,000-\$21,500
	Replace ballasted roof with fully adhered, section B	\$100,000	\$10,000-\$43,000	\$5,000-\$21,500
	Soffits need repaired along the older classrooms wing	\$12,900	\$1,300-\$5,600	\$645-\$2,774
- : 1	Replace roof top units	\$500,000	\$50,000-\$215,000	\$25,000-\$107,500
Tier 1 Funded by the	Upgrade to VAV reheat system (air distribution)	\$382,000	\$38,200-\$164,200	\$19,100-\$82,130
2018 Bond	Replace unit heaters at entries	\$44,000	\$4,400-\$19,000	\$2,200-\$9,460
2010 00110	Upgrade control system	\$220,000	\$22,000-\$94,600	\$11,000-\$47,300
	Commission if upgrades to current system made	\$59,600	\$5,900-\$25,500	\$2,980-\$12,814
	Replace original panels and transformers	\$5,800	\$500-\$2,400	\$290-\$1,247
	Install new generator and associated systems	\$75,000	\$7,500-\$32,300	\$3,750-\$16,125
	Replace pea gravel play area. Install new basketball hoops	\$122,600	\$12,200-\$52,700	\$6,130-\$26,359
	Exterior wall, recaulk control joints	\$3,600	\$300-\$1,500	\$180-\$774
	Exterior wall, repair cracks and deterioration in stucco	\$17,000	\$1,700-\$7,300	\$850-\$3,655
	Replace exterior windows	\$42,500	\$4,300-\$18,300	\$2,125-\$9,138
	Recaulk exterior windows	\$14,700	\$1,400-\$6,300	\$735-\$3,161
2-High	Replace sink countertop(s)	\$12,400	\$1,200-\$5,300	\$620-\$2,666
	Replace hallway/classroom flooring	\$11,500	\$1,100-\$4,900	\$575-\$2,473
	Replace restroom flooring	\$30,700	\$3,100-\$13,200	\$1,535-\$6,601
	Asphalt work and drainage-parking lot	\$169,100	\$16,900-\$72,700	\$8,455-\$36,357
	Repair/replace sidewalk(s)	\$15,600	\$1,500-\$6,600	\$780-\$3,354
2-Medium	Replace carpet	\$300,000	\$30,000-\$129,000	\$15,000-\$64,500
3-High	Recaulk wall foundation	\$2,500	\$200-\$1,000	\$125-\$538
	Vinyl coverings repair/replacement	\$19,100	\$1,900-\$8,200	\$955-\$4,107
3-Medium	Replace ceiling grid and tile	\$171,600	\$17,200-\$73,800	\$8,580-\$36,894
	Replace two light poles	\$18,700	\$1,900-\$8,100	\$935-\$4,021
4-High	Site drainage on east side of school needs addressed	\$23,300	\$2,300-\$9,900	\$1,165-\$5,010

Estimated Total Construction Costs (in 2021 Dollars): \$2,624,200 Estimated Project Management Costs Range: \$262,000 - \$1,127,900 Estimated Inflation Range: \$131,210 - \$564,203

Estimated Total Project Costs: \$3,017,410 - \$4,316,303


Summary of Projects	Total Cost	
2019-2020 Completed Projects		
Replace unrestricted with restricted key system Flooring Playgrounds	\$278,043	
2021 Contracted Projects		
No projects contracted for 2021	N/A	




6651 Pine Lane Avenue Parker, CO 80134 Chaparral High School Feeder Area, 7-8 Funded by 1974 Bond Opened in 1975

Site Acreage:50 Facility Square Feet: 115,538 Mobiles on-site: 1

Sierra Middle School-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$1,853,600 Estimated Total Project Costs: \$2,131,980 - \$3,049,124



Following is the list of currently unfunded and to be funded with the 2018 Bond facility projects at Sierra Middle

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
Tier 1 Funded by the 2018 Bond	Upgrade irrigation system	\$9,800	\$1,000-\$4,200	\$490-\$2,107
	Green metal and trim need painted	\$20,600	\$2,100-\$8,900	\$1,030-\$4,429
	Recaulk exterior windows	\$15,600	\$1,500-\$6,600	\$780-\$3,354
	Repair fixed wall(s)	\$1,100	\$200-\$500	\$55-\$237
	Refurbish/replace retractable partitions	\$25,600	\$2,500-\$10,900	\$1,280-\$5,504
	Replace sink countertop(s)	\$29,500	\$3,000-\$12,700	\$1,475-\$6,343
2-High	Replace fixed casework	\$150,000	\$15,000-\$64,500	\$7,500-\$32,250
	Resurface asphalt bus loop	\$75,000	\$7,500-\$32,300	\$3,750-\$16,125
	Resurface parking lot	\$81,900	\$8,200-\$35,200	\$4,095-\$17,609
	Repair/replace sections of sidewalk as necessary	\$5,500	\$600-\$2,400	\$275-\$1,183
	Replace playground play pads	\$30,700	\$3,100-\$13,200	\$1,535-\$6,601
	Paint site light poles	\$9,700	\$1,000-\$4,200	\$485-\$2,086
2-Medium	Replace restroom flooring	\$50,000	\$5,000-\$21,500	\$2,500-\$10,750
	Recaulk wall foundation	\$20,600	\$2,100-\$8,900	\$1,030-\$4,429
	Recaulk wall foundation	\$3,600	\$300-\$1,500	\$180-\$774
3-High	Replace interior door(s)	\$76,700	\$7,700-\$33,000	\$3,835-\$16,491
3-nigii	Rebuild greenhouse on south side of building	\$148,300	\$14,900-\$63,800	\$7,415-\$31,885
	Renovate multi-use field(s)	\$81,900	\$8,200-\$35,200	\$4,095-\$17,609
	Renovate football field	\$81,900	\$8,200-\$35,200	\$4,095-\$17,609
	Paint interior	\$153,300	\$15,300-\$65,900	\$7,665-\$32,960
	Fire sprinkle building	\$612,700	\$61,300-\$263,500	\$30,635-\$131,731
3-Medium	Repair retaining wall(s)	\$7,000	\$700-\$3,000	\$350-\$1,505
5-Medium	Resurface track.	\$30,700	\$3,100-\$13,200	\$1,535-\$6,601
	Replace goal posts with multi-function goals	\$95,100	\$9,500-\$40,900	\$4,755-\$20,447
	Replace outside basketball hoops if warranted	\$30,700	\$3,100-\$13,200	\$1,535-\$6,601
4-High	Renovate/repair areas of grass around school	\$6,100	\$600-\$2,600	\$305-\$1,312

Estimated Total Construction Costs (in 2021 Dollars): \$1,853,600 Estimated Project Management Costs Range: \$185,700 - \$797,000 Estimated Inflation Range: \$92,680 - \$398,524

Estimated Total Project Costs: \$2,131,980 - \$3,049,124


Summary of Projects	Total Cost
2019-2020 Completed Projects	
Replace cafeteria, classroom, restroom, and hallway flooring Replace unrestricted with restricted key system	\$1,094,417
2021 Contracted Projects	
Upgrade control system Replace rooftop units Replace generator and associated equipment Repair/seal cracks in exterior wall brick Replace toilet partitions Replace fully adhered roof sections Repair and paint downspouts Replace gas meter and associated piping	\$6,538,016




4665 Tanglevine Drive Castle Rock, CO 80109 Castle View High School Feeder Area, K-6 Funded by 2000 Bond Opened in 2004

Site Acreage:11 Facility Square Feet: 56,868 Mobiles on-site: 3

Soaring Hawk Elementary-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$1,248,200 Estimated Total Project Costs: \$1,435,510 - \$2,053,463



Following is the list of currently unfunded facility projects at Soaring Hawk Elementary

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
1-High	Install water sensing level switches in basement ²	\$25,000	\$2,500-\$10,800	\$1,250-\$5,375
rangn	Replace generator and associated equipment ²	\$75,000	\$7,500-\$32,300	\$3,750-\$16,125
2-High	Exterior wall, reseal CMU	\$12,800	\$1,300-\$5,500	\$640-\$2,752
2-High	Recaulk exterior windows	\$15,300	\$1,600-\$6,600	\$765-\$3,290
	Replace restroom flooring	\$40,000	\$4,000-\$17,200	\$2,000-\$8,600
	Replace gym carpet	\$40,000	\$4,000-\$17,200	\$2,000-\$8,600
2-Medium	Repair cafeteria VCT	\$20,000	\$2,000-\$8,600	\$1,000-\$4,300
	Replace carpet	\$350,000	\$35,000-\$150,500	\$17,500-\$75,250
	Resurface parking lot	\$663,900	\$66,400-\$285,500	\$33,195-\$142,739
3-Medium	Vinyl coverings repair/replacement	\$6,200	\$600-\$2,700	\$310-\$1,333

Estimated Total Construction Costs (in 2021 Dollars): \$1,248,200 Estimated Project Management Costs Range: \$124,900 - \$536,900 Estimated Inflation Range: \$62,410 - \$268,363

Estimated Total Project Costs: \$1,435,510 - \$2,053,463

Tier 1 Projects Not Using 2018 Bond Funding

Project Symbol	Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
5	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.


Summary of Projects	Total Cost	
2019-2020 Completed Projects		
Upgrade control system Recaulk exterior wall control joints Upgrade fire alarm system Replace ballasted with fully adhered roof	\$1,201,775	
2021 Contracted Projects		
No projects contracted for 2021	N/A	




1100 South Street Castle Rock, CO 80104 Douglas County High School Feeder Area, K-6 Funded by 1970 Bond Opened in 1972

Site Acreage: 8.9 Facility Square Feet: 52,287 Mobiles on-site: 4

South Ridge Elementary-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$1,489,200 Estimated Total Project Costs: \$1,712,660 - \$2,449,578



Following is the list of currently unfunded facility projects at South Ridge Elementary

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
1-High	Upgrade fire alarm system ¹	\$150,000	\$15,000-\$64,500	\$7,500-\$32,250
I-Medium	Replace main switchgear ¹	\$100,000	\$10,000-\$43,000	\$5,000-\$21,500
	Replace original panels and transformers ¹	\$100,000	\$10,000-\$43,000	\$5,000-\$21,500

Estimated Total Construction Costs (in 2021 Dollars): \$1,489,200 Estimated Project Management Costs Range: \$149,000 - \$640,200 Estimated Inflation Range: \$74,460 - \$320,178

Estimated Total Project Costs: \$1,712,660 - \$2,449,578

Tier 1 Projects Not Using 2018 Bond Funding

Project Symbol	Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
5	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.

Summary of Projects	Total Cost	
2019-2020 Completed Projects		
Upgrade control system Replace roof top units Replace generator and associated equipment Recaulk exterior wall control joints Recaulk windows Replace toilet partitions Replace original casework Replace restroom flooring Repair gutters and downspouts Replace/refinish interior doors and door frames Replace unrestricted with restricted key system Replace irrigation system. Install seperate irrigation meter Replace original panels and transformers Refurbish/replace classroom partitions in East wing Replace soffit Replace ballasted with fully adhered roof and roof finishes Refinish exterior doors Repair/replace entry storefronts Furniture	\$3,615,639	
2021 Contracted Projects		
No projects contracted for 2021	N/A	

South Ridge Elementary cont.

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Replace sound panels in music room	\$6,600	\$700-\$2,900	\$330-\$1,419
	Resurface asphalt bus loop	\$100,000	\$10,000-\$43,000	\$5,000-\$21,500
2-High	Resurface parking lot	\$61,400	\$6,200-\$26,400	\$3,070-\$13,201
	Repair/replace sidewalk(s)	\$5,500	\$600-\$2,400	\$275-\$1,183
	Replace asphalt playground	\$81,900	\$8,200-\$35,200	\$4,095-\$17,609
2-Medium	Repair/replace sidewalk(s)	\$5,500	\$600-\$2,400	\$275-\$1,183
	Repair rusting columns at gym	\$10,400	\$1,000-\$4,400	\$520-\$2,236
	Refinish all fixed walls	\$20,600	\$2,100-\$8,900	\$1,030-\$4,429
	Replace sound panels in music room and gym	\$27,900	\$2,800-\$11,900	\$1,395-\$5,999
	Replace/repair suspended ceiling	\$137,500	\$13,800-\$59,200	\$6,875-\$29,563
3-High	Replace hallway tack boards	\$25,300	\$2,600-\$10,900	\$1,265-\$5,440
	Repair/replace all fencing around school perimeter	\$25,600	\$2,500-\$10,900	\$1,280-\$5,504
	Repair fencing between parking lot and playground	\$84,600	\$8,500-\$36,400	\$4,230-\$18,189
	Renovate play field and other site improvements	\$46,100	\$4,600-\$19,900	\$2,305-\$9,912
	Install new synthetic turf for multi-use field	\$25,600	\$2,500-\$10,900	\$1,280-\$5,504
	Vinyl coverings repair/replacement	\$6,200	\$600-\$2,700	\$310-\$1,333
	Replace entry way floor tile	\$18,000	\$1,800-\$7,700	\$900-\$3,870
3-Medium	Fire sprinkle building	\$408,500	\$40,800-\$175,600	\$20,425-\$87,828
	Repair drainage issues, add retaining walls	\$18,700	\$1,900-\$8,100	\$935-\$4,021
	Repair/replace field backstop fencing	\$4,900	\$500-\$2,100	\$245-\$1,054
4 High	Recaulk wall foundation	\$5,800	\$500-\$2,400	\$290-\$1,247
4-High	Improve site landscape features	\$12,600	\$1,200-\$5,400	\$630-\$2,709

172


This page left intentionally blank




10625 Weathersfield Way Highlands Ranch, CO 80130 ThunderRidge High School Feeder Area, K-6 Funded by 2006 Bond Opened in 2007

Site Acreage:10 Facility Square Feet: 73,146 Mobiles on-site: 0

Stone Mountain Elementary-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$755,400 Estimated Total Project Costs: \$868,870 - \$1,242,811



Following is the list of currently unfunded facility projects at Stone Mountain Elementary

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Install water sensing level switches in basement crawl spaces ²	\$25,000	\$2,500-\$10,800	\$1,250-\$5,375
1-High	Upgrade control system ³	\$385,000	\$38,500-\$165,600	\$19,250-\$82,775
	Repair lighting on stairs to crawlspace ³	\$300	\$-\$100	\$15-\$65
	Upgrade fire alarm system ³	\$210,000	\$21,000-\$90,300	\$10,500-\$45,150
2-High	Exterior wall, recaulk expansion joints, reseal CMU	\$16,500	\$1,700-\$7,100	\$825-\$3,548
	Paint exterior metal, poles, railings, and sunshades	\$5,500	\$600-\$2,400	\$275-\$1,183
2-Medium	Recaulk exterior windows	\$16,500	\$1,700-\$7,100	\$825-\$3,548
	Repair/replace sidewalk(s)	\$56,400	\$5,600-\$24,200	\$2,820-\$12,126
3-High	Replace synthetic play field	\$30,700	\$3,100-\$13,200	\$1,535-\$6,601
3-Medium	Recaulk wall foundation	\$3,300	\$400-\$1,500	\$165-\$710
3-wealum	Renovate/repair areas of grass around school	\$6,200	\$600-\$2,700	\$310-\$1,333

Estimated Total Construction Costs (in 2021 Dollars): \$755,400 Estimated Project Management Costs Range: \$75,700 - \$325,000

Estimated Inflation Range: \$37,770 - \$162,411 Estimated Total Project Costs: \$868,870 - \$1,242,811

Tier 1 Projects Not Using 2018 Bond Funding

Project Symbol	Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
5	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.


Summary of Projects	Total Cost	
2019-2020 Completed Projects		
Elevator modernization	\$3,169	
2021 Contracted Projects		
No projects contracted for 2021	N/A	




10200 South Piedmont Way Highlands Ranch, CO 80126 Mountain Vista High School Feeder Area, K-6 Funded by Certificate of Participation Opened in 1992

Site Acreage:10 Facility Square Feet: 56,475 Mobiles on-site: 3

Summit View Elementary-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$1,540,000 Estimated Total Project Costs: \$1,771,100 - \$2,533,400



Following is the list of currently unfunded facility projects at Summit View Elementary

Tier & Priority Class	Project Description	Estimated Construction	Potential Regulatory, Professional Services,	Potential Inflation Costs
Oluss		Cost-2021	and Contracting Costs	
	Upgrade control system ²	\$300,000	\$30,000-\$129,000	\$15,000-\$64,500
1-High	Replace main switchgear ²	\$100,000	\$10,000-\$43,000	\$5,000-\$21,500
1-riigii	Replace original panels and transformers ¹	\$110,000	\$11,000-\$47,300	\$5,500-\$23,650
	Upgrade fire alarm system ¹	\$195,000	\$19,500-\$83,900	\$9,750-\$41,925
	Replace exterior windows	\$73,100	\$7,300-\$31,400	\$3,655-\$15,717
	Recaulk exterior windows	\$19,500	\$2,000-\$8,400	\$975-\$4,193
	Replace fabricated toilet partition(s)	\$35,000	\$3,500-\$15,100	\$1,750-\$7,525
	Replace restroom flooring	\$1,900	\$200-\$800	\$95-\$409
2-High	Replace fixtures in staff restrooms	\$2,800	\$300-\$1,200	\$140-\$602
	Replace sink fixtures in staff restrooms	\$1,900	\$200-\$800	\$95-\$409
	Reattach supports for gas line on roof. Replace piping	\$2,000	\$200-\$900	\$100-\$430
	Repair/replace sidewalk(s)	\$5,500	\$600-\$2,400	\$275-\$1,183
	Repair/resurface playground as necessary	\$81,900	\$8,200-\$35,200	\$4,095-\$17,609
	Replace carpet	\$350,000	\$35,000-\$150,500	\$17,500-\$75,250
2-Medium	Replace/repair suspended ceiling	\$165,000	\$16,500-\$71,000	\$8,250-\$35,475
2-Medium	Replace/refinish fixed casework as necessary	\$60,000	\$6,000-\$25,800	\$3,000-\$12,900
	Repair concrete service drive and cracks in asphalt lot	\$19,500	\$2,000-\$8,400	\$975-\$4,193
3-High	Recaulk wall foundation	\$3,500	\$300-\$1,400	\$175-\$753
4 High	Renovate/repair areas of grass around school	\$11,000	\$1,100-\$4,800	\$550-\$2,365
4-High	Replace metal edging with concrete mow strip	\$2,400	\$200-\$1,000	\$120-\$516

Estimated Total Construction Costs (in 2021 Dollars): \$1,540,000 Estimated Project Management Costs Range: \$154,100 - \$662,300 Estimated Inflation Range: \$77,000 - \$331,100

Estimated Total Project Costs: \$1,771,100 - \$2,533,400

Tier 1 Projects Not Using 2018 Bond Funding

Project Symbol	Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
5	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.


·	
Summary of Projects	Total Cost
2019-2020 Completed Projects	
No projects completed in 2019-20	N/A
2021 Contracted Projects	
Replace sealtite conduit and wiring to roof equipment Replace generator and associated equipment Recaulk exterior wall control joints Replace cafeteria and kitchen flooring Repair partitions between classrooms and between gym and cafeteria Replace sink countertops Replace/repair boiler room wiring	\$523,085




1991 Wildcat Reserve Parkway Highlands Ranch, CO 801296 ThunderRidge High School Feeder Area, 9-12 Funded by 1993 Bond Opened in 1996

Site Acreage: 50 Facility Square Feet: 240,640 Mobiles on-site: 1

ThunderRidge High School-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$1,725,600 Estimated Total Project Costs: \$1,984,480 - \$2,838,304



\$1,000,000

Following is the list of currently unfunded and to be funded with the 2018 Bond facility projects at ThunderRidge High

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
Tier 1 Funded by the 2018 Bond	Upgrade irrigation system	\$30,700	\$3,100-\$13,200	\$1,535-\$6,601
1-High	Replace boiler(s) ²	\$400,000	\$40,000-\$172,000	\$20,000-\$86,000
1-Medium	Replace main switchgear ²	\$100,000	\$10,000-\$43,000	\$5,000-\$21,500
	Replace original panels and transformers ²	\$100,000	\$10,000-\$43,000	\$5,000-\$21,500

Estimated Total Construction Costs (in 2021 Dollars): \$1,725,600 Estimated Project Management Costs Range: \$172,600 - \$741,700 Estimated Inflation Range: \$86,280 - \$371,004

Estimated Total Project Costs: \$1,984,480 - \$2,838,304

Tier 1 Projects Not Using 2018 Bond Funding

Project Symbol	Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
5	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.

Summary of Projects	Total Cost	
2019-2020 Completed Projects		
Update air distribution system Upgrade change over distribution system Replace rooftop units Replace generator and associated equipment. Repair generator cabinet Replace flooring in kitchen, cafeteria, main and pod hallways, classrooms, commons, and entry areas Replace toilet partitions Replace main gym bleachers Upgrade glycol distribution system Renovate elevator Replace roof sections with solar Replace sink counter tops	\$3,937,526	
2021 Contracted Projects		
No projects contracted for 2021	N/A	

ThunderRidge High cont.

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Exterior wall, recaulk expansion joints, reseal CMU	\$58,500	\$5,800-\$25,100	\$2,925-\$12,578
	Recaulk exterior windows	\$73,100	\$7,300-\$31,400	\$3,655-\$15,717
	Fix exterior window(s) leakage	\$76,700	\$7,700-\$33,000	\$3,835-\$16,491
	Replace commons storefront windows	\$29,900	\$2,900-\$12,800	\$1,495-\$6,429
	Replace (4) four rollup doors	\$18,700	\$1,900-\$8,100	\$935-\$4,021
2-High	Replace interior door(s)	\$3,600	\$300-\$1,500	\$180-\$774
2-nigii	Replace sink countertop(s)	\$61,200	\$6,100-\$26,300	\$3,060-\$13,158
	Upgrade/replace showers	\$12,000	\$1,200-\$5,200	\$600-\$2,580
	Replace stage curtains and ~100 seats in auditorium	\$18,600	\$1,900-\$8,000	\$930-\$3,999
	Upgrade theater lighting and sound systems.	\$100,000	\$10,000-\$43,000	\$5,000-\$21,500
	Repair/replace asphalt walks to athletic fields	\$4,800	\$500-\$2,000	\$240-\$1,032
	Repair/replace sidewalk(s)	\$30,700	\$3,100-\$13,200	\$1,535-\$6,601
	Replace/refinish fixed casework as necessary	\$200,000	\$20,000-\$86,000	\$10,000-\$43,000
2-Medium	Improve traffic flow at both schools	\$9,800	\$1,000-\$4,200	\$490-\$2,107
	Resurface asphalt parking lot, upper level	\$57,200	\$5,800-\$24,600	\$2,860-\$12,298
3-High	Recaulk wall foundation	\$9,800	\$1,000-\$4,200	\$490-\$2,107
3-Medium	Replace/repair suspended ceiling	\$9,000	\$900-\$3,800	\$450-\$1,935
5-iviedium	Fire sprinkle building with renovation	\$278,000	\$27,800-\$119,500	\$13,900-\$59,770
4-High	Paint parking lot poles	\$33,900	\$3,400-\$14,600	\$1,695-\$7,289
4-Medium	Repair hillside in front of snack shack	\$9,400	\$900-\$4,000	\$470-\$2,021


This page left intentionally blank




690 West Castle Pines Parkway Castle Pines, CO 80108 Rock Canyon High School Feeder Area, K-5 Funded by 2000 Bond Opened in 2003

Site Acreage: 6.98 Facility Square Feet: 56,868 Mobiles on-site: 0

Timber Trail Elementary-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021Dollars): \$784,200 Estimated Total Project Costs: \$901,810- \$1,289,803



Following is the list of currently unfunded facility projects at Timber Trail Elementary

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
1-High	Install water sensing level switches in basement ²	\$25,000	\$2,500-\$10,800	\$1,250-\$5,375
	Paint exterior trim, windows and doors	\$9,400	\$900-\$4,000	\$470-\$2,021
	Recaulk exterior windows	\$15,400	\$1,600-\$6,700	\$770-\$3,311
	Replace window wall frames	\$46,500	\$4,600-\$19,900	\$2,325-\$9,998
	Recaulk exterior door frames	\$1,100	\$200-\$500	\$55-\$237
2-High	Replace fabricated toilet partitions	\$35,000	\$3,500-\$15,100	\$1,750-\$7,525
2-nigii	Replace sink countertops with single surface	\$30,000	\$3,000-\$12,900	\$1,500-\$6,450
	Replace sink(s)	\$14,000	\$1,400-\$6,000	\$700-\$3,010
	Resurface asphalt bus loop	\$50,000	\$5,000-\$21,500	\$2,500-\$10,750
	Resurface parking lot	\$81,900	\$8,200-\$35,200	\$4,095-\$17,609
	Repair/replace sidewalk(s)	\$10,400	\$1,000-\$4,400	\$520-\$2,236
	Replace cafeteria VCT	\$20,000	\$2,000-\$8,600	\$1,000-\$4,300
	Replace restroom flooring	\$40,000	\$4,000-\$17,200	\$2,000-\$8,600
2-Medium	Replace gym carpet with sport flooring	\$40,000	\$4,000-\$17,200	\$2,000-\$8,600
	Replace gym carpet	\$15,100	\$1,500-\$6,500	\$755-\$3,247
	Replace carpet	\$330,000	\$33,000-\$141,900	\$16,500-\$70,950
3-High	Mitigate building movement, flooring and walls cracks	\$4,800	\$500-\$2,000	\$240-\$1,032
	Recaulk wall foundation	\$3,600	\$300-\$1,500	\$180-\$774
	Renovate multi-use field(s)	\$8,500	\$900-\$3,700	\$425-\$1,828
3-Medium	Vinyl coverings repair/replacement	\$3,500	\$300-\$1,400	\$175-\$753

Estimated Total Construction Costs (in 2021 Dollars): \$784,200 Estimated Project Management Costs Range: \$78,400 - \$337,000 Estimated Inflation Range: \$39,210 - \$168,603

Estimated Total Project Costs: \$901,810 - \$1,289,803

Tier 1 Projects Not Using 2018 Bond Funding

Project Symbol	Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
5	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.


Summary of Projects	Total Cost		
2019-2020 Completed Projects			
Replace ballasted with fully adhered roof	N/A		
2021 Contracted Projects	1477		
Upgrade control system Upgrade fire alarm system Replace generator and associated equipment Recaulk control joints, patch cracks and water seal (CMU) exterior wall	\$1,370,105		




9760 South Hackberry Highlands Ranch, CO 80129 ThunderRidge High School Feeder Area, K-6 Funded by DC Developers Trust Fund Opened in 1997

Site Acreage:10 Facility Square Feet: 51,020 Mobiles on-site: 1

Trailblazer Elementary-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$797,400 Estimated Total Project Costs: \$917,170 - \$1,311,741



Following is the list of currently unfunded and to be funded with the 2018 Bond facility projects at Trailblazer Elementary

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
Tier 1 Funded by the 2018 Bond	Upgrade irrigation system	\$4,900	\$500-\$2,100	\$245-\$1,054
	Recaulk exterior windows	\$15,300	\$1,600-\$6,600	\$765-\$3,290
	Repair/replace storefront windows	\$8,500	\$900-\$3,700	\$425-\$1,828
	Refurbish/replace retractable partitions	\$17,000	\$1,700-\$7,300	\$850-\$3,655
2-High	Replace cafeteria VCT	\$20,000	\$2,000-\$8,600	\$1,000-\$4,300
2-nigii	Replace kitchen flooring	\$75,000	\$7,500-\$32,300	\$3,750-\$16,125
	Resurface asphalt bus loop	\$50,000	\$5,000-\$21,500	\$2,500-\$10,750
	Repair/replace sections of sidewalk as necessary	\$25,600	\$2,500-\$10,900	\$1,280-\$5,504
	Replace, overlay playpad(s)	\$14,800	\$1,500-\$6,300	\$740-\$3,182
3-High	Repair cracks SE corner of gym, corner of building	\$12,900	\$1,300-\$5,600	\$645-\$2,774
	Vinyl coverings repair/replacement	\$8,500	\$900-\$3,700	\$425-\$1,828
3-Medium	Replace/repair suspended ceiling	\$6,900	\$700-\$2,900	\$345-\$1,484
	Bypass grease interceptor	\$8,500	\$900-\$3,700	\$425-\$1,828
	Install sprinkler system if remodeled	\$428,500	\$42,800-\$184,200	\$21,425-\$92,128
	Fix drainage issue on north end of playground	\$101,000	\$10,100-\$43,500	\$5,050-\$21,715

Estimated Total Construction Costs (in 2021 Dollars): \$797,400 Estimated Project Management Costs Range: \$79,900 - \$342,900 Estimated Inflation Range: \$39,870 - \$171,441

Estimated Total Project Costs: \$917,170 - \$1,311,741


Summary of Projects	Total Cost	
2019-2020 Completed Projects		
Upgrade control system Replace roof top units Upgrade backflow (water supply equipment) Replace generator and associated equipment Replace/upgrade kitchen hood exhaust Recaulk exterior wall control joints and reseal stress cracks Replace toilet partitions Replace cafeteria and gym flooring Replace ballasted with fully adhered roof	\$2,278,453	
2021 Contracted Projects		
No projects contracted for 2021	N/A	



6585 Lionshead Parkway Littleton, CO 80124 Rock Canyon High School Feeder Area, K-5 Funded by 1997 Bond Opened in 1998


Site Acreage:10 Facility Square Feet: 51,676 Mobiles on-site: 2

Wildcat Mountain Elementary-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



\$1,000,000

Estimated Total Construction Costs (in 2021 Dollars): \$959,100 Estimated Total Project Costs: \$1,102,955 - \$1,577,807



Following is the list of currently unfunded facility projects at Wildcat Mountain Elementary

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Install water sensing level switches in basement ²	\$25,000	\$2,500-\$10,800	\$1,250-\$5,375
1-High	Replace boiler(s) ²	\$250,000	\$25,000-\$107,500	\$12,500-\$53,750
	Chilled Water Systems. Replace chiller ¹	\$300,000	\$30,000-\$129,000	\$15,000-\$64,500
	Repair leakage at skylights	\$5,800	\$500-\$2,400	\$290-\$1,247
	Repair operable partition(s)	\$12,100	\$1,300-\$5,300	\$605-\$2,602
	Replace fabricated toilet partition(s)	\$35,000	\$3,500-\$15,100	\$1,750-\$7,525
2-High	Replace cafeteria VCT	\$20,000	\$2,000-\$8,600	\$1,000-\$4,300
	Replace hallway/classroom flooring	\$10,300	\$1,000-\$4,400	Potential Inflation Costs 2
	Replace kitchen flooring	\$75,000	\$7,500-\$32,300	
	Repair/replace sections of sidewalk as necessary	\$2,400	\$200-\$1,000	\$120-\$516
2-Medium	Resurface and crack fill asphalt and overlay parking lot	\$22,900	\$2,300-\$9,900	\$1,145-\$4,924
3-High	Recaulk wall foundation	\$3,500	\$300-\$1,400	\$175-\$753
	Vinyl coverings repair/replacement	\$17,000	\$1,700-\$7,300	\$1,250-\$5,375 \$12,500-\$53,750 \$15,000-\$64,500 \$290-\$1,247 \$605-\$2,602 \$1,750-\$7,525 \$1,000-\$4,300 \$515-\$2,215 \$3,750-\$16,125 \$120-\$516 \$1,145-\$4,924 \$175-\$753 \$850-\$3,655 \$8,580-\$36,894
3-Medium	Repair ceiling	\$171,600	\$17,200-\$73,800	\$8,580-\$36,894
	Bypass grease interceptor	\$8,500	\$900-\$3,700	\$425-\$1,828

Estimated Total Construction Costs (in 2021 Dollars): \$959,100 Estimated Project Management Costs Range: \$95,900 - \$412,500 Estimated Inflation Range: \$47,955 - \$206,207

Estimated Total Project Costs: \$1,102,955 - \$1,577,807

Tier 1 Projects Not Using 2018 Bond Funding

Project Symbol	Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.

Summary of Projects	Total Cost			
2019-2020 Completed Projects				
Repair air distribution system Rebuild/replace cooling tower Replace generator and associated equipment Recaulk exterior wall control joints, seal and repair CMU and stress cracks Recaulk windows, seal and maintain major gaps Replace cafeteria flooring Replace unrestricted with restricted key system Repair storefront entrance	\$795,802			
2021 Contracted Projects				
No projects contracted for 2021	N/A			



312 Cantril Street Castle Rock, CO 80104 Administration/District Offices and Preschool Facility Constructed in 1897

Cantril Building-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$1,926,600 Estimated Total Project Costs: \$2,216,030 - \$3,169,219

Following is the list of currently unfunded facility projects at the Cantril facility

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Replace shingled roof ⁵	\$200,000	\$20,000-\$86,000	\$10,000-\$43,000
	Replace EPDM gym roof ⁵	\$75,000	\$7,500-\$32,300	\$3,750-\$16,125
	Replace EPDM roof on pre-school addition ⁵	\$75,000	\$7,500-\$32,300	\$3,750-\$16,125
	Restoration of roof eaves and soffits ⁵	\$24,500	\$2,400-\$10,500	\$1,225-\$5,268
	Replace gutters, downspouts, reconfigure down spouts ⁵	\$8,000	\$800-\$3,400	\$400-\$1,720
	Replace roof top units ²	\$200,000	\$20,000-\$86,000	\$10,000-\$43,000
	Repair steam distribution system ⁵	\$55,000	\$5,500-\$23,700	\$2,750-\$11,825
	Add hot water distribution to fan coil, heat exchanger ⁵	\$69,800	\$7,000-\$30,000	\$3,490-\$15,007
1-High	Install new window AC units 5	\$4,900	\$500-\$2,100	\$245-\$1,054
	Improve steam distribution system ⁵	\$24,500	\$2,400-\$10,500	\$10,000-\$43,000 \$3,750-\$16,125 \$3,750-\$16,125 \$1,225-\$5,268 \$400-\$1,720 \$10,000-\$43,000 \$2,750-\$11,825 \$3,490-\$15,007
	Add new DDC controls with new HVAC 5	\$266,500	\$26,600-\$114,500	
	Upgrade branch wiring and devices to current code 5	\$24,500	\$2,400-\$10,500	\$1,225-\$5,268
	Upgrade electrical wiring to current code PS 5	\$4,900	\$500-\$2,100	\$3,750-\$16,125 \$3,750-\$16,125 \$1,225-\$5,268 \$400-\$1,720 \$10,000-\$43,000 \$2,750-\$11,825 \$3,490-\$15,007 \$245-\$1,054 \$1,225-\$5,268 \$13,325-\$57,298 \$1,225-\$5,268 \$245-\$1,054 \$155-\$667 \$135-\$581 \$245-\$1,054
	Replace incandescent lighting fixtures as necessary ⁵	\$3,100	\$300-\$1,400	
	Replace old incandescent fixtures in hallways PS ⁵	\$2,700	\$300-\$1,100	\$135-\$581
	Install new clock system ⁵	\$4,900	\$500-\$2,100	\$245-\$1,054
	Repair/replace sanitary sewer system piping ⁵	\$10,400	\$1,000-\$4,400	\$520-\$2,236
1-Medium	Add LED emergency/exit lighting ⁵	\$6,000	\$600-\$2,600	\$300-\$1,290
1-Wediuili	Add LED emergency/exit lighting PS 5	\$4,000	\$400-\$1,800	\$200-\$860

Estimated Total Construction Costs (in 2021 Dollars): \$1,926,600 Estimated Project Management Costs Range: \$193,100 - \$828,400 Estimated Inflation Range: \$96,330 - \$414,219

Estimated Total Project Costs: \$2,216,030 - \$3,169,219

Tier 1 Projects Not Using 2018 Bond Funding

Project Symbol	Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
5	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.

Cantril Building cont.


Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Exterior wall, repair, painting of stucco	\$4,000	\$400-\$1,700	\$200-\$860
	Exterior wall, re-point all stone masonry, repair chimneys	\$24,500	\$2,400-\$10,500	\$1,225-\$5,268
	Paint all exterior wood after restoration	\$9,800	\$1,000-\$4,200	\$490-\$2,107
	Replace exterior windows	\$218,900	\$21,900-\$94,200	\$10,945-\$47,064
	Restoration of two front entrances	\$3,100	\$300-\$1,400	\$155-\$667
	Replace north entry storefront	\$4,900	\$500-\$2,100	\$245-\$1,054
	Refinish interior window frames	\$1,100	\$200-\$500	\$55-\$237
	Replace approx 50% of doors. Sand and refinish rest of doors (historic)	\$9,800	\$1,000-\$4,200	\$490-\$2,107
	Refinish interior doors PS	\$4,900	\$500-\$2,100	\$245-\$1,054
	Refinish interior door frames PS	\$4,900	\$500-\$2,100	\$245-\$1,054
	Restore or replace (historic) partitions on lower level	\$7,300	\$700-\$3,100	\$365-\$1,570
	Refurbish or replace toilet partitions in boys preschool restroom PS	\$2,200	\$300-\$1,000	\$110-\$473
	Refurbish storage shelving and lockers	\$1,100	\$200-\$500	\$55-\$237
	Replace sink countertop(s)	\$2,900	\$300-\$1,200	\$145-\$624
	Repair multiple cracks in plaster walls	\$4,900	\$500-\$2,100	\$245-\$1,054
	Replace hallway/classroom flooring	\$9,800	\$1,000-\$4,200	\$490-\$2,107
2-High	Replace restoom flooring. Currently all 3 restrooms have vinyl tile	\$12,000	\$1,200-\$5,200	\$600-\$2,580
	Replace vinyl in all restrooms, includes abatement PS	\$5,000	\$500-\$2,200	\$250-\$1,075
	Replace carpet	\$2,000	\$200-\$900	\$100-\$430
	Repair cracked plaster ceiling in foyer area, stage, and stage hallways, repaint. Clean and restain wood ceiling in gym	\$14,700	\$1,400-\$6,300	\$735-\$3,161
	Repair cracked plaster ceiling in foyer area, stage, and stage hallways, repaint. Clean and restain wood ceiling in gym	\$9,800	\$1,000-\$4,200	\$490-\$2,107
	Replace/remove tiles in hallway, potential abatement	\$2,700	\$300-\$1,100	\$135-\$581
	Upgrade lavatories	\$2,700	\$300-\$1,100	\$135-\$581
	Replace older sinks in restrooms	\$2,900	\$300-\$1,200	\$145-\$624
	Replace sinks at preschool hall and boys restroom (2) PS	\$1,700	\$200-\$700	\$85-\$366
	Evaluate restroom waste piping	\$600	\$100-\$200	\$30-\$129
	Theatre & stage equipment, replace folding stage curtain	\$30,700	\$3,100-\$13,200	\$1,535-\$6,601
	Refinish existing storage cupboards and cabinets	\$77,000	\$7,700-\$33,200	\$3,850-\$16,555
	Replace sidewalk at SE entry, fix drainage issues	\$12,800	\$1,300-\$5,500	\$640-\$2,752
	Replace section of sidewalk at south preschool room. Fix trip hazard at north entry landing PS	\$5,300	\$600-\$2,300	\$265-\$1,140
2-Medium	Repair hallway/classroom flooring	\$24,500	\$2,400-\$10,500	\$1,225-\$5,268
2-Medium	Add site lighting controls	\$12,000	\$1,200-\$5,200	\$600-\$2,580
	Recaulk wall foundation	\$4,100	\$400-\$1,800	\$205-\$882
	Repair buckling at men's restroom floor	\$10,800	\$1,100-\$4,700	\$540-\$2,322
	Recoat garage flooring	\$4,900	\$500-\$2,100	\$245-\$1,054
2.111.1	Refinish interior door frames	\$9,800	\$1,000-\$4,200	\$490-\$2,107
3-High	Restoration of 2 sets of outside metal stairs	\$3,100	\$300-\$1,400	\$155-\$667
	Replace casework in classrooms, sink in preschool PS	\$66,000	\$6,600-\$28,400	\$3,300-\$14,190
	Replace blinds as necessary	\$17,500	\$1,800-\$7,600	\$875-\$3,763
	Repair chain link fencing around front perimeter	\$12,800	\$1,300-\$5,500	\$640-\$2,752
	Paint interior	\$18,000	\$1,800-\$7,700	\$900-\$3,870
	Paint interior	\$7,400	\$800-\$3,200	\$370-\$1,591
3-Medium	Sand and refinish wood wainscoating	\$24,500	\$2,400-\$10,500	\$1,225-\$5,268
	Install sprinkler system	\$97,500	\$9,800-\$41,900	\$4,875-\$20,963
	Install sprinkler service and standpipe	\$39,000	\$3,900-\$16,700	\$1,950-\$8,385
3-Low	IRe-install glass windows on hallway walls	\$6,000	\$600-\$2,500	\$300-\$1,290
3 2311	Re-landscape area in front of building	\$11,000	\$1,100-\$4,800	\$550-\$2,365

This page left intentionally blank



2842 Front Street Castle Rock, CO 80104 DCSD Stadium

Douglas County Schools Stadium-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$394,400 Estimated Total Project Costs: \$453,620 - \$648,796

Following is the list of currently unfunded facility projects at Douglas County Schools Stadium

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
1-High	Replace roof ⁵	\$60,000	\$6,000-\$25,800	\$3,000-\$12,900
1-High	Upgrade fire alarm system ⁵	\$30,000	\$3,000-\$12,900	\$1,500-\$6,450
2-High	Repair/replace sidewalk(s)	\$84,600	\$8,500-\$36,400	\$3,000-\$12,900
2-nigii	Replace bleachers, concrete supporting system	\$74,200	\$7,400-\$31,900	\$3,710-\$15,953
3-High	Replace band lockers	\$9,800	\$1,000-\$4,200	\$490-\$2,107
3-riigii	Repair/replace sections of fence around site	\$41,600	\$4,200-\$17,900	\$2,080-\$8,944
3-Medium	Caulk areas where ceiling meets CMU	\$2,400	\$200-\$1,000	\$120-\$516
5-Medium	Install retaining wall(s)	\$84,600	\$8,500-\$36,400	\$4,230-\$18,189
3-Low	Install concrete mow strip, crusher fines around track	\$2,000	\$200-\$900	\$100-\$430
4-High	Renovate immediate stadium area with new landscaping	\$5,200	\$500-\$2,200	\$260-\$1,118

Estimated Total Construction Costs (in 2021 Dollars): \$394,400 Estimated Project Management Costs Range: \$39,500 - \$169,600 Estimated Inflation Range: \$19,720 - \$84,796

Estimated Total Project Costs: \$453,620 - \$648,796

Tier 1 Projects Not Using 2018 Bond Funding


Project Symbol	Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.

Summary of Projects	Total Cost		
2019-2020 Completed Projects			
Stadium lighting	\$160,160		
2021 Contracted Projects			
No projects contracted for 2021	N/A		



3950 Trail Boss Lane Castle Rock, CO 80104 Early Childhood Center

Early Childhood Center-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$130,400 Estimated Total Project Costs: \$149,920 - \$214,436

Following is the list of currently unfunded facility projects at the Early Childhood Center-South facility

	Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	1-High	Upgrade fire alarm system ²	\$120,000	\$12,000-\$51,600	\$6,000-\$25,800
Γ	2-Medium	Resurface parking lot	\$10,400	\$1,000-\$4,400	\$520-\$2,236

Estimated Total Construction Costs (in 2021 Dollars): \$130,400 Estimated Project Management Costs Range: \$13,000 - \$56,000 Estimated Inflation Range: \$6,520 - \$28,036

Estimated Total Project Costs: \$149,920 - \$214,436


Tier 1 Projects Not Using 2018 Bond Funding

	,	3
Project Symbol	Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
5	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.



11901 Newlin Gulch Blvd. Parker, CO 80134 DCSD Stadium Funded by 2006 Bond Opened in 2009

EchoPark Stadium-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority




Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	— No capital projects identified at this time — capital has been summarized on the	•		

Summary of Projects	Total Cost	
2019-2020 Completed Projects		
Bleachers Structural	\$126,259	
2021 Contracted Projects		
No projects contracted for 2021	N/A	



9195 East Mineral Avenue Centennial, CO 80112 DCSD Fleet and Bus Service Center

Joint Service Center-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$1,197,800 Estimated Total Project Costs: \$1,377,290 - \$1,970,327

Following is the list of currently unfunded facility projects at the Joint Service Center

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Install new roof over admin and garage areas ⁵	\$110,300	\$11,100-\$47,500	\$5,515-\$23,715
1-High	Garage exhaust fans upgrade/insulation 5	\$2,700	\$300-\$1,100	\$135-\$581
1-riigii	Replace MAU for garage with DX heating and cooling unit 5	\$88,000	\$8,800-\$37,900	\$4,400-\$18,920
	Upgrade fire alarm system ⁵	\$70,000	\$7,000-\$30,100	\$3,500-\$15,050
1-Medium	Repair concrete bollards protecting bus heater outlets 5	\$59,600	\$5,900-\$25,500	\$2,980-\$12,814
	Exterior wall, recaulk expansion joints, reseal CMU	\$4,900	\$500-\$2,100	\$245-\$1,054
	Repair garage doors, repair controls	\$4,900	\$500-\$2,100	\$245-\$1,054
	Replace sink countertop(s)	\$2,600	\$200-\$1,100	\$130-\$559
	Replace hallway/classroom flooring	\$4,100	\$400-\$1,800	\$205-\$882
	Replace restroom flooring	\$8,000	\$800-\$3,400	\$400-\$1,720
2-High	Replace wash fountain at garage area	\$3,100	\$300-\$1,400	\$155-\$667
2g	Water drains into used oil holding area. Mitigate water flow into pit	\$408,500	\$40,800-\$175,600	\$20,425-\$87,828
	Repair areas of concrete parking area	\$6,100	\$600-\$2,600	\$305-\$1,312
	Improve lot drainage in front of admin entrance	\$151,400	\$15,100-\$65,100	\$7,570-\$32,551
	Repair/replace areas of curb as needed	\$225,200	\$22,500-\$96,800	\$11,260-\$48,418
	Repair/replace sections of sidewalk as necessary	\$18,700	\$1,900-\$8,100	\$935-\$4,021
2-Medium	Replace/refinish fixed casework as necessary	\$15,000	\$1,500-\$6,500	\$750-\$3,225
3-High	Repair floor (movement)	\$14,700	\$1,400-\$6,300	\$735-\$3,161

Estimated Total Construction Costs (in 2021 Dollars): \$1,197,800 Estimated Project Management Costs Range: \$119,600 - \$515,000 Estimated Inflation Range: \$59,890 - \$257,527

Estimated Total Project Costs: \$1,377,290 - \$1,970,327


Tier 1 Projects Not Using 2018 Bond Funding

	,	3
Project Symbol	Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.



3002 North State Highway 83 Franktown, CO 80116 DCSD Operations & Maintenance Facility

Operations & Maintenance East Facility-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$1,100,200 Estimated Total Project Costs: \$1,150,210 - \$1,645,143

Following is the list of currently unfunded facility projects at Operations & Maintenance East facility

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	New roof on north wood structure ⁵	\$20,000	\$2,000-\$8,600	\$1,000-\$4,300
	Replace interior door hardware as necessary ⁵	\$27,900	\$2,800-\$11,900	\$1,395-\$5,999
1-High	Replace main switchgear ²	\$82,500	\$8,300-\$35,500	\$4,125-\$17,738
	Replace branch wiring and devices ⁵	\$14,700	\$1,400-\$6,300	\$735-\$3,161
	Upgrade fire alarm system ²	\$100,000	\$10,000-\$43,000	\$5,000-\$21,500
1-Medium	Upgrade control system ²	\$100,000	\$10,000-\$43,000	\$5,000-\$21,500
1-Medium	Replace original panels and transformers ²	\$100,000	\$10,000-\$43,000	\$5,000-\$21,500
	Exterior wall, re-point areas of brick, repair cracks	\$4,900	\$500-\$2,100	\$245-\$1,054
	Caulk exterior windows	\$3,100	\$300-\$1,400	\$155-\$667
	Replace lavatory faucets	\$3,100	\$300-\$1,400	\$155-\$667
	Replace sink(s)	\$2,700	\$300-\$1,100	\$135-\$581
2-High	Replace wash fountain in shop area	\$13,200	\$1,400-\$5,700	\$660-\$2,838
	Replace water cooler(s), drinking fountain(s)	\$8,000	\$800-\$3,400	\$400-\$1,720
	Replace sections of concrete roadway around building	\$40,000	\$4,000-\$17,200	\$2,000-\$8,600
	Replace sections of concrete parking areas	\$275,000	\$27,500-\$118,300	\$13,750-\$59,125
	Repair/replace sections of sidewalk as necessary	\$25,600	\$2,500-\$10,900	\$1,280-\$5,504
2-Medium	Install curbs	\$4,900	\$500-\$2,100	\$245-\$1,054
3-High	Recaulk wall foundation	\$3,100	\$300-\$1,400	\$155-\$667
	Paint interior	\$9,800	\$1,000-\$4,200	\$490-\$2,107
3-Medium	Install sprinkler system	\$146,100	\$14,600-\$62,800	\$7,305-\$31,412
	Repair retaining wall(s)	\$15,600	\$1,500-\$6,600	\$780-\$3,354

Estimated Total Construction Costs (in 2021 Dollars): \$1,100,200 Estimated Project Management Costs Range: \$100,000 - \$429,900 Estimated Inflation Range: \$50,010-\$215,043

Estimated Total Project Costs: \$1,150,210 - \$1,645,143

Tier 1 Projects Not Using 2018 Bond Funding


Project Symbol	Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.

Summary of Projects	Total Cost	
2019-2020 Completed Projects		
Replace outisde gas piping to inside of building Replace furnace units Replace AC units	\$201,636	
2021 Contracted Projects		
No projects contracted for 2021	N/A	



2806 Highway 85, Building A Castle Rock, CO 80109 DCSD Operations & Maintenance Facility

Operations & Maintenance West Facility-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$52,800 Estimated Total Project Costs: \$60,840 - \$86,952

Following is the list of currently unfunded facility projects at the Operations & Maintenance West facility

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
1-High	Fix drainage issues at front and rear entries ⁵	\$2,700	\$300-\$1,100	\$135-\$581
1-High	Upgrade fire alarm system ⁵	\$35,000	\$3,500-\$15,100	\$1,750-\$7,525
	Paint exterior	\$8,000	\$800-\$3,400	\$400-\$1,720
	Replace exterior windows	\$2,000	\$200-\$900	\$100-\$430
2-High	Replace exterior basement windows	\$2,000	\$200-\$900	\$100-\$430
	Replace north and south entry doors	\$2,000	\$200-\$900	\$100-\$430
	Replace exterior door at NE office	\$1,100	\$200-\$500	\$55-\$237

Estimated Total Construction Costs (in 2021 Dollars): \$52,800 Estimated Project Management Costs Range: \$5,400 - \$22,800 Estimated Inflation Range: \$2,640 - \$11,352

Estimated Total Project Costs: \$60,840 - \$86,952

Tier 1 Projects Not Using 2018 Bond Funding

Project Symbol	Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
5	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.


Summary of Projects	Total Cost		
2019-2020 Completed Projects			
Replace carpet	\$13,507		
2021 Contracted Projects			
No projects contracted for 2021	N/A		



3270 Redstone Park Circle Littleton, CO 80129 DCSD Stadium

Funded by 1997 Bond Opened in 2000

Shea Stadium-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$870,800 Estimated Total Project Costs: \$1,001,540 - \$1,432,422

Following is the list of currently unfunded facility projects at Shea Stadium

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Replace domestic water heater vent pipe ⁵	\$4,000	\$400-\$1,700	\$200-\$860
1-High	Replace vent piping (air distribution) 5	\$4,000	\$400-\$1,700	\$200-\$860
i-nigii	Upgrade fire alarm system ⁵	\$25,000	\$2,500-\$10,800	\$1,250-\$5,375
	Replace generator and associated equipment 5	\$75,000	\$7,500-\$32,300	\$3,750-\$16,125
	Exterior wall, reseal and repair block walls	\$10,800	\$1,100-\$4,700	\$540-\$2,322
	Paint bleacher flooring, paint all metal	\$8,600	\$900-\$3,700	\$430-\$1,849
	Paint red steel and handrails	\$32,400	\$3,200-\$13,900	\$1,620-\$6,966
	Paint all red iron and trim	\$20,600	\$2,100-\$8,900	\$1,030-\$4,429
2-High	Replace exterior windows	\$21,600	\$2,200-\$9,300	\$1,080-\$4,644
	Replace fixed casework	\$9,200	\$900-\$3,900	\$460-\$1,978
	Resurface parking lot	\$88,000	\$8,800-\$37,900	\$4,400-\$18,920
	Repair/replace areas of curb as needed	\$408,500	\$40,800-\$175,600	\$20,425-\$87,828
	Repair/replace sections of sidewalk as necessary	\$18,700	\$1,900-\$8,100	\$935-\$4,021
	Fill foundation gaps around new classroom addition	\$88,200	\$8,800-\$37,800	\$4,410-\$18,963
3-High	Upper floor, repair water leaks at bleacher section	\$10,800	\$1,100-\$4,700	\$540-\$2,322
	Replace/repair suspended ceiling	\$700	\$100-\$300	\$35-\$151
	Paint interior	\$2,800	\$300-\$1,200	\$140-\$602
3-Medium	Repair/replace fencing around site and bleacher areas	\$39,000	\$3,900-\$16,700	\$1,950-\$8,385
	Repair retaining wall(s)	\$2,900	\$300-\$1,200	\$145-\$624

Estimated Total Construction Costs (in 2021 Dollars): \$870,800 Estimated Project Management Costs Range: \$87,200 - \$374,400 Estimated Inflation Range: \$43,540 - \$187,222

Estimated Total Project Costs: \$1,001,540 - \$1,432,422

Tier 1 Projects Not Using 2018 Bond Funding


Project Symbol	Lategory	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
5	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.

Summary of Projects	Total Cost	
2019-2020 Completed Projects		
Boiler Sound system Lighting Bleachers Site infrastructure	\$553,261	
2021 Contracted Projects		
No projects contracted for 2021	N/A	



11722 Dransfeldt Road, Building B Parker, CO 80134 **DCSD Support Services**


Student Support Center-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



\$0

\$500,000 Estimated Total Construction Costs (in 2021 Dollars): \$183,100

Estimated Total Project Costs: \$210,855 - \$301,167



\$1,000,000

Following is the list of currently unfunded facility projects at the Student Support Center

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
1-High	Replace roof. Asphalt shingle ⁵	\$20,000	\$2,000-\$8,600	\$1,000-\$4,300
1-Tilgii	Replace water baseboard heaters ⁵	\$3,100	\$300-\$1,400	\$155-\$667
1-Low	Improve ventilation in conference room (air distribution) 5	\$4,900	\$500-\$2,100	\$245-\$1,054
	Paint exterior	\$2,700	\$300-\$1,100	\$135-\$581
	Replace windows	\$8,000	\$800-\$3,400	\$400-\$1,720
	Replace restroom flooring	\$1,100	\$200-\$500	\$55-\$237
2-High	Replace carpetingge	\$4,900	\$500-\$2,100	\$245-\$1,054
	Replace sink(s)	\$1,100	\$200-\$500	\$55-\$237
	Resurface parking area	\$81,900	\$8,200-\$35,200	\$4,095-\$17,609
	Replace wooden decks front and rear	\$46,100	\$4,600-\$19,900	\$2,305-\$9,912
2-Medium	Enlarge restroom on main floor	\$4,900	\$500-\$2,100	\$245-\$1,054
2-wealum	Replace toilets (2)	\$1,700	\$200-\$700	\$85-\$366
3-Medium	Paint interior	\$2,700	\$300-\$1,100	\$135-\$581

Estimated Total Construction Costs (in 2021 Dollars): \$183,100 Estimated Project Management Costs Range: \$18,600 - \$78,700 Estimated Inflation Range: \$9,155 - \$39,367

Estimated Total Project Costs: \$210,855 - \$301,167

Tier 1 Projects Not Using 2018 Bond Funding


Project Symbol	Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.

Summary of Projects	Total Cost		
2019-2020 Completed Projects			
ADA compliance HVAC Boiler Carpet	\$110,068		
2021 Contracted Projects			
No projects contracted for 2021	N/A		



2808 Highway 85, Building B Castle Rock, CO 80109 **DCSD Transportation Terminal**

West Transportation Terminal-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$737,900 Estimated Total Project Costs: \$848,695 - \$1,213,849

Following is the list of currently unfunded facility projects at the Transportation Terminal West and Construction facility

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Replace interior door hardware as necessary ⁵	\$22,900	\$2,300-\$9,900	\$1,145-\$4,924
1-High	Replace branch wiring and devices ⁵	\$9,800	\$1,000-\$4,200	\$490-\$2,107
	Upgrade fire alarm system ⁵	\$50,000	\$5,000-\$21,500	\$2,500-\$10,750
1-Medium	Add daylighting ⁵	\$29,300	\$2,900-\$12,600	\$1,465-\$6,300
	Replace interior door(s)	\$9,800	\$1,000-\$4,200	\$490-\$2,107
	Replace fabricated toilet partition(s)	\$2,600	\$200-\$1,100	\$130-\$559
	Replace sink countertop(s)	\$1,600	\$100-\$700	\$80-\$344
2-High	Replace railing of storage area above electrical room	\$2,000	\$200-\$900	\$100-\$430
2-nigii	Replace restroom flooring	\$4,900	\$500-\$2,100	\$245-\$1,054
	Replace lavatory faucets	\$1,100	\$200-\$500	\$55-\$237
	Replace sink(s)	\$1,100	\$200-\$500	\$55-\$237
	Resurface parking lot	\$81,900	\$8,200-\$35,200	\$4,095-\$17,609
2-Medium	Pave areas of asphalt for excess parking	\$459,600	\$46,000-\$197,600	\$22,980-\$98,814
3-High	Replace interior door frames	\$4,900	\$500-\$2,100	\$245-\$1,054
3-Medium	Add site lighting to parking area	\$56,400	\$5,600-\$24,200	\$2,820-\$12,126

Estimated Total Construction Costs (in 2021 Dollars): \$737,900 Estimated Project Management Costs Range: \$73,900 - \$317,300

Estimated Inflation Range: \$36,895 - \$158,649 Estimated Total Project Costs: \$848,695 - \$1,213,849

Tier 1 Projects Not Using 2018 Bond Funding

Project Symbol	Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
5	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.

Summary of Projects	Total Cost		
2019-2020 Completed Projects			
Doors & door hardware Plumbing system & fixtures Flooring	\$282,643		
2021 Contracted Projects			
No projects contracted for 2021	N/A		



8236 Carter Court Littleton, CO 80125 **DCSD Transportation Terminal**

North Transportation Terminal-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$2,037,200 Estimated Total Project Costs: \$2,342,860 - \$3,351,198

Following is the list of currently unfunded facility projects at the Transportation Terminal North facility

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Replace roof, area D ⁵	\$60,000	\$6,000-\$25,800	\$3,000-\$12,900
	Replace facia board where necessary (eaves & soffits) 5	\$4,900	\$500-\$2,100	\$245-\$1,054
	Check roof drains for proper functionality ⁵	\$1,100	\$200-\$500	\$55-\$237
	Replace RTU's 5 total. Add split system for MDF closet ⁵	\$243,200	\$24,400-\$104,600	\$12,160-\$52,288
1-High	Replace exhaust fans ⁵	\$4,900	\$500-\$2,100	\$245-\$1,054
	Replace radiators. Replace fin tube heaters ⁵	\$4,900	\$500-\$2,100	\$245-\$1,054
	Upgrade control system ⁵	\$165,000	\$16,500-\$71,000	\$8,250-\$35,475
	Replace plastic lense diffusers on fixtures ⁵	\$4,900	\$500-\$2,100	\$245-\$1,054
	Replace natural gas service ⁵	\$2,400	\$200-\$1,000	\$120-\$516
1-Medium	Rework water entry to south pond, clean pond ⁵	\$31,000	\$3,100-\$13,300	\$1,550-\$6,665
1-Medium	Install electrical power for bus heaters ⁵	\$18,700	\$1,900-\$8,100	\$935-\$4,021

Estimated Total Construction Costs (in 2021 Dollars): \$2,037,200 Estimated Project Management Costs Range: \$203,800 - \$876,000 Estimated Inflation Range: \$101,860 - \$437,998

Estimated Total Project Costs: \$2,342,860 - \$3,351,198

Tier 1 Projects Not Using 2018 Bond Funding

Project Symbol	Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.

	3		
Summary of Projects	Total Cost		
2019-2020 Completed Projects			
Install new boiler Replace fire alarm system North transportation fuel tank	\$384,378		
2021 Contracted Projects			
No projects contracted for 2021	N/A		


Transportation Terminal North Facility cont.

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Exterior wall, repair/repoint CMU and brick	\$9,800	\$1,000-\$4,200	\$490-\$2,107
	Replace exterior windows	\$48,700	\$4,800-\$20,900	\$2,435-\$10,471
	Replace exterior doors	\$20,600	\$2,100-\$8,900	\$1,030-\$4,429
	Replace interior door(s)	\$21,600	\$2,200-\$9,300	\$1,080-\$4,644
	Install carpet over gym tile	\$14,700	\$1,400-\$6,300	\$735-\$3,161
2-High	Replace gym flooring	\$48,700	\$4,800-\$20,900	\$2,435-\$10,471
2-nigii	Replace carpet	\$125,400	\$12,500-\$53,900	\$6,270-\$26,961
	Piping and fittings need to be checked for replacement	\$1,100	\$200-\$500	\$55-\$237
	Replace fixed casework	\$15,000	\$1,500-\$6,500	\$750-\$3,225
	Resurface parking lot	\$630,800	\$63,100-\$271,200	\$31,540-\$135,622
	Repair/replace sidewalk(s)	\$9,400	\$900-\$4,000	\$470-\$2,021
	Repair/replace sidewalk(s)	\$9,800	\$1,000-\$4,200	\$490-\$2,107
	Replace gym flooring	\$44,200	\$4,500-\$19,100	\$2,210-\$9,503
2-Medium	Install carpet over gym tile	\$13,300	\$1,400-\$5,800	\$665-\$2,860
	Install asphalt for bus and employee parking	\$81,900	\$8,200-\$35,200	\$4,095-\$17,609
	Sand and refinish/paint interior windows	\$4,900	\$500-\$2,100	\$245-\$1,054
	Replace interior door jambs as necessary	\$8,000	\$800-\$3,400	\$400-\$1,720
3-High	Replace/repair suspended ceiling	\$11,400	\$1,100-\$4,900	\$570-\$2,451
3-High	Remove old ceiling tiles and refinish	\$43,900	\$4,400-\$18,900	\$2,195-\$9,439
	Replace blinds as necessary	\$4,700	\$400-\$2,000	\$235-\$1,011
	Install curb and gutter	\$194,700	\$19,500-\$83,800	\$9,735-\$41,861
3-Medium	Repair retaining wall(s)	\$3,600	\$300-\$1,500	\$180-\$774
3-Wedium	Add site lighting to parking	\$12,000	\$1,200-\$5,200	\$600-\$2,580
3-Low	Install markee sign at front entry	\$35,900	\$3,600-\$15,400	\$1,795-\$7,719
4-High	Remove dirt pile at north end of east parking lot	\$61,800	\$6,100-\$26,500	\$3,090-\$13,287
4-Medium	Install ornamental landscaping, replace dead trees	\$10,400	\$1,000-\$4,400	\$520-\$2,236
4-weulum	Trim cottonwood trees on canal	\$9,900	\$1,000-\$4,300	\$495-\$2,129

This page left intentionally blank

2812 Highway 85, Building E Castle Rock, CO 80109 Administration/District Offices Facility

Warehouse Service Center-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$476,900 Estimated Total Project Costs: \$548,645 - \$784,734

\$1,000,000

Following is the list of currently unfunded facility projects at Nutrition Services/Warehouse/Security facility

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Replace ballasted roof with fully adhered ⁵	\$96,000	\$9,600-\$41,300	\$4,800-\$20,640
	Apply roof coating to metal roof of warehouse ⁵	\$20,000	\$2,000-\$8,600	\$1,000-\$4,300
	Replace Whirlpool unit for warehouse offices ⁵	\$33,000	\$3,300-\$14,200	\$1,650-\$7,095
1-High	Replace split system for print room ⁵	\$55,000	\$5,500-\$23,700	\$2,750-\$11,825
	Replace outdoor AC unit closest to rear entry door ⁵	\$7,700	\$800-\$3,400	\$385-\$1,656
	Replace current control system 5	\$165,000	\$16,500-\$71,000	\$8,250-\$35,475
	Upgrade fire alarm system ²	\$60,000	\$6,000-\$25,800	\$3,000-\$12,900
	Exterior wall, reseal CMU	\$4,900	\$500-\$2,100	\$245-\$1,054
	Paint exterior	\$11,800	\$1,200-\$5,100	\$590-\$2,537
2-High	Replace hallway/classroom flooring	\$700	\$100-\$300	\$35-\$151
	Replace kitchen flooring	\$2,700	\$300-\$1,100	\$135-\$581
	Replace restroom flooring	\$1,100	\$200-\$500	\$55-\$237
2-Medium	Replace carpet	\$11,000	\$1,100-\$4,800	\$550-\$2,365
3-Medium	Paint interior	\$8,000	\$800-\$3,400	\$400-\$1,720

Estimated Total Construction Costs (in 2021 Dollars): \$476,900 Estimated Project Management Costs Range: \$47,900 - \$205,300 Estimated Inflation Range: \$23,845 - \$102,534

Estimated Total Project Costs: \$548,645 - \$784,734

Tier 1 Projects Not Using 2018 Bond Funding

Project Symbol	Latenory	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
5	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.


Completed and Contracted Projects Using 2018 Bond Funding

Summary of Projects	Total Cost	
2019-2020 Completed Projects		
HVAC	\$97,804	
2021 Contracted Projects		
No projects contracted for 2021	N/A	



701 Prairie Hawk Drive Castle Rock, CO 80109 Administration/District Offices Facility

West Support Center-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$320,600 Estimated Total Project Costs: \$368,830 - \$527,529

Following is the list of currently unfunded facility projects at the West Support Center facility

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Apply roof coating to metal roof to extend life ⁵	\$75,000	\$7,500-\$32,300	\$3,750-\$16,125
1-High	Flashings & Trim. Needs-Replace roof cap ⁵	\$3,100	\$300-\$1,400	\$155-\$667
1-High	Replace fiberglass translucent panels (glazed roof) 5	\$17,600	\$1,800-\$7,600	\$880-\$3,784
	Upgrade fire alarm system ²	\$120,000	\$12,000-\$51,600	\$6,000-\$25,800
2-High	Replace or insulate garage doors east side warehouse	\$4,900	\$500-\$2,100	\$245-\$1,054
2-riigii	Resurface parking lot	\$90,200	\$9,100-\$38,800	\$4,510-\$19,393
2-Medium	Exterior wall, improve insulation	\$9,800	\$1,000-\$4,200	\$490-\$2,107

Estimated Total Construction Costs (in 2021 Dollars): \$320,600 Estimated Project Management Costs Range: \$32,200 - \$138,000 Estimated Inflation Range: \$16,030 - \$68,929

Estimated Total Project Costs: \$368,830 - \$527,529

Tier 1 Projects Not Using 2018 Bond Funding

Project Symbol	Lategory	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
5	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.


Completed and Contracted Projects Using 2018 Bond Funding

Summary of Projects	Total Cost		
2019-2020 Completed Projects			
Asphalt & sidewalks Site infrastructure	\$238,056		
2021 Contracted Projects			
No projects contracted for 2021	N/A		



620 Wilcox Street Castle Rock, CO 80104 Administration/District Offices Facility

Wilcox Building-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$2,3462,900 Estimated Total Project Costs: \$2,694,345 - \$3,854,224

Following is the list of currently unfunded facility projects at the Wilcox facility

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Replace shingles on original building areas A,B,C,D ⁵	\$125,000	\$12,500-\$53,800	\$6,250-\$26,875
	Re-coat roof at main section ⁵	\$51,000	\$5,100-\$22,000	\$2,550-\$10,965
	Flashings and Trim. Needs-Paint roof flashings ⁵	\$2,700	\$300-\$1,100	\$135-\$581
	Paint gutters and downspouts ⁵	\$2,700	\$300-\$1,100	\$135-\$581
	Replace carpet ⁵	\$11,900	\$1,200-\$5,100	\$595-\$2,559
1-High	Overhaul elevator(s) ⁵	\$330,000	\$33,000-\$141,900	\$16,500-\$70,950
1-High	Replace roof top units ⁵	\$100,000	\$10,000-\$43,000	\$5,000-\$21,500
	Reset ceiling unit heater at front entrance 5	\$500	\$0-\$200	\$25-\$108
	Replace main switchgear ⁵	\$29,300	\$2,900-\$12,600	\$1,465-\$6,300
	Evaluate and replace branch wiring as needed ²	\$100,000	\$10,000-\$43,000	\$5,000-\$21,500
	Upgrade fire alarm system ⁵	\$120,000	\$12,000-\$51,600	\$6,000-\$25,800
	Replace generator and associated equipment ⁵	\$75,000	\$7,500-\$32,300	\$3,750-\$16,125
1-Medium	Replace current non-restricted key system with restricted 5	\$37,100	\$3,700-\$16,000	\$1,855-\$7,977
1-wealum	Install new intercom system for building ⁵	\$48,700	\$4,800-\$20,900	\$2,435-\$10,471

Estimated Total Construction Costs (in 2021 Dollars): \$2,342,900 Estimated Project Management Costs Range: \$234,300 - \$1,007,600 Estimated Inflation Range: \$117,145 - \$503,724

Estimated Total Project Costs: \$2,694,345 - \$3,854,224

Tier 1 Projects Not Using 2018 Bond Funding

Project Symbol	Category Category	Category Definition
1	Year 5 Project	The Master Capital Plan is a 5 year outlook. The 2018 Bond funds amounted to financing only four years of needs.
2	Newly Assessed Since 2018 Bond	The building component was assessed in 2020 and added after the Bond package was created.
3	Not Identified as Bond Funded in 2019-20 MCP	Tier 1 projects that were identified as not to be funded by the 2018 Bond in the 2019-20 Master Capital Plan due to the age of the facility.
4	Replacement Determined As Not Needed Upon Inspection	Upon inspection, the component was in good working order and determined not to need replacement at this time.
5	Determined Low Priority for Bond Funding. Monies Reallocated to School Projects.	Some Tier 1 components at support facilities included in the Bond were determined to be a lower priority than new urgent Tier 1 and 2 needs at schools not included in the Bond. These project funds were reallocated to these urgent school projects.

Completed and Contracted Projects Using 2018 Bond Funding

Summary of Projects	Total Cost	
2019-2020 Completed Projects		
Board of Education room audio/visual system Admin office repairs Electrical system HVAC	\$161,973	
2021 Contracted Projects		
No projects contracted for 2021	N/A	


Wilcox Building cont.

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Replace exterior windows	\$7,400	\$800-\$3,200	\$370-\$1,591
	Replace kitchen flooring	\$2,000	\$200-\$900	\$100-\$430
2-High	Replace carpet	\$146,100	\$14,600-\$62,800	\$7,305-\$31,412
	Resurface parking lot	\$50,500	\$5,100-\$21,800	\$2,525-\$10,858
	Repair/replace areas of curb as needed	\$292,000	\$29,200-\$125,500	\$14,600-\$62,780
2-Medium	Restain wood ceiling 2nd floor north (old gym)	\$9,800	\$1,000-\$4,200	\$490-\$2,107
	Recoat foundation walls on east side	\$2,700	\$300-\$1,100	\$135-\$581
3-High	Replace/repair suspended ceiling	\$1,100	\$200-\$500	\$55-\$237
	Re-attach blinds to wall in Board Rm	\$185,400	\$18,500-\$79,700	\$9,270-\$39,861
	Paint interior	\$48,700	\$4,800-\$20,900	\$2,435-\$10,471
3-Medium	Install sprinkler system for entire building	\$194,700	\$19,500-\$83,800	\$9,735-\$41,861
	Clean brick and stone entry barriers	\$204,300	\$20,400-\$87,900	\$10,215-\$43,925
4-High	Renovate/repair areas of grass around school	\$11,000	\$1,100-\$4,800	\$550-\$2,365
4-Medium	Paint lighting poles	\$153,300	\$15,300-\$65,900	\$7,665-\$32,960

This page left intentionally blank



Athletics-Identified Items Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$1,057,500 Estimated Total Project Costs: \$1,216,280 - \$1,739,780

Following is the list of currently unfunded athletics facility projects

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
2-Medium	EchoPark Automotive Stadium-Resurface track	\$528,750	\$528,750-\$227,450	\$26,440-\$113,690
2-Low	DCHS Stadium-Resurface track	\$528,750	\$528,750-\$227,450	\$26,440-\$113,690


Estimated Total Construction Costs (in 2021 Dollars): \$1,057,500 Estimated Project Management Costs Range: \$105,900-\$454,900 Estimated Inflation Range: \$52,880 - \$227,380

Estimated Total Project Costs: \$1,216,280 - \$1,739,780

Completed and Contracted Projects Using 2018 Bond Funding

Summary of Projects	Total Cost
2019-2020 Completed Projects	
DC Stadium turf Echo Park Stadium turf Castle View High School track ThunderRidge High School tennis courts Chaparral High School tennis courts Legend High School turf field	\$2,706,990
2021 Contracted Projects	
Legend High School track Legend High School tennis courts Mountain Vista High School track Castle View High School tennis courts	\$2,535,000

Furniture, Fixtures, and Equipment-Identified Items Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$6,785,000 Estimated Total Project Costs: \$7,802,750 - \$11,161,380

Following is the list of currently unfunded furniture, fixture, and equipment needs


Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Arrowwood ES-Replace classroom furniture	\$200,000	\$20,000-\$86,000	\$10,000-\$43,000
	Bear Canyon ES-Replace classroom furniture	\$200,000	\$20,000-\$86,000	\$10,000-\$43,000
	Buffalo Ridge ES-Replace classroom furniture	\$200,000	\$20,000-\$86,000	\$10,000-\$43,000
	Chaparral HS-Replace classroom furniture	\$400,000	\$40,000-\$172,000	\$20,000-\$86,000
	Cougar Run ES-Replace classroom furniture	\$200,000	\$20,000-\$86,000	\$10,000-\$43,000
	Coyote Creek ES-Replace classroom furniture	\$200,000	\$20,000-\$86,000	\$10,000-\$43,000
	Cresthill MS-Replace classroom furniture	\$300,000	\$30,000-\$129,000	\$15,000-\$64,500
	Eagle Ridge ES-Replace classroom furniture	\$200,000	\$20,000-\$86,000	\$10,000-\$43,000
	Eldorado ES-Replace classroom furniture	\$200,000	\$20,000-\$86,000	\$10,000-\$43,000
	Fox Creek ES-Replace classroom furniture	\$200,000	\$20,000-\$86,000	\$10,000-\$43,000
	Franktown ES-Replace classroom furniture	\$200,000	\$20,000-\$86,000	\$10,000-\$43,000
	Heritage ES-Replace classroom furniture	\$200,000	\$20,000-\$86,000	\$10,000-\$43,000
	Mountain Ridge MS-Replace classroom furniture with 21st century learning furniture	\$300,000	\$30,000-\$129,000	\$15,000-\$64,500
3-Medium	Mountain Vista HS-Replace classroom furniture	\$400,000	\$40,000-\$172,000	\$20,000-\$86,000
	Northridge ES-Replace classroom furniture	\$70,000	\$7,000-\$30,100	\$3,500-\$15,050
	Pine Grove ES-Replace classroom furniture	\$200,000	\$20,000-\$86,000	\$10,000-\$43,000
	Pine Lane ES-Replace classroom furniture	\$400,000	\$40,000-\$172,000	\$20,000-\$86,000
	Prairie Crossing ES-Replace classroom furniture	\$200,000	\$20,000-\$86,000	\$10,000-\$43,000
	Rocky Heights MS-Replace classroom furniture with 21st century learning furniture	\$300,000	\$30,000-\$129,000	\$15,000-\$64,500
	Roxborough Primary-Replace classroom furniture	\$200,000	\$20,000-\$86,000	\$10,000-\$43,000
	Sand Creek ES-Replace classroom furniture	\$200,000	\$20,000-\$86,000	\$10,000-\$43,000
	Sedalia ES-Replace classroom furniture	\$90,000	\$9,000-\$38,700	\$4,500-\$19,350
	Sierra MS-Replace classroom furniture	\$300,000	\$30,000-\$129,000	\$15,000-\$64,500
	ThunderRidge HS-Replace classroom furniture	\$400,000	\$40,000-\$172,000	\$20,000-\$86,000
	Timber Trail ES-Replace furniture with 21st century learning furniture	\$200,000	\$20,000-\$86,000	\$10,000-\$43,000
	Trailblazer ES-Replace classroom furniture	\$200,000	\$20,000-\$86,000	\$10,000-\$43,000
	DC Oakes HS/District Media Center-Replace furniture with 21st century learning furniture	\$25,000	\$2,500-\$10,800	\$1,250-\$5,380
3-Low	Rock Canyon HS-Replace furniture with 21st century learning furniture	\$400,000	\$40,000-\$172,000	\$20,000-\$86,000
	Soaring Hawk ES-Replace furniture with 21st century learning furniture	\$200,000	\$20,000-\$86,000	\$10,000-\$43,000

Estimated Total Construction Costs (in 2021 Dollars): \$6,785,000 Estimated Project Management Costs Range: \$678,500 - \$2,917,600 Estimated Inflation Range: \$339,250 - \$1,458,780

Estimated Total Project Costs: \$7,802,750 - \$11,161,380



District-wide Facilities-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority



Estimated Total Construction Costs (in 2021 Dollars): \$13,715,820 Estimated Total Project Costs: \$14,715,820 - \$15,392,820

Note Estimated total costs include ADA contingency, Special Education contingency, and playground equipment. These needs are not prioritized and are not displayed in the graph above.

Following is the list of currently unfunded district-wide needs

Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
1-High	Support Vehicles-Vehicles over 15 years old and heavy duty use vehicles needing replacement	\$3,535,820	N/A	N/A
1-Medium	Support Vehicles-Vehicles over 10 years old	\$1,365,000	N/A	N/A
1-Low	Support Vehicles-Vehicles that will become over 10 years old in the next 5 years	\$1,015,000	N/A	N/A
	Bear Canyon Elementary - Replace Mobile 18	\$200,000	N/A	\$10,000-\$43,000
	Castle View High School - Replace Mobile 20	\$200,000	N/A	\$10,000-\$43,000
	Cherokee Trail Elementary - Replace Mobile 11	\$200,000	N/A	\$10,000-\$43,000
	Eagle Ridge Elementary - Replace Mobile 32	\$200,000	N/A	\$10,000-\$43,000
	Frontier Valley Elementary - Replace Mobile 27	\$200,000	N/A	\$10,000-\$43,000
	Heritage Elementary - Replace Mobile 17	\$200,000	N/A	\$10,000-\$43,000
	Legend High School - Replace Mobile 19	\$200,000	N/A	\$10,000-\$43,000
	Northridge Elementary - Replace Mobile 3	\$200,000	N/A	\$10,000-\$43,000
	Pine Lane North - Replace Mobile 7	\$200,000	N/A	\$10,000-\$43,000
	Pine Lane South - Replace Mobile 4	\$200,000	N/A	\$10,000-\$43,000
2.111.1	Pine Lane South - Replace Mobile 5	\$200,000	N/A	\$10,000-\$43,000
3-High	Pioneer Elementary - Replace Mobile 1	\$200,000	N/A	\$10,000-\$43,000
	Pioneer Elementary - Replace Mobile 12	\$200,000	N/A	\$10,000-\$43,000
	Rock Ridge Elementary - Replace Mobile 16	\$200,000	N/A	\$10,000-\$43,000
	Rocky Heights Middle School - Replace Mobile 13	\$200,000	N/A	\$10,000-\$43,000
	Rocky Heights Middle School - Replace Mobile 23	\$200,000	N/A	\$10,000-\$43,000
	Sand Creek Elementary - Replace Mobile 15	\$200,000	N/A	\$10,000-\$43,000
	Sierra Middle School -Replace Mobile 26	\$200,000	N/A	\$10,000-\$43,000
	Soaring Hawk Elementary - Replace Mobile 14	\$200,000	N/A	\$10,000-\$43,000
	South Ridge Elementary - Replace Mobile 24	\$200,000	N/A	\$10,000-\$43,000
	South Ridge Elementary - Replace Mobile 28	\$200,000	N/A	\$10,000-\$43,000
	Wildcat Mtn Elementary - Replace Mobile 22	\$200,000	N/A	\$10,000-\$43,000
	Castle View High School - Replace Mobile 36	\$200,000	N/A	\$10,000-\$43,000
	Frontier Valley Elementary - Replace Mobile 47	\$200,000	N/A	\$10,000-\$43,000
	Legacy Point Elementary - Replace Mobile 42	\$200,000	N/A	\$10,000-\$43,000
	Pine Grove Elementary - Replace Mobile 39	\$200,000	N/A	\$10,000-\$43,000
	Pine Grove Elementary - Replace Mobile 43	\$200,000	N/A	\$10,000-\$43,000
3-Medium	Prarie Crossing Elementary - Replace Mobile 38	\$200,000	N/A	\$10,000-\$43,000
	Rocky Heights Middle School - Replace Mobile 44	\$200,000	N/A	\$10,000-\$43,000
	Saddle Ranch Elementary - Replace Mobile 35	\$200,000	N/A	\$10,000-\$43,000
	Saddle Ranch Elementary - Replace Mobile 35	\$200,000	N/A	\$10,000-\$43,000
	Sand Creek Elementary - Replace Mobile 30	\$200,000	N/A	\$10,000-\$43,000
	Summit View Elementary - Replace Mobile 31	\$200,000	N/A	\$10,000-\$43,000
	Contingency for ADA Compliance Projects	\$500,000	N/A	\$25,000-\$107,500
N/A	Contingency for Special Education Needs Projects	\$500,000	N/A	\$25,000-\$107,500
,	Playground Equipment	\$200,000	N/A	\$10,000-\$43,000

Estimated Total Construction Costs (in 2019 Dollars): \$13,715,820 Estimated Inflation Range: \$390,000 - \$1,677,000

Estimated Total Project Costs: \$14,105,820 - \$15,392,820

Completed and Contracted Projects Using 2018 Bond Funding

Summary of Projects	Total Cost
2019-2020 Completed Projects	
Support vehicles Special Education Needs related projects ADA compliance projects	\$1,141,000
2021 Contracted Projects	
ADA compliance projects	\$300,000




The DCSD Safety and Security Department supports all of the district security applications and infrastructure distributed throughout our schools and office buildings. The safety and security of our students, staff and visitors are incredibly dependent upon the availability of these systems. Any issues with these systems can impact response and resolution to incidents. Critical Security projects are being addressed with the funding made available from the 2018 Bond funds. Master Capital Plan requirements will continue to be assessed during the 2021-22 planning cycle

Currently, DCSD owns and is responsible for:

- 100+/- servers to run and operate security systems
- 150+/- client computers
- 3,200+/- cameras
- 560+/- access controlled doors
- 400+ system clients
- 3,800+/- radios
- 70+/- front door entry intercom
- Intrusion Systems

The Safety and Security Department's currently identified solutions and projects are prioritized on the effectiveness and urgency. District safety and security initiatives are proposed by the department based on continual review of local, state and federal requirements, administrative leadership, and reference to industry best practice solutions. A business case is developed to define scope, deliverables, resources, and cost estimates which then is prioritized by leadership. A portfolio review is conducted to ensure new initiatives are unified solutions across the district and maximize safety in alignment with our strategic goals.



Following is the list of currently unfunded safety & security needs

Tier	Project Description	Total Cost
	Bring DCSD facilities that are not to standard up to current Security Standards	\$385,000
	Replacement of aged window hardening products	\$3,528,000
	Replacement of end of life alarm hardware and monitoring solution	\$800,000
	Replace aged servers where resources are limited and can no longer keep up with demands and requirements of systems currently in place	\$404,200
High	Refresh Dispatch station desk hardware as current hardware is at end of life mechanically and parts are no longer available	\$54,000
	Replace Transportation fleet radios that are no longer serviceable, lacking current standardized functions or supported on the system, to ensure communication and reliability during normal and emergency use	\$1,785,000
	Middle school secure front entry project (design funded under 2018 Bond)	\$1,500,000
	Elementary school secure front entry project	\$10,000,000
	Install Bi-Directional Amplification/Distributed Antenna System at middle schools, elementary schools and support buildings for First Responders and Emergency School Radios	\$18,000,000
	Software License Renewal for Unified Video Management and Access Control system in 2025, to include neighborhood Charter schools	\$1,176,000
Medium	Radio Network Infrastructure maintenance, updates, upgrades and replacement	\$265,000
	Replace aged/legacy cameras, approximately 600, to current standards	\$1,260,000
	Enhance monitoring of ingress/egress points at middle schools, elementary schools and support building	\$2,520,000
	Replace HVAC and VAVs in the Emergency Operations Center. Install ceiling grid to dampen noise levels	\$500,000
	Replacement of aged security vehicle fleet	\$260,000
	Hardware refresh of security supported client computers	\$262,500
	Hardware refresh of security devices (cameras, access control) to newer technology and end of life devices	\$2,380,000
Low	Upgrade school radios to DTRS. Relies on completion of BDA/DAS installations and approvals from all involved agencies	\$4,600,000
	Design and implement redundancy in security systems to minimize outages	\$222,000
	Enhance security systems with new technology and analytics, based on feedback from site administrators	TBD
	Persistent VPN solution when moving between networks	\$25,000

Estimated Total Capital Costs (in 2021 Dollars): \$49,926,700 Estimated Project Management Cost Range: \$0 Estimated Inflation Range: \$0

Estimated Total Project Costs: \$49,926,700

Information Technology

The DCSD Information Technology Department supports all of the district technology applications and infrastructure distributed throughout our schools and office buildings. Teaching and learning in our schools and the support of teaching and learning are incredibly dependent upon the availability of high speed internet access. Any issues with this access can have a large impact on the entire education system. To that end, the District's IT team continuously performs system updates to ensure connectivity of phone, internet, and other critical systems is maintained at the highest levels of operation. Critical Information Technology projects are being addressed with the funding made available from the 2018 Bond funds. Master Capital Plan requirements will continue to be assessed during the 2021-22 planning cycle

Currently, DCSD owns and is responsible for:

- 80+ core district application services
- 730+/- servers to run and operate the district infrastructure
- 6,000 phones and 3,800 wireless access points across all building/schools
- 2,000+/- network switches
- 58,000+ devices connected wirelessly (Laptops, Tablets, Notebooks, Smartphones, etc.)
- 300+ Terabytes of storage
- 130,000+ active directory accounts (staff, students, parents etc.)

The Information Technology Department's currently identified solutions and projects are prioritized on the effectiveness and impact to student education delivery. District technology initiatives are proposed by the IT department based on continual review of school staff and student educational requirements, administrative leadership, and reference to industry best practice solutions. A business case is developed to define scope, deliverables, resources, and cost estimates which then is prioritized by IT leadership. A portfolio review is conducted to ensure new initiatives are unified solutions across the district and maximize delivery of student education in alignment with our strategic goals. With a wealth of technology solutions and opportunities, the IT department focuses priority on providing the district students, staff, and administration with the most value to provide the greatest education for the students. A business case is developed to define scope, deliverables, resources, and cost estimates which then is prioritized by leadership. A portfolio review is conducted to ensure new initiatives are unified solutions across the district and maximize safety in alignment with our strategic goals.


Following is the list of currently unfunded information technology needs

Tier	Project Description	Total Cost
	Student Device Replacement: replace the student devices in the district over a 5 year cycle with \$3.4M per year	\$17,000,000
	Staff Device Replacement: replace the devices for 9,000 staff at \$1,100 per device	\$9,900,000
1	Replacement of Wireless Controllers and Access Points: upgrade 2500 access points throughout the district and the controller hardware	\$4,000,000
	Data Center Hardware Server Replacement: upgrade hyper converged hardware and data warehouse equipment	\$500,000
	Replacement of Access Layer Switches at Administration	\$150,000
	Identity Service Engine Upgrade for Wireless Authentication Service	TBD
	Classroom Projector Replacement	TBD
2	Classroom Audio System Upgrade/Replacement	TBD
2	Firewall Hardware Replacement	\$750,000
	Data Center Backbone Hardware Replacement	TBD

Estimated Total Capital Costs (in 2021 Dollars): \$32,300,000 Estimated Project Management Cost Range: \$0 Estimated Inflation Range: \$0

Estimated Total Project Costs: \$32,300,000

Information Technology -Identified Items Estimated Capital Costs (in 2021 Dollars) by Tier



Estimated Total Project Costs: \$32,300,000




The Douglas County School District Transportation Fleet Department provides transportation for approximately 10,600 general education students and 1,000 special education students. The district has 3 bus terminals (Parker, Highlands Ranch, and Castle Rock), and a training facility at Ponderosa High School. The training team has 3 certified CDL trainers and the Transportation department as a whole has approximately 380 staff. The Transportation Fleet Maintenance Department employs 18 mechanics of which we have 10 Automotive Service Excellence (ASE) Master Mechanics and 7 mechanics that are Certified Colorado Department of Education (CDE) Inspectors.

Currently, the district owns a total of 331 buses. Of these, 104 are over 15 years old with the oldest bus being 1996. In addition, there are 18 buses that are no longer roadworthy and are being used for parts. As an example, the average age of a bus across similar Colorado districts is 9 years. Buses are removed from the fleet when they become cost prohibitive to repair or are no longer safe to transport students.

Only fleet related capital items are identified and discussed on this page. Capital needs at the three bus terminals are considered facility needs and are assessed, inventoried, and prioritized as part of the facility assessment and Capital Improvement Plan process discussed in the Methodology section. The need for new terminals is assessed and priced as part of the District's review of new construction needs.

Transportation-Identified Items Estimated Capital Costs (in 2021 Dollars) by Tier and Priority



Estimated Total Project Costs: \$32,755,000

Following is the list of currently unfunded transportation needs

Tier & Priority Class	Project Description		
1-High	Replace 18 General Education buses and 5 Field Trip buses ranging in age from 1996-2006. Cost for GenEd buses is \$125,000-\$185,000 each depending on fuel type. Cost for Field trip buses is approximately \$200,000.	\$4,330,000	
	See footnote below for Bond funding information		
2-High	Additional service truck to support the Castle Rock area including Larkspur for emergency response, on-site repairs and maintenance assistance. This vehicle, fully equipped, would be \$90,000.	\$90,000	
2-Medium	Replace 104 buses that are 2006 and older. Of those there are 7-32 passenger Special Needs buses at \$95,000; 7 Field trip buses at \$200,000; and 90-77 passenger buses at \$155,000.	\$16,015,000	
3-High	In order to align with the direction of the Federal Department of Transportation, gas and diesel buses will be replaced with electric buses. The first phase is to replace 20 of the 77 passenger GenEd buses and 24 of the 32 passenger Special Needs buses with electric buses. The cost estimate for an electric bus is in the range of \$250,000 - \$300,000. This capital requirement is contingent upon new bus terminal facilities being constructed since infrastructure is needed for charging stations, electrical transformers, and unique maintenance bays and equipment.	\$12,320,000	

Estimated Total Capital Costs (in 2021 Dollars): \$32,755,000 Estimated Project Management Cost Range: \$0 Estimated Inflation Range: \$0

Estimated Total Project Costs: \$32,755,000

*Not all General Education and Field Trip buses listed as a Tier 1 need in the 2019-20 Master Capital Plan were funded by the 2018 Bond and remain as an unfunded need. An additional six Special Education buses than anticipated in the 2019-20 MCP were purchased with Bond funds as the buses are multipurpose and can be used for both General Education and Special Education purposes. Some Tier II needs such as a wrecker and service truck were prioritized for funding due to the increased need and increased rate of towing. In addition, a parts runner and roll back truck were not identified as a need in the 2019-20 MCP but were purchased due to unanticipated break downs.

Completed and Contracted Projects Using 2018 Bond Funding

Summary of Projects	Total Cost
2019-2020 Completed Projects	
Conventional gas 77 passenger buses-21 Conventional diesel 77 passenger buses-10 Special Education diesel 32 passenger buses-10 Special Education gas 14 passenger buses-5 Field trip diesel passenger bus-1 Large wrecker for bus recovery-1 Fully outfitted service trucks-2 Parts runner small vehicle-1 Bus & dispatch radios SMARTag software and implementation	\$6,792,923
2021 Contracted Projects	
Conventional gas 77 passenger buses-2 Dispatch radios Maintenance shop equipment (lifts, welders, parts washer, etc.) Field trip 72 passenger diesel bus Safety vision cameras Contingency bus purchase	\$1,007,077

This page left intentionally blank

Charter Schools

Public Charter Schools were authorized by the Colorado Charter School Act in 1993, and DCSD chartered the first charter school in the state shortly thereafter, Academy Charter School. The Charter School Act authorizes teachers, parents and/or community members to contract with the local board of education to establish a publicly funded school. Charter schools operate under a "charter contract" between the charter school and the local board of education which defines the charter school's goals, standards, education design, governance, and operations. All charter schools must meet accreditation standards as set by their authorizing school district and comply with federal and state statutes related to non-discrimination, school accountability, assessments, finance and financial transparency, and performance.

All charter schools authorized by the Douglas County School District Board of Education have legal arrangements to lease, acquire, utilize, and maintain their own facilities, including grounds and buildings. Each charter facility is an individual operating entity utilizing different ownership structures and business models. Each charter school, while always a public school, is individually managed by an independent board of directors. Ultimately, charter schools are accountable to provide educational spaces that are safe to all students and staff through its charter with the Board of Education. Charters must also properly maintain each facility to support their defined programs and objectives. Currently, this maintenance, and any facility modifications or additions, is carried out by each individual charter school.

Each charter school must fund its educational programs (including salaries for teachers, support staff, and administrators) and pay for all infrastructure needs. These may include facility purchases, technology, supplies, routine and emergency maintenance items, facility modifications or new construction. These costs are paid by the charter school from the per pupil revenue and mill levy override dollars received from the authorizing school district. Like all other public school facilities, charters must also always meet all federal, state and local code requirements for health and safety.

DCSD charter schools occupy a variety of different types of buildings of different ages and histories, from converted warehouses to new commercial construction not dissimilar from standard neighborhood schools. When financed, each facility carries its own terms using interest rates often greater than rates for public debt offered to school districts like DCSD. Charter schools generally target spending 12% to 18% of their total annual budget on their facility debt service or lease payments. As public schools subject to TABOR, charters do not solicit voter funding through bonds, so capital expenses must be funded through their annual budgets and contingency reserves. Each charter school is 100% liable for these costs, which are not covered by the District.

While DCSD is not directly responsible for charter school capital needs, this inventory of charter school facilities is required to fully appreciate the cost needs and public ownership value of buildings and other capital required for public K-12 education throughout the District.

For this MCP, all DCSD charter schools were asked to submit their capital needs data. Charter schools have submitted needs other than capital renewal needs. These identified needs are listed on each individual charter school page. For neighborhood schools, these needs are identified as district-wide needs and broken out and summed as separate costs.

Bond funding is generally used for capital needs such as facility repairs, security upgrades, purchasing classroom equipment, buses and technology.

1551 Prairie Hawk Drive Castle Rock, CO 80109 Castle View High School Feeder Area, K-8 School built in 2001 Opened in 1996


Site Acreage:10 Facility Square Feet: 52,000

Academy Charter-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier



Estimated Total Construction Costs (in 2021 Dollars): \$288,900 Estimated Total Project Costs: \$332,845 - \$475,914

Note Estimated total costs include facility upgrade and facility modification items. These items were not assigned a Tier or Priority score by Academy Charter School and therefore will not be displayed on the graph above.



Tier	Project Type	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Capital	Intercommunication and Paging System. Life cycle at 15-20 years.	\$22,210	\$2,290-\$9,590	\$1,111-\$4,775
1	Renewal	Interior Door Hardware. Replacement need in about 5 years.	\$166,570	\$16,730-\$71,630	\$8,329-\$35,813
	Maintenance	Water Treatment Systems. Check water treatment systems when HVAC systems replaced.	\$5,560	\$640-\$2,440	\$278-\$1,195
		Curbs, Rails and Barriers. Repair as necessary	\$11,110	\$1,190-\$4,790	\$556-\$2,389
		Exhaust Fans. Life cycle replacement at 15-20 years	\$33,320	\$3,380-\$14,380	\$1,666-\$7,164
	Capital Renewal	Exterior Wall Construction. Repair cracks at stucco	\$2,790	\$310-\$1,210	\$140-\$600
2		Exterior Windows. Recaulking of windows	\$11,110	\$1,190-\$4,790	\$556-\$2,389
		Glazed Doors and EntrancesRecaulk front entry	\$1,120	\$180-\$580	\$56-\$241
		Paving and Surfacing. Sidewalks. Repair areas of damaged concrete	\$1,120	\$180-\$580	\$56-\$241
		Sink Countertops. Replace sink counter tops	\$33,320	\$3,380-\$14,380	\$1,666-\$7,164
	Capital	Replace gym floor	\$78,000	\$7,800-\$33,600	\$3,900-\$16,770
Camital		Repair, paint, and install new mats on gym walls	\$10,000	\$1,000-\$4,300	\$500-\$2,150
Capital Renewal		Replace/repair drainage solutions on playground and driveways	\$45,000	\$4,500-\$19,400	\$2,250-\$9,675
		Replace/add property signage	\$2,000	\$200-\$900	\$100-\$430
		Replace/add trees	\$5,000	\$500-\$2,200	\$250-\$1,075
Facility	Facility	Upgrade Middle School Technology Lab	\$10,000	\$1,000-\$4,300	\$500-\$2,150
Upgrade	Upgrades	Air purification additions to HVAC system	\$18,000	\$1,800-\$7,800	\$900-\$3,870
		Replace phones and phone system	\$30,000	\$3,000-\$12,900	\$1,500-\$6,450
IT	ΙΤ	Replace staff laptops	\$50,000	\$5,000-\$21,500	\$2,500-\$10,750
		Replace network servers and battery backups	\$12,000	\$1,200-\$5,200	\$600-\$2,580
Security	Security	Additions to visitor management system	\$1,500	\$200-\$700	\$75-\$323

Estimated Total Construction Costs (in 2021 Dollars): \$288,900 Estimated Project Management Costs Range: \$29,500 - \$124,900 Estimated Inflation Range: \$14,445 - \$62,114

Estimated Total Project Costs: \$332,845 - \$475,914

Completed and Contracted Projects Using 2018 Bond Funding

Summary of Projects	Total Cost
2019-2020 Completed Projects	
Fire alarm	\$382,890
2021 Contracted Projects	
No projects contracted for 2021	N/A
2022 Scheduled Projects	
Doors & door hardware Intercoms & paging systems	\$412,568

Castle Pines Campus 6971 Mira Vista Lane Castle Pines, CO 80108 Rock Canyon High School Feeder Area, K-8


Castle Pines school built/opened in 2009

Site Acreage: 5.5 Facility Square Feet: 83,000



Estimated Total Construction Costs (in 2021Dollars): \$645,500 Estimated Total Project Costs: \$742,675 - \$1,062,283

^{*}Note* Estimated total costs include facility upgrade and facility modification items. These items were not assigned a Tier or Priority score by American Academy Charter School and therefore will not be displayed on the graph above.



Tier	Project Type	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
1	Capital Renewal	BAS System (for HVAC) Replacement	\$100,000	\$10,000-\$43,000	\$5,000-\$21,500
2	Capital Renewal	Painting Hallways	\$33,400	\$3,400-\$14,400	\$1,670-\$7,181
Facility	Facility	Monument Sign	\$100,000	\$10,000-\$43,000	\$5,000-\$21,500
Modification	Modification	Playgrounds-Add pour and play surface and new equipment	\$233,300	\$23,400-\$100,400	\$11,665-\$50,160
Facility	Facility	Additional Sidewalks	\$45,600	\$4,600-\$19,700	\$2,280-\$9,804
Facility Upgrade	Facility Upgrade	Repair roof	\$66,600	\$6,700-\$28,700	\$3,330-\$14,319
	opgrade	Replace all carpets	\$33,300	\$3,400-\$14,400	\$1,665-\$7,160
IT	ΙΤ	Replace phones and phone system	\$33,300	\$3,400-\$14,400	\$1,665-\$7,160

Estimated Total Construction Costs (in 2021 Dollars): \$645,500 Estimated Project Management Costs Range: \$64,900 - \$278,000 Estimated Inflation Range: \$32,275 - \$138,783


Estimated Total Project Costs: \$742,675- \$1,062,283

Parker Campus 11155 Motsenbocker Rd Parker, CO 80134 Chaparral High School Feeder Area, K-8

Motsenbocker campus built/opened in


Site Acreage: 9.1

Facility Square Feet: 93,000



Estimated Total Construction Costs (in 2021 Dollars): \$556,100 Estimated Total Project Costs: \$639,905 -\$915,262

Note Estimated total costs include facility upgrade and facility modification items. These items were not assigned a Tier or Priority score by American Academy Charter School and therefore will not be displayed on the graph above.



Tier	Project Type	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
2	Capital Renewal	Paint Hallways	\$33,400	\$3,400-\$14,400	\$1,670-\$7,181
Facility	Facility	Barrier Netting Fence for soccer fields	\$8,400	\$900-\$3,700	\$420-\$1,806
Modification	Modification	Playgrounds-Add pour and play surface and new equipment	\$233,300	\$23,400-\$100,400	\$11,665-\$50,160
		Repair roof	\$66,600	\$6,700-\$28,700	\$3,330-\$14,319
Facility	Facility	Replace all carpets	\$33,300	\$3,400-\$14,400	\$1,665-\$7,160
Upgrade	Upgrade	Change all internal lights to LED	\$120,000	\$12,000-\$51,600	\$6,000-\$25,800
		Additional Shrubs, Trees and Plantings	\$27,800	\$2,800-\$12,000	\$1,390-\$5,977
IT	IT	Replace phones and phone system	\$33,300	\$3,400-\$14,400	\$1,665-\$7,160

Estimated Total Construction Costs (in 2021 Dollars): \$556,100 Estimated Project Management Costs Range: \$56,000 - \$239,600 Estimated Inflation Range: \$27,805 - \$119,562

Estimated Total Project Costs: \$639,905 - \$915,262

Lincoln Meadows Campus 10260 Twenty Mile Rd. Parker, CO 80134 Chaparral High School Feeder Area, K-8

Lincoln Meadows campus school built/ opened in 2017


Site Acreage: 8.776 Facility Square Feet: 93,100

American Academy-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier



Estimated Total Construction Costs (in 2021 Dollars): \$486,500 Estimated Total Project Costs: \$559,725 -\$800,598

Note Estimated total costs include facility upgrade and facility modification items. These items were not assigned a Tier or Priority score by American Academy Charter School and therefore will not be displayed on the graph above.




Tier	Project Type	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
Facility Modification	Facility Modification	Playgrounds-Add pour and play surface and new equipment	\$233,300	\$23,400-\$100,400	\$11,665-\$50,160
		Put in turf in place of grass/dirt	\$120,000	\$12,000-\$51,600	\$6,000-\$25,800
Facility Upgrade		Repair roof	\$66,600	\$6,700-\$28,700	\$3,330-\$14,319
		Replace all carpets	\$33,300	\$3,400-\$14,400	\$1,665-\$7,160
IT	IT	Replace phones and phone system	\$33,300	\$3,400-\$14,400	\$1,665-\$7,160

Estimated Total Construction Costs (in 2021 Dollars): \$486,500 Estimated Project Management Costs Range: \$48,900 - \$209,500


Estimated Inflation Range: \$24,325 - \$104,598 Estimated Total Project Costs: \$559,725 - \$800,598

2131 Low Meadow Boulevard Castle Rock, CO 80109 Castle View High School Feeder Area, K-8 School built in 2013 School opened in 2013 Site Acreage: 10 Facility Square Feet: 78,376



Estimated Total Construction Costs (in 2021 Dollars): \$451,800 Estimated Total Project Costs: \$520,390 - \$744,237

Note Estimated total costs include facility upgrade and facility modification items. These items were not assigned a Tier or Priority score by Aspen View Charter School and therefore will not be displayed on the graph above.



Tier	Project Type	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
2	Capital	Add parking lot signage	\$5,600	\$600-\$2,500	\$280-\$1,204
	Renewal	Paint the interior of the building	\$27,800	\$2,800-\$12,000	\$1,390-\$5,977
	Security	Security-Replace security camera system	\$44,500	\$4,500-\$19,200	\$2,225-\$9,568
3	Capital Renewal	Resurface parking lot	\$55,600	\$5,600-\$24,000	\$2,780-\$11,954
	Security	Security-Add safety film to first floor windows	\$11,200	\$1,200-\$4,900	\$560-\$2,408
	Capital Renewal	Add/replace trees along Low Meadow Blvd	\$7,800	\$800-\$3,400	\$390-\$1,677
4		Seal concrete floor	\$16,700	\$1,700-\$7,200	\$835-\$3,591
	IT	Replace/update staff laptops	\$33,400	\$3,400-\$14,400	\$1,670-\$7,181
	Security	Upgrade card readers	\$7,300	\$800-\$3,200	\$365-\$1,570
Facility Modification	Facility Modification	Air duct cleaning	\$11,200	\$1,200-\$4,900	\$560-\$2,408
		Divide 2 large rooms in half creating 4 medium rooms	\$55,600	\$5,600-\$24,000	\$2,780-\$11,954
		Replace classroom projectors for SMART boards	\$27,800	\$2,800-\$12,000	\$1,390-\$5,977
Facility Upgrade	Facility Upgrade	Install a grease trap in the kitchen	\$108,200	\$10,900-\$46,600	\$5,410-\$23,263
		Install concrete ramp from building to turf field	\$16,700	\$1,700-\$7,200	\$835-\$3,591
		Install fence between turf field and new community	\$11,200	\$1,200-\$4,900	\$560-\$2,408
		Upgrade the school library	\$11,200	\$1,200-\$4,900	\$560-\$2,408


Estimated Total Construction Costs (in 2021 Dollars): \$451,800 Estimated Project Management Costs Range: \$46,000 - \$195,300 Estimated Inflation Range: \$22,590 - \$97,137

Estimated Inflation Range: \$22,590 - \$97,137 Estimated Total Project Costs: \$520,390 - \$744,237

^{**}DCSD charter schools submit facility and infrastructure needs to the Planning Department for inclusion in the Master Capital Plan. Facility and infrastructure needs were not submitted by Aspen View Academy Charter in 2021 for inclusion in the Master Capital Plan.


2270 Plaza Drive Highlands Ranch, CO 80129 Mountain Vista High School Feeder Area, K-8 School built in 2011 School opened in 2011 Site Acreage: 10.13 Facility Square Feet: 64,779

Benjamin Franklin Academy-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier



Estimated Total Construction Costs (in 2021Dollars): \$177,700 Estimated Total Project Costs: \$205,085 - \$293,206

Note Estimated total costs include facility upgrade and facility modification items. These items were not assigned a Tier or Priority score by Benjamin Franklin Charter School and therefore will not be displayed on the graph above.



Tier	Project Type	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
1	Capital Renewal	Change out 3 backflow valves in the fire suppressing room	\$3,340	\$360-\$1,460	\$167-\$718
2	Capital Renewal	Exterior Building paint	\$22,210	\$2,290-\$9,590	\$1,111-\$4,775
		Parking Lot Light replacements (6)	\$1,120	\$180-\$580	\$56-\$241
		Replacing outside safety lighting	\$1,790	\$210-\$810	\$90-\$385
	Security	Install surveillance cameras	\$4,230	\$470-\$1,870	\$212-\$909
	Capital Renewal	Construct a fence at the west end of the playground	\$4,900	\$500-\$2,200	\$245-\$1,054
3		Construct concrete steps leading from sidewalk to playground	\$6,100	\$700-\$2,700	\$305-\$1,312
	Security	Harden lower level	\$7,230	\$770-\$3,170	\$362-\$1,554
4	Capital Renewal	Add Irrigation for trees along Plaza	\$2,800	\$300-\$1,300	\$140-\$602
		Add privacy slatting to playground fence	\$5,900	\$600-\$2,600	\$295-\$1,269
		Construct a housing for the trash dumpsters	\$5,560	\$640-\$2,440	\$278-\$1,195
		Plant Oak trees to create privacy along playground	\$24,500	\$2,500-\$10,600	\$1,225-\$5,268
		Replace classroom projectors	\$26,650	\$2,750-\$11,550	\$1,333-\$5,730
	IT	IT-Replace computer lab desk top computers (26)	\$34,650	\$3,550-\$14,950	\$1,733-\$7,450
Capital Renewal	Capital Renewal	Replace coconut husk filler in turf field by playground	\$22,000	\$2,200-\$9,500	\$1,100-\$4,730
		Contract with third party/outside firm to assess facility for future capital needs	\$10,000	\$0	\$0
Facility Modification	Facility Modification	Construct a shed for turf groomer	\$6,120	\$680-\$2,680	\$306-\$1,316
Facility Upgrade	Facility Upgrade	Replace current faucets with touchless faucets	\$20,000	\$2,000-\$8,600	\$1,000-\$4,300

Estimated Total Construction Costs (in 2021 Dollars): \$177,700 Estimated Project Management Costs Range: \$128,500 - \$77,300 Estimated Inflation Range: \$8,885 - \$38,206

Estimated Total Project Costs: \$2056,085 - \$293,206



16995 East Carlson Drive Parker, CO 80134 Chaparral High School Feeder Area, K-8 School built in 2004 Opened in 2002


Site Acreage: 7.5 Facility Square Feet: 40,000

Challenge to Excellence Charter-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier



Estimated Total Construction Costs (in 2021 Dollars): \$2,075,900 Estimated Total Project Costs: \$2,388,395 - \$3,416,019

Note Estimated total costs include facility upgrade, facility modification. and facility addition items. These items were not assigned a Tier or Priority score by Challenge to Excellence Charter School and therefore will not be displayed on the graph above.



Tier	Project Type	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
		Carpeting 18 classrooms	\$77,800	\$7,800-\$33,500	\$3,890-\$16,727
		Caulk windows	\$7,300	\$800-\$3,200	\$365-\$1,570
		Hallways need patched and painted	\$41,700	\$4,200-\$18,000	\$2,085-\$8,966
		Mill, overlay, patch parking lot	\$22,300	\$2,300-\$9,600	\$1,115-\$4,795
	Camital	Replace areas of curb cracking	\$12,300	\$1,300-\$5,300	\$615-\$2,645
	Capital Renewal	Replace sections of sidewalk	\$30,600	\$3,100-\$13,200	\$1,530-\$6,579
2	Kenewai	Replace toilet partitions	\$22,300	\$2,300-\$9,600	\$1,115-\$4,795
2		Resurface Playground	\$73,300	\$7,400-\$31,600	\$3,665-\$15,760
		Seal and caulk exterior wall	\$24,500	\$2,500-\$10,600	\$1,225-\$5,268
		Steel doors and frames need painted	\$18,400	\$1,900-\$8,000	
		Upgrade irrigation system	\$94,400	\$9,500-\$40,600	\$4,720-\$20,296
		Access control system	\$11,200	\$1,200-\$4,900	\$560-\$2,408
	Security	Install security cameras	\$38,900	\$3,900-\$16,800	\$1,225-\$5,268 \$920-\$3,956 \$4,720-\$20,296
		Update alarm system	\$15,600	\$1,600-\$6,800	\$780-\$3,354
3	Capital	Parking lot signage & marking	\$9,800	\$1,000-\$4,300	\$490-\$2,107
5	Renewal	Provide fencing for dumpsters and transformers	\$6,200	\$700-\$2,700	\$310-\$1,333
	Capital	Entire site landscape work	\$88,900	\$8,900-\$38,300	\$4,445-\$19,114
4	Renewal	Replace/add trees and shrubs	\$6,200	\$700-\$2,700	\$310-\$1,333
Facility Modification	Facility Modification	Install storage shed	\$22,300	\$2,300-\$9,600	\$1,115-\$4,795
Facility Upgrade	Facility Upgrade	Library upgrade	\$8,400	\$900-\$3,700	\$420-\$1,806
Building Addition	Building Addition	Building expansion	\$1,443,500	\$144,400-\$620,800	\$72,175-\$310,353

Estimated Total Construction Costs (in 2021 Dollars): \$2,075,900 Estimated Project Management Costs Range: \$208,700 - \$893,800 Estimated Inflation Range: \$103,795 - \$446,319

Estimated Total Project Costs: \$2,388,395 - \$3,416,019

Completed and Contracted Projects Using 2018 Bond Funding

Summary of Projects	Total Cost			
2019-2020 Completed Projects				
No projects completed in 2019-20	N/A			
2021 Contracted Projects				
Fire Alarm HVAC, Roof Top Units & Controls Phone System	\$1,384,160			
2022 Scheduled Projects				
Intercoms & paging systems	\$336,113			

249


^{**}DCSD charter schools submit facility and infrastructure needs to the Planning Department for inclusion in the Master Capital Plan. Facility and infrastructure needs were not submitted by Challenge to Excellence Charter in 2021 for inclusion in the Master Capital Plan.



311 East Castle Pines Parkway Castle Pines, CO 80108 Rock Canyon High School Feeder, K-8 School built in 2000 Opened in 1997


Site Acreage: 8.5 Facility Square Feet: 41,800

DCS Montessori Charter-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier



Estimated Total Construction Costs (in 2021 Dollars): \$350,100 Estimated Total Project Costs: \$402,905 -\$576,172

Note Estimated total costs include facility modification, IT, security, and untiered capital renewal items. These items were not assigned a Tier or Priority score by DCS Montessori Charter School and therefore will not be displayed on the graph above.



Tier	Project Type	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
1	Maintenance	Replace Roof	\$250,000	\$65,000-\$65,000	\$12,500-\$53,750
2	Capital Renewal	Interior Finishes-Painting, flooring, ceiling maintenance, plumbing.	\$55,600	\$4,400-\$4,400	\$2,780-\$11,954
3	Capital Renewal	Exterior painting and sealing	\$16,700	\$1,700-\$7,200	\$835-\$3,591
	Capital	Parking lot repair/replacement	\$65,000	\$0	\$3,250-\$13,975
4	Renewal	Renovate landscaping to be less water intensive	\$38,100	\$6,900-\$6,900	\$1,905-\$8,192
		Exterior door replacement-10+ external entrances	\$65,000	\$0	\$3,250-\$13,975
Capital Renewal	Capital Renewal	Replace gym floor	\$75,000	\$10,000-\$10,000	\$3,750-\$16,125
		Retrofit elevator	\$48,000	\$2,000-\$2,000	\$2,400-\$10,320
		Convert existing turf field to artificial turf field	\$42,100	\$5,900-\$5,900	\$2,105-\$9,052
Facility Modification	Facility Modification	Add ADA access to Middle School basement	\$35,000	\$3,000-\$3,000	\$1,750-\$7,525
		Rebuild staff entrance (aging retaining wall, Concrete walk w/ heat, hand railings)	\$85,000	\$15,000-\$15,000	\$4,250-\$18,275
IT	IT	Wifi or Radio to back-up hardwire lines (requires new line installation)	\$21,000	\$0	\$1,050-\$4,515
	- 11	Electrical and Wifi and 3D Printing Device installation and training	\$10,000	\$5,000-\$5,000	\$500-\$2,150
		Entry controls installation	\$34,000	\$2,000-\$2,000	\$1,700-\$7,310
Security	Security	Interior Bllinds for Lock Downs	\$8,000	\$1,000-\$1,000	\$400-\$1,720
Security	Security	Security Camera installation	\$19,000	\$2,000-\$2,000	\$950-\$4,085
		Classroom Keyless entry	\$48,000	\$7,000-\$7,000	\$2,400-\$10,320

Estimated Total Construction Costs (in 2021 Dollars): \$350,100 Estimated Project Management Costs Range: \$35,300 - \$150,800 Estimated Inflation Range: \$17,505 - \$75,272

Estimated Total Project Costs: \$402,905 - \$576,172

Summary of Projects	Total Cost
2019-2020 Completed Projects	
Boiler HVAC Roof Top Units	\$825,865
2021 Contracted Projects	
No projects contracted for 2021	N/A


18451 Ponderosa Drive Parker, CO 80134 Chaparral High School Feeder Area, K-6 Opened in 2015

Site Acreage: 7.39 Facility Square Feet: 27,481



Estimated Total Construction Costs (in 2021 Dollars): \$1,456,600 Estimated Total Project Costs: \$1,675,830 - \$2,396,669

Note Estimated total costs include security, facility upgrade. facility modification. a proposed addition, and mobiles. These items were not assigned a Tier or Priority score by Global Village Academy Charter School and therefore will not be displayed on the graph above.



Tier	Project Type	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
4	Capital Renewal	Landscaping of the property to maintain asthetics	\$11,300	\$1,200-\$4,900	\$565-\$2,430
		Install 20' x 30' storage building	\$26,700	\$2,700-\$11,500	\$1,335-\$5,741
Facility	Facility	Replacement of bark chips on the playground	\$49,200	\$5,000-\$21,200	\$2,460-\$10,578
Modification	Modification	Ride-on lawn mower / snow plow	\$10,300	\$1,100-\$4,500	\$515-\$2,215
		Smart Boards for classrooms to assist with SPED and general instruction (x5)	\$4,500	\$500-\$2,000	\$225-\$968
		Fencing around exterior of property to increase security and keep children away from creek / open space	\$75,100	\$7,600-\$32,300	\$3,755-\$16,147
Facility	Facility	Installation of Closed-Circuit TV (CCTV) security system	\$44,900	\$4,500-\$19,400	\$19,400 \$2,245-\$9,654
Upgrade	Upgrade	Installation of turf on the sports field	\$94,400	\$9,500-\$40,600	\$4,720-\$20,296
		Retractable wall partions for installation in the library to allow multi-use room to be converted into additional classroom / testing space as and when needed	\$46,700	\$4,700-\$20,100	\$2,335-\$10,041
Building Addition	Building Addition	Construction of a school gym	\$890,200	\$89,100-\$382,800	\$44,510-\$191,393
Security	Security	Harden facility by updating access control	\$12,600	\$1,300-\$5,500	\$630-\$2,709
		ADA compliant ramp for modular classroom (including installation)	\$19,500	\$2,000-\$8,400	\$975-\$4,193
Mobiles	Mobiles	Installation of a modular building to house additional classes (dry or wet)	\$166,600	\$16,700-\$71,700	\$8,330-\$35,819
		Paving for modular installation	\$4,600	\$500-\$2,000	\$230-\$989

Estimated Total Construction Costs (in 2021 Dollars): \$1,456,600 Estimated Project Management Costs Range: \$146,400 - \$626,900 Estimated Inflation Range: \$72,830 - \$313,169

Estimated Total Project Costs: 1,675,830 - \$2,396,669

^{**}DCSD charter schools submit facility and infrastructure needs to the Planning Department for inclusion in the Master Capital Plan. Facility and infrastructure needs were not submitted by Global Village Academy Charter in 2021 for inclusion in the Master Capital Plan.

19560 Stroh Rd. Parker, CO 80134 Chaparral High School Feeder Area, K-8


Built in 2017 Opened in 2018 Site Acreage: 8.02 Facility Square Feet: 44,596

Leman Academy-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier



Estimated Total Construction Costs (in 2021 Dollars): \$50,000 Estimated Total Project Costs: \$57,500 - \$82,250

Note Estimated total costs include a facility modification. This item was not assigned a Tier or Priority score by Leman Academy of Excellence Charter School and therefore will not be displayed on the graph above.



Tier	Project Type	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
Facility Modification	Facility Modification	Install ground level, climate controlled breezeway between buildings 1 and 2	\$50,000	\$5,000-\$21,500	\$2,500-\$10,750

Estimated Total Construction Costs (in 2021 Dollars): \$50,000 Estimated Project Management Costs Range: \$5,000 - \$21,500 Estimated Inflation Range: \$2,500 - \$10,750

Estimated Total Project Costs: \$57,500 - \$82,250


16700 Keystone Boulevard Parker, CO 80134 Chaparral High School Feeder, K-8 Opened in 2005

Site Acreage: 4.8 Facility Square Feet: 28,900

North Star Academy-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier



Estimated Total Construction Costs (in 2021 Dollars): \$619,600 Estimated Total Project Costs: \$713,380 - \$1,020,114



Tier	Project Type	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
		Carpet Replacement.	\$150,000	\$15,000-\$64,500	\$7,500-\$32,250
		Install new bathroom flooring.	\$30,000	\$3,000-\$12,900	\$1,500-\$6,450
		Air Duct Cleaning	\$16,700	\$1,700-\$7,200	\$835-\$3,591
		Concrete Curb and Gutter Repair	\$15,600	\$1,600-\$6,800	\$780-\$3,354
		Internal painting	\$11,200	\$1,200-\$4,900	\$560-\$2,408
	Capital Renewal	Mill and overlay parking lot/take middle islands out and add parking spots	\$111,100	\$11,200-\$47,800	\$5,555-\$23,887
2	Renewal	Repair sunk in floor in middle school and library (foundation)	\$138,800	\$13,900-\$59,700	\$6,940-\$29,842 \$560-\$2,408 \$390-\$1,677 \$225-\$968
		Replace Handicap door opener at Kindergarten playground	\$11,200	\$1,200-\$4,900	
		Replace Handicap elevator	\$7,800	\$800-\$3,400	
		Replace plumbing Fixtures	\$4,500	\$500-\$2,000	\$225-\$968
	ΙΤ	Replace Telephone System	\$33,400	\$3,400-\$14,400	\$1,670-\$7,181
	Security	Upgrade Video Surveillance System	\$16,700	\$1,700-\$7,200	\$835-\$3,591
		Concrete outside of music room	\$11,200	\$1,200-\$4,900	\$560-\$2,408
3	Capital	Maintenance work on turf playing field (addition of in fill and removal of insects)	\$16,700	\$1,700-\$7,200	\$835-\$3,591
	Renewal	Repair and Replacement of chain link Fence	\$22,300	\$2,300-\$9,600	\$1,115-\$4,795
		Replace/Add Parking Lot Signage	\$5,600	\$600-\$2,500	\$280-\$1,204
4	Capital	Mulch Ground Cover	\$11,200	\$1,200-\$4,900	\$560-\$2,408
4	Renewal	Replace/Add Parking Lot Signage	\$5,600	\$600-\$2,500	\$280-\$1,204

Estimated Total Construction Costs (in 2021 Dollars): \$619,600 Estimated Project Management Costs Range: \$62,800 - \$267,300 Estimated Inflation Range: \$30,980 - \$133,214

Estimated Total Project Costs: \$713,380 - \$1,020,114

Summary of Projects	Total Cost		
2019-2020 Completed Projects			
HVAC Roof Top Units	\$458,811		
2021 Contracted Projects			
No projects contracted for 2021	N/A		
2022 Scheduled Projects			
Elevator modernization (cafeteria lift) Plumbing (water service piping repair)	\$134,860		

^{**}DCSD charter schools submit facility and infrastructure needs to the Planning Department for inclusion in the Master Capital Plan. Facility and infrastructure needs were not submitted by North Star Academy Charter in 2021 for inclusion in the Master Capital Plan.



11661 Pine Drive Parker, CO 80138 Chaparral High School Feeder Area, K-8

School built in 2000 Opened in 2000


Site Acreage: 6.5 Facility Square Feet: 53,190

Parker Core Knowledge-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier



Estimated Total Construction Costs (in 2021 Dollars): \$3,164,600 Estimated Total Project Costs: \$3,640,030 - \$5,206,489

Note Estimated total costs include facility modifications, facility upgrades, and IT and security needs. These items were not assigned a Tier or Priority score by Parker Core Knowledge Charter School and therefore will not be displayed on the graph above.



Tier	Project Type	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	Capital	Install new DDC Controls	\$367,600	\$36,800-\$158,100	\$18,380-\$79,034
1	Renewal	Install new heat tape for north side downspout.	\$1,600	\$200-\$700	\$80-\$344
	Maintenance	Replace roof 2005 & 2010 building.	\$213,700	\$21,400-\$91,900	\$10,685-\$45,946
		Replace carpet in original building.	\$396,500	\$39,700-\$170,500	\$19,825-\$85,248
		Replace VCT throughout building.	\$77,800	\$7,800-\$33,500	\$3,890-\$16,727
		Install barrier around kiln	\$1,600	\$200-\$700	\$80-\$344
		Install card readers on 10 exterior doors	\$7,400	\$800-\$3,200	\$370-\$1,591
		Paint exterior downspouts	\$400	\$100-\$200	\$20-\$86
		Recaulk control joints	\$2,600	\$300-\$1,200	\$130-\$559
2	Capital Renewal	Replace intercom and clock system with hard wired system	\$137,500	\$13,800-\$59,200	
		Replace/repair damaged ceramic tile in restrooms	\$13,300	\$1,400-\$5,800	\$665-\$2,860
		Re-seal asphalt parking lot	\$12,900	\$1,300-\$5,600	\$665-\$2,860 \$645-\$2,774 \$135-\$581 \$5,000-\$21,500
		Re-seal CMU	\$2,700	\$300-\$1,200	
		Update tile, counters, flooring, and stalls of bathrooms in original wing	\$100,000	\$10,000-\$43,000	\$5,000-\$21,500
		Patch, prime and paint interior walls	\$237,500	\$23,800-\$102,200	\$11,875-\$51,063
3	Capital Renewal	Refurbish interior doors and jambs in original building	\$8,100	\$900-\$3,500	\$405-\$1,742
		Replace ceiling grid and tile	\$418,400	\$41,900-\$180,000	\$18,380-\$79,034 \$80-\$344 \$10,685-\$45,946 \$19,825-\$85,248 \$3,890-\$16,727 \$80-\$344 \$370-\$1,591 \$20-\$86 \$130-\$559 \$6,875-\$29,563 \$665-\$2,860 \$645-\$2,774 \$135-\$581 \$5,000-\$21,500 \$11,875-\$51,063 \$405-\$1,742 \$20,920-\$89,956 \$45,000-\$193,50
Facility Modification	Facility Modification	Modify 5th and 6th grade classrooms, locker hallway space and East entrance to achieve proper classroom space	\$900,000	\$90,000-\$387,000	\$45,000-\$193,500
		Regrade and pave the school parking lot	\$150,000	\$15,000-\$64,500	\$7,500-\$32,250
Facility	Facility	Add parking spaces along North side of facility	No cost provided	N/A	N/A
Facility Upgrade	Upgrade	Replace older outside building and parking lot lighting with LED light fixtures	No cost provided	N/A	N/A
		Replace interior classroom and hallway lighting to LED	No cost provided	N/A	N/A
IT	IT	Replace teacher laptops (approximately 57 new MacBrook Pro laptops)	\$115,000	\$11,500-\$49,500	\$5,750-\$24,725
Security	Security	Update security cameras	No cost provided	N/A	N/A

Estimated Total Construction Costs (in 2021 Dollars): \$3,164,600 Estimated Project Management Costs Range: \$317,200 - \$1,361,500 Estimated Inflation Range: \$158,230 - \$680,389


Estimated Total Project Costs: \$3,640,030 - \$5,206,489


Summary of Projects	Total Cost			
2019-2020 Completed Projects				
HVAC Roof Top Units	\$675,715			
2021 Contracted Projects				
No projects contracted for 2021	N/A			
2022 Scheduled Projects				
Generators	\$404,354			

15035 Compark Blvd Parker, CO 80134 Chaparral High School Feeder, K-8 School built in 2016 Opened in 2016

Site Acreage: 7.2

Parker Performing Arts-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier





Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	No capital projects identifi	ed at this ti	me.	

^{**}DCSD charter schools submit facility and infrastructure needs to the Planning Department for inclusion in the Master Capital Plan. Facility and infrastructure needs were not submitted by Parker Performing Arts Charter in 2021 for inclusion in the Master Capital Plan.

4085 Lark Sparrow Street Highlands Ranch, CO 80126 Highlands Ranch High School Feeder Area, K-8

School built in 1997 Opened in 2003


Site Acreage: 5.28 Facility Square Feet: 35,533

Platte River Academy-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier



Estimated Total Construction Costs (in 2021 Dollars): \$1,230,500 Estimated Total Project Costs: \$1,415,625 - \$2,024,858

Note Estimated total costs include facility modifications and new construction needs. These items were not assigned a Tier or Priority score by Platte River Academy Charter School and therefor are not displayed on the graph above.



Tier	Project Type	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
1	Maintenance	Ballasted EPDM Roofing	\$367,500	\$36,800-\$158,100	\$18,375-\$79,013
		Carpet Replacement	\$150,000	\$15,000-\$64,500	\$7,500-\$32,250
		Air Duct Cleaning	\$16,700	\$1,700-\$7,200	\$835-\$3,591
		Concrete Curb and Gutter Repair	\$7,800	\$800-\$3,400	\$390-\$1,677
	Capital	Internal painting	\$3,400	\$400-\$1,500	\$170-\$731
2	Renewal	Mill and overlay parking lot	\$111,100	\$11,200-\$47,800	\$5,555-\$23,887
		Replace plumbing Fixtures	\$11,200	\$1,200-\$4,900	\$560-\$2,408
		Replace/Add Parking Lot Signage	\$5,600	\$600-\$2,500	\$280-\$1,204
		Resurface gym floor	\$27,800	\$2,800-\$12,000	\$1,390-\$5,977
	Security	Upgrade Video Surveillance System	\$35,000	\$3,500-\$15,100	\$1,750-\$7,525
		Expand sink area and drainage in Art Room	\$27,800	\$2,800-\$12,000	\$1,390-\$5,977
	Capital	Maintenance work on playing field (drainage, aerate, seeding, top dress)	\$20,000	\$2,000-\$8,600	\$1,000-\$4,300
3	Renewal	Replace playground (equipment and turf)	\$500,000	\$250,000-\$250,000	\$25,000-\$107,500
		Repair and Replacement of Wood Fence	\$6,700	\$700-\$2,900	\$335-\$1,441
4	Capital Renewal	Bark Ground Cover	\$11,200	\$1,200-\$4,900	\$560-\$2,408
Facility Modification	Facility	Install artificial turf field	\$750,000	\$250,000-\$250,000	\$37,500-\$161,250
	Modification	Expand parking lot	\$1,500,000	\$250,000-\$250,000	\$75,000-\$322,500
New	New	Additional classrooms	\$4,000,000	\$500,000-\$500,000	\$200,000-\$860,000
Construction	Construction	Gymnasium with performing arts facilities	\$2,000,000	\$250,000-\$250,000	\$100,000-\$430,000

Estimated Total Construction Costs (in 2021 Dollars): \$1,230,500 Estimated Project Management Costs Range: \$123,600 - \$529,800 Estimated Inflation Range: \$61,525 - \$264,558

Estimated Total Project Costs: \$1,415,625 - \$2,024,858


Summary of Projects	Total Cost
2019-2020 Completed Projects	
HVAC Roof Top Units & Controls Phone System	\$959,888
2021 Contracted Projects	
No projects contracted for 2021	N/A

3954 Trail Boss Ln. Castle Rock, CO 80104 Douglas County High School Feeder, K-8 School built/opened in 2017

Site Acreage: 15.969

Parker Performing Arts-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier and Priority





Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	N		1 • .•	
	No capital projects id	entified at t	his time.	

^{**}DCSD charter schools submit facility and infrastructure needs to the Planning Department for inclusion in the Master Capital Plan. Facility and infrastructure needs were not submitted by Renaissance Secondary School Charter in 2021 for inclusion in the Master Capital Plan.




6161 Business Center Drive Highlands Ranch, CO 80132 Highlands Ranch High School Feeder Area, K-12

Opened in 2010


Site Acreage: 14 Facility Square Feet: 110,000

Sky View Academy-Identified Facility Projects Estimated Construction Costs (in 2021Dollars) by Site Component Tier



Estimated Total Construction Costs (in 2021 Dollars): \$13,031,400 Estimated Total Project Costs: \$14,986,170 - \$21,437,051

Note Estimated total costs include facility upgrade items, mobiles, and an addition. These items were not assigned a Tier or Priority score and therefore will not be displayed on the graph above.



Tier	Project Type	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
		Replace HVAC units	\$2,100,000	\$210,000-\$903,000	\$105,000-\$451,500
		Replace fire alarm system	\$900,000	\$90,000-\$387,000	\$45,000-\$193,500
1	Capital	Replace water heater	\$10,000	\$1,000-\$4,300	\$500-\$2,150
	Renewal	Three (3) LED lights to light underground playground area	\$10,000	\$1,000-\$4,300	\$500-\$2,150
		Door hardware upgrades	\$15,000	\$1,500-\$6,500	\$750-\$3,225
		Repair VCT in cafeteria	\$40,000	\$4,000-\$17,200	\$2,000-\$8,600
		Replace carpet in elementary section	\$450,000	\$45,000-\$193,500	\$22,500-\$96,750
	Camital	Curb repair	\$50,000	\$5,000-\$21,500	\$2,500-\$10,750
	Capital Renewal	Repair lighting control system	\$20,000	\$2,000-\$8,600	\$1,000-\$4,300
	Kenewai	Recaulk, seal and paint exterior	\$200,000	\$20,000-\$86,000	\$10,000-\$43,000
		Resurface parking lot	\$500,000	\$50,000-\$215,000	\$25,000-\$107,500
2		Weight room flooring	\$4,000	\$400-\$1,800	\$200-\$860
	IT	Device replacement	\$35,000	\$3,500-\$15,100	\$1,750-\$7,525
	''	Upgrade smartboard technology	\$70,000	\$7,000-\$30,100	\$3,500-\$15,050
	Coourity	Install additional Access Control/Door Alarms/Buzzers	\$30,000	\$3,000-\$12,900	\$1,500-\$6,450
	Security	Install additional security cameras, replace cameras	\$85,000	\$8,500-\$36,600	\$4,250-\$18,275
		Add additional parking	\$388,700	\$38,900-\$167,200	\$19,435-\$83,571
		Upgrade to LED lighting	\$150,000	\$15,000-\$64,500	\$7,500-\$32,250
3	Capital	Soundproof gym (sound boards)	\$10,000	\$1,000-\$4,300	\$500-\$2,150
,	Renewal	Improvements to gym sound system and speakers	\$10,000	\$1,000-\$4,300	\$500-\$2,150
		Repair lower half of gym wall	\$10,000	\$1,000-\$4,300	\$500-\$2,150
4	Capital Renewal	Clean up landscape	\$10,000	\$1,000-\$4,300	\$500-\$2,150
		Install 2 lane track around athletic field	\$175,000	\$17,500-\$75,300	\$8,750-\$37,625
		Repair and replace turf field	\$40,000	\$4,000-\$17,200	\$2,000-\$8,600
Facility	Facility	Add additional parking	\$388,700	\$38,900-\$167,200	\$19,435-\$83,571
Upgrade	Upgrade	Add lighting to athletic field	\$200,000	\$20,000-\$86,000	\$10,000-\$43,000
		Expand library	\$20,000	\$2,000-\$8,600	\$1,000-\$4,300
		Perform traffic flow study	\$10,000	\$1,000-\$4,300	\$500-\$2,150
Building Addition	Building Addition	Elementary Addition	\$7,000,000	\$700,000-\$3,010,000	\$350,000-\$1,505,000
Mobiles	Mobiles	Add modulars	\$100,000	\$10,000-\$43,000	\$5,000-\$21,500

Estimated Total Construction Costs (in 2021 Dollars): \$13,031,400 Estimated Project Management Costs Range: \$1,303,200 - \$5,603,900 Estimated Inflation Range: \$651,570 - \$2,801,751

Estimated Total Project Costs: \$14,986,170 - \$21,437,051

Summary of Projects	Total Cost
2019-2020 Completed Projects	
Electrical (Exterior Lighting & Light Fixture)	\$15,461
2021 Contracted Projects	
No projects contracted for 2021	N/A
2022 Scheduled Projects	
Doors & door hardware	\$202,152

8773 Ridgeline Boulevard Highlands Ranch, CO 80129 Mountain Vista High School Feeder Area, K-12

Opened in 2011

Site Acreage: 10


Facility Square Feet: 134,000

STEM School Highlands Ranch-Identified Facility Projects Estimated Construction Costs (in 2021 Dollars) by Site Component Tier



Estimated Total Construction Costs (in 2019 Dollars): \$2,849,300 Estimated Total Project Costs: \$3,278,065 - \$4,688,700

Note Estimated total costs include facility upgrade and facility modification items. These items were not assigned a Tier or Priority score by STEM School and therefore will not be displayed on the graph above.



Tier	Project Type	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
1	IT	Procure and replace IT network switches	\$23,400	\$2,400-\$10,100	\$1,170-\$5,031
2	Capital Renewal	Replacement flooring	\$27,800	\$2,800-\$12,000	\$1,390-\$5,977
	Keriewai	Replace MS kitchen door and frame	\$3,900	\$400-\$1,700	\$195-\$839
3	Capital Renewal	Ridgeline roof replacement	\$547,500	\$54,800-\$235,500	\$27,375-\$117,713
		ES RTU # 5B & 6B Replacement	\$350,000	\$34,703-\$34,703	\$17,500-\$75,250
		Ext. caulking weatherization HS	\$15,000	\$4,500-\$4,500	\$750-\$3,225
		Ext. joint weatherization ES	\$150,000	\$4,500-\$4,500	\$7,500-\$32,250
		Paint - Ext. water infiltration HS	\$66,000	\$19,800-\$19,800	\$3,300-\$14,190
		Paint - Ext. /water infiltration/ ES	\$72,000	\$19,800-\$19,800	\$3,600-\$15,480
		Carpet Replacement	\$50,000	\$21,500-\$21,500	\$2,500-\$10,750
		Roof replacement	\$85,300	\$29,900-\$29,900	\$4,265-\$18,340
Canital	Camital	Lot asphalt mill and overlay care	\$47,100	\$9,000-\$9,000	\$2,355-\$10,127
Capital Renewal	Capital Renewal	MS/HS roof replacement 2025	\$493,000	\$147,900-\$147,900	\$24,650-\$105,995
Kellewal	Kenewai	Roof clean, walkway pavers, etc.	\$12,000	\$4,600-\$4,600	\$600-\$2,580
		Replace existing exhaust fans	\$10,000	\$6,450-\$6,450	\$500-\$2,150
		ES water heater and piping retrofit	\$17,600	\$1,500-\$1,500	\$880-\$3,784
		Cafeteria sound attenuation	\$8,000	\$3,900-\$3,900	\$400-\$1,720
		MS Café electrical adds	\$3,600	\$1,750-\$1,750	\$180-\$774
		Gym sound attenuation	\$12,000	\$6,600-\$6,600	\$600-\$2,580
		RTU # old 7A Carrier 10 ton	\$72,000	\$20,000-\$20,000	\$3,600-\$15,480
		RTU # old 5A Carrier 5 ton	\$40,000	\$15,000-\$15,000	\$2,000-\$8,600
		Monument Sign refacing	\$9,400	\$1,000-\$4,100	\$470-\$2,021
		P-TechProgram/Project Fit-up	\$200,000	\$58,400-\$58,400	\$10,000-\$43,000
Facility	Facility	Cyber Security Program Fit-up	\$234,000	\$46,700-\$46,700	\$11,700-\$50,310
Modification	Facility Modification	Nursing program Fit-up	\$165,800	\$35,000-\$35,000	\$8,290-\$35,647
Modification	14.00IIICation	New Grades 2-5 Playground	\$175,000	\$2,875-\$2,875	\$8,750-\$37,625
		Ridgeline entrance re-alignment	\$4,000,000	\$80,000-\$80,000	\$200,000-\$860,000
		HS Patio Tent	\$38,500	\$4,000-\$4,000	\$1,925-\$8,278

Estimated Total Construction Costs (in 2021 Dollars): \$2,849,300 Estimated Project Management Costs Range: \$286,300 - \$1,226,800 Estimated Inflation Range: \$142,465-\$612,600

Estimated Total Project Costs: \$3,278,065 - \$4,688,700

Summary of Projects	Total Cost
2019-2020 Completed Projects	
No projects completed in 2019-20	N/A
2021 Contracted Projects	
Fire Alarm HVAC Roof Top Units & Controls	\$968,578
2022 Scheduled Projects	
Electrical (switchgear)	\$273,759

STEM School Highlands Ranch Charter School cont.

Tier	Project Type	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
		MS Patio / Flagpole	\$45,000	\$4,500-\$19,400	\$2,250-\$9,675
		Site Pratice / play field /lawn	\$888,300	\$88,900-\$382,000	\$44,415-\$190,985
		STEM DDC Controls	\$144,700	\$11,576-\$11,576	\$7,235-\$31,111
Facility	Facility	Replace school store front doors	\$16,500	\$2,000-\$2,000	\$825-\$3,548
Upgrade	Upgrade	Replace MS/HS/ lights to LED	\$78,700	\$9,500-\$9,500	\$3,935-\$16,921
		Replace ES lights to LED	\$50,300	\$6,000-\$6,000	\$2,515-\$10,815
		Site Xeriscape	\$85,000	\$10,200-\$10,200	\$4,250-\$18,275
		Replace 2nd trash enclosure	\$24,600	\$4,690-\$4,690	\$1,230-\$5,289
Building	Building	2 story classroom/cafe add	\$3,800,800	\$500,000-\$500,000	\$190,040-\$817,172
Addition	Addition	2 story classroom/K1 Play add	\$3,500,000	\$500,000-\$500,000	\$175,000-\$752,500
		New network servers	\$13,300	\$3,400-\$3,400	\$665-\$2,860
		Intrusion Detect annunciation/control	\$16,500	\$4,200-\$4,200	\$825-\$3,548
IT	IT	Mass notification messaging system	\$21,000	\$11,900-\$11,900	\$1,050-\$4,515
		Electronic Sys. interface intregration	\$7,900	\$3,500-\$3,500	\$395-\$1,699
		Pik My Kid expansion software	\$4,500	\$2,450-\$2,450	\$225-\$968
		MS café window safety tinting	\$10,000	\$4,300-\$4,300	\$500-\$2,150
Security	Security	Open Options access control	\$24,000	\$5,700-\$5,700	\$1,200-\$5,160
		Louroe Duress systems	\$37,800	\$5,670-\$5,670	\$1,890-\$8,127
New	New	Relocate MS cafeteria	\$1,500,000	\$270,000-\$270,000	\$75,000-\$322,500
Construction	Construction	New CHASSA Gym	\$5,000,000	\$850,000-\$850,000	\$250,000-\$1,075,000


This page left intentionally blank

2490 South Perry Street Castle Rock, CO 80104 Douglas County High School Feeder Area, K-6 Opened in 2015

Site Acreage: 7 Facility Square Feet: 39,663

World Compass Academy-Identified Facility Projects Estimated Construction Costs (in 2021Dollars) by Site Component Tier






Tier & Priority Class	Project Description	Estimated Construction Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs
	No expiral municipal descriptions			
	No capital projects identi	ned at this	ime.	

^{**}DCSD charter schools submit facility and infrastructure needs to the Planning Department for inclusion in the Master Capital Plan. Facility and infrastructure needs were not submitted by World Compass Academy Charter in 2021 for inclusion in the Master Capital Plan.



2021-2025 Capital Needs

Estimated Cost (in 2021 Dollars)



Capital Item	Estimated Capital Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs	Estimated Total Project Cost
New Construction (1-5, DCSD Standards)	\$423,089,448	\$0	\$0	\$423,089,448
Facility Reinvestment (Neighborhood, Magnet, Alt Schools, Support Facilities)	\$120,250,900	\$12,003,800-\$51,706,700	\$6,012,545-\$25,854,133	\$138,267,245-\$197,811,544
Charter Schools	\$55,594,330	\$6,948,534-\$15,293,034	\$2,779,217-\$11,950,631	\$65,322,081-\$82,837,995
Safety & Security	\$49,926,700	\$0	\$0	\$49,926,700
Transportation	\$32,755,000	\$0	\$0	\$32,755,000
Information Technology	\$32,300,000	\$0	\$0	\$32,300,000
FFE	\$6,785,000	\$678,500-\$2,917,600	\$339,250-\$1,458,780	\$7,802,750-\$11,161,380
Mobiles	\$6,600,000	\$0	\$330,000-\$1,419,000	\$6,930,000-\$8,019,000
Support Fleet	\$5,915,820	\$0	\$0	\$5,915,820
Athletics	\$1,057,500	\$105,900-\$454,900	\$52,880-\$227,380	\$1,216,280-\$1,739,780
ADA Contingency	\$500,000	\$0	\$25,000-\$107,500	\$525,000-\$607,500
SPED Contingency	\$500,000	\$0	\$25,000-\$107,500	\$525,000-\$607,500
Playgrounds	\$200,000	\$0	\$10,000-\$43,000	\$210,000-\$243,000

Estimated Cost (in 2021 Dollars): \$735,474,698

Estimated Project Management Costs Range: \$19,736,734 - \$70,372,234


Estimated Inflation Range: \$9,573,892 - \$41,167,923

Estimated Total Cost: \$764,785,324 - \$847,014,666



2021-2025 Capital Needs by Tier

Estimated Cost (in 2021 Dollars)



Note Untiered needs include ADA compliance contingency costs, Special Education needs contingency costs, some charter school needs, new construction, and playground equipment.

Tier	Estimated Capital Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs	Estimated Total Project Cost
Tier 1	\$109,128,100	\$4,900,720-\$20,977,820	\$2,443,804-\$10,508,357	\$116,472,624-\$140,614,277
Tier 2	\$94,460,940	\$5,397,260-\$23,154,760	\$2,694,252-\$11,585,280	\$102,552,452-\$129,200,980
Tier 3	\$47,976,030	\$3,106,370-\$12,525,970	\$1,782,802-\$7,666,051	\$52,865,202-\$68,168,051
Tier 4	\$11,647,360	\$386,840-\$1,638,940	\$194,893-\$838,040	\$12,229,093-\$14,124,340
Tier 1 Funded by the 2018 Bond	\$3,486,500	\$348,400-\$1,499,300	\$174,325-\$749,598	\$4,009,225-\$5,735,398
Untiered	\$468,775,768	\$5,597,144-\$10,575,444	\$2,283,816-\$9,820,409	\$476,656,728-\$489,171,621


Estimated Cost (in 2021 Dollars): \$735,474,698

Estimated Project Management Costs Range: \$19,736,734 - \$70,372,234


Estimated Inflation Range: \$9,573,892 - \$41,167,923

Estimated Total Cost: \$764,785,324 - \$847,014,666

2021-2025 New Construction





Total: \$423,089,448



Total: \$360,956,908

2026-2031 New Construction







Appendix 1: History of Capital Improvements Neighborhood, Magnet, Alternative Schools, and Support Facilities

cres Green Elementary		
1990 3,100 SF Addition	2005 Roof Replacement	2016 Smoke Detectors & Horn Strobe Replacement
1995 Drainage	2005 Student Bathrooms	2016 Replace Electrical Switchgear, Transformers, & Panels
1997 Drainage/Fire Hydrant	2005 Security Access Control	2017 Exterior Maintenance Painting
1998 Air Conditioning	2008 Elevator	2018 Makeup Air Unit
2000 2,600 SF Addition	2011 White Boards	2018 Painting
2000 Playground Improvements	2012 Flooring Replacement	2019 Upgrade control system
2004 Security Cameras/Radios	2013 Daylighting Enhancement	2019 Replace interior door hinges
2004 Technology Improvements	2014 Resurface Gymnasium Floor	2019 Interior doors
rrowwood Elementary		
2004 Mechanical Repair	2012 Tile Replacement	2019 Replace kitchen flooring
2004 Movement Repair	2013 Resurface Paved Areas	2019 Replacer door hardware with restrictive key system
2004 Technology Improvements	2014 Clock System	2019 Upgrade irrigation system
2004 Security Cameras/Radios	2014 Mechanical System Automated Controls	2019 Replace generator
2004 Security Access Control	2014 Carpet	2019 Replace and paint roof
2010 Carpet Replacement	2019 Replace fire alarm system	2019 Replace sink countertops
2011 Carpet Replacement	2019 Reseal and caulk exterior wall joints and wi	2019 Replace cooling towers
ear Canyon Elementary		
1996 Parking Lot Improvements	2003 Carpet Replacement	2012 Carpet Replacement - Mobiles
1997 Air Conditioning	2004 Technology Improvements	2013 Replace Restroom Floors
2003 Playground Improvements	2004 Security Cameras/Radios	2017 Replace Generator
2003 Bathroom Improvements	2004 Security Access Control	2017 Window Replacement-Multiple Areas
2003 Make-up Air	2009 3,100 SF Addition	2017 Replace Entry Walk-Off Carpet
uffalo Ridge Elementary		
2006 Carpet Replacement	2012 Repair Bus Loop Paving	2014 Clock System
0000 B 1: 1 /1	2012 Carpet Replacement - Mobiles	2017 Rebuild Generator
2006 Parking Lot Improvements	2012 Carper Replacement - Mobiles	
2006 Playground Improvements	2013 Flooring Repair	2018 Generator Rebuild
2006 Playground Improvements 2006 Security Access Control		
2006 Playground Improvements	2013 Flooring Repair	
2006 Playground Improvements 2006 Security Access Control ridge North 2018 Additional Bridge Classrooms antril	2013 Flooring Repair 2013 Fire Alarm Panel Replacement	2018 Generator Rebuild
2006 Playground Improvements 2006 Security Access Control ridge North 2018 Additional Bridge Classrooms antril 1994 Roof repair	2013 Flooring Repair 2013 Fire Alarm Panel Replacement 2013 Gym and Pre-school Roof	2018 Generator Rebuild 2015 Replace Cooling in Gym
2006 Playground Improvements 2006 Security Access Control ridge North 2018 Additional Bridge Classrooms antril 1994 Roof repair 1996 Asbestos Removal	2013 Flooring Repair 2013 Fire Alarm Panel Replacement 2011 Gym and Pre-school Roof 2006 Parking Lot	2018 Generator Rebuild 2015 Replace Cooling in Gym 2015 Restore Lunchroom
2006 Playground Improvements 2006 Security Access Control ridge North 2018 Additional Bridge Classrooms antril 1994 Roof repair 1996 Asbestos Removal 1997 Roof Replacement	2013 Flooring Repair 2013 Fire Alarm Panel Replacement 2011 Gym and Pre-school Roof 2006 Parking Lot 2006 Upgrade Local Area Network	2018 Generator Rebuild 2015 Replace Cooling in Gym
2006 Playground Improvements 2006 Security Access Control ridge North 2018 Additional Bridge Classrooms antril 1994 Roof repair 1996 Asbestos Removal	2013 Flooring Repair 2013 Fire Alarm Panel Replacement 2011 Gym and Pre-school Roof 2006 Parking Lot	2018 Generator Rebuild 2015 Replace Cooling in Gym 2015 Restore Lunchroom
2006 Playground Improvements 2006 Security Access Control ridge North 2018 Additional Bridge Classrooms antril 1994 Roof repair 1996 Asbestos Removal 1997 Roof Replacement 2000 Carpet 2001 Boiler	2013 Flooring Repair 2013 Fire Alarm Panel Replacement 2011 Gym and Pre-school Roof 2006 Parking Lot 2006 Upgrade Local Area Network 2006 Fire Alarms	2018 Generator Rebuild 2015 Replace Cooling in Gym 2015 Restore Lunchroom
2006 Playground Improvements 2006 Security Access Control ridge North 2018 Additional Bridge Classrooms antril 1994 Roof repair 1996 Asbestos Removal 1997 Roof Replacement 2000 Carpet	2013 Flooring Repair 2013 Fire Alarm Panel Replacement 2011 Gym and Pre-school Roof 2006 Parking Lot 2006 Upgrade Local Area Network 2006 Fire Alarms	2018 Generator Rebuild 2015 Replace Cooling in Gym 2015 Restore Lunchroom
2006 Playground Improvements 2006 Security Access Control ridge North 2018 Additional Bridge Classrooms antril 1994 Roof repair 1996 Asbestos Removal 1997 Roof Replacement 2000 Carpet 2001 Boiler astle Rock Elementary	2013 Flooring Repair 2013 Fire Alarm Panel Replacement 2001 Gym and Pre-school Roof 2006 Parking Lot 2006 Upgrade Local Area Network 2006 Fire Alarms 2010 Exterior Paint	2018 Generator Rebuild 2015 Replace Cooling in Gym 2015 Restore Lunchroom 2015 ADA Restroom Addition
2006 Playground Improvements 2006 Security Access Control ridge North 2018 Additional Bridge Classrooms antril 1994 Roof repair 1996 Asbestos Removal 1997 Roof Replacement 2000 Carpet 2001 Boiler astle Rock Elementary 1996 Playground Improvements	2013 Flooring Repair 2013 Fire Alarm Panel Replacement 2001 Gym and Pre-school Roof 2006 Parking Lot 2006 Upgrade Local Area Network 2006 Fire Alarms 2010 Exterior Paint	2018 Generator Rebuild 2015 Replace Cooling in Gym 2015 Restore Lunchroom 2015 ADA Restroom Addition
2006 Playground Improvements 2006 Security Access Control ridge North 2018 Additional Bridge Classrooms antril 1994 Roof repair 1996 Asbestos Removal 1997 Roof Replacement 2000 Carpet 2001 Boiler astle Rock Elementary 1996 Playground Improvements 1999 Air Conditioning	2013 Flooring Repair 2013 Fire Alarm Panel Replacement 2001 Gym and Pre-school Roof 2006 Parking Lot 2006 Upgrade Local Area Network 2006 Fire Alarms 2010 Exterior Paint 2004 Technology Improvements 2004 Security Cameras/Radios	2018 Generator Rebuild 2015 Replace Cooling in Gym 2015 Restore Lunchroom 2015 ADA Restroom Addition 2012 Playground Paving 2012 Carpet Replacement - Mobiles
2006 Playground Improvements 2006 Security Access Control ridge North 2018 Additional Bridge Classrooms antril 1994 Roof repair 1996 Asbestos Removal 1997 Roof Replacement 2000 Carpet 2001 Boiler astle Rock Elementary 1996 Playground Improvements 1999 Air Conditioning 2001 Playground Improvements	2013 Flooring Repair 2013 Fire Alarm Panel Replacement 2001 Gym and Pre-school Roof 2006 Parking Lot 2006 Upgrade Local Area Network 2006 Fire Alarms 2010 Exterior Paint 2004 Technology Improvements 2004 Security Cameras/Radios 2004 Security Access Control	2018 Generator Rebuild 2015 Replace Cooling in Gym 2015 Restore Lunchroom 2015 ADA Restroom Addition 2012 Playground Paving 2012 Carpet Replacement - Mobiles
2006 Playground Improvements 2006 Security Access Control ridge North 2018 Additional Bridge Classrooms antril 1994 Roof repair 1996 Asbestos Removal 1997 Roof Replacement 2000 Carpet 2001 Boiler astle Rock Elementary 1996 Playground Improvements 1999 Air Conditioning 2001 Playground Improvements 2003 Re-ballast	2013 Flooring Repair 2013 Fire Alarm Panel Replacement 2001 Gym and Pre-school Roof 2006 Parking Lot 2006 Upgrade Local Area Network 2006 Fire Alarms 2010 Exterior Paint 2004 Technology Improvements 2004 Security Cameras/Radios 2004 Security Access Control 2011 White Boards	2018 Generator Rebuild 2015 Replace Cooling in Gym 2015 Restore Lunchroom 2015 ADA Restroom Addition 2012 Playground Paving 2012 Carpet Replacement - Mobiles
2006 Playground Improvements 2006 Security Access Control ridge North 2018 Additional Bridge Classrooms antril 1994 Roof repair 1996 Asbestos Removal 1997 Roof Replacement 2000 Carpet 2001 Boiler astle Rock Elementary 1996 Playground Improvements 1999 Air Conditioning 2001 Playground Improvements 2003 Re-ballast 2004 2,965 SF Addition	2013 Flooring Repair 2013 Fire Alarm Panel Replacement 2001 Gym and Pre-school Roof 2006 Parking Lot 2006 Upgrade Local Area Network 2006 Fire Alarms 2010 Exterior Paint 2004 Technology Improvements 2004 Security Cameras/Radios 2004 Security Access Control 2011 White Boards	2018 Generator Rebuild 2015 Replace Cooling in Gym 2015 Restore Lunchroom 2015 ADA Restroom Addition 2012 Playground Paving 2012 Carpet Replacement - Mobiles
2006 Playground Improvements 2006 Security Access Control ridge North 2018 Additional Bridge Classrooms antril 1994 Roof repair 1996 Asbestos Removal 1997 Roof Replacement 2000 Carpet 2001 Boiler astle Rock Elementary 1996 Playground Improvements 1999 Air Conditioning 2001 Playground Improvements 2003 Re-ballast 2004 2,965 SF Addition astle Rock Middle School	2013 Flooring Repair 2013 Fire Alarm Panel Replacement 2001 Gym and Pre-school Roof 2006 Parking Lot 2006 Upgrade Local Area Network 2006 Fire Alarms 2010 Exterior Paint 2004 Technology Improvements 2004 Security Cameras/Radios 2004 Security Access Control 2011 White Boards 2012 Parking Lot Paving	2015 Replace Cooling in Gym 2015 Restore Lunchroom 2015 ADA Restroom Addition 2012 Playground Paving 2012 Carpet Replacement - Mobiles 2014 Clock System
2006 Playground Improvements 2006 Security Access Control ridge North 2018 Additional Bridge Classrooms antril 1994 Roof repair 1996 Asbestos Removal 1997 Roof Replacement 2000 Carpet 2001 Boiler astle Rock Elementary 1996 Playground Improvements 1999 Air Conditioning 2001 Playground Improvements 2003 Re-ballast 2004 2,965 SF Addition astle Rock Middle School 2004 Technology Improvements	2013 Flooring Repair 2013 Fire Alarm Panel Replacement 2001 Gym and Pre-school Roof 2006 Parking Lot 2006 Upgrade Local Area Network 2006 Fire Alarms 2010 Exterior Paint 2004 Technology Improvements 2004 Security Cameras/Radios 2004 Security Access Control 2011 White Boards 2012 Parking Lot Paving	2018 Generator Rebuild 2015 Replace Cooling in Gym 2015 Restore Lunchroom 2015 ADA Restroom Addition 2012 Playground Paving 2012 Carpet Replacement - Mobiles 2014 Clock System 2018 Hallway Carpet
2006 Playground Improvements 2006 Security Access Control ridge North 2018 Additional Bridge Classrooms antril 1994 Roof repair 1996 Asbestos Removal 1997 Roof Replacement 2000 Carpet 2001 Boiler astle Rock Elementary 1996 Playground Improvements 1999 Air Conditioning 2001 Playground Improvements 2003 Re-ballast 2004 2,965 SF Addition astle Rock Middle School 2004 Technology Improvements 2004 Security Cameras	2013 Flooring Repair 2013 Fire Alarm Panel Replacement 2011 Gym and Pre-school Roof 2006 Parking Lot 2006 Upgrade Local Area Network 2006 Fire Alarms 2010 Exterior Paint 2004 Technology Improvements 2004 Security Cameras/Radios 2004 Security Access Control 2011 White Boards 2012 Parking Lot Paving 2014 Clock System 2014 Restroom Flooring	2018 Generator Rebuild 2015 Replace Cooling in Gym 2015 Restore Lunchroom 2015 ADA Restroom Addition 2012 Playground Paving 2012 Carpet Replacement - Mobiles 2014 Clock System 2018 Hallway Carpet 2019 Update HVAC 2019 Commission system
2006 Playground Improvements 2006 Security Access Control ridge North 2018 Additional Bridge Classrooms antril 1994 Roof repair 1996 Asbestos Removal 1997 Roof Replacement 2000 Carpet 2001 Boiler astle Rock Elementary 1996 Playground Improvements 1999 Air Conditioning 2001 Playground Improvements 2003 Re-ballast 2004 2,965 SF Addition astle Rock Middle School 2004 Technology Improvements 2004 Security Cameras 2004 Security Access Control 2006 HVAC Upgrades	2013 Flooring Repair 2013 Fire Alarm Panel Replacement 2011 Gym and Pre-school Roof 2006 Parking Lot 2006 Upgrade Local Area Network 2006 Fire Alarms 2010 Exterior Paint 2004 Technology Improvements 2004 Security Cameras/Radios 2004 Security Access Control 2011 White Boards 2012 Parking Lot Paving 2014 Clock System 2014 Restroom Flooring 2014 Domestic Hot Water System Upgrade 2017 Chiller Replacement	2018 Generator Rebuild 2015 Replace Cooling in Gym 2015 Restore Lunchroom 2015 ADA Restroom Addition 2012 Playground Paving 2012 Carpet Replacement - Mobiles 2014 Clock System 2018 Hallway Carpet 2019 Update HVAC 2019 Commission system 2019 Replace generator and associated equipment
2006 Playground Improvements 2006 Security Access Control ridge North 2018 Additional Bridge Classrooms antril 1994 Roof repair 1996 Asbestos Removal 1997 Roof Replacement 2000 Carpet 2001 Boiler astle Rock Elementary 1996 Playground Improvements 1999 Air Conditioning 2001 Playground Improvements 2003 Re-ballast 2004 2,965 SF Addition astle Rock Middle School 2004 Technology Improvements 2004 Security Cameras 2004 Security Access Control 2006 HVAC Upgrades 2012 Kitchen Floor Repair	2013 Flooring Repair 2013 Fire Alarm Panel Replacement 2001 Gym and Pre-school Roof 2006 Parking Lot 2006 Upgrade Local Area Network 2006 Fire Alarms 2010 Exterior Paint 2004 Technology Improvements 2004 Security Cameras/Radios 2004 Security Access Control 2011 White Boards 2012 Parking Lot Paving 2014 Clock System 2014 Restroom Flooring 2014 Domestic Hot Water System Upgrade 2017 Chiller Replacement 2017 Addition of Secured Folding Partition Wall a	2018 Generator Rebuild 2015 Replace Cooling in Gym 2015 Restore Lunchroom 2015 ADA Restroom Addition 2012 Playground Paving 2012 Carpet Replacement - Mobiles 2014 Clock System 2018 Hallway Carpet 2019 Update HVAC 2019 Commission system 2019 Replace generator and associated equipment 2019 Replace carpet and VCT flooring in classroom
2006 Playground Improvements 2006 Security Access Control ridge North 2018 Additional Bridge Classrooms antril 1994 Roof repair 1996 Asbestos Removal 1997 Roof Replacement 2000 Carpet 2001 Boiler astle Rock Elementary 1996 Playground Improvements 1999 Air Conditioning 2001 Playground Improvements 2003 Re-ballast 2004 2,965 SF Addition astle Rock Middle School 2004 Technology Improvements 2004 Security Cameras 2004 Security Access Control 2006 HVAC Upgrades 2012 Kitchen Floor Repair 2012 Roof Replacement	2013 Flooring Repair 2013 Fire Alarm Panel Replacement 2001 Gym and Pre-school Roof 2006 Parking Lot 2006 Upgrade Local Area Network 2006 Fire Alarms 2010 Exterior Paint 2004 Technology Improvements 2004 Security Cameras/Radios 2004 Security Access Control 2011 White Boards 2012 Parking Lot Paving 2014 Clock System 2014 Restroom Flooring 2014 Domestic Hot Water System Upgrade 2017 Chiller Replacement 2017 Addition of Secured Folding Partition Wall a 2017 Replace Entry Walk-Off Carpet	2018 Generator Rebuild 2015 Replace Cooling in Gym 2015 Restore Lunchroom 2015 ADA Restroom Addition 2012 Playground Paving 2012 Carpet Replacement - Mobiles 2014 Clock System 2018 Hallway Carpet 2019 Update HVAC 2019 Commission system 2019 Replace generator and associated equipment 2019 Replace carpet and VCT flooring in classroom 2019 Replace non-restricted key system with restricted system
2006 Playground Improvements 2006 Security Access Control ridge North 2018 Additional Bridge Classrooms antril 1994 Roof repair 1996 Asbestos Removal 1997 Roof Replacement 2000 Carpet 2001 Boiler astle Rock Elementary 1996 Playground Improvements 1999 Air Conditioning 2001 Playground Improvements 2003 Re-ballast 2004 2,965 SF Addition astle Rock Middle School 2004 Technology Improvements 2004 Security Cameras 2004 Security Access Control 2006 HVAC Upgrades 2012 Kitchen Floor Repair	2013 Flooring Repair 2013 Fire Alarm Panel Replacement 2001 Gym and Pre-school Roof 2006 Parking Lot 2006 Upgrade Local Area Network 2006 Fire Alarms 2010 Exterior Paint 2004 Technology Improvements 2004 Security Cameras/Radios 2004 Security Access Control 2011 White Boards 2012 Parking Lot Paving 2014 Clock System 2014 Restroom Flooring 2014 Domestic Hot Water System Upgrade 2017 Chiller Replacement 2017 Addition of Secured Folding Partition Wall a	2018 Generator Rebuild 2015 Replace Cooling in Gym 2015 Restore Lunchroom 2015 ADA Restroom Addition 2012 Playground Paving 2012 Carpet Replacement - Mobiles 2014 Clock System 2018 Hallway Carpet 2019 Update HVAC 2019 Commission system 2019 Replace generator and associated equipment 2019 Replace carpet and VCT flooring in classroom
2006 Playground Improvements 2006 Security Access Control ridge North 2018 Additional Bridge Classrooms antril 1994 Roof repair 1996 Asbestos Removal 1997 Roof Replacement 2000 Carpet 2001 Boiler astle Rock Elementary 1996 Playground Improvements 1999 Air Conditioning 2001 Playground Improvements 2003 Re-ballast 2004 2,965 SF Addition astle Rock Middle School 2004 Technology Improvements 2004 Security Cameras 2004 Security Cameras 2004 Security Access Control 2006 HVAC Upgrades 2012 Kitchen Floor Repair 2012 Roof Replacement 2013 Fire Alarm Replacement 2013 Refinish Gymnasium Floor	2013 Flooring Repair 2013 Fire Alarm Panel Replacement 2001 Gym and Pre-school Roof 2006 Parking Lot 2006 Upgrade Local Area Network 2006 Fire Alarms 2010 Exterior Paint 2004 Technology Improvements 2004 Security Cameras/Radios 2004 Security Access Control 2011 White Boards 2012 Parking Lot Paving 2014 Clock System 2014 Restroom Flooring 2014 Domestic Hot Water System Upgrade 2017 Chiller Replacement 2017 Addition of Secured Folding Partition Wall a 2017 Replace Entry Walk-Off Carpet	2018 Generator Rebuild 2015 Replace Cooling in Gym 2015 Restore Lunchroom 2015 ADA Restroom Addition 2012 Playground Paving 2012 Carpet Replacement - Mobiles 2014 Clock System 2018 Hallway Carpet 2019 Update HVAC 2019 Commission system 2019 Replace generator and associated equipment 2019 Replace carpet and VCT flooring in classroom 2019 Replace non-restricted key system with restricted system
2006 Playground Improvements 2006 Security Access Control ridge North 2018 Additional Bridge Classrooms antril 1994 Roof repair 1996 Asbestos Removal 1997 Roof Replacement 2000 Carpet 2001 Boiler astle Rock Elementary 1996 Playground Improvements 1999 Air Conditioning 2001 Playground Improvements 2003 Re-ballast 2004 2,965 SF Addition astle Rock Middle School 2004 Technology Improvements 2004 Security Cameras 2004 Security Cameras 2004 Security Cameras 2012 Kitchen Floor Repair 2012 Roof Replacement 2013 Fire Alarm Replacement 2013 Refinish Gymnasium Floor	2013 Flooring Repair 2013 Fire Alarm Panel Replacement 2001 Gym and Pre-school Roof 2006 Parking Lot 2006 Upgrade Local Area Network 2006 Fire Alarms 2010 Exterior Paint 2004 Technology Improvements 2004 Security Cameras/Radios 2004 Security Access Control 2011 White Boards 2012 Parking Lot Paving 2014 Clock System 2014 Restroom Flooring 2014 Domestic Hot Water System Upgrade 2017 Chiller Replacement 2017 Addition of Secured Folding Partition Wall a 2017 Replace Entry Walk-Off Carpet 2018 Blearchers	2018 Generator Rebuild 2015 Replace Cooling in Gym 2015 Restore Lunchroom 2015 ADA Restroom Addition 2012 Playground Paving 2012 Carpet Replacement - Mobiles 2014 Clock System 2018 Hallway Carpet 2019 Update HVAC 2019 Commission system 2019 Replace generator and associated equipment 2019 Replace carpet and VCT flooring in classroom 2019 Replace ink countertops with single surface
2006 Playground Improvements 2006 Security Access Control ridge North 2018 Additional Bridge Classrooms antril 1994 Roof repair 1996 Asbestos Removal 1997 Roof Replacement 2000 Carpet 2001 Boiler astle Rock Elementary 1996 Playground Improvements 1999 Air Conditioning 2001 Playground Improvements 2003 Re-ballast 2004 2,965 SF Addition astle Rock Middle School 2004 Technology Improvements 2004 Security Cameras 2004 Security Cameras 2004 Security Access Control 2006 HVAC Upgrades 2012 Kitchen Floor Repair 2013 Fire Alarm Replacement 2013 Refinish Gymnasium Floor astle View High School 2006 New Construction	2013 Flooring Repair 2013 Fire Alarm Panel Replacement 2001 Gym and Pre-school Roof 2006 Parking Lot 2006 Upgrade Local Area Network 2006 Fire Alarms 2010 Exterior Paint 2004 Technology Improvements 2004 Security Cameras/Radios 2004 Security Access Control 2011 White Boards 2012 Parking Lot Paving 2014 Clock System 2014 Restroom Flooring 2014 Domestic Hot Water System Upgrade 2017 Chiller Replacement 2017 Addition of Secured Folding Partition Wall a 2017 Replace Entry Walk-Off Carpet 2018 Blearchers	2018 Generator Rebuild 2015 Replace Cooling in Gym 2015 Restore Lunchroom 2015 ADA Restroom Addition 2012 Playground Paving 2012 Carpet Replacement - Mobiles 2014 Clock System 2018 Hallway Carpet 2019 Update HVAC 2019 Commission system 2019 Replace generator and associated equipment 2019 Replace carpet and VCT flooring in classroom 2019 Replace sink countertops with single surface
2006 Playground Improvements 2006 Security Access Control ridge North 2018 Additional Bridge Classrooms antril 1994 Roof repair 1996 Asbestos Removal 1997 Roof Replacement 2000 Carpet 2001 Boiler astle Rock Elementary 1996 Playground Improvements 1999 Air Conditioning 2001 Playground Improvements 2003 Re-ballast 2004 2,965 SF Addition astle Rock Middle School 2004 Technology Improvements 2004 Security Cameras 2004 Security Cameras 2004 Security Cameras 2012 Kitchen Floor Repair 2012 Roof Replacement 2013 Fire Alarm Replacement 2013 Refinish Gymnasium Floor	2013 Flooring Repair 2013 Fire Alarm Panel Replacement 2001 Gym and Pre-school Roof 2006 Parking Lot 2006 Upgrade Local Area Network 2006 Fire Alarms 2010 Exterior Paint 2004 Technology Improvements 2004 Security Cameras/Radios 2004 Security Access Control 2011 White Boards 2012 Parking Lot Paving 2014 Clock System 2014 Restroom Flooring 2014 Domestic Hot Water System Upgrade 2017 Chiller Replacement 2017 Addition of Secured Folding Partition Wall a 2017 Replace Entry Walk-Off Carpet 2018 Blearchers	2015 Replace Cooling in Gym 2015 Restore Lunchroom 2015 ADA Restroom Addition 2012 Playground Paving 2012 Carpet Replacement - Mobiles 2014 Clock System 2018 Hallway Carpet 2019 Update HVAC 2019 Commission system 2019 Replace generator and associated equipment 2019 Replace carpet and VCT flooring in classroom 2019 Replace ink countertops with single surface

Chaparral High School	0040 0-66-115: 115	0045 Terrain Orand Brane's '
2002 34,368 SF Addition	2010 Softball Field Fencing	2015 Tennis Court Resurfacing
2004 Flush Valves/Chiller	2010 Chiller	2015 Carpet Replacement - Drama Room
2004 Bleachers	2010 Security Detection System	2017 Building Automation System Upgrade
2004 Security Cameras/Radios	2010 Concrete Slab Repair	2017 Replace Generator
2004 Security Access Control	2011 Chillers	2017 Replace Carpet in Main Hallways, Pod Hallways,
2004 Artificial Turf Playfield	2012 Tile Replacement	and Vestibules
2004 Dugouts	2012 Carpet Replacement - Mobiles	2018 Electrical Panels
2004 Technology Improvements	2013 Synthetic Turf Replacement	2018 Theater Stand Lighting
2006 Clearstory Windows	2013 Interior Door Hardware Replacement	2018 Auxillary Gym Joist Repairs
2006 Parking Lot Improvements	2014 Clock System	2018 Testing and Balancing
2006 Gymnasium Floor	2014 Resurface Track	2019 Replace gym bleachers
2007 Tennis Courts	2014 Intercom and Paging System Replacement	2019 Replace flooring in cafeteria, commons, and hallways
2007 Security Kiosk	2015 Fire Alarm System Replacement	2019 Tennis Court Repair/Resurfacing
2008 Special Education Wing Remodel	2015 Partial Roof Replacement	
Cherokee Trail Elementary		
2001 Air Conditioning	2005 3,000 SF Addition	2014 Resurface Gymnasium Floor
2001 Countertops/Partitions	2005 Playground Improvements	2016 Restroom Countertops Replacement
2003 Reballast	2005 Reballast	2017 Replace Generator
2003 Carpet Replacement	2005 Roof Replacement	2017 Replace Flooring in Restrooms
2004 Security Cameras/Radios	2012 Parking Lot Paving	2017 Replace Entry Walk-Off Closet
2004 Technology Improvements	2012 Playground Paving	2018 RTU Replacement
2004 Security Access Control	2014 Cafeteria Floor Replacement	
Cherry Valley Elementary		
1996 Roof Replacement	2008 Major Renovation	2019 Replace gym and restroom flooring
1998 Playground Improvements	2014 Update Water Well System	2019 Replace non-restricted key system with restricted system
1999 981 SF Addition	2017 Window Replacement-Multiple Areas	2019 Repair soffit on original building
2004 Security Cameras/Radios	2019 Caulk, seal exterior wall	2019 Replace two exterior doors
2004 Technology Improvements	2019 Replace single pane windows	2019 Sidewalks
2005 Security Access Control	3 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	
2006 Parking Lot Improvements		
ů ,		
0: 14:14:01:1		
Cimarron Middle School	2012 Art & Computer Poom Pemodal	2018 Floyator Modernization
2010 New Construction	2012 Art & Computer Room Remodel	2018 Elevator Modernization
	2012 Art & Computer Room Remodel 2018 Landscaping	2018 Elevator Modernization
2010 New Construction 2011 Turn Lane and Stop Light Clear Sky Elementary	2018 Landscaping	
2010 New Construction 2011 Turn Lane and Stop Light Clear Sky Elementary 2008 New Construction	•	2018 Elevator Modernization 2019 Elevator modernization
2010 New Construction 2011 Turn Lane and Stop Light Clear Sky Elementary	2018 Landscaping	
2010 New Construction 2011 Turn Lane and Stop Light Clear Sky Elementary 2008 New Construction 2012 Carpet Replacement - Mobiles Copper Mesa Elementary	2018 Landscaping 2018 Movement Issues	
2010 New Construction 2011 Turn Lane and Stop Light Clear Sky Elementary 2008 New Construction 2012 Carpet Replacement - Mobiles	2018 Landscaping	
2010 New Construction 2011 Turn Lane and Stop Light Clear Sky Elementary 2008 New Construction 2012 Carpet Replacement - Mobiles Copper Mesa Elementary 2006 New Construction Cougar Run Elementary	2018 Landscaping 2018 Movement Issues 2017 Replace Entry Walk-Off Carpet	2019 Elevator modernization
2010 New Construction 2011 Turn Lane and Stop Light Clear Sky Elementary 2008 New Construction 2012 Carpet Replacement - Mobiles Copper Mesa Elementary 2006 New Construction Cougar Run Elementary 2003 Playground Improvements	2018 Landscaping 2018 Movement Issues 2017 Replace Entry Walk-Off Carpet 2014 Clock System	2019 Elevator modernization 2019 Replace generator and associated equipment
2010 New Construction 2011 Turn Lane and Stop Light Clear Sky Elementary 2008 New Construction 2012 Carpet Replacement - Mobiles Copper Mesa Elementary 2006 New Construction Cougar Run Elementary 2003 Playground Improvements 2003 Flooring Improvements	2018 Landscaping 2018 Movement Issues 2017 Replace Entry Walk-Off Carpet 2014 Clock System 2016 Concrete Slab Repairs	2019 Elevator modernization 2019 Replace generator and associated equipment 2019 Recoat exterior wall CMU weather proofing, recaulk control joints
2010 New Construction 2011 Turn Lane and Stop Light Clear Sky Elementary 2008 New Construction 2012 Carpet Replacement - Mobiles Copper Mesa Elementary 2006 New Construction Cougar Run Elementary 2003 Playground Improvements 2003 Flooring Improvements 2004 Security Cameras/Radios	2018 Landscaping 2018 Movement Issues 2017 Replace Entry Walk-Off Carpet 2014 Clock System 2016 Concrete Slab Repairs 2017 Replace Entry Walk-Off Carpet	2019 Elevator modernization 2019 Replace generator and associated equipment 2019 Recoat exterior wall CMU weather proofing, recaulk control joint 2019 Replace exterior windows
2010 New Construction 2011 Turn Lane and Stop Light Clear Sky Elementary 2008 New Construction 2012 Carpet Replacement - Mobiles Copper Mesa Elementary 2006 New Construction Cougar Run Elementary 2003 Playground Improvements 2003 Flooring Improvements 2004 Security Cameras/Radios 2005 Security Access Control	2018 Landscaping 2018 Movement Issues 2017 Replace Entry Walk-Off Carpet 2014 Clock System 2016 Concrete Slab Repairs 2017 Replace Entry Walk-Off Carpet 2018 Makeup Air Unit	2019 Elevator modernization 2019 Replace generator and associated equipment 2019 Recoat exterior wall CMU weather proofing, recaulk control joint 2019 Replace exterior windows 2019 Replace gym carpet
2010 New Construction 2011 Turn Lane and Stop Light Clear Sky Elementary 2008 New Construction 2012 Carpet Replacement - Mobiles Copper Mesa Elementary 2006 New Construction Cougar Run Elementary 2003 Playground Improvements 2003 Flooring Improvements 2004 Security Cameras/Radios 2005 Security Access Control 2007 Carpet Replacement	2018 Landscaping 2018 Movement Issues 2017 Replace Entry Walk-Off Carpet 2014 Clock System 2016 Concrete Slab Repairs 2017 Replace Entry Walk-Off Carpet 2018 Makeup Air Unit 2018 Window Film	2019 Elevator modernization 2019 Replace generator and associated equipment 2019 Recoat exterior wall CMU weather proofing, recaulk control joint 2019 Replace exterior windows 2019 Replace gym carpet 2019 Move hot water heater, install on demand pumps
2010 New Construction 2011 Turn Lane and Stop Light Clear Sky Elementary 2008 New Construction 2012 Carpet Replacement - Mobiles Copper Mesa Elementary 2006 New Construction Cougar Run Elementary 2003 Playground Improvements 2003 Flooring Improvements 2004 Security Cameras/Radios 2005 Security Access Control 2007 Carpet Replacement 2013 Fire Alarm Replacement	2018 Landscaping 2018 Movement Issues 2017 Replace Entry Walk-Off Carpet 2014 Clock System 2016 Concrete Slab Repairs 2017 Replace Entry Walk-Off Carpet 2018 Makeup Air Unit 2018 Window Film 2019 Replace VAV boxes (air distribution system	2019 Elevator modernization 2019 Replace generator and associated equipment 2019 Recoat exterior wall CMU weather proofing, recaulk control joint 2019 Replace exterior windows 2019 Replace gym carpet 2019 Move hot water heater, install on demand pumps 2019 Replace interior door hardware
2010 New Construction 2011 Turn Lane and Stop Light Clear Sky Elementary 2008 New Construction 2012 Carpet Replacement - Mobiles Copper Mesa Elementary 2006 New Construction Cougar Run Elementary 2003 Playground Improvements 2003 Flooring Improvements 2004 Security Cameras/Radios 2005 Security Access Control 2007 Carpet Replacement 2013 Fire Alarm Replacement 2013 Restroom Flooring	2018 Landscaping 2018 Movement Issues 2017 Replace Entry Walk-Off Carpet 2014 Clock System 2016 Concrete Slab Repairs 2017 Replace Entry Walk-Off Carpet 2018 Makeup Air Unit 2018 Window Film	2019 Elevator modernization 2019 Replace generator and associated equipment 2019 Recoat exterior wall CMU weather proofing, recaulk control joint 2019 Replace exterior windows 2019 Replace gym carpet 2019 Move hot water heater, install on demand pumps
2010 New Construction 2011 Turn Lane and Stop Light Clear Sky Elementary 2008 New Construction 2012 Carpet Replacement - Mobiles Copper Mesa Elementary 2006 New Construction Cougar Run Elementary 2003 Playground Improvements 2003 Flooring Improvements 2004 Security Cameras/Radios 2005 Security Access Control 2007 Carpet Replacement 2013 Fire Alarm Replacement	2018 Landscaping 2018 Movement Issues 2017 Replace Entry Walk-Off Carpet 2014 Clock System 2016 Concrete Slab Repairs 2017 Replace Entry Walk-Off Carpet 2018 Makeup Air Unit 2018 Window Film 2019 Replace VAV boxes (air distribution system	2019 Elevator modernization 2019 Replace generator and associated equipment 2019 Recoat exterior wall CMU weather proofing, recaulk control joints 2019 Replace exterior windows 2019 Replace gym carpet 2019 Move hot water heater, install on demand pumps 2019 Replace interior door hardware
2010 New Construction 2011 Turn Lane and Stop Light Clear Sky Elementary 2008 New Construction 2012 Carpet Replacement - Mobiles Copper Mesa Elementary 2006 New Construction Cougar Run Elementary 2003 Playground Improvements 2003 Flooring Improvements 2004 Security Cameras/Radios 2005 Security Access Control 2007 Carpet Replacement 2013 Fire Alarm Replacement 2013 Restroom Flooring 2013 Roof Replacement	2018 Landscaping 2018 Movement Issues 2017 Replace Entry Walk-Off Carpet 2014 Clock System 2016 Concrete Slab Repairs 2017 Replace Entry Walk-Off Carpet 2018 Makeup Air Unit 2018 Window Film 2019 Replace VAV boxes (air distribution system 2019 Upgrade control system	2019 Elevator modernization 2019 Replace generator and associated equipment 2019 Recoat exterior wall CMU weather proofing, recaulk control joint 2019 Replace exterior windows 2019 Replace gym carpet 2019 Move hot water heater, install on demand pumps 2019 Replace interior door hardware
2010 New Construction 2011 Turn Lane and Stop Light Clear Sky Elementary 2008 New Construction 2012 Carpet Replacement - Mobiles Copper Mesa Elementary 2006 New Construction Cougar Run Elementary 2003 Playground Improvements 2004 Security Cameras/Radios 2005 Security Access Control 2007 Carpet Replacement 2013 Fire Alarm Replacement 2013 Restroom Flooring 2013 Roof Replacement	2018 Landscaping 2018 Movement Issues 2017 Replace Entry Walk-Off Carpet 2014 Clock System 2016 Concrete Slab Repairs 2017 Replace Entry Walk-Off Carpet 2018 Makeup Air Unit 2018 Window Film 2019 Replace VAV boxes (air distribution system 2019 Upgrade control system	2019 Elevator modernization 2019 Replace generator and associated equipment 2019 Recoat exterior wall CMU weather proofing, recaulk control joints 2019 Replace exterior windows 2019 Replace gym carpet 2019 Move hot water heater, install on demand pumps 2019 Replace interior door hardware
2010 New Construction 2011 Turn Lane and Stop Light Clear Sky Elementary 2008 New Construction 2012 Carpet Replacement - Mobiles Copper Mesa Elementary 2006 New Construction Cougar Run Elementary 2003 Playground Improvements 2004 Security Cameras/Radios 2005 Security Access Control 2007 Carpet Replacement 2013 Fire Alarm Replacement 2013 Restroom Flooring 2013 Roof Replacement	2018 Landscaping 2018 Movement Issues 2017 Replace Entry Walk-Off Carpet 2014 Clock System 2016 Concrete Slab Repairs 2017 Replace Entry Walk-Off Carpet 2018 Makeup Air Unit 2018 Window Film 2019 Replace VAV boxes (air distribution system 2019 Upgrade control system 2019 Replace roof top units	2019 Replace generator and associated equipment 2019 Recoat exterior wall CMU weather proofing, recaulk control joint 2019 Replace exterior windows 2019 Replace gym carpet 2019 Move hot water heater, install on demand pumps 2019 Replace interior door hardware 2019 Upgrade switchgear for surge suppression
2010 New Construction 2011 Turn Lane and Stop Light Clear Sky Elementary 2008 New Construction 2012 Carpet Replacement - Mobiles Copper Mesa Elementary 2006 New Construction Cougar Run Elementary 2003 Playground Improvements 2004 Security Cameras/Radios 2005 Security Access Control 2007 Carpet Replacement 2013 Fire Alarm Replacement 2013 Restroom Flooring 2013 Roof Replacement Coyote Creek Elementary 2004 Security Cameras/Radios	2018 Landscaping 2018 Movement Issues 2017 Replace Entry Walk-Off Carpet 2014 Clock System 2016 Concrete Slab Repairs 2017 Replace Entry Walk-Off Carpet 2018 Makeup Air Unit 2018 Window Film 2019 Replace VAV boxes (air distribution system 2019 Upgrade control system 2019 Replace roof top units	2019 Elevator modernization 2019 Replace generator and associated equipment 2019 Recoat exterior wall CMU weather proofing, recaulk control joint 2019 Replace exterior windows 2019 Replace gym carpet 2019 Move hot water heater, install on demand pumps 2019 Replace interior door hardware 2019 Upgrade switchgear for surge suppression
2010 New Construction 2011 Turn Lane and Stop Light Clear Sky Elementary 2008 New Construction 2012 Carpet Replacement - Mobiles Copper Mesa Elementary 2006 New Construction Cougar Run Elementary 2003 Playground Improvements 2003 Flooring Improvements 2004 Security Cameras/Radios 2005 Security Access Control 2007 Carpet Replacement 2013 Fire Alarm Replacement 2013 Restroom Flooring 2013 Roof Replacement Coyote Creek Elementary 2004 Security Cameras/Radios 2004 Technology Upgrades 2005 Security Access Control	2018 Landscaping 2018 Movement Issues 2017 Replace Entry Walk-Off Carpet 2014 Clock System 2016 Concrete Slab Repairs 2017 Replace Entry Walk-Off Carpet 2018 Makeup Air Unit 2018 Window Film 2019 Replace VAV boxes (air distribution system 2019 Upgrade control system 2019 Replace roof top units 2007 Carpet Replacement 2007 Playground Improvements	2019 Elevator modernization 2019 Replace generator and associated equipment 2019 Recoat exterior wall CMU weather proofing, recaulk control joint 2019 Replace exterior windows 2019 Replace gym carpet 2019 Move hot water heater, install on demand pumps 2019 Replace interior door hardware 2019 Upgrade switchgear for surge suppression
2010 New Construction 2011 Turn Lane and Stop Light Clear Sky Elementary 2008 New Construction 2012 Carpet Replacement - Mobiles Copper Mesa Elementary 2006 New Construction Cougar Run Elementary 2003 Playground Improvements 2003 Flooring Improvements 2004 Security Cameras/Radios 2005 Security Access Control 2007 Carpet Replacement 2013 Fire Alarm Replacement 2013 Restroom Flooring 2013 Roof Replacement Coyote Creek Elementary 2004 Security Cameras/Radios 2004 Technology Upgrades 2005 Security Access Control	2018 Landscaping 2018 Movement Issues 2017 Replace Entry Walk-Off Carpet 2014 Clock System 2016 Concrete Slab Repairs 2017 Replace Entry Walk-Off Carpet 2018 Makeup Air Unit 2018 Window Film 2019 Replace VAV boxes (air distribution system 2019 Upgrade control system 2019 Replace roof top units 2007 Carpet Replacement 2007 Playground Improvements	2019 Elevator modernization 2019 Replace generator and associated equipment 2019 Recoat exterior wall CMU weather proofing, recaulk control joint 2019 Replace exterior windows 2019 Replace gym carpet 2019 Move hot water heater, install on demand pumps 2019 Replace interior door hardware 2019 Upgrade switchgear for surge suppression
2010 New Construction 2011 Turn Lane and Stop Light Clear Sky Elementary 2008 New Construction 2012 Carpet Replacement - Mobiles Copper Mesa Elementary 2006 New Construction Cougar Run Elementary 2003 Playground Improvements 2004 Security Cameras/Radios 2005 Security Access Control 2007 Carpet Replacement 2013 Fire Alarm Replacement 2013 Restroom Flooring 2013 Roof Replacement Coyote Creek Elementary 2004 Security Cameras/Radios 2004 Technology Upgrades 2005 Security Access Control	2018 Landscaping 2018 Movement Issues 2017 Replace Entry Walk-Off Carpet 2014 Clock System 2016 Concrete Slab Repairs 2017 Replace Entry Walk-Off Carpet 2018 Makeup Air Unit 2018 Window Film 2019 Replace VAV boxes (air distribution system 2019 Upgrade control system 2019 Replace roof top units 2007 Carpet Replacement 2007 Playground Improvements 2010 3,200 SF Addition	2019 Elevator modernization 2019 Replace generator and associated equipment 2019 Recoat exterior wall CMU weather proofing, recaulk control joint 2019 Replace exterior windows 2019 Replace gym carpet 2019 Move hot water heater, install on demand pumps 2019 Replace interior door hardware 2019 Upgrade switchgear for surge suppression 2010 Playing Field Improvements 2017 Replace Entry Walk-Off Carpet
2010 New Construction 2011 Turn Lane and Stop Light Clear Sky Elementary 2008 New Construction 2012 Carpet Replacement - Mobiles Copper Mesa Elementary 2006 New Construction Cougar Run Elementary 2003 Playground Improvements 2004 Security Cameras/Radios 2005 Security Access Control 2007 Carpet Replacement 2013 Fire Alarm Replacement 2013 Restroom Flooring 2013 Roof Replacement Coyote Creek Elementary 2004 Security Cameras/Radios 2004 Technology Upgrades 2005 Security Access Control Cresthill Middle School 1998 Tile Replacement	2018 Landscaping 2018 Movement Issues 2017 Replace Entry Walk-Off Carpet 2014 Clock System 2016 Concrete Slab Repairs 2017 Replace Entry Walk-Off Carpet 2018 Makeup Air Unit 2018 Window Film 2019 Replace VAV boxes (air distribution system 2019 Upgrade control system 2019 Replace roof top units 2007 Carpet Replacement 2007 Playground Improvements 2010 3,200 SF Addition	2019 Elevator modernization 2019 Replace generator and associated equipment 2019 Recoat exterior wall CMU weather proofing, recaulk control joint 2019 Replace exterior windows 2019 Replace gym carpet 2019 Move hot water heater, install on demand pumps 2019 Replace interior door hardware 2019 Upgrade switchgear for surge suppression 2010 Playing Field Improvements 2017 Replace Entry Walk-Off Carpet

Panial C. Oakaa Hish Sahaal		
Daniel C. Oakes High School	0000 Maior Borovetico	0007 Dest Destaurant
2000 Add Mobile/AC	2002 Major Renovation	2007 Roof Replacement
2001 Parking Lot	2007 Science Rooms	2019 Doors and door hardware
District-Wide		
2018 Preschool Playground Equipment	2018 Wallpaper Seam Repairs	
Douglas County High School		
1992 30,890 SF Addition	2004 Cooling Units	2012 Bathroom Improvements
1995 Team Room/Tennis Courts	2004 Security Cameras/Radios	2012 Partial Roof Replacement
1995 Replace DDC	2004 Technology Improvements	2013 Projector Mounting
1997 Air Conditioning	2005 Security Access Control	2013 Blackboard Removal
2000 Running Track	2005 Security Kiosk	2013 Energy Performance Contracting
2001 Water System	2008 Renovation - Phase I	2014 Electrical Switchgear and Panel board Replacement
2002 Parking Lot Improvements	2010 Renovation - Phase II	2017 Elevator Modernization
2002 Artificial Turf	2010 Communications Equipment	2018 Shop MAU Replacement
2003 Bell System	2010 Addition - Athletic Complex	2017 Window Replacement-Multiple Areas
2003 Bathroom Improvements	2006 Sidewalk Improvements	2017 Replace Entry Walk-Off Carpet
1985 18,016 SF Addition	2008 Roof Replacement	2018 Entry Carpet
1993 Remodel - Phase I	2010 Communication Equipment	2019 Replace/repair doors and door hardware
1997 Remodel - Phase II	2011 Life Safety Upgrade	2019 Replace exterior doors, frames, and hardware
2001 Water System	2012 Replace Carpet	2019 Stadium lighting & turf
2003 Science Room Conversion		
Douglas County Opportunity Center		
2017 Original Tenant Finish/Buildout		
Douglas County Support Center		
2019 HVAC	2019 Replace carpet	
2019 Boiler	2019 Repair roof	
Facile Dieles Flamania		
Eagle Ridge Elementary		
1997 Air Conditioning	2004 Technology Improvements	2014 Resurface Gymnasium Floor
1998 Tile Replacement	2005 Security Access Control	2016 Restroom Countertops Replacement
2001 Carpet Replacement	2007 Playground Improvements	2017 Replace Flooring in Restrooms
2003 Reballast	2013 Kitchen Floor Repair 2014 Cafeteria Flooring	2018 Bathrooms-Partitions, Countertops, & Flooring
2004 3,000 SF Addition	2014 Caletena Flooring	2019 Replace cafeteria VCT flooring 2019 Replace carpet
Fault Childhaad Cantar		
Early Childhood Center 2013 Gutter and Drain Repairs	2018 Window Tinting	
2018 Sinks	2018 SPED Calming Room	
5.1.5.1.0.1		
Echo Park Stadium 2012 Track Timing Stations	2018 Track Repair	2019 Structural (gap between bleachers and retaining wall)
2013 Tenant Finish to Building	2018 Water Infiltration	2019 Stadium turf
2013 Drainage Repairs	2019 Bleachers	2010 0.000
Eldovodo Elomonto:		
Eldorado Elementary	0007 Tark adams law announced	0040 He was de fine aleman control
2001 New Construction	2007 Technology Improvements	2019 Upgrade fire alarm system
2004 Security Compress (Redies	2017 Convert Classroom to Special Education C	2019 Replace cafeteria, and gym flooring
2004 Security Cameras/Radios	2017 Replace Entry Walk-Off Carpet	2019 Replace non-restricted key system with restricted
2005 Technology Improvements	2019 Upgrade control system	2019 Replace roof (ballasted with fully adhered)
2005 Security Access Control	2019 Generator replacement	2019 Paint metal roof
2006 Technology Improvements		
Flagstone Elementary		
	2005 Technology Improvements	2018 Carpet Replacement - Mobile
2003 New Construction		2010 Upgrade central system
2003 New Construction 2004 Security Cameras/Radios	2013 Carpet Replacement - Mobile	2019 Upgrade control system
	2013 Carpet Replacement - Mobile 2017 Replace Entry Walk-Off Carpet	2019 Opprade Control System
2004 Security Cameras/Radios 2005 Security Access Control		2019 Opgrave Control System
2004 Security Cameras/Radios		2012 Carpet Replacement - Mobile
2004 Security Cameras/Radios 2005 Security Access Control Fox Creek Elementary	2017 Replace Entry Walk-Off Carpet	

1007 Dethuses Insurer	2012 Dealing Lating Transcript	2010 Bessellt windows
1997 Bathroom Improvements	2012 Parking Lot Improvements	2019 Recaulk windows
1998 Carpet Replacement	2014 Update Water Well System	2019 Replace toilet partitions
2000 Roof Replacement	2014 Resurface Gymnasium Floor	2019 Upgrade fire alarm system
2002 Remodel	2016 Domestic Hot Water System Upgrade	2019 Replace kitchen and restroom flooring
2004 Security Cameras/Radios	2018 Landscaping	2019 Replace interior door hardware
2004 Security Access Control	2019 Upgrade clock system	2019 Repair entry soffit
2004 Technology Improvements	2019 Upgrade control system	2019 Repair entry soffit
2007 ADA Ramp	2019 Replace roof top units	2019 Replace/repair entry classroom storefronts
2008 ADA Bathroom	2019 Generator replacement	2019 Sand and paint exterior doors
2012 Carpet Replacement	2019 Caulk, seal exterior wall	
rontier Valley Elementary		
2002 New Construction	2014 Clock System	2019 Caulk, seal exterior wall
2004 Technology Improvements	2014 Update Water Well System	2019 Upgrade fire alarm system
2005 Technology Improvements	2019 Upgrade control system	2019 Replace carpet
2013 Cafeteria Floor Replacement	2019 Generator replacement	2019 Replace roof
old Rush Elementary		
2010 New Construction	2017 Addition of Fence	2018 Landscaping
		2019 Elevator modernization
leritage Elementary		
2001 New Construction	2017 Replace Entry Walk-Off Carpet	2019 Upgrade fire alarm system
2004 Security Cameras/Radios	2018 Carpet Replacement	2019 Replace restroom flooring
2005 Security Access Controls	2019 Replace cooling tower	2019 Replace non-restricted key system with restricted
2005 Technology Improvements	2019 Generator replacement	2019 Reglaze skylights
2012 Restroom Countertops	2019 Caulk, seal exterior wall	2019 Replace ballasted roof with fully adhered
2013 Carpet Replacement - Mobile	2019 Recaulk windows	2019 Paint metal roof
lighlands Ranch High School 1989 12,400 SF Addition	2002 35,175 SF Addition	2014 Intercom and Paging System Replacement
1994 Track Replacement	2004 Retaining Wall	2014 Partial Roof Replacement
1994 22,833 SF Addition	2004 Security Cameras/Radios	2015 Fire Alarm System Replacement
1995 Hallway Infill	2004 Security Access Control	2015 Generator Replacement
	2004 Tochnology Improvements	2016 Parking Lat Pacurface (Partions Only)
1995 Parking Lot Improvements	2004 Technology Improvements	2016 Parking Lot Resurface (Portions Only)
1996 Vehicle Access	2005 Gas Shutoff Valves	2017 Elevator Modernization
- · ·		
1996 Vehicle Access	2005 Gas Shutoff Valves	2017 Elevator Modernization
1996 Vehicle Access 1997 Catwalk/Fire Doors	2005 Gas Shutoff Valves 2007 Security Kiosk	2017 Elevator Modernization 2017 Convert Classroom to Special Education Calm Room
1996 Vehicle Access 1997 Catwalk/Fire Doors 1997 Air Conditioning	2005 Gas Shutoff Valves2007 Security Kiosk2010 Fire Alarm System Upgrade	2017 Elevator Modernization 2017 Convert Classroom to Special Education Calm Room 2018 Building Automation System
1996 Vehicle Access 1997 Catwalk/Fire Doors 1997 Air Conditioning 1999 Floor Tile Replacement	2005 Gas Shutoff Valves2007 Security Kiosk2010 Fire Alarm System Upgrade2012 Replace Artificial Turf Playfield	2017 Elevator Modernization 2017 Convert Classroom to Special Education Calm Room 2018 Building Automation System 2018 Domestic Hot Water System
1996 Vehicle Access 1997 Catwalk/Fire Doors 1997 Air Conditioning 1999 Floor Tile Replacement 1999 Boilers	2005 Gas Shutoff Valves2007 Security Kiosk2010 Fire Alarm System Upgrade2012 Replace Artificial Turf Playfield2012 Partial Roof Replacement	2017 Elevator Modernization 2017 Convert Classroom to Special Education Calm Room 2018 Building Automation System 2018 Domestic Hot Water System 2018 Bathroom-Toilet Partitions, Countertops, and Flooring
1996 Vehicle Access 1997 Catwalk/Fire Doors 1997 Air Conditioning 1999 Floor Tile Replacement 1999 Boilers 2000 Artificial Turf Playfield	 2005 Gas Shutoff Valves 2007 Security Kiosk 2010 Fire Alarm System Upgrade 2012 Replace Artificial Turf Playfield 2012 Partial Roof Replacement 2012 Replace Tile Flooring 	2017 Elevator Modernization 2017 Convert Classroom to Special Education Calm Room 2018 Building Automation System 2018 Domestic Hot Water System 2018 Bathroom-Toilet Partitions, Countertops, and Flooring 2018 SPED Calming Room
1996 Vehicle Access 1997 Catwalk/Fire Doors 1997 Air Conditioning 1999 Floor Tile Replacement 1999 Boilers 2000 Artificial Turf Playfield 2000 Batting Cages/Dugouts	2005 Gas Shutoff Valves 2007 Security Kiosk 2010 Fire Alarm System Upgrade 2012 Replace Artificial Turf Playfield 2012 Partial Roof Replacement 2012 Replace Tile Flooring 2012 Resurface Tennis Courts	2017 Elevator Modernization 2017 Convert Classroom to Special Education Calm Room 2018 Building Automation System 2018 Domestic Hot Water System 2018 Bathroom-Toilet Partitions, Countertops, and Flooring 2018 SPED Calming Room 2019 Replace main gym bleachers
1996 Vehicle Access 1997 Catwalk/Fire Doors 1997 Air Conditioning 1999 Floor Tile Replacement 1999 Boilers 2000 Artificial Turf Playfield 2000 Batting Cages/Dugouts 2000 Parking Lot Improvements	2005 Gas Shutoff Valves 2007 Security Kiosk 2010 Fire Alarm System Upgrade 2012 Replace Artificial Turf Playfield 2012 Partial Roof Replacement 2012 Replace Tile Flooring 2012 Resurface Tennis Courts 2014 Stage Lights and Catwalk 2014 Resurface Track	2017 Elevator Modernization 2017 Convert Classroom to Special Education Calm Room 2018 Building Automation System 2018 Domestic Hot Water System 2018 Bathroom-Toilet Partitions, Countertops, and Flooring 2018 SPED Calming Room 2019 Replace main gym bleachers
1996 Vehicle Access 1997 Catwalk/Fire Doors 1997 Air Conditioning 1999 Floor Tile Replacement 1999 Boilers 2000 Artificial Turf Playfield 2000 Batting Cages/Dugouts 2000 Parking Lot Improvements 2002 Fencing	2005 Gas Shutoff Valves 2007 Security Kiosk 2010 Fire Alarm System Upgrade 2012 Replace Artificial Turf Playfield 2012 Partial Roof Replacement 2012 Replace Tile Flooring 2012 Resurface Tennis Courts 2014 Stage Lights and Catwalk 2014 Resurface Track	2017 Elevator Modernization 2017 Convert Classroom to Special Education Calm Room 2018 Building Automation System 2018 Domestic Hot Water System 2018 Bathroom-Toilet Partitions, Countertops, and Flooring 2018 SPED Calming Room 2019 Replace main gym bleachers
1996 Vehicle Access 1997 Catwalk/Fire Doors 1997 Air Conditioning 1999 Floor Tile Replacement 1999 Boilers 2000 Artificial Turf Playfield 2000 Batting Cages/Dugouts 2000 Parking Lot Improvements 2002 Fencing	2005 Gas Shutoff Valves 2007 Security Kiosk 2010 Fire Alarm System Upgrade 2012 Replace Artificial Turf Playfield 2012 Partial Roof Replacement 2012 Replace Tile Flooring 2012 Resurface Tennis Courts 2014 Stage Lights and Catwalk 2014 Resurface Track	2017 Elevator Modernization 2017 Convert Classroom to Special Education Calm Room 2018 Building Automation System 2018 Domestic Hot Water System 2018 Bathroom-Toilet Partitions, Countertops, and Flooring 2018 SPED Calming Room 2019 Replace main gym bleachers 2019 Replace door hardware
1996 Vehicle Access 1997 Catwalk/Fire Doors 1997 Air Conditioning 1999 Floor Tile Replacement 1999 Boilers 2000 Artificial Turf Playfield 2000 Batting Cages/Dugouts 2000 Parking Lot Improvements 2002 Fencing lighlands Ranch Transportation Ser 2017 Addition of Mechanics Bay	2005 Gas Shutoff Valves 2007 Security Kiosk 2010 Fire Alarm System Upgrade 2012 Replace Artificial Turf Playfield 2012 Partial Roof Replacement 2012 Replace Tile Flooring 2012 Resurface Tennis Courts 2014 Stage Lights and Catwalk 2014 Resurface Track vice Center 2018 Oil/Lube System	2017 Elevator Modernization 2017 Convert Classroom to Special Education Calm Room 2018 Building Automation System 2018 Domestic Hot Water System 2018 Bathroom-Toilet Partitions, Countertops, and Flooring 2018 SPED Calming Room 2019 Replace main gym bleachers 2019 Replace door hardware
1996 Vehicle Access 1997 Catwalk/Fire Doors 1997 Air Conditioning 1999 Floor Tile Replacement 1999 Boilers 2000 Artificial Turf Playfield 2000 Batting Cages/Dugouts 2000 Parking Lot Improvements 2002 Fencing lighlands Ranch Transportation Ser 2017 Addition of Mechanics Bay 2018 Sidewalks	2005 Gas Shutoff Valves 2007 Security Kiosk 2010 Fire Alarm System Upgrade 2012 Replace Artificial Turf Playfield 2012 Partial Roof Replacement 2012 Replace Tile Flooring 2012 Resurface Tennis Courts 2014 Stage Lights and Catwalk 2014 Resurface Track vice Center 2018 Oil/Lube System	2017 Elevator Modernization 2017 Convert Classroom to Special Education Calm Room 2018 Building Automation System 2018 Domestic Hot Water System 2018 Bathroom-Toilet Partitions, Countertops, and Flooring 2018 SPED Calming Room 2019 Replace main gym bleachers 2019 Replace door hardware
1996 Vehicle Access 1997 Catwalk/Fire Doors 1997 Air Conditioning 1999 Floor Tile Replacement 1999 Boilers 2000 Artificial Turf Playfield 2000 Batting Cages/Dugouts 2000 Parking Lot Improvements 2002 Fencing lighlands Ranch Transportation Ser 2017 Addition of Mechanics Bay 2018 Sidewalks	2005 Gas Shutoff Valves 2007 Security Kiosk 2010 Fire Alarm System Upgrade 2012 Replace Artificial Turf Playfield 2012 Partial Roof Replacement 2012 Replace Tile Flooring 2012 Resurface Tennis Courts 2014 Stage Lights and Catwalk 2014 Resurface Track vice Center 2018 Oil/Lube System 2019 Boiler	2017 Elevator Modernization 2017 Convert Classroom to Special Education Calm Room 2018 Building Automation System 2018 Domestic Hot Water System 2018 Bathroom-Toilet Partitions, Countertops, and Flooring 2018 SPED Calming Room 2019 Replace main gym bleachers 2019 Replace door hardware
1996 Vehicle Access 1997 Catwalk/Fire Doors 1997 Air Conditioning 1999 Floor Tile Replacement 1999 Boilers 2000 Artificial Turf Playfield 2000 Batting Cages/Dugouts 2000 Parking Lot Improvements 2002 Fencing lighlands Ranch Transportation Ser 2017 Addition of Mechanics Bay 2018 Sidewalks on Horse Elementary 2004 Security Cameras/Radios	2005 Gas Shutoff Valves 2007 Security Kiosk 2010 Fire Alarm System Upgrade 2012 Replace Artificial Turf Playfield 2012 Partial Roof Replacement 2012 Replace Tile Flooring 2012 Resurface Tennis Courts 2014 Stage Lights and Catwalk 2014 Resurface Track Vice Center 2018 Oil/Lube System 2019 Boiler	2017 Elevator Modernization 2017 Convert Classroom to Special Education Calm Room 2018 Building Automation System 2018 Domestic Hot Water System 2018 Bathroom-Toilet Partitions, Countertops, and Flooring 2018 SPED Calming Room 2019 Replace main gym bleachers 2019 Replace door hardware 2019 Fire alarm system
1996 Vehicle Access 1997 Catwalk/Fire Doors 1997 Air Conditioning 1999 Floor Tile Replacement 1999 Boilers 2000 Artificial Turf Playfield 2000 Batting Cages/Dugouts 2000 Parking Lot Improvements 2002 Fencing lighlands Ranch Transportation Ser 2017 Addition of Mechanics Bay 2018 Sidewalks on Horse Elementary 2004 Security Cameras/Radios 2004 Technology Improvements	2005 Gas Shutoff Valves 2007 Security Kiosk 2010 Fire Alarm System Upgrade 2012 Replace Artificial Turf Playfield 2012 Partial Roof Replacement 2012 Replace Tile Flooring 2012 Resurface Tennis Courts 2014 Stage Lights and Catwalk 2014 Resurface Track vice Center 2018 Oil/Lube System 2019 Boiler 2014 Fire Alarm System Replacement 2017 Concrete Stabilization of Pods (2)	2017 Elevator Modernization 2017 Convert Classroom to Special Education Calm Room 2018 Building Automation System 2018 Domestic Hot Water System 2018 Bathroom-Toilet Partitions, Countertops, and Flooring 2018 SPED Calming Room 2019 Replace main gym bleachers 2019 Replace door hardware 2019 Fire alarm system 2019 Replace roof flashing and trim 2019 Replace cafeteria and kitchen flooring
1996 Vehicle Access 1997 Catwalk/Fire Doors 1997 Air Conditioning 1999 Floor Tile Replacement 1999 Boilers 2000 Artificial Turf Playfield 2000 Batting Cages/Dugouts 2000 Parking Lot Improvements 2002 Fencing lighlands Ranch Transportation Ser 2017 Addition of Mechanics Bay 2018 Sidewalks on Horse Elementary 2004 Security Cameras/Radios 2004 Technology Improvements 2005 Security Access Control	2005 Gas Shutoff Valves 2007 Security Kiosk 2010 Fire Alarm System Upgrade 2012 Replace Artificial Turf Playfield 2012 Partial Roof Replacement 2012 Replace Tile Flooring 2012 Resurface Tennis Courts 2014 Stage Lights and Catwalk 2014 Resurface Track Vice Center 2018 Oil/Lube System 2019 Boiler 2014 Fire Alarm System Replacement 2017 Concrete Stabilization of Pods (2) 2018 Soccer Field Fence	2017 Elevator Modernization 2017 Convert Classroom to Special Education Calm Room 2018 Building Automation System 2018 Domestic Hot Water System 2018 Bathroom-Toilet Partitions, Countertops, and Flooring 2018 SPED Calming Room 2019 Replace main gym bleachers 2019 Replace door hardware 2019 Fire alarm system 2019 Replace cafeteria and kitchen flooring 2019 Replace unrestricted with restricted key system
1996 Vehicle Access 1997 Catwalk/Fire Doors 1997 Air Conditioning 1999 Floor Tile Replacement 1999 Boilers 2000 Artificial Turf Playfield 2000 Batting Cages/Dugouts 2000 Parking Lot Improvements 2002 Fencing lighlands Ranch Transportation Ser 2017 Addition of Mechanics Bay 2018 Sidewalks 2019 Horse Elementary 2004 Security Cameras/Radios 2004 Technology Improvements 2005 Security Access Control 2010 Carpet Replacement 2010 Cafeteria Flooring Repairs	2005 Gas Shutoff Valves 2007 Security Kiosk 2010 Fire Alarm System Upgrade 2012 Replace Artificial Turf Playfield 2012 Partial Roof Replacement 2012 Replace Tile Flooring 2012 Resurface Tennis Courts 2014 Stage Lights and Catwalk 2014 Resurface Track Vice Center 2018 Oil/Lube System 2019 Boiler 2014 Fire Alarm System Replacement 2017 Concrete Stabilization of Pods (2) 2018 Soccer Field Fence 2018 Pod Settling 2018 Mobile Ramp	2017 Elevator Modernization 2017 Convert Classroom to Special Education Calm Room 2018 Building Automation System 2018 Domestic Hot Water System 2018 Bathroom-Toilet Partitions, Countertops, and Flooring 2018 SPED Calming Room 2019 Replace main gym bleachers 2019 Replace door hardware 2019 Fire alarm system 2019 Replace cafeteria and kitchen flooring 2019 Replace unrestricted with restricted key system 2019 Upgrade irrigation system controller 2019 Expand MDF closet
1996 Vehicle Access 1997 Catwalk/Fire Doors 1997 Air Conditioning 1999 Floor Tile Replacement 1999 Boilers 2000 Artificial Turf Playfield 2000 Batting Cages/Dugouts 2000 Parking Lot Improvements 2002 Fencing lighlands Ranch Transportation Ser 2017 Addition of Mechanics Bay 2018 Sidewalks 2019 Morse Elementary 2004 Security Cameras/Radios 2004 Technology Improvements 2005 Security Access Control 2010 Carpet Replacement 2010 Cafeteria Flooring Repairs 2012 Upgrade Controls System	2005 Gas Shutoff Valves 2007 Security Kiosk 2010 Fire Alarm System Upgrade 2012 Replace Artificial Turf Playfield 2012 Partial Roof Replacement 2012 Replace Tile Flooring 2012 Resurface Tennis Courts 2014 Stage Lights and Catwalk 2014 Resurface Track Vice Center 2018 Oil/Lube System 2019 Boiler 2014 Fire Alarm System Replacement 2017 Concrete Stabilization of Pods (2) 2018 Soccer Field Fence 2018 Pod Settling 2018 Mobile Ramp 2019 Replace chiller and cooling tower	2017 Elevator Modernization 2017 Convert Classroom to Special Education Calm Room 2018 Building Automation System 2018 Domestic Hot Water System 2018 Bathroom-Toilet Partitions, Countertops, and Flooring 2018 SPED Calming Room 2019 Replace main gym bleachers 2019 Replace door hardware 2019 Fire alarm system 2019 Replace cafeteria and kitchen flooring 2019 Replace unrestricted with restricted key system 2019 Upgrade irrigation system controller
1996 Vehicle Access 1997 Catwalk/Fire Doors 1997 Air Conditioning 1999 Floor Tile Replacement 1999 Boilers 2000 Artificial Turf Playfield 2000 Batting Cages/Dugouts 2000 Parking Lot Improvements 2002 Fencing lighlands Ranch Transportation Ser 2017 Addition of Mechanics Bay 2018 Sidewalks 2019 Horse Elementary 2004 Security Cameras/Radios 2004 Technology Improvements 2005 Security Access Control 2010 Carpet Replacement 2010 Cafeteria Flooring Repairs	2005 Gas Shutoff Valves 2007 Security Kiosk 2010 Fire Alarm System Upgrade 2012 Replace Artificial Turf Playfield 2012 Partial Roof Replacement 2012 Replace Tile Flooring 2012 Resurface Tennis Courts 2014 Stage Lights and Catwalk 2014 Resurface Track Vice Center 2018 Oil/Lube System 2019 Boiler 2014 Fire Alarm System Replacement 2017 Concrete Stabilization of Pods (2) 2018 Soccer Field Fence 2018 Pod Settling 2018 Mobile Ramp	2017 Elevator Modernization 2017 Convert Classroom to Special Education Calm Room 2018 Building Automation System 2018 Domestic Hot Water System 2018 Bathroom-Toilet Partitions, Countertops, and Flooring 2018 SPED Calming Room 2019 Replace main gym bleachers 2019 Replace door hardware 2019 Fire alarm system 2019 Replace cafeteria and kitchen flooring 2019 Replace unrestricted with restricted key system 2019 Upgrade irrigation system controller 2019 Expand MDF closet

arkspur Elementary		
1992 Addition	2004 Technology Improvements	2010 Parking Lot Improvements
1994 Rooftop Units	2005 Security Access Control	2013 Exterior Enhancement
1997 Carpet Replacement	2009 Carpet Replacement	2016 Electrical Switchgear, Transformers, & Panel Replacement
2000 Addition/Remodel	2006 Entry Tile Replacement	2018 Bathrooms-Partitions, Countertops, & Flooring
2002 Playground Improvements	2008 Elevator	2019 Replace interior doors,door frames, hardware
2003 Intercom	2010 Gym Floor	2019 Roofing
2004 Clock System	2011 Roof Replacement	3
Lagary Paint Flamenton		
Legacy Point Elementary	0044 Objek Overteer	0040 Dealess and to see the size
2003 New Construction	2014 Clock System	2019 Replace restroom flooring
2004 Security Cameras/Radios	2017 Replace Entry Walk-Off Carpet	2019 Repair elevator
2004 Security Access Control	2019 Upgrade controls system	2019 Replace ballasted with fully adhered roof
2004 Technology Improvements	2019 Recaulk exterior wall control joints, cracks,	2019 Replace sink countertops with single surface
2012 Carpet Replacement - Mobile	2019 Upgrade fire system	
Legend High School		
2008 New Construction	2013 Resand Gymnasium Floor	2014 Hilltop Road Traffic Signal
2008 22,097 SF Addition	2013 Repair Security Gate	2018 Reinforce Weight Room Floor
Lone Tree Elementary		2019 Turf field repair/replacement
2007 New Construction		
Mammoth Heights Elementary		
2007 New Construction	2012 Carpet Replacement - Mobile	2019 Elevator modernization
Meadow View Elementary		
2000 New Construction	2014 Clock System	2019 Recaulk windows
2004 Technology Improvements	2014 Interior Doors	2019 Upgrade fire alarm system
2004 Security Cameras/Radios	2014 Carpet	2019 Replace kitchen and restroom flooring
•	•	
2005 Security Access Control	2018 Fire Alarm Dampers	2019 Upgrade irrigation controller
2012 Concrete Repairs - service entry	2019 Upgrade control system	2019 Replace ballasted with fully adhered roof
2013 Carpet Replacement - Mobile	2019 Restricted key system	2019 Replace sink countertops with single surface
2013 Window Replacement	2019 Replace generator	2019 Repair water infiltraiton at storefront entrances
2013 Interior Door Replacement	2019 Caulk, seal repair exterior wall	2019 Install water sensing level switches in basement 2019 Replace boiler(s)
Mesa Middle School		2010 Replace Bollet(s)
2008 New Construction	2018 SPED Calming Room	
2000 11011 001101110011011		
Mountain Ridge Middle School 2003 New Construction	2004 Security Access Control	2018 Bathrooms-Partitions, Countertops, & Flooring
Mountain Ridge Middle School 2003 New Construction	2004 Security Access Control 2014 Clock System	2018 Bathrooms-Partitions, Countertops, & Flooring
Mountain Ridge Middle School	•	2018 Bathrooms-Partitions, Countertops, & Flooring
Mountain Ridge Middle School 2003 New Construction 2004 Technology Improvements	2014 Clock System	2018 Bathrooms-Partitions, Countertops, & Flooring
Mountain Ridge Middle School 2003 New Construction 2004 Technology Improvements 2004 Security Cameras/Radios	2014 Clock System	2018 Bathrooms-Partitions, Countertops, & Flooring 2019 Replace restroom partitions and flooring
Mountain Ridge Middle School 2003 New Construction 2004 Technology Improvements 2004 Security Cameras/Radios Mountain View Elementary	2014 Clock System 2017 Addition of Secured Folding Partition Wall	
Mountain Ridge Middle School 2003 New Construction 2004 Technology Improvements 2004 Security Cameras/Radios Mountain View Elementary 1994 Roof Improvements	2014 Clock System 2017 Addition of Secured Folding Partition Wall 2004 Technology Improvements	2019 Replace restroom partitions and flooring
Mountain Ridge Middle School 2003 New Construction 2004 Technology Improvements 2004 Security Cameras/Radios Mountain View Elementary 1994 Roof Improvements 1997 Carpet Replacement	2014 Clock System 2017 Addition of Secured Folding Partition Wall 2004 Technology Improvements 2007 Carpet Replacement	2019 Replace restroom partitions and flooring 2019 Upgrade fire alarm system
Mountain Ridge Middle School 2003 New Construction 2004 Technology Improvements 2004 Security Cameras/Radios Mountain View Elementary 1994 Roof Improvements 1997 Carpet Replacement 1999 Bathroom Improvements 2000 Parking Lot Improvements	2014 Clock System 2017 Addition of Secured Folding Partition Wall 2004 Technology Improvements 2007 Carpet Replacement 2008 Roof Replacement 2014 Kitchen and Gymnasium Flooring	2019 Replace restroom partitions and flooring 2019 Upgrade fire alarm system 2019 Upgrade irrigation system 2019 Resurface bus loop and parking lot
Mountain Ridge Middle School 2003 New Construction 2004 Technology Improvements 2004 Security Cameras/Radios Mountain View Elementary 1994 Roof Improvements 1997 Carpet Replacement 1999 Bathroom Improvements 2000 Parking Lot Improvements 2000 Playground Improvements	2014 Clock System 2017 Addition of Secured Folding Partition Wall 2004 Technology Improvements 2007 Carpet Replacement 2008 Roof Replacement 2014 Kitchen and Gymnasium Flooring 2016 Switchgear, Transformers, & Panels	2019 Replace restroom partitions and flooring 2019 Upgrade fire alarm system 2019 Upgrade irrigation system 2019 Resurface bus loop and parking lot 2019 Silver coat parapet walls
Mountain Ridge Middle School 2003 New Construction 2004 Technology Improvements 2004 Security Cameras/Radios Mountain View Elementary 1994 Roof Improvements 1997 Carpet Replacement 1999 Bathroom Improvements 2000 Parking Lot Improvements 2000 Playground Improvements 2001 5,278 SF Addition	2014 Clock System 2017 Addition of Secured Folding Partition Wall 2004 Technology Improvements 2007 Carpet Replacement 2008 Roof Replacement 2014 Kitchen and Gymnasium Flooring 2016 Switchgear, Transformers, & Panels 2019 Upgrade control system	2019 Replace restroom partitions and flooring 2019 Upgrade fire alarm system 2019 Upgrade irrigation system 2019 Resurface bus loop and parking lot 2019 Silver coat parapet walls 2019 Repair and refinish exterior doors
Mountain Ridge Middle School 2003 New Construction 2004 Technology Improvements 2004 Security Cameras/Radios Mountain View Elementary 1994 Roof Improvements 1997 Carpet Replacement 1999 Bathroom Improvements 2000 Parking Lot Improvements 2000 Playground Improvements	2014 Clock System 2017 Addition of Secured Folding Partition Wall 2004 Technology Improvements 2007 Carpet Replacement 2008 Roof Replacement 2014 Kitchen and Gymnasium Flooring 2016 Switchgear, Transformers, & Panels	2019 Replace restroom partitions and flooring 2019 Upgrade fire alarm system 2019 Upgrade irrigation system 2019 Resurface bus loop and parking lot 2019 Silver coat parapet walls
Mountain Ridge Middle School 2003 New Construction 2004 Technology Improvements 2004 Security Cameras/Radios Mountain View Elementary 1994 Roof Improvements 1997 Carpet Replacement 1999 Bathroom Improvements 2000 Parking Lot Improvements 2000 Playground Improvements 2001 5,278 SF Addition 2004 Security Cameras/Radios 2004 Security Access Control	2014 Clock System 2017 Addition of Secured Folding Partition Wall 2004 Technology Improvements 2007 Carpet Replacement 2008 Roof Replacement 2014 Kitchen and Gymnasium Flooring 2016 Switchgear, Transformers, & Panels 2019 Upgrade control system 2019 Replace rooftop units	2019 Replace restroom partitions and flooring 2019 Upgrade fire alarm system 2019 Upgrade irrigation system 2019 Resurface bus loop and parking lot 2019 Silver coat parapet walls 2019 Repair and refinish exterior doors
Mountain Ridge Middle School 2003 New Construction 2004 Technology Improvements 2004 Security Cameras/Radios Mountain View Elementary 1994 Roof Improvements 1997 Carpet Replacement 1999 Bathroom Improvements 2000 Parking Lot Improvements 2000 Playground Improvements 2001 5,278 SF Addition 2004 Security Cameras/Radios 2004 Security Access Control Mountain Vista High School	2014 Clock System 2017 Addition of Secured Folding Partition Wall 2004 Technology Improvements 2007 Carpet Replacement 2008 Roof Replacement 2014 Kitchen and Gymnasium Flooring 2016 Switchgear, Transformers, & Panels 2019 Upgrade control system 2019 Replace rooftop units 2019 Recaulk windows, repair rusted windows	2019 Replace restroom partitions and flooring 2019 Upgrade fire alarm system 2019 Upgrade irrigation system 2019 Resurface bus loop and parking lot 2019 Silver coat parapet walls 2019 Repair and refinish exterior doors 2019 Repair and replace classroom storefronts
Mountain Ridge Middle School 2003 New Construction 2004 Technology Improvements 2004 Security Cameras/Radios Mountain View Elementary 1994 Roof Improvements 1997 Carpet Replacement 1999 Bathroom Improvements 2000 Parking Lot Improvements 2000 Playground Improvements 2001 5,278 SF Addition 2004 Security Cameras/Radios 2004 Security Access Control	2014 Clock System 2017 Addition of Secured Folding Partition Wall 2004 Technology Improvements 2007 Carpet Replacement 2008 Roof Replacement 2014 Kitchen and Gymnasium Flooring 2016 Switchgear, Transformers, & Panels 2019 Upgrade control system 2019 Replace rooftop units	2019 Replace restroom partitions and flooring 2019 Upgrade fire alarm system 2019 Upgrade irrigation system 2019 Resurface bus loop and parking lot 2019 Silver coat parapet walls 2019 Repair and refinish exterior doors
Mountain Ridge Middle School 2003 New Construction 2004 Technology Improvements 2004 Security Cameras/Radios Mountain View Elementary 1994 Roof Improvements 1997 Carpet Replacement 1999 Bathroom Improvements 2000 Parking Lot Improvements 2000 Playground Improvements 2001 5,278 SF Addition 2004 Security Cameras/Radios 2004 Security Access Control Mountain Vista High School 2001 New Construction 2007 Security Kiosk	2014 Clock System 2017 Addition of Secured Folding Partition Wall 2004 Technology Improvements 2007 Carpet Replacement 2008 Roof Replacement 2014 Kitchen and Gymnasium Flooring 2016 Switchgear, Transformers, & Panels 2019 Upgrade control system 2019 Replace rooftop units 2019 Recaulk windows, repair rusted windows	2019 Replace restroom partitions and flooring 2019 Upgrade fire alarm system 2019 Upgrade irrigation system 2019 Resurface bus loop and parking lot 2019 Silver coat parapet walls 2019 Repair and refinish exterior doors 2019 Repair and replace classroom storefronts
Mountain Ridge Middle School 2003 New Construction 2004 Technology Improvements 2004 Security Cameras/Radios Mountain View Elementary 1994 Roof Improvements 1997 Carpet Replacement 1999 Bathroom Improvements 2000 Parking Lot Improvements 2000 Playground Improvements 2001 5,278 SF Addition 2004 Security Cameras/Radios 2004 Security Access Control Mountain Vista High School 2001 New Construction	2014 Clock System 2017 Addition of Secured Folding Partition Wall 2004 Technology Improvements 2007 Carpet Replacement 2008 Roof Replacement 2014 Kitchen and Gymnasium Flooring 2016 Switchgear, Transformers, & Panels 2019 Upgrade control system 2019 Replace rooftop units 2019 Recaulk windows, repair rusted windows 2014 Fire Alarm System Replacement 2019 Replace carpet in hallways and office	2019 Replace restroom partitions and flooring 2019 Upgrade fire alarm system 2019 Upgrade irrigation system 2019 Resurface bus loop and parking lot 2019 Silver coat parapet walls 2019 Repair and refinish exterior doors 2019 Repair and replace classroom storefronts 2019 Replace non-restricted with restricted key system
Mountain Ridge Middle School 2003 New Construction 2004 Technology Improvements 2004 Security Cameras/Radios Mountain View Elementary 1994 Roof Improvements 1997 Carpet Replacement 1999 Bathroom Improvements 2000 Parking Lot Improvements 2000 Playground Improvements 2001 5,278 SF Addition 2004 Security Cameras/Radios 2004 Security Access Control Mountain Vista High School 2007 Security Kiosk Mountain Vista High School Cont. 2004 Chiller	2014 Clock System 2017 Addition of Secured Folding Partition Wall 2004 Technology Improvements 2007 Carpet Replacement 2008 Roof Replacement 2014 Kitchen and Gymnasium Flooring 2016 Switchgear, Transformers, & Panels 2019 Upgrade control system 2019 Replace rooftop units 2019 Recaulk windows, repair rusted windows 2014 Fire Alarm System Replacement 2019 Replace carpet in hallways and office	2019 Replace restroom partitions and flooring 2019 Upgrade fire alarm system 2019 Upgrade irrigation system 2019 Resurface bus loop and parking lot 2019 Silver coat parapet walls 2019 Repair and refinish exterior doors 2019 Repair and replace classroom storefronts 2019 Replace non-restricted with restricted key system 2014 Intercom and Paging System Replacement
Mountain Ridge Middle School 2003 New Construction 2004 Technology Improvements 2004 Security Cameras/Radios Mountain View Elementary 1994 Roof Improvements 1997 Carpet Replacement 1999 Bathroom Improvements 2000 Parking Lot Improvements 2000 Playground Improvements 2001 5,278 SF Addition 2004 Security Cameras/Radios 2004 Security Access Control Mountain Vista High School 2007 Security Kiosk Mountain Vista High School Cont. 2004 Chiller 2004 Security Cameras/Radios	2014 Clock System 2017 Addition of Secured Folding Partition Wall 2004 Technology Improvements 2007 Carpet Replacement 2008 Roof Replacement 2014 Kitchen and Gymnasium Flooring 2016 Switchgear, Transformers, & Panels 2019 Upgrade control system 2019 Replace rooftop units 2019 Recaulk windows, repair rusted windows 2014 Fire Alarm System Replacement 2019 Replace carpet in hallways and office 2010 Site Improvements - Curb 2012 Tile Replacement - Halls/Classrooms	2019 Replace restroom partitions and flooring 2019 Upgrade fire alarm system 2019 Upgrade irrigation system 2019 Resurface bus loop and parking lot 2019 Silver coat parapet walls 2019 Repair and refinish exterior doors 2019 Repair and replace classroom storefronts 2019 Replace non-restricted with restricted key system 2014 Intercom and Paging System Replacement 2017 Convert Tennis Courts to Post Tension
Mountain Ridge Middle School 2003 New Construction 2004 Technology Improvements 2004 Security Cameras/Radios Mountain View Elementary 1994 Roof Improvements 1997 Carpet Replacement 1999 Bathroom Improvements 2000 Parking Lot Improvements 2000 Playground Improvements 2001 5,278 SF Addition 2004 Security Cameras/Radios 2004 Security Access Control Mountain Vista High School 2001 New Construction 2007 Security Kiosk Mountain Vista High School Cont. 2004 Chiller 2004 Security Cameras/Radios 2004 Security Cameras/Radios 2004 Security Cameras/Radios	2014 Clock System 2017 Addition of Secured Folding Partition Wall 2004 Technology Improvements 2007 Carpet Replacement 2008 Roof Replacement 2014 Kitchen and Gymnasium Flooring 2016 Switchgear, Transformers, & Panels 2019 Upgrade control system 2019 Replace rooftop units 2019 Recaulk windows, repair rusted windows 2014 Fire Alarm System Replacement 2019 Replace carpet in hallways and office 2010 Site Improvements - Curb 2012 Tile Replacement - Halls/Classrooms 2013 Resand Gymnasium Floor	2019 Replace restroom partitions and flooring 2019 Upgrade fire alarm system 2019 Upgrade irrigation system 2019 Resurface bus loop and parking lot 2019 Silver coat parapet walls 2019 Repair and refinish exterior doors 2019 Repair and replace classroom storefronts 2019 Replace non-restricted with restricted key system 2014 Intercom and Paging System Replacement 2017 Convert Tennis Courts to Post Tension 2018 Bleachers
Mountain Ridge Middle School 2003 New Construction 2004 Technology Improvements 2004 Security Cameras/Radios Mountain View Elementary 1994 Roof Improvements 1997 Carpet Replacement 1999 Bathroom Improvements 2000 Parking Lot Improvements 2000 Playground Improvements 2001 5,278 SF Addition 2004 Security Cameras/Radios 2004 Security Access Control Mountain Vista High School 2001 New Construction 2007 Security Kiosk Mountain Vista High School Cont. 2004 Chiller 2004 Security Cameras/Radios 2004 Security Cameras/Radios 2004 Security Cameras/Radios 2004 Security Cameras/Radios 2004 Security Access Control 2004 Technology Improvements	2014 Clock System 2017 Addition of Secured Folding Partition Wall 2004 Technology Improvements 2007 Carpet Replacement 2008 Roof Replacement 2014 Kitchen and Gymnasium Flooring 2016 Switchgear, Transformers, & Panels 2019 Upgrade control system 2019 Replace rooftop units 2019 Recaulk windows, repair rusted windows 2014 Fire Alarm System Replacement 2019 Replace carpet in hallways and office 2010 Site Improvements - Curb 2012 Tile Replacement - Halls/Classrooms 2013 Resand Gymnasium Floor 2013 Tennis Courts	2019 Replace restroom partitions and flooring 2019 Upgrade fire alarm system 2019 Upgrade irrigation system 2019 Resurface bus loop and parking lot 2019 Silver coat parapet walls 2019 Repair and refinish exterior doors 2019 Repair and replace classroom storefronts 2019 Replace non-restricted with restricted key system 2014 Intercom and Paging System Replacement 2017 Convert Tennis Courts to Post Tension 2018 Bleachers 2018 Synthetic Turf
Mountain Ridge Middle School 2003 New Construction 2004 Technology Improvements 2004 Security Cameras/Radios Mountain View Elementary 1994 Roof Improvements 1997 Carpet Replacement 1999 Bathroom Improvements 2000 Parking Lot Improvements 2000 Playground Improvements 2001 5,278 SF Addition 2004 Security Cameras/Radios 2004 Security Access Control Mountain Vista High School 2001 New Construction 2007 Security Kiosk Mountain Vista High School Cont. 2004 Chiller 2004 Security Cameras/Radios 2004 Security Cameras/Radios 2004 Security Cameras/Radios	2014 Clock System 2017 Addition of Secured Folding Partition Wall 2004 Technology Improvements 2007 Carpet Replacement 2008 Roof Replacement 2014 Kitchen and Gymnasium Flooring 2016 Switchgear, Transformers, & Panels 2019 Upgrade control system 2019 Replace rooftop units 2019 Recaulk windows, repair rusted windows 2014 Fire Alarm System Replacement 2019 Replace carpet in hallways and office 2010 Site Improvements - Curb 2012 Tile Replacement - Halls/Classrooms 2013 Resand Gymnasium Floor	2019 Replace restroom partitions and flooring 2019 Upgrade fire alarm system 2019 Upgrade irrigation system 2019 Resurface bus loop and parking lot 2019 Silver coat parapet walls 2019 Repair and refinish exterior doors 2019 Repair and replace classroom storefronts 2019 Replace non-restricted with restricted key system 2014 Intercom and Paging System Replacement 2017 Convert Tennis Courts to Post Tension 2018 Bleachers

Mowthooot	[
Normeasi	Elementary

Northeast Elementary		
1992 8,642 SF Addition	2011 White Boards	2019 Caulk, repair exterior wall
1999 Roof Replacement	2012 Site Lighting Poles	2019 Replace all old casework
1999 Sidewalk	2012 Tile Replacement - Halls/Classrooms	2019 Replace cafeteria, gym, and restroom flooring
2001 Playground Improvements	2013 Playfield Replacement	2019 Replace carpet
2001 Access Road	2014 Clock System	2019 Fix gutter and downspout drainage
2002 1,540 SF Addition	2015 Fire Alarm System Replacement	2019 Replace non-restricted with restricted key system
2004 Technology Improvements	2015 Boiler, Chiller, and Controls Upgrade	2019 Replace original panel and transformers
2004 Security Cameras/Radios	2017 Window Replacement-Multiple Areas	2019 Replace original panel and transformers
2004 Security Access Control	2018 Bathrooms-Partitions, Countertops, & Floor	2019 Sand and paint exterior doors
2006 Kitchen Make-up Air	2019 Generator replacement	
Northridge Elementary		
1996 Playground Improvements	2004 Security Cameras/Radios	2014 Cafeteria Flooring
1997 Air Conditioning	2005 Security Access Control	2014 Resurface Gymnasium Floor
2000 Carpet Replacement	2005 Playground Improvements	2018 Fire Alarm Devices
2004 3,590 SF Addition	2011 Sidewalk/Bridge	2019 Flooring
2004 Technology Improvements	2013 Stage Partition	2019 Bathroom partitions
Operations & Maintenance East Facility	у	
2019 Replace outside gas piping	2019 Replace furnace units	2019 Replace AC units
Parker Joint Use Facility		
1993 Addition/Remodel	2003 Addition/Remodel	2014 Partial Roof Replacement
Pine Grove Elementary		
2004 Technology Improvements	2005 Security Access Controls	2010 3,996 SF Addition
2004 Security Cameras/Radios	2006 Carpet Replacement	2018 Mobile Ramp
Pine Lane Intermediate		
1992 1,980 SF Addition	2004 Security Cameras/Radios	2013 Daylighting Enhancement
1998 1,874 SF Addition	2005 Security Access Control	2014 Carpet
2003 HVAC Improvements	2005 Playground Imrovements	2016 Electrical Switchgear, Transformers, & Panel Replacement
2004 Intercom	2005 Elevator	2016 Roof Replacement (1 Section)
2004 Technology Improvements	2010 Roof Replacement	2019 Refinish interior doors and doorframes
	·	2019 Replace non-restricted with restricted key system
Pine Lane Primary		
1994 Roof Replacement	2001 Bus Loop Improvements	2010 Roof Replacement
1996 Connect to Public Water	2003 6,951 SF Addition	2012 Carpet Replacement
1996 Playground Improvements	2004 Technology Improvements	2012 Carpet Replacement - Mobile
1996 Carpet Replacement	2004 Security Improvements	2013 Restroom Remodel
1998 Playground Improvements	2006 Parking Lot Improvements	2016 Electrical Switchgear, Transformers, & Panel Replacement
Pioneer Elementary		
2005 Security Access Control	2014 Restroom Flooring	2019 Upgrade and replace exhaust fans
2006 Parking Lot Improvements	2014 Fire Alarm System Replacement	2019 Recaulk and reseal exterior CMU wall
2008 Carpet Replacement	2019 Upgrade controls	2019 Replace kitchen flooring
2011 Restroom Flooring Replacement	2019 Replace roof top units	2019 Replace hot water storage tank
2014 Clock System	2019 Replace generator and associated equipme	2019 Replace unrestricted with restricted key system
2014 Roof Repair	2019 Replace original carpeting in gym	2019 Repair and replace areas of sidewalk

F	Pondero	sa High Schoo
	1995	Parking Lot Impro

Ponderosa High School		
1995 Parking Lot Improvements	2013 ADA Compliance	2019 Replace ballasted with fully adhered roof
1996 HVAC Improvements	2014 Resurface Turf Field	2019 Evaluate and redesign terminal self contained units
1998 Roof Repair	2014 Autoshop Expansion	2019 Upgrade controls
1998 Water Main	2014 Intercom	2019 Replace band area roof top unit
1999 Gym Floor Replacement	2014 Hallway/Classroom Flooring	2019 Install new gas supply lines for kitchen
2000 Boilers	2014 Roof Replacement	2019 Replace toilet partitions
2001 Running Track	2015 Electrical Switchgear and Panel Board Rep	2019 Replace toilet partitions
2002 Addition/Remodel	2015 Track Replacement	2019 Replace main gym bleachers
2003 Artificial Turf Playfield	2016 Boiler and Condensing Units	2019 Replace carpet, VCT, and tile flooring throughout building
2004 Air Handling Units	2017 ADA Modifications in Auditorium	2019 Upgrade glycol distribution systems
2004 Security Access Control	2017 Theater Lighting System Processor	2019 Upgrade hot water distribution
2004 Security Cameras/Radios	2017 Addition of Dust Collector	2019 Replace insulation
2004 Technology Improvements	2018 Post Tension Tennis Courts	2019 Renovate kitchen
2006 Special Education Restrooms	2018 Theater Strand Lighting	2019 Replace irrigation controllers
2007 Security Kiosk	2019 Air distribution system	2019 Upgrade lavatory to autosensor
2010 Security Detection System	2019 Auxiliary equipment	2019 Upgrade lavatory to autosensor
2011 Carpet Replacement	2019 Boiler replacement	2019 Evaluate and redesign package units
2012 Door Replacement/Repair	2019 Change-over distribution system	2019 Renovate elevators
2012 Tile Replacement - Halls-Classrooms	2019 Retest and recommission air and water syste	
Plum Creek Academy		
1997 Boiler	2001 Water Tap	2008 Roof Repairs
1998 Air Conditioning	2003 Addition	2009 Carpet
1999 Roof		(· · ·
Prairie Crossing Elementary 2001 New Construction	2018 Carpet Replacement	2019 Replace kitchen flooring
2001 New Construction 2004 Technology Improvements	2018 Carpet Replacement 2018 Bathrooms renovation	2019 Replace kitchen hooring 2019 Replace unrestricted with restricted key system
== :		
2004 Security Improvements	2019 Upgrade control system	2019 Paint metal roof
2012 Carpet Replacement - Mobile	2019 Generator replacement	2019 Repair/replace sections of sidewalk
	2019 Upgrade fire alarm system	2019 Replace roof
Ranch View Middle School		
1997 New Construction	2017 Replace Fire Alarm System	2019 Recaulk exterior wall control joints
2004 Technology Improvements	2017 Folding Partition Wall at Pods	2019 Replace restroom toilet partitions
2004 Security Access Control	2017 SPED Calming Room	2019 Replace restroom toilet partitions
2004 Security Cameras/Radios	2018 Cooling Tower	2019 Replace kitchen and hallway flooring
2007 Security Kiosk	2018 SPED Calming Room	2019 Replace unrestricted with restricted key system
2013 Resand Gymnasium Floor	2019 Replace current Simplex clock system	2019 Replace ballasted with fully adhered roof
•	2019 Upgrade control system	2019 Repair and paint exterior doors
2014 Domestic Hot Water System Ungrade		
2014 Domestic Hot Water System Upgrade		2019 Nepali and paint exterior doors
Redstone Elementary		
_	2013 Carpet Replacement - Mobile	2017 Replace Entry Walk-Off Carpet
Redstone Elementary 2005 New Construction Renaissance Elementary	2013 Carpet Replacement - Mobile	
Redstone Elementary 2005 New Construction		
Redstone Elementary 2005 New Construction Renaissance Elementary 2006 New Construction Rock Canyon High School	2013 Carpet Replacement - Mobile 2012 Restroom Countertops	2017 Replace Entry Walk-Off Carpet
Redstone Elementary 2005 New Construction Renaissance Elementary 2006 New Construction Rock Canyon High School 2003 New Construction	2013 Carpet Replacement - Mobile 2012 Restroom Countertops 2007 Security Kiosk	2017 Replace Entry Walk-Off Carpet 2014 Resurface Turf Field
Redstone Elementary 2005 New Construction Renaissance Elementary 2006 New Construction Rock Canyon High School	2013 Carpet Replacement - Mobile 2012 Restroom Countertops	2017 Replace Entry Walk-Off Carpet 2014 Resurface Turf Field 2014 Intercom and Paging System Replacement
Redstone Elementary 2005 New Construction Renaissance Elementary 2006 New Construction Rock Canyon High School 2003 New Construction	2013 Carpet Replacement - Mobile 2012 Restroom Countertops 2007 Security Kiosk	2017 Replace Entry Walk-Off Carpet 2014 Resurface Turf Field
Redstone Elementary 2005 New Construction Renaissance Elementary 2006 New Construction Rock Canyon High School 2003 New Construction 2004 Security Access Control	2013 Carpet Replacement - Mobile 2012 Restroom Countertops 2007 Security Kiosk 2010 28,249 SF Addition	2017 Replace Entry Walk-Off Carpet 2014 Resurface Turf Field 2014 Intercom and Paging System Replacement
Redstone Elementary 2005 New Construction Renaissance Elementary 2006 New Construction Rock Canyon High School 2003 New Construction 2004 Security Access Control 2004 Security Cameras/Radios 2004 Technology Improvements	2013 Carpet Replacement - Mobile 2012 Restroom Countertops 2007 Security Kiosk 2010 28,249 SF Addition 2010 Clearstory Windows	2017 Replace Entry Walk-Off Carpet 2014 Resurface Turf Field 2014 Intercom and Paging System Replacement 2018 Landscaping
Redstone Elementary 2005 New Construction Renaissance Elementary 2006 New Construction Rock Canyon High School 2003 New Construction 2004 Security Access Control 2004 Security Cameras/Radios 2004 Technology Improvements Rock Ridge Elementary	2013 Carpet Replacement - Mobile 2012 Restroom Countertops 2007 Security Kiosk 2010 28,249 SF Addition 2010 Clearstory Windows 2013 Track Replacement	2017 Replace Entry Walk-Off Carpet 2014 Resurface Turf Field 2014 Intercom and Paging System Replacement 2018 Landscaping 2019 Upgrade control system 2019 SPED calming room(s)
Redstone Elementary 2005 New Construction Renaissance Elementary 2006 New Construction Rock Canyon High School 2003 New Construction 2004 Security Access Control 2004 Security Cameras/Radios 2004 Technology Improvements	2013 Carpet Replacement - Mobile 2012 Restroom Countertops 2007 Security Kiosk 2010 28,249 SF Addition 2010 Clearstory Windows	2017 Replace Entry Walk-Off Carpet 2014 Resurface Turf Field 2014 Intercom and Paging System Replacement 2018 Landscaping 2019 Upgrade control system
Redstone Elementary 2005 New Construction Renaissance Elementary 2006 New Construction Rock Canyon High School 2003 New Construction 2004 Security Access Control 2004 Security Cameras/Radios 2004 Technology Improvements Rock Ridge Elementary	2013 Carpet Replacement - Mobile 2012 Restroom Countertops 2007 Security Kiosk 2010 28,249 SF Addition 2010 Clearstory Windows 2013 Track Replacement	2017 Replace Entry Walk-Off Carpet 2014 Resurface Turf Field 2014 Intercom and Paging System Replacement 2018 Landscaping 2019 Upgrade control system 2019 SPED calming room(s)
Redstone Elementary 2005 New Construction Renaissance Elementary 2006 New Construction Rock Canyon High School 2003 New Construction 2004 Security Access Control 2004 Security Cameras/Radios 2004 Technology Improvements Rock Ridge Elementary 1995 Parking Lot Improvements	2013 Carpet Replacement - Mobile 2012 Restroom Countertops 2007 Security Kiosk 2010 28,249 SF Addition 2010 Clearstory Windows 2013 Track Replacement	2017 Replace Entry Walk-Off Carpet 2014 Resurface Turf Field 2014 Intercom and Paging System Replacement 2018 Landscaping 2019 Upgrade control system 2019 SPED calming room(s) 2012 Parking Lot/Playground Paving
Redstone Elementary 2005 New Construction Renaissance Elementary 2006 New Construction Rock Canyon High School 2003 New Construction 2004 Security Access Control 2004 Security Cameras/Radios 2004 Technology Improvements Rock Ridge Elementary 1995 Parking Lot Improvements 1996 Parking Lot Improvements	2013 Carpet Replacement - Mobile 2012 Restroom Countertops 2007 Security Kiosk 2010 28,249 SF Addition 2010 Clearstory Windows 2013 Track Replacement 2003 Carpet Replacement 2004 Security Cameras/Radios	2017 Replace Entry Walk-Off Carpet 2014 Resurface Turf Field 2014 Intercom and Paging System Replacement 2018 Landscaping 2019 Upgrade control system 2019 SPED calming room(s) 2012 Parking Lot/Playground Paving 2013 Carpet Replacement - Mobile
Redstone Elementary 2005 New Construction Renaissance Elementary 2006 New Construction Rock Canyon High School 2003 New Construction 2004 Security Access Control 2004 Security Cameras/Radios 2004 Technology Improvements Rock Ridge Elementary 1995 Parking Lot Improvements 1996 Parking Lot Improvements 1997 Air Conditioning	2013 Carpet Replacement - Mobile 2012 Restroom Countertops 2007 Security Kiosk 2010 28,249 SF Addition 2010 Clearstory Windows 2013 Track Replacement 2003 Carpet Replacement 2004 Security Cameras/Radios 2004 Technology Improvements	2017 Replace Entry Walk-Off Carpet 2014 Resurface Turf Field 2014 Intercom and Paging System Replacement 2018 Landscaping 2019 Upgrade control system 2019 SPED calming room(s) 2012 Parking Lot/Playground Paving 2013 Carpet Replacement - Mobile 2014 Fence
Redstone Elementary 2005 New Construction Renaissance Elementary 2006 New Construction Rock Canyon High School 2003 New Construction 2004 Security Access Control 2004 Security Cameras/Radios 2004 Technology Improvements Rock Ridge Elementary 1995 Parking Lot Improvements 1996 Parking Lot Improvements 1997 Air Conditioning 2000 Playground Improvements 2001 Playground Improvements	2013 Carpet Replacement - Mobile 2012 Restroom Countertops 2007 Security Kiosk 2010 28,249 SF Addition 2010 Clearstory Windows 2013 Track Replacement 2003 Carpet Replacement 2004 Security Cameras/Radios 2004 Technology Improvements 2005 Security Access Control	2017 Replace Entry Walk-Off Carpet 2014 Resurface Turf Field 2014 Intercom and Paging System Replacement 2018 Landscaping 2019 Upgrade control system 2019 SPED calming room(s) 2012 Parking Lot/Playground Paving 2013 Carpet Replacement - Mobile 2014 Fence 2014 Cafeteria Flooring
Redstone Elementary 2005 New Construction Renaissance Elementary 2006 New Construction Rock Canyon High School 2003 New Construction 2004 Security Access Control 2004 Security Cameras/Radios 2004 Technology Improvements Rock Ridge Elementary 1995 Parking Lot Improvements 1996 Parking Lot Improvements 1997 Air Conditioning 2000 Playground Improvements 2001 Playground Improvements	2013 Carpet Replacement - Mobile 2012 Restroom Countertops 2007 Security Kiosk 2010 28,249 SF Addition 2010 Clearstory Windows 2013 Track Replacement 2003 Carpet Replacement 2004 Security Cameras/Radios 2004 Technology Improvements 2005 Security Access Control 2005 3,000 SF Addition	2017 Replace Entry Walk-Off Carpet 2014 Resurface Turf Field 2014 Intercom and Paging System Replacement 2018 Landscaping 2019 Upgrade control system 2019 SPED calming room(s) 2012 Parking Lot/Playground Paving 2013 Carpet Replacement - Mobile 2014 Fence 2014 Cafeteria Flooring 2017 Replace Entry Walk-Off Carpet
Redstone Elementary 2005 New Construction Renaissance Elementary 2006 New Construction Rock Canyon High School 2003 New Construction 2004 Security Access Control 2004 Security Cameras/Radios 2004 Technology Improvements Rock Ridge Elementary 1995 Parking Lot Improvements 1996 Parking Lot Improvements 1997 Air Conditioning 2000 Playground Improvements 2001 Playground Improvements Rocky Heights Middle School	2013 Carpet Replacement - Mobile 2012 Restroom Countertops 2007 Security Kiosk 2010 28,249 SF Addition 2010 Clearstory Windows 2013 Track Replacement 2003 Carpet Replacement 2004 Security Cameras/Radios 2004 Technology Improvements 2005 Security Access Control	2017 Replace Entry Walk-Off Carpet 2014 Resurface Turf Field 2014 Intercom and Paging System Replacement 2018 Landscaping 2019 Upgrade control system 2019 SPED calming room(s) 2012 Parking Lot/Playground Paving 2013 Carpet Replacement - Mobile 2014 Fence 2014 Cafeteria Flooring

Roxborough Intermediate	2019 Mayamant Issues	2010 Florester modernization
2008 New Construction	2018 Movement Issues	2019 Elevator modernization
Poxborough Primary		
2000 Playground Improvements	2004 Intercom	2010 1,000 SF Addition
2001 Parking Lot Improvements	2004 Security Cameras/Radios	2013 Kitchen Floor Repair
2002 Generator	2004 Technology Improvements	2017 Replace Entry Walk-Off Carpet
2004 Carpet Replacement	2005 Security Access Control	
addle Ranch Elementary		
1999 New Construction	2016 Boiler Replacement (2)	2019 Upgrade fire alarm system
2004 Technology Improvements	2019 Replace chiller and cooling tower	2019 Art room coun tertops
2004 Security Cameras/Radios	2019 Generator replacement	2019 Replace irrigation controllers and sprinkler heads
2005 Security Access Control	2019 Caulk, seal, repair exterior wall	2019 Replace roof
2013 Flooring Replacement	2019 Storefront window/skylight	2019 Recplace door hardware, install restricted key system
2014 Clock System		, _, _, _, _,
Paga Canyan Flamantany		
Sage Canyon Elementary 2010 New Construction	2014 Repair to Handicap Ramp	2018 Window Tinting
Consumed Middle Colored		2019 Elevator modernization
agewood Middle School	2017 Folding Postition Wall	2010. Gum bloochors
2004 Security Access Control	2017 Folding Partition Wall	2019 Gym bleachers
2004 Security Cameras/Radios	2017 Window Glazing in Commons Area	2019 Roof replacement
2004 Technology Improvement	2018 Window Tinting	2019 Flooring
2006 HVAC Upgrade	2019 Cooling tower	2019 Skylight(s) replacement
2010 Track Resurface	2019 Control System	2019 Door hardware (restricted system)
2015 Fire Alarm System Replacement	2019 Generator Replacement	2019 Irrigation system upgrade
2016 Domestic Hot Water System Upgrade	2019 Caulk exterior wall, crack repair	
Sand Creek Elementary		
1990 8,237 SF Addition	2004 Security Cameras/Radios	2017 Replace Flooring in Restrooms
1999 Air Conditioning	2005 Security Access Control	2017 Window Replacement in Multiple Areas
2000 Playground Improvements	2005 3,000 SF Addition	2017 Replace Entry Walk-Off Carpet
2002 Carpet Replacement	2013 Carpet Replacement - Mobile	
2003 Reballast	2014 Cafeteria Flooring	
2004 Technology Improvements	2016 Restroom Countertop Replacement	
Sedalia Elementary		
1966 Gutters/Downspouts	2005 Security Access Control	2014 Fire Alarm System Replacement
1992 Addition	2005 Carpet Replacement	2014 Resurface Gymnasium Floor
1999 Addition	2006 HVAC Upgrades	2016 Rooftop Unit Replacement (2)
2001 Countertops/Fountains	2006 Playground Improvements	2017 Window Replacement-Multiple Areas
2003 HVAC Controls	2006 Roof Replacement	2019 Door hardware (restricted system)
2004 Roof Replacement	2011 Playfield Replacement	2019 Flooring
2004 Clock Replacement	2012 Sanitary Improvements	2019 Playgrounds
2004 Technology Improvements	2013 Daylighting Enhancement	
2004 Security Cameras/Radios		
Shea Stadium		
2019 Boiler	2019 Sound system	2019 Lighting
2019 Bleachers	2019 Site infrastructure	
Sierra Middle School		
1995 Partial Roof Replacement	2006 Gym Floor	2014 Resurface Gym Floor
1996 Heat Piping	2006 Road Connection	2014 Domestic Hot Water System Upgrade
1997 Partial Roof Replacement	2006 Bus Loop Improvements	2016 Electrical Panel Replacement
2003 Bathroom Improvements	2006 Lockers	2016 Emergency Generator Replacement
2003 Site Improvements	2007 Bleachers	2017 Replace Fire Alarm System
2004 Electrical Improvements	2011 Tile Replacement - Hallways	2017 Window Replacement-Multiple Areas
2004 9,000 SF Addition	2012 Clock System Upgrade	2017 Additional Lighting in Cafeteria
2004 Clock Replacement	2012 Kitchen Floor Repair	2018 Cafeteria Lighting
2004 Technology Improvements	2012 Partial Roof Replacement	2018 Entrance Improvements
2004 Security Cameras/Radios	2013 Cooling - Gymnasiums	2019 Flooring replacement
2005 Security Access Control	2014 Fence	2019 Door hardware (restricted key system)
2000 Occurry Access Control		
2005 Partial Roof Replacement	2014 Update Water Well System	

ring Hawk Elementary		
2004 New Construction	2012 Carpet Replacement - Mobile	2019 Recaulk exterior wall
2004 Technology Improvements	2014 Clock System	2019 Fire alarm system upgrade
2004 Security Cameras/Radios	2019 Control system	2019 Roof replacement
2005 Security Access Control		
th Ridge Elementary		
1992 5,380 SF Addition	2012 Carpet Replacement	2019 Toilet partitions
1994 Rooftop Units	2013 Daylighting Enhancement	2019 Casework replacement
1995 Mechanical Improvements	2014 Clock System	2019 Restroom flooring
1997 Playground Improvements	2014 Resurface Gymnasium Floor	2019 Gutters & downspouts
1998 Drainage	2016 Roof Replacement (1 Section)	2019 Interior doors and door frames
2003 Rooftop Units	2017 ADA Restrooms	2019 Door hardware (restricted key system)
2003 Water Service	2017 Replace Handwash Basins	2019 Install seperate irrigation meter
2004 Security Cameras/Radios	2018 Bathrooms-Partitions, Countertops, & Floor	2019 Panels and transformers
2004 Security Access Control	2019 Control system	2019 Classroom partitions
2004 Technology Improvements	2019 Roof replacement	2019 Roof replacement
2006 Roof Replacement	2019 Generator replacement	2019 Refinish exterior doors
2006 Elevator	2019 Caulk exterior wall	2019 Entry storefronts
2012 Door Hardware Replacement		
ne Mountain Elementary 2007 New Construction	2019 Elevator modernization	
ne Mountain Elementary 2007 New Construction	2019 Elevator modernization	
ne Mountain Elementary	2019 Elevator modernization	
ne Mountain Elementary 2007 New Construction dent Support Center 2007 New Mobile	2019 Elevator modernization	
ne Mountain Elementary 2007 New Construction dent Support Center	2019 Elevator modernization 2005 Security Access Control	2014 Cafeteria Flooring
ne Mountain Elementary 2007 New Construction dent Support Center 2007 New Mobile mmit View Elementary		2014 Cafeteria Flooring 2014 Resurface Gymnasium Floor
ne Mountain Elementary 2007 New Construction dent Support Center 2007 New Mobile mmit View Elementary 2000 Playground Improvements	2005 Security Access Control	<u> </u>
ne Mountain Elementary 2007 New Construction dent Support Center 2007 New Mobile mmit View Elementary 2000 Playground Improvements 2004 Security Cameras/Radios 2004 Technology Improvements	2005 Security Access Control 2005 Carpet Replacement	2014 Resurface Gymnasium Floor
ne Mountain Elementary 2007 New Construction dent Support Center 2007 New Mobile mmit View Elementary 2000 Playground Improvements 2004 Security Cameras/Radios 2004 Technology Improvements underRidge High School	2005 Security Access Control 2005 Carpet Replacement 2008 2,684 SF Addition	2014 Resurface Gymnasium Floor 2018 Bathrooms-Partitions, Countertops, & Flooring
ne Mountain Elementary 2007 New Construction dent Support Center 2007 New Mobile mmit View Elementary 2000 Playground Improvements 2004 Security Cameras/Radios 2004 Technology Improvements inderRidge High School 1998 34,368 SF Addition	2005 Security Access Control 2005 Carpet Replacement 2008 2,684 SF Addition	2014 Resurface Gymnasium Floor 2018 Bathrooms-Partitions, Countertops, & Flooring 2018 SPED Calming Room
ne Mountain Elementary 2007 New Construction dent Support Center 2007 New Mobile mmit View Elementary 2000 Playground Improvements 2004 Security Cameras/Radios 2004 Technology Improvements inderRidge High School 1998 34,368 SF Addition 2004 Artificial Turf Playfield	2005 Security Access Control 2005 Carpet Replacement 2008 2,684 SF Addition 2012 Resurface Track 2012 Resurface Tennis Courts	2014 Resurface Gymnasium Floor 2018 Bathrooms-Partitions, Countertops, & Flooring 2018 SPED Calming Room 2019 Air distribution system
ne Mountain Elementary 2007 New Construction dent Support Center 2007 New Mobile mmit View Elementary 2000 Playground Improvements 2004 Security Cameras/Radios 2004 Technology Improvements inderRidge High School 1998 34,368 SF Addition 2004 Artificial Turf Playfield 2004 Batting Cages	2005 Security Access Control 2005 Carpet Replacement 2008 2,684 SF Addition 2012 Resurface Track 2012 Resurface Tennis Courts 2014 Fire Alarm System Replacement	2014 Resurface Gymnasium Floor 2018 Bathrooms-Partitions, Countertops, & Flooring 2018 SPED Calming Room 2019 Air distribution system 2019 Roof replacement & solar
ne Mountain Elementary 2007 New Construction dent Support Center 2007 New Mobile mmit View Elementary 2000 Playground Improvements 2004 Security Cameras/Radios 2004 Technology Improvements underRidge High School 1998 34,368 SF Addition 2004 Artificial Turf Playfield 2004 Batting Cages 2004 Chiller	2005 Security Access Control 2005 Carpet Replacement 2008 2,684 SF Addition 2012 Resurface Track 2012 Resurface Tennis Courts 2014 Fire Alarm System Replacement 2014 Partial Roof Replacement	2014 Resurface Gymnasium Floor 2018 Bathrooms-Partitions, Countertops, & Flooring 2018 SPED Calming Room 2019 Air distribution system 2019 Roof replacement & solar 2019 Generator replacement
ne Mountain Elementary 2007 New Construction dent Support Center 2007 New Mobile mmit View Elementary 2000 Playground Improvements 2004 Security Cameras/Radios 2004 Technology Improvements underRidge High School 1998 34,368 SF Addition 2004 Artificial Turf Playfield 2004 Batting Cages 2004 Chiller 2004 Security Cameras/Radios	2005 Security Access Control 2005 Carpet Replacement 2008 2,684 SF Addition 2012 Resurface Track 2012 Resurface Tennis Courts 2014 Fire Alarm System Replacement 2014 Partial Roof Replacement 2014 Intercom and Paging System Replacement	2014 Resurface Gymnasium Floor 2018 Bathrooms-Partitions, Countertops, & Flooring 2018 SPED Calming Room 2019 Air distribution system 2019 Roof replacement & solar 2019 Generator replacement 2019 Flooring
ne Mountain Elementary 2007 New Construction dent Support Center 2007 New Mobile mmit View Elementary 2000 Playground Improvements 2004 Security Cameras/Radios 2004 Technology Improvements underRidge High School 1998 34,368 SF Addition 2004 Artificial Turf Playfield 2004 Batting Cages 2004 Chiller 2004 Security Cameras/Radios 2004 Security Cameras/Radios	2005 Security Access Control 2005 Carpet Replacement 2008 2,684 SF Addition 2012 Resurface Track 2012 Resurface Tennis Courts 2014 Fire Alarm System Replacement 2014 Partial Roof Replacement 2014 Intercom and Paging System Replacement 2015 Tennis Court Resurfacing	2014 Resurface Gymnasium Floor 2018 Bathrooms-Partitions, Countertops, & Flooring 2018 SPED Calming Room 2019 Air distribution system 2019 Roof replacement & solar 2019 Generator replacement 2019 Flooring 2019 Toilet partitions
ne Mountain Elementary 2007 New Construction dent Support Center 2007 New Mobile mmit View Elementary 2000 Playground Improvements 2004 Security Cameras/Radios 2004 Technology Improvements underRidge High School 1998 34,368 SF Addition 2004 Artificial Turf Playfield 2004 Batting Cages 2004 Chiller 2004 Security Cameras/Radios 2004 Security Cameras/Radios 2004 Security Access Control 2004 Technology Improvements	2005 Security Access Control 2005 Carpet Replacement 2008 2,684 SF Addition 2012 Resurface Track 2012 Resurface Tennis Courts 2014 Fire Alarm System Replacement 2014 Partial Roof Replacement 2014 Intercom and Paging System Replacement 2015 Tennis Court Resurfacing 2016 Turf Field Replacement	2014 Resurface Gymnasium Floor 2018 Bathrooms-Partitions, Countertops, & Flooring 2018 SPED Calming Room 2019 Air distribution system 2019 Roof replacement & solar 2019 Generator replacement 2019 Flooring 2019 Toilet partitions 2019 Gym bleachers
ne Mountain Elementary 2007 New Construction dent Support Center 2007 New Mobile mmit View Elementary 2000 Playground Improvements 2004 Security Cameras/Radios 2004 Technology Improvements underRidge High School 1998 34,368 SF Addition 2004 Artificial Turf Playfield 2004 Batting Cages 2004 Chiller 2004 Security Cameras/Radios 2004 Security Access Control 2004 Technology Improvements 2006 Clearstory Windows	2005 Security Access Control 2005 Carpet Replacement 2008 2,684 SF Addition 2012 Resurface Track 2012 Resurface Tennis Courts 2014 Fire Alarm System Replacement 2014 Partial Roof Replacement 2014 Intercom and Paging System Replacement 2015 Tennis Court Resurfacing 2016 Turf Field Replacement 2016 Interior Door Hardware	2014 Resurface Gymnasium Floor 2018 Bathrooms-Partitions, Countertops, & Flooring 2018 SPED Calming Room 2019 Air distribution system 2019 Roof replacement & solar 2019 Generator replacement 2019 Flooring 2019 Toilet partitions 2019 Gym bleachers 2019 Elevator renovation
ne Mountain Elementary 2007 New Construction dent Support Center 2007 New Mobile mmit View Elementary 2000 Playground Improvements 2004 Security Cameras/Radios 2004 Technology Improvements underRidge High School 1998 34,368 SF Addition 2004 Artificial Turf Playfield 2004 Batting Cages 2004 Chiller 2004 Security Cameras/Radios 2004 Security Access Control 2004 Technology Improvements 2006 Clearstory Windows 2007 Resurface Tennis Courts	2005 Security Access Control 2005 Carpet Replacement 2008 2,684 SF Addition 2012 Resurface Track 2012 Resurface Tennis Courts 2014 Fire Alarm System Replacement 2014 Partial Roof Replacement 2014 Intercom and Paging System Replacement 2015 Tennis Court Resurfacing 2016 Turf Field Replacement 2016 Interior Door Hardware 2017 Replace Carpet in Main and Pod Hallways	2014 Resurface Gymnasium Floor 2018 Bathrooms-Partitions, Countertops, & Flooring 2018 SPED Calming Room 2019 Air distribution system 2019 Roof replacement & solar 2019 Generator replacement 2019 Flooring 2019 Toilet partitions 2019 Gym bleachers 2019 Elevator renovation 2019 Glycol distribution system
ne Mountain Elementary 2007 New Construction dent Support Center 2007 New Mobile mmit View Elementary 2000 Playground Improvements 2004 Security Cameras/Radios 2004 Technology Improvements underRidge High School 1998 34,368 SF Addition 2004 Artificial Turf Playfield 2004 Batting Cages 2004 Chiller 2004 Security Cameras/Radios 2004 Security Access Control 2004 Technology Improvements 2006 Clearstory Windows	2005 Security Access Control 2005 Carpet Replacement 2008 2,684 SF Addition 2012 Resurface Track 2012 Resurface Tennis Courts 2014 Fire Alarm System Replacement 2014 Partial Roof Replacement 2014 Intercom and Paging System Replacement 2015 Tennis Court Resurfacing 2016 Turf Field Replacement 2016 Interior Door Hardware	2014 Resurface Gymnasium Floor 2018 Bathrooms-Partitions, Countertops, & Flooring 2018 SPED Calming Room 2019 Air distribution system 2019 Roof replacement & solar 2019 Generator replacement 2019 Flooring 2019 Toilet partitions 2019 Gym bleachers 2019 Elevator renovation

Timher	Trail	Elementary
11111001	Hun	

2003 New Construction	2012 Chiller Replacement	2018 Bathrooms-Partitions, Countertops, & Flooring
2004 Technology Improvements	2014 Clock System	


Trailblazer Elementary

2004 Security Access Control	2014 Clock System	2019 Upgrade backflow
2004 Security Cameras/Radios	2017 Replace Entry Walk-Off Carpet	2019 Generator replacement
2004 Technology Improvements	2018 Door Hardware	2019 Upgrade kitchen hood exhaust
2006 Parking Lot Improvements	2018 Roof Repair	2019 Caulk exterior wall, seal cracks
2007 Carpet Replacement	2018 SPED Calming Room	2019 Toilet partitions
2011 Security Door	2019 Control system	2019 Flooring
2013 Restroom Flooring	2019 Roof top units replacement	2019 Roof replacement

Marchai	ise-Service	Contor
vvarenoi	ISA-SANVICA	L.enter

warenouse-Service Center		
1996 Warehouse Expansion	2007 Parking Lot	2019 Transportation fuel tank
1996 Tran Fuel Tank Removal	2007 Security Gate	2019 Doors & door hardware
2000 A/C Print Shop	2009 O&M HVAC	2019 Plumbing system & fixtures
2003 CSAP Processing Center	2009 Construction Office Remodel	2019 Garage door coating
2003 Tran Carpet	2012 Freezer Roof Replacement	2019 Replace garage door
2003 Asphalt Parking Lot	2017 Addition of Transportation Building F	2019 Carpet replacement
2003 O&M Gutter Stucco	2018 Electrical Maintenance	2019 HVAC
2003 Tran Thermal Performance	2018 Fuel Tank Upgrade	2019 Roofing
2006 Warehouse Freezer Addition		
West Support Center		
2012 Install Generator	2012 Office Reconfiguration	2019 Asphalt & sidewalk repair
2012 Insulat Outer Walls and Windos	2018 RTU Replacement	2019 Storm water drainage
		2019 Roofing
Wilcox		
1989 Renovation	2000 Renovation	2002 Data Center
1994 Mechanical	2000 Renovation	2013 North Roof Replacement
1996 Renovation	2001 Renovation	2016 Additional Card Access and Cameras
Wildcat Mountain Elementary		
2004 Security Cameras/Radios	2012 Controls System Upgrade	2019 Generator replacement
2004 Security Access/Control	2013 Fire Alarm Panel Replacement	2019 Caulk, seal exterior wall
2004 Technology Improvements	2013 Resurface Playground	2019 Caulk, seal windows
2006 Bus Loop Improvements	2014 Clock System	2019 Cafeteria flooring
2006 Carpet Replacement	2019 Air distribution system	2019 Door hardware (restricted system)





Funding Source	2012	2013	2014	2015	2016	2017	2018	2019	2020	Total (By Funding Source)
2006 Bond Building Fund	\$5,736,968	\$2,572,041	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$8,309,009
2009 COP Building Fund	\$0	\$7,137,584	\$6,195,979	\$0	\$0	\$0	\$0	\$0	\$0	\$13,333,563
2012 COP Building Fund	\$0	\$0	\$0	\$0	\$931,000	\$0	\$0	\$0	\$0	\$931,000
2014 COP Building Fund	\$0	\$0	\$0	\$5,751,380	\$792,000	\$3,740,000	\$0	\$0	\$0	\$10,283,380
Capital Projects Fund	\$0	\$0	\$979,738	\$304,875	\$2,263,000	\$5,750,000	\$4,952,070	\$142,461	\$49,959	\$14,442,103
Capital Projects Fund (Performance Contracts)	\$0	\$3,000,000	\$1,055,000	\$0	\$0	\$0	\$0	\$0	\$0	\$4,055,000
Facilities Rental Revenue	\$0	\$0	\$0	\$80,000	\$250,000	\$0	\$265,679	\$33,615	\$795,696	\$1,424,990
Transportation	\$0	\$0	\$0	\$0	\$408,000	\$312,000	\$0	\$0	\$0	\$720,000
Cash in Lieu	\$0	\$0	\$0	\$0	\$0	\$2,100,000	\$266,500	\$140,785	\$72,830	\$2,580,115
Grand Total	\$5,738,980	\$12,711,638	\$8,232,731	\$6,138,270	\$4,646,016	\$11,904,017	\$5,486,267	\$318,880	\$920,505	\$56,079,160


Capital Funding 2012-2020: \$56,079,160

**Totals for 2018 Bond funded capital not included in the above chart and table. For 2018 Bond funded capital totals please refer to: https://www.dcsdk12.org/cms/One.aspx?portalId=220484&pageId=8648502



Development Growth Cycle

The following diagram illustrates the correlation between residential housing development (certificates of occupancy) and the generation of school-age children. As neighborhoods develop and build out, there is a lag time of nearly seven to 12 years before the number of students generated at elementary, middle, and high school reaches its maximum impact in a school. As neighborhoods mature and students grow older, some families move away and neighborhoods continue their cycle of generating students again, only this time at a more consistent pace.



The district may utilize the four-track year-round calendar at the elementary level, and mobile classrooms at all levels to help mitigate the peak impact of development as depicted by the dotted lines on the diagram.

Development Impact

When determining the impact of residential development, Douglas County School District evaluates how many students are expected from any given development based on density. Once the student generation is calculated, it is then determined how much land would be required to build a school as well as capital mitigation. Often times, a development will generate acreage, but not enough for an entire school site. In these cases, the district may choose to accept a portion of the acreage in a commercial area if there is a commercial area as part of the project. These areas would help mitigate the growing needs for support service space as the district grows. The district may also collect cash-inlieu of land, or a combination of both. Collecting cash-in-lieu for smaller dedications allows the district to use this money to mitigate capacity needs with mobile classrooms, construction modifications, or the purchase of land in the future with consolidated funding.

The district has a voluntary capital mitigation process that evaluates the amount of taxes a development will produce, including both residential and commercial if applicable, and determines the gap between what is paid to the district in taxes and what it costs to construct a school through bonds and debt retirement. The district evaluates the impact over a 20, 30, and 40-year school building life cycle. Knowing that buildings have a longer life than 20-years, but acknowledging building components have limited operational life spans, the District asks the developer to voluntarily contribute mid-range between the 30 and 40-year numbers.

Although not inclusive of all development in the planning areas, a development summary in each Planning Area is provided on the following pages. These developments are in the building phase or in various stages of the review processes within the County. A map and summary table of the sites dedicated to the district for future schools have also been included.


Development Summary-North Planning Area

Development	Jurisdiction	Built from 01/01/2020 to 01/01/2021
Castle Pines Town Center	Castle Pines	67
Lagae Ranch	Castle Pines	126
The Canyons (North Canyons)	Castle Pines	150
Castle Pines Village	Douglas County	20
Copeland Canyon Condos	Douglas County	9
Erickson	Douglas County	1
Highlands Ranch	Douglas County	117
Hunting Hill	Douglas County	25
Inverness	Douglas County	2
River Canyon	Douglas County	16
Roxborough Downs	Douglas County	8
Roxborough Park	Douglas County	1
Roxborough Village	Douglas County	2
Shadow Canyon Condos	Douglas County	23
Solstice	Douglas County	37
Sterling Ranch	Douglas County	315
Surrey Ridge (Includes Estates and Peak Subdivisions)	Douglas County	1
Heritage Hills (Amendment 6)	Lone Tree	7
Retreat at Ridgegate	Lone Tree	14

The table above summarizes the number of units built in the last calendar year within the North Planning Area. The North Planning Area consists of Highlands Ranch, Lone Tree, Castle Pines, Roxborough, and portions of Littleton. Data on the number of units built was collected from Douglas County Department of Community Development.

Land Inventory-North Planning Area

• The table and map below show dedicated land for potential future school sites in the North Planning Area.



Feeder	Site Name	Site Type	Site Size (Acres)	Site Status
Highlands Ranch High School	Acres Green	Elementary	31.83	Platted
Highlands Ranch High School	Eastridge	Elementary	10.041	Platted
Highlands Ranch High School	Colorado Boulevard	Alternative Site	0.756	Platted
Highlands Ranch High School	Ridgegate A	Elementary	10	Unplatted
Highlands Ranch High School	Ridgegate B	Elementary	10	Unplatted
Highlands Ranch High School	Ridgegate C	Elementary	10	Unplatted
Highlands Ranch High School	Ridgegate D&E	Middle & High	75	Unplatted
Mountain View High School	Toepfer Park A	Elementary	6.984	Platted
Mountain View High School	Toepfer Park B	Elementary	3.016	Platted
Rock Canyon High School	Hidden Pointe	Elementary	10.44	Platted
Highlands Ranch High School	Ridgegate	Elementary	9.63	Unplatted
Rock Canyon High School	Canyons North B	Elementary	12	Unplatted
Rock Canyon High School	Canyons North A	Elementary	12	Unplatted
Rock Canyon High School	Canyons North C	Middle	25	Unplatted
Rock Canyon High School	Castle Pines Village	Elementary	10.1	Unplatted
ThunderRidge High School	Westridge Glen	Elementary	10.677	Platted
ThunderRidge High School	Sterling Ranch F	Elementary or K-8	12.512	Platted
ThunderRidge High School	Sterling Ranch B	Elementary or K-8	17	Unplatted
ThunderRidge High School	Sterling Ranch C	Elementary or K-8	17	Unplatted
ThunderRidge High School	Sterling Ranch D	Elementary or K-8	17	Unplatted
ThunderRidge High School	Sterling Ranch E	High	60	Unplatted
ThunderRidge High School	Sterling Ranch F	Elementary or K-8	17	Unplatted
ThunderRidge High School	Solstice	Elementary or K-8	15.2	Unplatted


Development Summary-West Planning Area

Development	Jurisdiction	Built from 01/01/2020 to 01/01/2021
Castle Oaks (aka Terrain)	Castle Rock	187
Castleview Estates (Includes The Oaks of Castle Rock)	Castle Rock	6
Crystal Valley Ranch	Castle Rock	294
Founders Village (Includes Founders and Bella Mesa)	Castle Rock	76
Meadows	Castle Rock	261
Plum Creek Ridge	Castle Rock	14
Bell Mountain Ranch	Douglas County	5
Perry Park	Douglas County	6
Sage Port	Douglas County	6

The table above summarizes the number of units built in the last calendar year within the West Planning Area. The West Planning Area consists of Castle Rock, Larkspur, Sedalia and portions of Unincorporated Douglas County. Data on the number of units built was collected from Douglas County Department of Community Development.

Land Inventory-West Planning Area

• The table and map below show dedicated land for potential future school sites in the West Planning Area.



Feeder	Site Type	Site Size (Acres)	Site Name	Site Status
Douglas County High School	Elementary	11.6	Castle Oaks Estates	Platted
Douglas County High School	High	62.869	Castlewood Ranch	Platted
Douglas County High School	Elementary	10	Crystal Valley A	Platted
Douglas County High School	Elementary	10.1	Crystal Valley B	Platted
Douglas County High School	Middle	20.17	Crystal Valley C	Platted
Douglas County High School	Middle	27.02	Macanta A	Platted
Douglas County High School	Elementary	10.09	Macanta B	Platted
Douglas County High School	Elementary	17.8	Plum Creek	Platted
Douglas County High School	Elementary	9	Sapphire Pointe	Platted
Douglas County High School	Alternative Site	3.8	Hazen Moore	Platted
Douglas County High School	PK-8	25.49	Lanterns	Unplatted
Douglas County High School	Elementary	10	Rock Canyon Ranch	Unplatted
Douglas County High School	Elementary	12.3	Bella Mesa	Unplatted
Douglas County High School	Elementary	10	Pine Canyon	Unplatted
Douglas County High School	PK-8	17.78	Pioneer Ranch	Unplatted
Douglas County High School	Elementary	12.3	Bella Mesa	Unplatted
Castle View High School	Middle	4.72	Hockaday A	Platted
Castle View High School	Middle	13.59	Hockaday B	Platted
Castle View High School	Middle	6.69	Hockaday C	Platted
Castle View High School	Elementary	10	Larkspur	Platted
Castle View High School	Alternative Site	1	Pine Cliff	Platted
Castle View High School	Elementary	10.01	Red Hawk	Platted
Castle View High School	Elementary	10.014	The Meadows Filing 20	Platted
Castle View High School	Elementary	10	Dawson Ridge A	Unplatted
Castle View High School	Elementary	10	Dawson Ridge B	Unplatted
Castle View High School	Elementary	50	Dawson Ridge D	Unplatted
Castle View High School	Elementary	10	Dawson Ridge C	Unplatted


Development Summary-East Planning Area

Development	Jurisdiction	Built from 01/01/2020 to 01/01/2021
Rocking Horse	Aurora	247
Liberty Village (aka Cobblestone Ranch, aka Villages at Castle Rock)	Castle Rock	93
Cottonwood South	Douglas County	24
Foxhill	Douglas County	8
High Prairie International Polo Club	Douglas County	10
Lincoln Creek Village	Douglas County	101
Meridian International Business Center	Douglas County	220
Pinery West	Douglas County	13
Prairie Walk on Cherry Creek Condos	Douglas County	25
Reata South	Douglas County	8
Sierra Ridge	Douglas County	38
Stone Creek (aka Stone Creek Ranch)	Douglas County	92
Stonegate	Douglas County	33
Tallman Gulch	Douglas County	7
The Pinery (includes Pradera and Timbers)	Douglas County	46
Carousel Farms	Parker	5
Compark	Parker	38
Cottonwood Highlands	Parker	23
Olde Towne (Neu Towne)	Parker	88
Overlook at Cherry Creek	Parker	15
Pine Bluffs	Parker	49
Reata North (Idyllwilde)	Parker	59
Stroh Crossing	Parker	15
Stroh Ranch (Includes Ironstone Condominiums at Stroh Ranch)	Parker	78

The table to the right summarizes the number of units built in the last calendar year within the East Planning Area. The East Planning Area consists of Parker, Franktown, Cherry Valley, and portions of Aurora, Elbert County, North-East Castle Rock, and Unincorporated Douglas County. Data on the number of units zoned and built was collected from Douglas County Department of Community Development.

Land Inventory-East Planning Area

• The table and map below show dedicated land for potential future school sites in the East Planning Area.



Feeder	Site Type	Site Size (Acres)	Site Name	Site Status
Chaparral High School	Elementary	10	Elkhorn Ranch	Unplatted
Chaparral High School	Elementary	11.7	Kings Point South	Unplatted
Chaparral High School	Elementary	10.1	Meridian Village	Platted
Chaparral High School	Alternative Site	5.832	Newlin Crossing	Unplatted
Chaparral High School	Elementary	12.817	Rocking Horse	Platted
Chaparral High School	Elementary	10.033	Sierra Ridge	Platted
Chaparral High School	Elementary or PK-8	26.8	Spring Valley Ranch	Unplatted
Legend High School	Undetermined	3.492	Kime Ranch	Unplatted
Chaparral High School	PK-8	18	Pine Drive	Platted
Ponderosa High School	Elementary	12	Anthology A	Unplatted
Ponderosa High School	Elementary	12	Anthology B	Unplatted
Ponderosa High School	Elementary	12	Anthology C	Unplatted
Ponderosa High School	Elementary	12	Anthology D	Unplatted
Ponderosa High School	Middle	25	Anthology E	Unplatted
Ponderosa High School	High	50	Anthology F	Unplatted
Ponderosa High School	K-8	22.482	Cielo	Platted
Ponderosa High School	Elementary	11.21	Cobblestone Ranch	Platted
Ponderosa High School	Other	2	Hilltop	Platted
Ponderosa High School	Alternative Site	6.678	Meadowlark	Unplatted
Ponderosa High School	Elementary	12.352	Pinery	Platted
Ponderosa High School	Alternative Site	2	Pinery West	Unplatted
Ponderosa High School	Alternative Site	7.5	Stone Creek Ranch	Unplatted
Ponderosa High School	Elementary	10.011	Pradera	Platted
Ponderosa High School	Elementary	10.321	Timbers	Platted

	Estimated Construction Cost	Estimated Inflation	Potential Regulatory, Professional Services, and Contracting Costs	Estimated Total Project Cost
Acres Green Elementary				
2021-22	\$2,143,400	\$2,143,400	\$214,100-\$921,600	\$4,500,900-\$5,208,400
2023-24	\$75,000	\$82,688	\$7,500-\$32,300	\$165,188-\$189,988
2024-25	\$250,000	\$289,500	\$25,000-\$107,500	\$564,500-\$647,000
Arrowwood Elementary				
2021-22	\$297,100	\$297,100	\$30,200-\$128,100	\$624,400-\$722,300
2024-25	\$550,000	\$636,900	\$55,000-\$236,500	\$1,241,900-\$1,423,400
Bear Canyon Elementary				
2021-22	\$505,400	\$505,400	\$50,600-\$217,100	\$1,061,400-\$1,227,900
2022-23	\$670,000	\$703,500	\$67,000-\$288,100	\$1,440,500-\$1,661,600
2023-24	\$350,000	\$385,875	\$35,000-\$150,500	\$770,875-\$886,375
Buffalo Ridge Elementary				
2021-22	\$917,800	\$917,800	\$91,900-\$394,800	\$1,927,500-\$2,230,400
Cantril Building				
2021-22	\$1,576,600	\$1,576,600	\$158,100-\$677,800	\$3,311,300-\$3,831,000
2022-23	\$150,000	\$157,500	\$15,000-\$64,600	\$322,500-\$372,100
2023-24	\$200,000	\$220,500	\$20,000-\$86,000	\$440,500-\$506,500
Castle Rock Elementary				
2021-22	\$547,500	\$547,500	\$54,900-\$235,400	\$1,149,900-\$1,330,400
2023-24	\$215,000	\$237,038	\$21,500-\$92,500	\$473,538-\$544,538
Castle Rock Middle School	· ·	•		· · ·
2021-22	\$1,004,800	\$1,004,800	\$100,600-\$432,100	\$2,110,200-\$2,441,700
2025-26	\$350,000	\$425,250	\$35,000-\$150,500	\$810,250-\$925,750
Castle View High School				
2021-22	\$268,900	\$268,900	\$27,000-\$115,600	\$564,800-\$653,400
2025-26	\$3,400,000	\$4,131,000	\$340,000-\$1,462,100	\$7,871,000-\$8,993,100
Chaparral High School				
2021-22	\$1,524,800	\$1,524,800	\$152,600-\$655,700	\$3,202,200-\$3,705,300
2025-26	\$250,000	\$303,750	\$25,000-\$107,500	\$578,750-\$661,250
Cherokee Trail Elementary		,		· ·
2021-22	\$550,400	\$550,400	\$55,200-\$236,900	\$1,156,000-\$1,337,700
2022-23	\$330,000	\$346,500	\$33,000-\$141,900	\$709,500-\$818,400
2025-26	\$15,000	\$18,225	\$1,500-\$6,500	\$34,725-\$39,725
Cherry Valley Elementary			. , , , , , , , , , , , , , , , , , , ,	
2021-22	\$169,400	\$169,400	\$16,900-\$72,700	\$355,700-\$411,500
2022-23	\$53,100	\$55,755	\$5,400-\$22,900	\$114,255-\$131,755
2025-26	\$25,000	\$30,375	\$2,500-\$10,800	\$57,875-\$66,175
Cimarron Middle School	,	,	, , ,	,
2024-25	\$725,000	\$839,550	\$72,500-\$311,800	\$1,637,050-\$1,876,350
Clear Sky Elementary		,	, , , , , , , , , , , , , , , , , , , ,	, , , , , , , , , , , , , , , , , , , ,
2021-22	\$25,000	\$25,000	\$2,500-\$10,800	\$52,500-\$60,800
2022-23	\$916,100	\$961,905	\$91,700-\$394,000	\$1,969,705-\$2,272,005
Copper Mesa Elementary			.,	. ,, 42,2.2,300
2021-22	\$276,600	\$276,600	\$27,900-\$119,100	\$581,100-\$672,300
2023-24	\$560,000	\$617,400	\$56,000-\$240,900	\$1,233,400-\$1,418,300
	4300,000	÷017,100	+50,000 #2 10,500	,=55,100 \$1,110,500

	Estimated Construction Cost	Estimated Inflation	Potential Regulatory, Professional Services, and Contracting Costs	Estimated Total Project Cost
Cougar Run Elementary				
2021-22	\$1,051,000	\$1,051,000	\$105,200-\$452,100	\$2,207,200-\$2,554,100
2025-26	\$260,000	\$315,900	\$26,000-\$111,800	\$601,900-\$687,700
Coyote Creek Elementary	•			
2021-22	\$639,600	\$639,600	\$64,000-\$274,700	\$1,343,200-\$1,553,900
2024-25	\$1,130,000	\$1,308,540	\$113,000-\$485,900	\$2,551,540-\$2,924,440
Cresthill Middle School			•	
2021-22	\$613,100	\$613,100	\$61,300-\$263,600	\$1,287,500-\$1,489,800
2022-23	\$44,000	\$46,200	\$4,400-\$19,000	\$94,600-\$109,200
2023-24	\$950,000	\$1,047,375	\$95,000-\$408,500	\$2,092,375-\$2,405,875
2024-25	\$750,000	\$868,500	\$75,000-\$322,500	\$1,693,500-\$1,941,000
DC Oakes High School / District N		7000,000	***************************************	4 1,000,000 4 1,0 11,000
2021-22	\$335,000	\$335,000	\$33,500-\$144,200	\$703,500-\$814,200
2022-23	\$80,000	\$84,000	\$8,000-\$34,400	\$172,000-\$198,400
2023-24	\$300,000	\$330,750	\$30,000-\$129,100	\$660,750-\$759,850
2025-26	\$100,000	\$121,500	\$10,000-\$43,000	\$231,500-\$264,500
DCHS Stadium	\$100,000	\$121,300	\$10,000 \$43,000	\$231,300 \$20 1 ,300
2021-22	\$394,400	\$394,400	\$39,500-\$169,600	\$828,300-\$958,400
Douglas County High School	\$354,400	\$39 1 ,700	\$39,300-\$109,000	\$020,500-\$950,400
2021-22	\$7,924,000	\$7,924,000	\$792,700-\$3,405,300	\$16,640,700-\$19,253,300
2022-23	\$50,000	\$52,500	\$5,000-\$21,500	\$107,500-\$124,000
2025-26	\$950,000	\$1,154,250	\$95,000-\$21,300	
	\$930,000	\$1,134,230	\$95,000-\$406,500	\$2,199,250-\$2,512,750
Eagle Ridge Elementary	¢522.700	¢522.700	¢52,200,¢225,200	£1,000,700,£1,272,600
2021-22	\$523,700	\$523,700	\$52,300-\$225,200	\$1,099,700-\$1,272,600
Early Childhood Center-CR	¢130.400	¢120.400	\$13,000 \$55,000	¢272.000.¢216.000
2021-22	\$130,400	\$130,400	\$13,000-\$56,000	\$273,800-\$316,800
Echo Park Stadium	¢1,000,000	¢1,000,000	¢100,000,¢420,000	£3.100.000 £3.430.000
2021-22	\$1,000,000	\$1,000,000	\$100,000-\$430,000	\$2,100,000-\$2,430,000
Eldorado Elementary		* 410.000	442 100 4100 100	* 0.70 700 #1 01 7 700
2021-22	\$418,800	\$418,800	\$42,100-\$180,100	\$879,700-\$1,017,700
2022-23	\$198,400	\$208,320	\$19,900-\$85,300	\$426,620-\$492,020
2025-26	\$550,000	\$668,250	\$55,000-\$236,500	\$1,273,250-\$1,454,750
Flagstone Elementary			T	
2021-22	\$467,500	\$467,500	\$46,700-\$200,800	\$981,700-\$1,135,800
2022-23	\$600,000	\$630,000	\$60,000-\$258,100	\$1,290,000-\$1,488,100
Fox Creek Elementary				
2021-22	\$506,200	\$506,200	\$50,500-\$217,500	\$1,062,900-\$1,229,900
2024-25	\$660,000	\$764,280	\$66,000-\$283,800	\$1,490,280-\$1,708,080
2025-26	\$430,000	\$522,450	\$43,000-\$184,900	\$995,450-\$1,137,350
Franktown Elementary				
2021-22	\$850,000	\$850,000	\$84,900-\$365,400	\$1,784,900-\$2,065,400
2022-23	\$90,700	\$95,235	\$9,100-\$39,100	\$195,035-\$225,035
Frontier Valley Elementary				
2021-22	\$693,400	\$693,400	\$69,600-\$298,200	\$1,456,400-\$1,685,000
2022-23	\$101,100	\$106,155	\$10,200-\$43,500	\$217,455-\$250,755
Gold Rush Elementary				
2021-22	\$25,000	\$25,000	\$2,500-\$10,800	\$52,500-\$60,800
2022-23	\$1,443,100	\$1,515,255	\$144,700-\$620,600	\$3,103,055-\$3,578,955
Heritage Elementary		. ,		
2021-22	\$390,500	\$390,500	\$38,900-\$167,700	\$819,900-\$948,700

	Estimated Construction Cost	Estimated Inflation	Potential Regulatory, Professional Services, and Contracting Costs	Estimated Total Project Cost
Heritage Elementary				
2022-23	\$50,800	\$53,340	\$5,200-\$21,900	\$109,340-\$126,040
2025-26	\$650,000	\$789,750	\$65,000-\$279,500	\$1,504,750-\$1,719,250
Highlands Ranch High School				
2021-22	\$2,151,500	\$2,151,500	\$215,400-\$925,300	\$4,518,400-\$5,228,300
2022-23	\$247,500	\$259,875	\$24,800-\$106,500	\$532,175-\$613,875
2025-26	\$100,000	\$121,500	\$10,000-\$43,000	\$231,500-\$264,500
Iron Horse Elementary				
2021-22	\$1,308,500	\$1,308,500	\$130,900-\$562,700	\$2,747,900-\$3,179,700
2022-23	\$250,000	\$262,500	\$25,000-\$107,500	\$537,500-\$620,000
Joint Service Center				
2021-22	\$1,182,800	\$1,182,800	\$118,100-\$508,500	\$2,483,700-\$2,874,100
2023-24	\$15,000	\$16,538	\$1,500-\$6,500	\$33,038-\$38,038
Larkspur Elementary				
2021-22	\$990,400	\$990,400	\$98,800-\$425,500	\$2,079,600-\$2,406,300
2022-23	\$606,400	\$636,720	\$60,600-\$260,600	\$1,303,720-\$1,503,720
2024-25	\$350,000	\$405,300	\$35,000-\$150,500	\$790,300-\$905,800
Legacy Point Elementary				
2021-22	\$262,000	\$262,000	\$26,100-\$112,400	\$550,100-\$636,400
2022-23	\$986,000	\$1,035,300	\$98,600-\$424,100	\$2,119,900-\$2,445,400
Legend High School				
2021-22	\$100,000	\$100,000	\$10,000-\$43,000	\$210,000-\$243,000
2022-23	\$2,504,600	\$2,629,830	\$250,800-\$1,077,300	\$5,385,230-\$6,211,730
Lone Tree Elementary	T			
2021-22	\$675,000	\$675,000	\$67,500-\$290,300	\$1,417,500-\$1,640,300
2022-23	\$628,000	\$659,400	\$63,300-\$270,300	\$1,350,700-\$1,557,700
Mammoth Heights Elementary	I		T	
2021-22	\$25,000	\$25,000	\$2,500-\$10,800	\$52,500-\$60,800
2022-23	\$986,900	\$1,036,245	\$99,100-\$424,600	\$2,122,245-\$2,447,745
Meadow View Elementary				
2021-22	\$342,200	\$342,200	\$34,300-\$147,300	\$718,700-\$831,700
2022-23	\$100,000	\$105,000	\$10,000-\$43,000	\$215,000-\$248,000
Mesa Middle School	#25.000	* 25.000	#2.500.#10.000	#52 500 #50 000
2021-22	\$25,000	\$25,000	\$2,500-\$10,800	\$52,500-\$60,800
2022-23	\$1,257,800	\$1,320,690	\$126,100-\$540,900	\$2,704,590-\$3,119,390
Mountain Ridge Middle School 2021-22	¢601 200	¢601.200	\$69,200-\$297,000	¢1 451 600 ¢1 670 400
	\$691,200 \$1,890,000	\$691,200	\$189,000-\$812,800	\$1,451,600-\$1,679,400 \$4,063,500-\$4,687,300
2022-23	\$1,890,000	\$1,984,500	\$189,000-\$812,800	\$4,065,500-\$4,667,500
Mountain View Elementary	¢014.000	¢014.000	¢01 500 ¢202 200	¢1 021 200 ¢2 222 100
2021-22	\$914,900 \$2,800	\$914,900 \$2,940	\$91,500-\$393,300 \$300-\$1,200	\$1,921,300-\$2,223,100 \$6,040-\$6,940
2022-23 Mountain Vista High School	\$2,800	\$2,940	\$300-\$1,200	\$0,040-\$0,940
	\$561,700	\$561.700	\$56,000,\$241,500	\$1 170 400 \$1 364 000
2021-22 2022-23	\$1,350,000	\$561,700 \$1,417,500	\$56,000-\$241,500 \$135,100-\$580,500	\$1,179,400-\$1,364,900 \$2,902,600-\$3,348,000
2025-26	\$925,000	\$1,123,875	\$92,500-\$397,800	\$2,141,375-\$2,446,675
Northeast Elementary	Ψ923,000	Ψ1,143,073	\$32,300°\$337,000	Ψ2,1 T1,373 - Ψ2, 14 0,073
,	\$1,833,400	\$1,833,400	\$183,500-\$788,500	\$3,850,300-\$4,455,300
2021-22 2022-23	\$1,833,400	\$1,833,400	\$14,300-\$61,600	\$308,065-\$355,365
Northridge Elementary	₽143,300	⊋1.JU, 1 U.J	ψ1-7,300°-000	200,000-2000
2021-22	\$2.025.000	\$2,025,000	\$202 500 ¢074 000	¢4 272 500 ¢4 044 000
2021-22	\$2,035,000	\$2,035,000	\$203,500-\$874,900	\$4,273,500-\$4,944,900

	Estimated Construction Cost	Estimated Inflation	Potential Regulatory, Professional Services, and Contracting Costs	Estimated Total Project Cost
Northridge Elementary				
2022-23	\$100,000	\$105,000	\$10,000-\$43,000	\$215,000-\$248,000
Operations & Maintenance East Fa	cility			
2021-22	\$700,200	\$700,200	\$70,000-\$300,900	\$1,470,400-\$1,701,300
2025-26	\$300,000	\$364,500	\$30,000-\$129,000	\$694,500-\$793,500
Operations & Maintenance West Fa	acility			
2021-22	\$17,800	\$17,800	\$1,900-\$7,700	\$37,500-\$43,300
2022-23	\$35,000	\$36,750	\$3,500-\$15,100	\$75,250-\$86,850
Pine Grove Elementary				
2021-22	\$221,000	\$221,000	\$22,000-\$94,700	\$464,000-\$536,700
2024-25	\$735,000	\$851,130	\$73,500-\$316,100	\$1,659,630-\$1,902,230
2025-26	\$450,000	\$546,750	\$45,000-\$193,500	\$1,041,750-\$1,190,250
Pine Lane				
2021-22	\$2,153,300	\$2,153,300	\$215,400-\$926,000	\$4,522,000-\$5,232,600
2022-23	\$316,600	\$332,430	\$31,900-\$136,400	\$680,930-\$785,430
2023-24	\$1,000,000	\$1,102,500	\$100,000-\$430,000	\$2,202,500-\$2,532,500
Pioneer Elementary			<u> </u>	
2021-22	\$988,100	\$988,100	\$99,100-\$424,900	\$2,075,300-\$2,401,100
Plum Creek Academy	·	·		
2023-24	\$270,000	\$297,675	\$27,000-\$116,100	\$594,675-\$683,775
Ponderosa High School				
2021-22	\$1,959,100	\$1,959,100	\$196,100-\$842,100	\$4,114,300-\$4,760,300
2022-23	\$275,000	\$288,750	\$27,500-\$118,300	\$591,250-\$682,050
Prairie Crossing Elementary	·	·		·
2021-22	\$538,500	\$538,500	\$53,900-\$231,600	\$1,130,900-\$1,308,600
2022-23	\$146,800	\$154,140	\$14,700-\$63,100	\$315,640-\$364,040
2025-26	\$550,000	\$668,250	\$55,000-\$236,500	\$1,273,250-\$1,454,750
Ranch View Middle School	·	·		
2021-22	\$1,307,400	\$1,307,400	\$130,400-\$561,800	\$2,745,200-\$3,176,600
2023-24	\$725,000	\$799,313	\$72,500-\$311,800	\$1,596,813-\$1,836,113
Redstone Elementary	·	·		
2021-22	\$727,200	\$727,200	\$72,700-\$312,600	\$1,527,100-\$1,767,000
2023-24	\$560,000	\$617,400	\$56,000-\$240,900	\$1,233,400-\$1,418,300
Renaissance Magnet School	·	·		
2021-22	\$56,100	\$56,100	\$5,500-\$24,000	\$117,700-\$136,200
2025-26	\$1,385,000	\$1,682,775	\$138,500-\$595,700	\$3,206,275-\$3,663,475
Rock Canyon High School				
2021-22	\$418,000	\$418,000	\$41,700-\$179,700	\$877,700-\$1,015,700
2023-24	\$3,477,200	\$3,833,613	\$347,700-\$1,495,300	\$7,658,513-\$8,806,113
Rock Ridge Elementary	· ·			
2021-22	\$78,600	\$78,600	\$7,800-\$33,800	\$165,000-\$191,000
2022-23	\$385,800	\$405,090	\$38,600-\$165,900	\$829,490-\$956,790
Rocky Heights Middle School			, , , , , , , , , , , , , , , , , , ,	
2021-22	\$832,800	\$832,800	\$83,400-\$357,900	\$1,749,000-\$2,023,500
2022-23	\$1,790,000	\$1,879,500	\$179,000-\$769,800	\$3,848,500-\$4,439,300
Roxborough Intermediate				
2021-22	\$80,000	\$80,000	\$8,000-\$34,500	\$168,000-\$194,500
2022-23	\$644,000	\$676,200	\$64,700-\$277,100	\$1,384,900-\$1,597,300
Roxborough Primary	,,,,,,			, , , , , , , , , , , , , , , , , , , ,
2021-22	\$1,770,600	\$1,770,600	\$176,900-\$761,300	\$3,718,100-\$4,302,500
·	\$1,770,000	\$1,770,000	\$170,500 \$701,500	+3,7 13,133 \$ 1,332,300


	Estimated Construction Cost	Estimated Inflation	Potential Regulatory, Professional Services, and Contracting Costs	Estimated Total Project Cost
Roxborough Primary				
2022-23	\$220,000	\$231,000	\$22,000-\$94,600	\$473,000-\$545,600
2023-24	\$75,000	\$82,688	\$7,500-\$32,300	\$165,188-\$189,988
2024-25	\$510,000	\$590,580	\$51,000-\$219,300	\$1,151,580-\$1,319,880
Saddle Ranch Elementary			•	
2021-22	\$444,100	\$444,100	\$44,400-\$190,900	\$932,600-\$1,079,100
Sage Canyon Elementary				
2021-22	\$25,000	\$25,000	\$2,500-\$10,800	\$52,500-\$60,800
2023-24	\$560,000	\$617,400	\$56,000-\$240,800	\$1,233,400-\$1,418,200
Sagewood Middle School	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	7011,100	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	+
2021-22	\$875,700	\$875,700	\$87,700-\$376,800	\$1,839,100-\$2,128,200
2023-24	\$725,000	\$799,313	\$72,500-\$311,800	\$1,596,813-\$1,836,113
Sand Creek Elementary	\$723,000	\$755,515	\$72,300 \$311,000	\$1,330,013 \$1,030,113
2021-22	\$1,568,100	\$1,568,100	\$156,700-\$674,000	\$3,292,900-\$3,810,200
2025-26	\$100,000	\$121,500	\$10,000-\$43,000	\$231,500-\$264,500
Sedalia Elementary	\$100,000	\$121,300	\$10,000-\$43,000	\$231,300-\$204,300
2021-22	\$2,324,200	\$2,324,200	\$232,000-\$998,900	\$4,880,400-\$5,647,300
2025-26	\$300,000	\$364,500	\$30,000-\$129,000	\$694,500-\$793,500
Shea Stadium	\$300,000	\$304,300	\$30,000-\$129,000	\$094,300-\$793,300
	¢970,900	¢970.900	¢07.200 ¢274.400	¢1 939 900 ¢3 116 000
2021-22	\$870,800	\$870,800	\$87,200-\$374,400	\$1,828,800-\$2,116,000
Sierra Middle School	#1 002 C00	¢1 002 000	¢100 700 ¢775 500	¢2.707.000.¢4.202.700
2021-22	\$1,803,600	\$1,803,600	\$180,700-\$775,500	\$3,787,900-\$4,382,700
2022-23	\$50,000	\$52,500	\$5,000-\$21,500	\$107,500-\$124,000
Soaring Hawk Elementary	1	4	I +== +== +== +==	
2021-22	\$723,200	\$723,200	\$72,400-\$311,100	\$1,518,800-\$1,757,500
2023-24	\$525,000	\$578,813	\$52,500-\$225,800	\$1,156,313-\$1,329,613
South Ridge Elementary	T		•	
2021-22	\$1,289,200	\$1,289,200	\$129,000-\$554,200	\$2,707,400-\$3,132,600
2024-25	\$200,000	\$231,600	\$20,000-\$86,000	\$451,600-\$517,600
Stone Mountain Elementary				
2021-22	\$55,700	\$55,700	\$5,600-\$24,000	\$117,000-\$135,400
2022-23	\$699,700	\$734,685	\$70,100-\$301,000	\$1,504,485-\$1,735,385
Student Assistance Office				
2021-22	\$183,100	\$183,100	\$18,600-\$78,700	\$384,800-\$444,900
Summit View Elementary				
2021-22	\$525,000	\$525,000	\$52,600-\$225,800	\$1,102,600-\$1,275,800
2022-23	\$665,000	\$698,250	\$66,500-\$286,000	\$1,429,750-\$1,649,250
2024-25	\$350,000	\$405,300	\$35,000-\$150,500	\$790,300-\$905,800
ThunderRidge High School				
2021-22	\$1,325,600	\$1,325,600	\$132,600-\$569,700	\$2,783,800-\$3,220,900
2025-26	\$400,000	\$486,000	\$40,000-\$172,000	\$926,000-\$1,058,000
Timber Trail Elementary				
2021-22	\$339,100	\$339,100	\$33,900-\$145,600	\$712,100-\$823,800
2022-23	\$445,100	\$467,355	\$44,500-\$191,400	\$956,955-\$1,103,855
Trailblazer Elementary			•	
2021-22	\$797,400	\$797,400	\$79,900-\$342,900	\$1,674,700-\$1,937,700
Transportation Terminal West Fa		·		
2021-22	\$687,900	\$687,900	\$68,900-\$295,800	\$1,444,700-\$1,671,600
2022-23	\$50,000	\$52,500	\$5,000-\$21,500	\$107,500-\$124,000

	Estimated Construction Cost	Estimated Inflation	Potential Regulatory, Professional Services, and Contracting Costs	Estimated Total Project Cost
Transportation Terminal North Fac	cility			
2021-22	\$2,037,200	\$2,037,200	\$203,800-\$876,000	\$4,278,200-\$4,950,400
Nutrition/Food Services Warehous	e/Service Center/Se	curity		
2021-22	\$465,900	\$465,900	\$46,800-\$200,500	\$978,600-\$1,132,300
2022-23	\$11,000	\$11,550	\$1,100-\$4,800	\$23,650-\$27,350
West Support Center				
2021-22	\$320,600	\$320,600	\$32,200-\$138,000	\$673,400-\$779,200
Wilcox Building				
2021-22	\$2,342,900	\$2,342,900	\$234,300-\$1,007,600	\$4,920,100-\$5,693,400
Wildcat Mountain Elementary				
2021-22	\$409,100	\$409,100	\$40,900-\$176,000	\$859,100-\$994,200
2022-23	\$550,000	\$577,500	\$55,000-\$236,500	\$1,182,500-\$1,364,000

^{*}Note* The Needs by Year list shown above is inclusive of only those needs that have been estimated by year. This includes those needs identified on each individual facility profile page.

Appendix 4 Capital Needs Deltas Since 2019-20

Capital Item	2019-20 Total Project Cost Estimate	2021-22 Total Project Cost Estimate	2019-20 vs. 2021-22 Total Project Cost Delta
ADA Contingency	\$525,000-\$607,500	\$525,000-\$607,500	\$0
Athletics	\$4,340,110-\$6,208,070	\$1,216,280-\$1,739,780	(\$3,123,830) - (\$4,468,290)
Charter Schools	\$26,514,717-\$37,193,017	\$65,322,081-\$82,837,995	\$38,807,364 - \$46,644,978
Facility Reinvestment-Neighborhood Schools, Support Facilities	\$196,905,620-\$281,618,500	\$138,267,245 -\$197,811,544	(\$58,638,375) - (\$83,806,956)
FF&E	\$13,587,250-\$18,254,225	\$7,802,750-\$11,161,380	(\$5,784,500) - (\$7,092,845)
Information Technology	\$0	\$32,300,000	\$32,300,000
Mobiles	\$6,930,000-\$8,019,000	\$6,930,000-\$8,019,000	\$0
New Construction (1-5 Years, DCSD Standards)	\$455,699,301	\$394,960,418	(\$60,738,883)
Playground Equipment	\$525,000-\$607,500	\$210,000-\$243,000	(\$315,000) -(\$364,500)
Safety & Security	\$4,980,215	\$49,926,700	\$44,946,485
SPED Contingency	\$525,000-\$607,500	\$525,000-\$607,500	\$0
Support Fleet	\$6,715,820	\$5,915,820	(\$800,000)
Transportation	\$19,369,895	\$32,755,000	\$13,385,105



Capital Need by Tier	Estimated Capital Cost-2021	Potential Regulatory, Professional Services, and Contracting Costs	Potential Inflation Costs	Total Project Cost
New Construction	\$423,089,448	\$0	\$0	\$423,089,448
Facility Reinvestment	\$120,250,900	\$12,003,800-\$51,706,700	\$6,012,545-\$25,854,133	\$138,267,245-\$197,811,544
Bond Funded	\$3,486,500	\$348,400-\$1,499,300	\$174,325-\$749,598	\$4,009,225-\$5,735,398
1	\$44,687,200	\$4,441,400-\$19,218,800	\$2,234,360-\$9,607,748	\$51,362,960-\$73,513,748
2	\$48,829,300	\$4,889,800-\$20,997,000	\$2,441,465-\$10,498,300	\$56,160,565-\$80,324,600
3	\$19,762,800	\$1,976,100-\$8,493,700	\$988,140-\$4,249,002	\$22,727,040-\$32,505,502
4	\$3,485,100	\$348,100-\$1,497,900	\$174,255-\$749,297	\$4,007,455-\$5,732,297
Charter Schools	\$55,594,330	\$6,948,534-\$15,293,034	\$2,779,217-\$11,950,631	\$65,322,081-\$82,837,995
1	\$4,188,880	\$459,320-\$1,759,020	\$209,444-\$900,609	\$4,857,644-\$6,848,509
2	\$3,998,140	\$401,560-\$1,702,860	\$199,907-\$859,600	\$4,599,607-\$6,560,600
3	\$2,508,230	\$451,770-\$1,114,670	\$125,412-\$539,269	\$3,085,412-\$4,162,169
4	\$412,760	\$38,740-\$141,040	\$20,638-\$88,743	\$472,138-\$642,543
Untiered	\$44,486,320	\$5,597,144-\$10,575,444	\$2,223,816-\$9,562,409	\$52,307,280-\$64,624,173
Safety & Security	\$49,926,700	\$0	\$0	\$49,926,700
1	\$18,456,200	\$O	\$0	\$18,456,200
2	\$23,721,000	\$0	\$0	\$23,721,000
4	\$7,749,500	\$O	\$0	\$7,749,500
Transportation	\$32,755,000	\$0	\$0	\$32,755,000
1	\$4,330,000	\$0	\$0	\$4,330,000
2	\$16,105,000	\$0	\$0	\$16,105,000
3	\$12,320,000	\$0	\$0	\$12,320,000
Information Technology	\$32,300,000	\$0	\$0	\$32,300,000
1	\$31,550,000	\$0	\$0	\$31,550,000
2	\$750,000	\$0	\$0	\$750,000
FF&E	\$6,785,000	\$678,500-\$2,917,600	\$339,250-\$1,458,780	\$7,802,750-\$11,161,380
3	\$6,785,000	\$678,500-\$2,917,600	\$339,250-\$1,458,780	\$7,802,750-\$11,161,380
Athletics	\$1,057,500	\$105,900-\$454,900	\$52,880-\$227,380	\$1,216,280-\$1,739,780
2	\$1,057,500	\$105,900-\$454,900	\$52,880-\$227,380	\$1,216,280-\$1,739,780
Support Fleet	\$5,915,820	\$0	\$0	\$5,915,820
1	\$5,915,820	\$0	\$0	\$5,915,820
Mobiles	\$6,600,000	\$0	\$330,000-\$1,419,000	\$6,600,000-\$8,019,000
3	\$6,600,000	\$0	\$330,000-\$1,419,000	\$6,930,000-\$8,019,000
ADA Contingency	\$500,000	\$0	\$25,000-\$107,500	\$525,000-\$607,500
SPED Contingency	\$500,000	\$0	\$25,000-\$107,500	\$525,000-\$607,500
Playgrounds	\$200,000	\$0	\$10,000-\$43,000	\$210,000-\$243,000
Grand Total	\$735,474,698	\$19,736,734-\$70,372,234	\$9,573,892-\$41,167,923	\$764,785,324-\$847,014,666



