

## Rocky Heights Middle School

- 12 total drinking water fixtures tested
- 11 water fixtures resulted less than 15 ppb
- Replacement/Removal of 1 water fixtures occurred
  - A fixture in room 210 was replaced and retested
- Following Replacement/Removal, all results less than 15 ppb - no further action needed

Site	Sample ID	Initial Result (ppb)	1st Collection Date	Validation Result (ppb)	2nd Collection Date	Clearance Result (ppb)	3rd Collection Date
Rocky Heights MS	HR 359 Kitchen 3rd Sink	4.4	3/13/2018	N/A	N/A	N/A	N/A
Rocky Heights MS	HR 360 Bottle Filler Next to Kitchen	0.1	3/13/2018	N/A	N/A	N/A	N/A
Rocky Heights MS	HR 361 132 5th Sink	1.1	3/13/2018	N/A	N/A	N/A	N/A
Rocky Heights MS	HR 362 Fountain Next to Gym	0.1	3/13/2018	N/A	N/A	N/A	N/A
Rocky Heights MS	HR 363 214 1st Sink	0.5	3/13/2018	N/A	N/A	N/A	N/A
Rocky Heights MS	HR 364 210 2nd Sink	370.4	3/13/2018	490	3/28/2018	9.4	4/28/2018
Rocky Heights MS	RH001 Office Breakroom Sink	0.4	5/17/2018	N/A	N/A	N/A	N/A
Rocky Heights MS	RH002 Drinking Fountain Next to Rm 110	0.1	5/17/2018	N/A	N/A	N/A	N/A
Rocky Heights MS	RH003 Room 114 Sink	0.5	5/17/2018	N/A	N/A	N/A	N/A
Rocky Heights MS	RH004 Drinking Fountain Next to 222	0.1	5/17/2018	N/A	N/A	N/A	N/A
Rocky Heights MS	RH005 Drinking Fountain Next to Rm 224	0.1	5/17/2018	N/A	N/A	N/A	N/A
Rocky Heights MS	RH006 Drinking Fountain Next to Rm 145	0.1	5/17/2018	N/A	N/A	N/A	N/A