

## Pine Lane Intermediate

- 41 total drinking water fixtures tested
- 39 water fixtures resulted less than 15 ppb
- Replacement/Removal of 2 water fixtures occurred
  - Specific fixtures in rooms 41 and 44 were replaced and retested
- Following Replacement/Removal, all results less than 15 ppb – no further action needed

Site	Sample ID	Initial Result (ppb)	1st Collection Date	Validation Result (ppb)	2nd Collection Date	Clearance Result (ppb)	3rd Collection Date
Pine Lane Intermediate	06 Copy Room	10.9	4/28/2018	N/A	N/A	N/A	N/A
Pine Lane Intermediate	08 Sink	0.9	4/28/2018	N/A	N/A	N/A	N/A
Pine Lane Intermediate	10 Fountain	2.8	4/28/2018	N/A	N/A	N/A	N/A
Pine Lane Intermediate	10 Sink	11.1	4/28/2018	N/A	N/A	N/A	N/A
Pine Lane Intermediate	13 Fountain	2.6	4/28/2018	N/A	N/A	N/A	N/A
Pine Lane Intermediate	13 Sink	3.8	4/28/2018	N/A	N/A	N/A	N/A
Pine Lane Intermediate	Gym Fountain	1.9	4/28/2018	N/A	N/A	N/A	N/A
Pine Lane Intermediate	Kitchen # 1	3.2	4/28/2018	N/A	N/A	N/A	N/A
Pine Lane Intermediate	Kitchen # 2	3.5	4/28/2018	N/A	N/A	N/A	N/A
Pine Lane Intermediate	Kitchen # 3	6.1	4/28/2018	N/A	N/A	N/A	N/A
Pine Lane Intermediate	Lobby Bottle Filler	0.2	4/28/2018	N/A	N/A	N/A	N/A
Pine Lane Intermediate	Lobby Lower Sink	0.2	4/28/2018	N/A	N/A	N/A	N/A
Pine Lane Intermediate	Lobby Upper Sink	0.2	4/28/2018	N/A	N/A	N/A	N/A
Pine Lane Intermediate	Lower Fountain by Room 22	0.3	4/28/2018	N/A	N/A	N/A	N/A
Pine Lane Intermediate	Lower Fountain By Room 33	0.4	4/28/2018	N/A	N/A	N/A	N/A
Pine Lane Intermediate	Room 20 Sink	6.2	4/28/2018	N/A	N/A	N/A	N/A
Pine Lane Intermediate	Room 25 Fountain	3.0	4/28/2018	N/A	N/A	N/A	N/A
Pine Lane Intermediate	Room 25 Sink	1.3	4/28/2018	N/A	N/A	N/A	N/A
Pine Lane Intermediate	Room 26 Fountain	5.0	4/28/2018	N/A	N/A	N/A	N/A
Pine Lane Intermediate	Room 26 Sink	14.7	4/28/2018	N/A	N/A	N/A	N/A
Pine Lane Intermediate	Room 27 Fountain	1.2	4/28/2018	N/A	N/A	N/A	N/A
Pine Lane Intermediate	Room 27 Sink	4.5	4/28/2018	N/A	N/A	N/A	N/A
Pine Lane Intermediate	Room 28 Fountain	2.1	4/28/2018	N/A	N/A	N/A	N/A
Pine Lane Intermediate	Room 28 Sink	2.2	4/28/2018	N/A	N/A	N/A	N/A
Pine Lane Intermediate	Room 29 Sink	0.7	4/28/2018	N/A	N/A	N/A	N/A
Pine Lane Intermediate	Room 31 Fountain	1.6	4/28/2018	N/A	N/A	N/A	N/A
Pine Lane Intermediate	Room 31 Sink	3.9	4/28/2018	N/A	N/A	N/A	N/A
Pine Lane Intermediate	Room 32 Fountain	1.5	4/28/2018	N/A	N/A	N/A	N/A

Pine Lane Intermediate School

Site	Sample ID	Initial Result (ppb)	1st Collection Date	Validation Result (ppb)	2nd Collection Date	Clearance Result (ppb)	3rd Collection Date
Pine Lane Intermediate	Room 32 Sink	12.2	4/28/2018	N/A	N/A	N/A	N/A
Pine Lane Intermediate	Room 40 Fountain	2.8	4/28/2018	N/A	N/A	N/A	N/A
Pine Lane Intermediate	Room 40 Sink	7.0	4/28/2018	N/A	N/A	N/A	N/A
Pine Lane Intermediate	Room 41 Fountain	2.0	4/28/2018	N/A	N/A	N/A	N/A
Pine Lane Intermediate	Room 41 Sink	17.3	4/28/2018	6.6	5/19/2018	N/A	N/A
Pine Lane Intermediate	Room 42 Sink # 1	0.0	4/28/2018	N/A	N/A	N/A	N/A
Pine Lane Intermediate	Room 42 Sink # 2	2.1	4/28/2018	N/A	N/A	N/A	N/A
Pine Lane Intermediate	Room 43 Fountain	1.3	4/28/2018	N/A	N/A	N/A	N/A
Pine Lane Intermediate	Room 43 Sink	7.5	4/28/2018	N/A	N/A	N/A	N/A
Pine Lane Intermediate	Room 44 Fountain	3.2	4/28/2018	N/A	N/A	N/A	N/A
Pine Lane Intermediate	Room 44 Sink	17.2	4/28/2018	0.3	5/19/2018	N/A	N/A
Pine Lane Intermediate	Upper Fountain by Room 22	0.2	4/28/2018	N/A	N/A	N/A	N/A
Pine Lane Intermediate	Upper Fountain By Room 33	0.4	4/28/2018	N/A	N/A	N/A	N/A