ECC South

- 3 drinking water fixtures tested
 All results less than 15 ppb no further action needed

Site	Sample ID	Initial Result (ppb)	1st Collection Date
ECC South	CR062 A117 Sink	0.6	3/3/2018
ECC South	CR061 A107 Sink	0.4	3/3/2018
ECC South	CR063 Lower Fountain in Lobby	0.1	3/3/2018