## Cherry Valley Elementary

- 9 total drinking water fixtures tested
- 8 water fixtures resulted less than 15 ppb
- Replacement/Removal of 1 water fixture occurred
  - A fixture in the kitchen was removed from service, replaced and retested
- Following Replacement/Removal, all results less than 15 ppb no further action needed

Site	Sample ID	Initial Result	1st Collection	Validation Result	2nd Collection	Clearance Result	3rd Collection
		(ppb)	Date	(ppb)	Date	(ppb)	Date
Cherry Valley ES	180310001-332 Break Room Sink	1.1	3/17/2018	N/A	N/A	N/A	N/A
Cherry Valley ES	180310001-333 Hall Bottle Filler	0.5	3/17/2018	N/A	N/A	N/A	N/A
Cherry Valley ES	180310001-334 Hall Fountain	0.8	3/17/2018	N/A	N/A	N/A	N/A
Cherry Valley ES	180310001-335 Kitchen #1	5.5	3/17/2018	N/A	N/A	N/A	N/A
Cherry Valley ES	180310001-336 Kitchen #2	4.1	3/17/2018	N/A	N/A	N/A	N/A
Cherry Valley ES	180310001-337 Kitchen #3	7.0	3/17/2018	N/A	N/A	N/A	N/A
Cherry Valley ES	180310001-338 Kitchen #4	19.0	3/17/2018	23	4/21/2018	12.9	6/28/2018
Cherry Valley ES	180310001-339 CV Schoolhouse Sink	5.0	3/17/2018	N/A	N/A	N/A	N/A
Cherry Valley ES	180310001-340 School House Faucet	2.2	3/17/2018	N/A	N/A	N/A	N/A