

Castle Rock Elementary School

- 60 drinking water fixtures tested
- All results less than 15 ppb - no further action needed

| Site | Sample ID | Initial Result (ppb) | 1st Collection Date |
|-------------------------------|----------------------|----------------------|---------------------|
| Castle Rock Elementary School | CR321 Rm 311 Sink | 14.1 | 4/14/2018 |
| Castle Rock Elementary School | CR325 Rm 309 Sink | 11.4 | 4/14/2018 |
| Castle Rock Elementary School | CR298 Rm 104 Bubbler | 10.4 | 4/14/2018 |
| Castle Rock Elementary School | CR314 Rm 314 Sink | 10.3 | 4/14/2018 |
| Castle Rock Elementary School | CR295 Rm 106 Sink | 10.1 | 4/14/2018 |
| Castle Rock Elementary School | CR276 Rm 212 Sink | 9.1 | 4/14/2018 |
| Castle Rock Elementary School | CR319 Rm 312 Sink | 9.0 | 4/14/2018 |
| Castle Rock Elementary School | CR323 Rm 310 Sink | 8.8 | 4/14/2018 |
| Castle Rock Elementary School | CR293 Rm 107 Sink | 8.7 | 4/14/2018 |
| Castle Rock Elementary School | CR294 Rm 107 Bubbler | 8.4 | 4/14/2018 |
| Castle Rock Elementary School | CR285 Rm 110 Sink | 8.2 | 4/14/2018 |
| Castle Rock Elementary School | CR306 Rm 318 Sink | 7.8 | 4/14/2018 |
| Castle Rock Elementary School | CR315 Rm 314 Bubbler | 7.6 | 4/14/2018 |
| Castle Rock Elementary School | CR279 Rm 113 Sink | 7.5 | 4/14/2018 |
| Castle Rock Elementary School | CR308 Rm 317 Sink | 7.5 | 4/14/2018 |
| Castle Rock Elementary School | CR281 Rm 112 Sink | 6.7 | 4/14/2018 |
| Castle Rock Elementary School | CR310 Rm 316 Sink | 6.6 | 4/14/2018 |
| Castle Rock Elementary School | CR326 Rm 309 Bubbler | 6.3 | 4/14/2018 |
| Castle Rock Elementary School | CR296 Rm 106 Bubbler | 6.2 | 4/14/2018 |
| Castle Rock Elementary School | CR307 Rm 318 Bubbler | 6.1 | 4/14/2018 |
| Castle Rock Elementary School | CR283 Rm 111 Sink | 5.8 | 4/14/2018 |
| Castle Rock Elementary School | CR299 Rm 101 Sink | 5.7 | 4/14/2018 |
| Castle Rock Elementary School | CR268 Room 205 Sink | 5.6 | 4/14/2018 |
| Castle Rock Elementary School | CR312 Rm 315 Sink | 5.5 | 4/14/2018 |

Castle Rock Elementary School

| Site | Sample ID | Initial Result (ppb) | 1st Collection Date |
|-------------------------------|--|----------------------|---------------------|
| Castle Rock Elementary School | CR271 Cafeteria Sink | 5.3 | 4/14/2018 |
| Castle Rock Elementary School | CR300 Rm 101 Bubbler | 5.2 | 4/14/2018 |
| Castle Rock Elementary School | CR287 Rm 109 Sink | 5.1 | 4/14/2018 |
| Castle Rock Elementary School | CR309 Rm 317 Bubbler | 5.1 | 4/14/2018 |
| Castle Rock Elementary School | CR291 Rm 108 Sink | 4.8 | 4/14/2018 |
| Castle Rock Elementary School | CR280 Rm 113 Bubbler | 4.5 | 4/14/2018 |
| Castle Rock Elementary School | CR322 Rm 311 Bubbler | 4.5 | 4/14/2018 |
| Castle Rock Elementary School | CR277 Rm 114 Sink | 4.2 | 4/14/2018 |
| Castle Rock Elementary School | CR282 Rm 112 Bubbler | 4.1 | 4/14/2018 |
| Castle Rock Elementary School | CR284 Rm 111 Bubbler | 3.8 | 4/14/2018 |
| Castle Rock Elementary School | CR292 Rm 108 Bubbler | 3.6 | 4/14/2018 |
| Castle Rock Elementary School | CR320 Rm 312 Bubbler | 3.5 | 4/14/2018 |
| Castle Rock Elementary School | CR301 Rm 102 Sink | 3.4 | 4/14/2018 |
| Castle Rock Elementary School | CR302 Rm 102 Bubbler | 3.1 | 4/14/2018 |
| Castle Rock Elementary School | CR297 Rm 104 Sink | 2.7 | 4/14/2018 |
| Castle Rock Elementary School | CR286 Rm110 Bubbler | 2.6 | 4/14/2018 |
| Castle Rock Elementary School | CR278 Drinking Fountain Next to Rm 114 | 2.4 | 4/14/2018 |
| Castle Rock Elementary School | CR273 Kitchen 2nd Sink | 2.3 | 4/14/2018 |
| Castle Rock Elementary School | CR317 Rm 313 Bubbler | 2.1 | 4/14/2018 |
| Castle Rock Elementary School | CR272 Kitchen 1st Sink | 2.0 | 4/14/2018 |
| Castle Rock Elementary School | CR313 Rm 315 Bubbler | 1.9 | 4/14/2018 |
| Castle Rock Elementary School | CR275 Kitchen 4th Sink | 1.7 | 4/14/2018 |
| Castle Rock Elementary School | CR288 Rm 109 Bubbler | 1.4 | 4/14/2018 |
| Castle Rock Elementary School | CR324 Rm 310 Bubbler | 1.3 | 4/14/2018 |
| Castle Rock Elementary School | CR316 Rm 313 Sink | 1.2 | 4/14/2018 |
| Castle Rock Elementary School | CR274 Kitchen 3rd Sink | 1.1 | 4/14/2018 |
| Castle Rock Elementary School | CR311 Rm 316 Bubbler | 0.9 | 4/14/2018 |
| Castle Rock Elementary School | CR267 Room 206 Sink | 0.5 | 4/14/2018 |
| Castle Rock Elementary School | CR318 Drinking Fountain Next to Rm 307 | 0.4 | 4/14/2018 |
| Castle Rock Elementary School | CR303 Teacher Lounge Sink | 0.3 | 4/14/2018 |

Castle Rock Elementary School

| Site | Sample ID | Initial Result (ppb) | 1st Collection Date |
|-------------------------------|--|----------------------|---------------------|
| Castle Rock Elementary School | CR269 Bottle Filler next to Stairwell | 0.2 | 4/14/2018 |
| Castle Rock Elementary School | CR270 DF Next to Stairwell | 0.2 | 4/14/2018 |
| Castle Rock Elementary School | CR289 Bottle Filler Next to Rm 100 | 0.1 | 4/14/2018 |
| Castle Rock Elementary School | CR290 Drinking Fountain Next to Rm 100 | 0.1 | 4/14/2018 |
| Castle Rock Elementary School | CR304 Bottle Filler Next to Rm 318 | 0.1 | 4/14/2018 |
| Castle Rock Elementary School | CR305 Drinking Fountain next to Rm 318 | 0.1 | 4/14/2018 |