

Wilcox

- 6 drinking water fixtures tested
- All results less than 15 ppb - no further action needed

Site	Sample ID	Initial Result (ppb)	1st Collection Date
Wilcox	CR074 Board Room Sink	2.3	3/3/2018
Wilcox	CR076 111 Sink	0.6	3/3/2018
Wilcox	CR075 Pk-12 Sink	0.5	3/3/2018
Wilcox	CR072 Fountain 3rd Floor Top of Stairs	0.4	3/3/2018
Wilcox	CR073 307 Sink	0.3	3/3/2018
Wilcox	CR077 Fountain in Basement	0.1	3/3/2018