

West Support Building

- **3 drinking water fixtures tested**
- **All results less than 15 ppb - no further action needed**

Site	Sample ID	Initial Result (ppb)	1st Collection Date
West Support Building	CR042 Upper Fountain Next to 118A	0.4	3/3/2018
West Support Building	CR043 113 Sink	0.4	3/3/2018
West Support Building	CR044 Sink in Hallway Next to 260	0.4	3/3/2018